



DEPARTMENT OF THE NAVY
HEADQUARTERS UNITED STATES MARINE CORPS
3000 MARINE CORPS PENTAGON
WASHINGTON DC 20350-3000

MCO 13670.1E
ASL
14 MAR 2016

MARINE CORPS ORDER 13670.1E

From: Commandant of the Marine Corps
To: Distribution List

Subj: MANAGEMENT AND ADMINISTRATION OF UNITED STATES MARINE
CORPS MOBILE FACILITY (MF) PROGRAM AND RELATED EQUIPMENT

Ref: (a) DTR 4500.9-R, "Defense Transportation Regulations,"
May 2008
(b) MIL-HDBK-138B
(c) COMNAVAIRFORINST 4790.2B
(d) MCWP 3-21.2
(e) NAVAIRINST 13670.1C
(f) NAVAIR 17-1-125
(g) NAVAIR 19-25-177
(h) AG-360MF-IIN-000
(i) AG-360MF-CCD-000
(j) SECNAV M-5210.1
(k) 5 U.S.C. 552a
(l) SECNAVINST 5211.5E
(m) SECNAV M-5214.1

Encl: (1) Sample Mobile Facility Deployable Readiness Report
(2) USMC MF TBA by Configuration Code
(3) USMC MF TBA by Contingency Support Package
(4) USMC MF TBA by Division
(5) USMC MF TBA Support Equipment by Configuration Code
(6) Mobile Facility/Ancillary Equipment/Administrative
Note Cross Reference
(7) Sample MF User O-Level Maintenance Syllabus

Report Required: Mobile Facility Deployable Readiness Report
(Report Control Symbol EXEMPT), par. 4b(3)(k)
and encl (1)

1. Situation. To promulgate policies, procedures, and guidance
regarding the management and administration of MFs and related
equipment assigned to U.S. Marine Corps commands.

2. Cancellation. MCO 13670.1D.

DISTRIBUTION STATEMENT A: Approved for public release;
distribution is unlimited.

14 MAR 2016

3. Mission. To provide Marine Corps Forces with deployable and environmentally controlled shelters for aircraft logistic support in tactical and garrison environments. All MFs and ancillary equipment will be managed, utilized and maintained in accordance with references (a) through (m) and policies set forth in this Order. Successful execution of this program relies heavily on proper management at all levels, but mission accomplishment requires appropriate actions at the user levels.

4. Execution

a. Commander's Intent and Concept of Operations

(1) Commander's Intent. Ensure the readiness of all MFs and ancillary equipment by providing support and sustainment in accordance with established policies and procedures.

(2) Concept of Operations. This program must be conducted on multiple levels.

(a) Headquarters Marine Corps (HQMC). The Aviation Support Logistics Avionics section (ASL-34) provides oversight and guidance to subordinate elements. ASL-34 also acts as the liaison and establishes the MF program requirements, on behalf of the Deputy Commandant of Aviation (DC AVN), to the U.S. Navy Naval Air Systems Command (NAVAIR) MF Program Manager.

(b) Marine Forces (MARFORs). The MARFOR Aviation Logistics Division (ALD) Avionics section provides oversight and guidance to subordinate elements. The MARFOR also acts as the liaison to HQMC (ASL-34) and the NAVAIR MF Program Manager.

(c) Marine Aircraft Wing (MAW). The MAW ALD Avionics Branch manages all MFs and ancillary equipment and coordinates the distribution of MF assets between higher and lower echelons.

(d) Marine Aviation Logistics Squadron (MALS). The MALS Avionics Officer (AVO) is responsible for the day-to-day operation, maintenance and management of all MF assets within the Marine Aircraft Group (MAG), to include supported units, such as Marine Wing Support Squadron (MWSS) and the Marine Air Control Squadron (MACS).

(e) Supported Units/Training Commands. The Commanding Officer/Officer-in-Charge (CO/OIC) of supported units using MF assets, must work in concert with the MALS AVO to ensure the successful execution of the MF program.

b. Subordinate Element Missions

(1) HQMC (ASL)

(a) Responsible for the management and the coordination of the U.S. Marine Corps MF program.

(b) Serve as the Table of Basic Allowance (TBA) program sponsor who publishes the MFs and associated ancillary equipment requirements in support of Marine Corps aviation.

(c) Collaborate with the MARFORs and the NAVAIR MF Program Office for production priorities, MF TBA requirements and incorporation. Annual review of the TBA will address any updates. Changes for the next MCO/TBA revision will be due by 30 September.

(2) Marine Forces (MARFORs)

(a) Responsible for the management and the coordination of the MARFOR MF program in accordance with references (a) through (m) and policies set forth in this Order.

(b) Assign, in writing, the MARFOR Mobile Facility Coordinator (MFC).

(c) Require the MARFOR MFC to be a certified International Convention for Safe Containers (CSC) inspector.

(d) Publish an MF inspection schedule via Naval message to ensure the MAW MF program is inspected by the MARFOR MFC biennially using the current Computerized Self Evaluation (CSEC) checklist.

(e) Forward biennial inspection results in Naval message format to Commandant of the Marine Corps (CMC) (ASL-34).

(f) Maintain file copies of the MF biennial inspection for a minimum of two years per reference (j).

(g) Upon MF survey approval, monitor MF disposition in accordance with this Order.

(h) Coordinate with the other MARFORs to establish MF requirements and production priorities. Deliver consolidated TBA inputs and production prioritization in email format to ASL-34B annually NLT 1 March.

(3) Marine Aircraft Wing (MAW)

(a) Responsible for the management and coordination of the MF program in accordance with references (a) through (m) and policies set forth in this Order.

(b) Assign, in writing, a MAW MFC. The MAW MFC shall be assigned duties as the MAW T-AVB Coordinator, who is responsible for providing training and oversight to the MALS MFC during T-AVB exercises.

(c) Ensure that the MAW MFC is a certified CSC inspector.

(d) Ensure the best possible MF deployable posture is maintained using assets within the MAW, through close coordination with MARFOR Aviation Logistics Department, Avionics (ALD-E) and strict adherence to the CSC program.

(e) Ensure timely and accurate submission of MF reports as required.

(f) Ensure that the MAW MFC accompanies the MARFOR MFC during the biennial MARFOR inspection of the MAW.

(g) Ensure that the MALS programs are inspected by the MAW MFC annually using the current CSEC checklist. On biennial years where MARFOR inspects the MALS, the MAW MFC is only responsible to perform a follow-up inspection on those discrepancy areas noted during the MARFOR inspection. Inspection results shall be forward DC AVN (ASL-34) in Naval message format via the MARFOR.

(h) Inform MARFOR ALD-E of changes in status of MF program equipment as they occur.

(i) Maintain file copies of the MF annual inspection for a minimum of two years per reference (j).

(j) Upon MF survey approval, ensure MF is disposed of per this Order.

(k) Provide a quarterly MF Deployable Readiness Report (MFDRR) in accordance with enclosure (1) to DC AVN (ASL) via the MARFOR by the last working day of each fiscal quarter. This reporting requirement is exempt from reports control according to reference (m), Part IV, paragraph 7j.

(4) Marine Aviation Logistics Squadron (MALS)

(a) Manage the local MF program, to include all divisions within MALS, deployed and deploying units and other supported units with MF requirements, in accordance with references (a) through (m) and policies set forth in this Order.

(b) Assign, in writing work center (W/C) 60C Staff Non Commissioned Officer in Charge (SNCOIC) as the MALS MFC.

(c) Ensure the MALS MFC holds the 6499 Military Occupational Specialty (MOS) and is a certified CSC inspector.

(d) Ensure the MALS MFC conducts periodic (quarterly) site visits to supported units to assist in management of the MF program.

(e) Ensure the best possible MF deployable posture through close coordination with the MAW MFC and strict adherence to the CSC program.

(f) Ensure that at least four members of the unit are certified CSC reinspectors and all CSC reinspectors are designated by the Avionics Officer via the Mobile Facility Coordinator (MFC). For new 6499 qualified Marines, who receive initial CSC training at the school house; will need to demonstrate to the MFC and Chain of Command proficiency and competence in the execution of CSC reinspection as per reference (b). Once this rapport has been established, the MFC may recommend locally the Marine be qualified through online AMMO-43-DL CSC Container Re-inspection course and designated as a CSC inspector.

(g) Ensure the established training tracks are being utilized to qualify user (i.e., department, division and section) personnel in MF Organizational Level (O-Level) maintenance in accordance with enclosure (7). Selected user personnel shall be trained to the level necessary to perform collateral duty inspections (i.e., scheduled maintenance and corrosion control). This training will be documented in the Collateral Duty Inspector (CDI) syllabus and miscellaneous sections, respectively, of the individual's training record. Training will be conducted by W/C 60C CDIs. The MALS MFC shall retain training records for personnel that do not have active ASM accounts.

(h) Ensure that Logbook and Inventory Records (LIRs) and OPNAV 4790/51, "Support Equipment Custody and Maintenance

History Record" are maintained by the Aircraft Maintenance Administration Specialist (6046) Marine in W/C 60C in accordance with references (c) and (j).

(i) Ensure that Quality Assurance (QA) conducts program audits on W/C 60C as required by reference (c).

(j) Ensure receipt and transfer messages that are required by this Order are prepared and submitted in accordance with reference (c). Receipt and transfer messages shall be maintained for a minimum of one year per reference (j).

(k) Maintain file copies of the MF annual inventory for a minimum of two years per reference (j).

(l) Submit MF disposition/survey requests in accordance with reference (c), as required. Upon survey approval, prepare MF for disposal per this Order. MF disposition/survey approvals shall be maintained for a minimum of two years per reference (j).

(5) Supported Units Commanding Officer/Officer-in-Charge (CO/OIC)

(a) Assign, in writing, an MFC.

1. The MFC will be directly responsible to the CO/OIC for implementation, coordination, and management of the unit's MF program in accordance with references (a) through (l) and policies set forth in this Order.

2. The MFC will be the liaison between their unit and the MALS MFC providing I-Level support.

(b) Ensure that the MFC accompanies the supporting MALS MFC during site visits.

(c) Ensure the best possible MF deployable posture through close coordination with the MALS MFC and strict adherence to the CSC program.

(d) Ensure that the CSC inspections are kept current on all active MFs. The supporting MALS CSC inspector will be used for CSC program required re-inspections.

(e) Enforce a comprehensive MF maintenance program, per applicable references and this Order, to provide maximum

support with an emphasis on readiness. This will be accomplished by performing all user-related maintenance actions and by coordinating with the supporting MALS W/C 60C for those repair actions requiring support.

(f) Ensure that a minimum of two personnel per section are trained to a level necessary to perform limited MF QA inspections (e.g., scheduled maintenance and corrosion control). The supporting MALS W/C 60C will provide the training necessary to qualify user personnel in MF O-Level maintenance. For non-maintenance sections/work centers (e.g., Production Control, Individual Material Readiness List (IMRL), ALIMs, and Supply) W/C 60C will coordinate with QA to assign a production W/C representative to perform the CDI function of each maintenance action, (e.g., W/C 51A CDIs will perform the CDI function for the Hazardous Materials W/C).

(g) Maintain a current MFTOOL inventory database of all MF equipment supported by the MALS.

(h) Report all MF movement, inventory, readiness and updates to the supporting MALS MFC.

c. Coordinating Instructions

(1) Mobile Facilities Coordinator (MFC). The MFC shall be a Staff Noncommissioned Officer (SNCO) that holds the 6499 MOS. The MFC shall maintain a copy of this Order and be familiar and comply with references (a) through (m) and policies set forth in this Order. The MFC shall ensure that the subject line of all Naval messages regarding MF program equipment begins with "SE-4 MOBILE FACILITY (MF)."

(2) International Convention for Safe Containers (CSC). MFs are military dry cargo intermodal containers constructed to International Organization for Standardization (ISO) standards and support multiple modes of handling and transportation. MFs are required to meet ISO container and international shipping standards. All active MFs must comply with international regulations governing intermodal dry cargo containers. MFs, therefore, require certification under the CSC Program.

(a) Every active MF is required to have a CSC inspection data plate permanently attached. The data plate will display the next CSC inspection due date.

(b) Inspections are conducted in accordance with reference (b).

(c) MFs that fail a CSC inspection or whose CSC inspection due date has lapsed will be considered a CSC failure and are, therefore, non-deployable until such time that the material condition of the MF has been restored to a passing condition.

(d) CSC Inspectors can be initially certified and recertified by completing the AMMO-43-DL CSC Container Re-inspection Course. available at link: <https://www.nko.navy.mil>; click Navy eLearning link; search Navy Training Course Catalog.

1. Each CSC Inspector shall maintain a copy of their original AMMO-43-DL course completion certificate within the MALS MFC turnover jacket.

(3) Movement Control. The term movement applies to deployments, transfers, and temporary loans. Movement control is a high impact issue because it has a direct effect on inventory control. All movement must be approved prior to execution and must be reported to the MF Program Office via Naval message, citing the approval authority, to facilitate inventory control. As with all matters pertaining to MFs and ancillary equipment, movement must be coordinated through the MALS MFC.

(a) Intra-wing movement must be approved by MAW ALD Avionics. Intra-wing movement is defined as any movement where the MF/equipment will remain in the custody of a MALS, or supported unit, assigned to MAW.

(b) Any movement of MFs and/or ancillary equipment Outside Continental United States (OCONUS) (with the exceptions of intra-wing movement within 1st MAW, and the Marine Expeditionary Unit Aviation Combat Element (ACE) onboard ship) must be approved by the MARFOR.

(c) Inter-wing movement, when the MF/equipment will be in the physical custody of a unit not within the MAW, must be approved by the MARFOR.

(d) Movement of MFs housing hard-mounted IMRL equipment outside of the parent MALS must be approved by the IMRL Type Commander (TYCOM) Commander, Naval Air Forces/Commander,

Navy Air Force Reserve (COMNAVAIRFOR/COMNAVAIRFORRES) as well as the appropriate MF authority.

(e) Prior to movement, the MFs must be prepared in accordance with reference (h) and inspected in accordance with reference (b). MF must have a minimum of six months remaining on the CSC inspection due date at the time of shipment or transfer. A conditional inspection will be performed prior to shipment and annotated on the Naval message to ensure the MF is still within CSC standards.

(f) No MF will be transferred with equipment shortages unless approved by the MF Program Office. All shortages will be annotated on the transfer Naval message and in the LIR.

(g) Authorized modes of transportation are: air-ride truck, ship, or air (when operational considerations require urgent delivery). Rail transportation is not authorized. Note: Air louvers must be opened during air transport to prevent over-pressurization of MFs.

(h) All documentation of movement controls will be maintained per reference (j) as appropriate.

(4) Inventory Control. A current inventory of all assigned MF program equipment will be maintained by the MFC using the MF Tool database. This format will be used to submit the annual inventory report. Each MALS inventory will include all MF program equipment used by supported units (MWSS, ATC, etc).

(a) Report any changes to the MF inventory database, as they occur, to the next higher echelon.

(b) As MFs are received, they will be assigned to a specific Contingency Support Package, Division, and Work Center/Branch based on the Configuration Code, needs of the unit, and consideration for older MFs that have reached their service life. To assist in this task, utilize the MF TBA, enclosure (2). A procedure checklist will be initiated for every MF transferred/received and a completed copy retained in the LIR for a minimum of one year per reference (j). A checklist is a locally created checklist of shipping and receiving procedures as they apply in each respective 60C work center.

14 MAR 2016

(c) All receipts and transfers of MFs or ancillary equipment will be reported via Naval message within 24 hours of transfer and four working days from receipt.

(d) Receipt, transfer and disposition/survey messages, and inventories, for all MF TBA equipment will be submitted by the supporting MALS to the MF Program Office via the respective chain of command.

(e) MF transactions, such as receipts, transfers, rework, and surveys, will be annotated in the "REMARKS" column of the inventory report by entering the date-time-group (DTG) and the originating activity of the message directing the action.

(f) MFs that are assigned to a unit per enclosures (2) through (5) will not be assigned to, or used by, units or organizations that do not have a defined MF requirement contained within enclosures (2) through (5) or T/M/S Weapons System Planning Document, unless specifically authorized by DC AVN (ASL-34).

(g) Units that possess MFs within their inventory that are no longer authorized due to TBA requirements change must request disposition from the NAVAIR MF Program in accordance with reference (c) within 90 days of TBA change. Those MFs that are defined as "Excess" within MFTOOL by the MF Program Office are not authorized and disposition should be requested immediately upon discovery.

(h) Maximum effort shall be made to utilize the Tactical Quiet Generator (TQG) storage facility in Marine Corps Base (MCB) Albany in an effort to reduce fleet maintenance and increase TQG readiness. A minimum amount of TQGs should be retained for training purposes at each MALS. Each MARFOR should determine the appropriate quantity of TQGs required at each MALS to accommodate this training.

(i) MARFOR and Wing MFCs will verify the accuracy of each unit's MFDRR, utilizing MFTOOL, during their annual/biennial inspections.

(5) Maintenance. Maintenance concepts and maintenance management systems for MF program ancillary equipment (e.g., Tactical Quiet Generators, Load Banks, Power Distribution Boxes, and all other SE in support of the MF) are the same as delineated in reference (c) for Support Equipment. MFs and related equipment, in use or in storage, will be maintained in a state of

operational readiness, in accordance with references (c), (f) and (g) and as further defined within this Order. The MF container itself is a facility and not Support Equipment. Any similarities with the Support Equipment program are in an effort to properly manage inventory and readiness. All scheduled maintenance pertaining to MFs shall be maintained utilizing reference (c) 10.17. All CNAF 4790/51 records shall be maintained in accordance with reference (c) 10.17.4.1.3.

(a) O-Level maintenance will be performed by the MF user (i.e., sections and W/Cs to which the MFs were assigned according to the TBA). O-Level maintenance involves conducting the Preventive Maintenance (PM) Inspections on the Environmental Control Unit (ECU) and MF, keeping the ECU filters clean and unobstructed, keeping the inside and outside of MFs clean, changing light bulbs, keeping hinges lubricated and corrosion free, touch up painting, corrosion control and surface corrosion repair. There is no special qualification required for touch up painting on a MF. Use of power tools are authorized locally by the MFC as deemed necessary in the performance of O-Level corrosion control. The SNCOIC of W/C 60C will determine if severe levels of corrosion requiring the use of power tools will be classified as O-Level or I-Level maintenance. The NCOIC of W/C 60C has the final determination on the level of repair for any issue in question.

(b) The term I-Level within the MF program refers to that level of maintenance performed by the MALS W/C 60C. I-Level involves all maintenance, beyond that of the O-Level, necessary to return an MF or ECU to ready-for-use (RFU) condition, to include the incorporation of applicable Technical Directives (TDs) and maintenance beyond touch up painting. There is no special qualification, beyond the basic 6499 MOS graduation, required to paint a MF and all painting will be performed as outlined in reference (g). I-Level maintenance is provided by the supporting MALS for all supported users.

(c) W/C 60C is responsible for all maintenance requirements, to include TDs, corrosion control and surface corrosion repair on the MF program ancillary equipment, (e.g., Complexing/Decomplexing Tools (CDTs), generators, frequency converters, and scaffolding).

(d) ECU access panels and doors, if removed while complexed, will be stored in an area protected from the elements. A remark will be annotated in the LIR shortages section as to the whereabouts of the removed items and they will be serialized to

the MF they belong to in a manner which is easily removable. Side opening MF panels will be properly stored in a manner that will not cause damage to the panel and will protect it from the elements. CDTs and generators (not required for periodic use) shall be preserved and properly stored when not in use.

(e) In garrison, MF generators, and associated equipment, that are not in a state of preservation will be operated one hour per month, or as local regulations permit, to prevent generator down time and provide operator training.

(f) MF generator/ancillary equipment rework shall be requested, via Naval message, in accordance with reference (c).

(g) The unauthorized alteration or modification of an MF from its original configuration, or intended use, is strictly prohibited. The temporary addition or relocation of original internal MF equipment requires approval from the MALS AVO and all changes will be documented in the LIRs. Requests for transferring IMRL to a hard mounted site will be submitted to the MARFOR and info the MF Program Office and HQMC ASL-34B. Additionally, should the hard sited IMRL need to be replaced, requests for new assets shall be requested to the appropriate MARFOR.

(6) MF Complexes. There are many factors to consider when complexing MFs, such as, power requirements, fire and safety regulations and overall size limitations. Additionally, ensure all local, state, and federal environmental regulations are followed, to include painting restrictions, oil/water separators, hazardous material containment and emissions, etc. All regulations, requirements and restrictions for MF complexes are provided in reference (h).

(7) Equipment Disposition Requests. If a CSC inspector determines that an MF is damaged beyond economical repair, that MF is a candidate for survey.

(a) Disposition requests for MFs and ancillary equipment will be submitted to MAW MFC via Naval message, in accordance with reference (c). The MAW MFC must validate the request. If the MAW concurs with the request, it must be forwarded to MARFOR ALD for concurrence/endorsement. The request will then be forwarded to the MF Program Office for final disposition approval.

(b) If MF survey disposition is approved, surveyed MFs must be sent to the Defense Reutilization and Marketing Office (DRMO) in accordance with local instructions. A completed copy of DD 1348-1A, "Issue Release/Receipt Document" must be forwarded to NAVAIR's MF Program Office. Any request for retention of surveyed MFs must be submitted via Naval message to HQMC (ASL-34) and endorsed by the respective MAW and MARFOR, for approval. Upon approval, contact the nearest DRMO to complete the DD 1348-1A to avoid any unnecessary transportation disposal costs.

(c) No surveyed MF will be physically attached, or electrically connected to, an active MF or MF complex.

(d) Surveyed MFs, which are electrically connected to separate power sources other than active MFs, must remain in their original electrical configuration to include proper grounding per reference (h).

(e) Once an MF has been approved for survey, the following will be complied with by the surveying activity:

1. Permanently remove or paint over all MF markings or decals as applicable and remove the CSC data plate.

2. Clearly stencil "SURVEYED-NOT FOR EMBARK" in six-inch red letters, centered on both side walls and centered above the doors on both ends. Stencil the DTG of the MF Program NAVAIR authorization message in six-inch red letters centered below the SURVEYED markings on both side walls of the MF.

3. All butting kits, walkways, environmental control units, and fire bottles will be removed from a surveyed MF prior to its disposition. Should a surveyed MF be connected to a power source, a fire bottle must be maintained within the MF.

4. Complete Receipt/Transfer/Survey procedures as per reference (e).

5. Comply with survey disposition instructions for the MF LIR as outlined in the MF Program Office disposition message.

(f) Surveyed MFs will not have equipment installed for which a "SHORTAGE" is noted in any active (non-surveyed) MF.

(g) Surveyed MFs are not deployable and cannot be stacked or hoisted via ISO corners.

(h) An Environmental Control Unit is not an integral part of an MF; therefore, the ECU will not be disposed of with the MF. No RFU ECU will be placed in a surveyed MF if an active MF requires one. W/C 60C will maintain a signed custody card on each ECU being used in a surveyed MF. All scheduled and unscheduled maintenance will continue on every active ECU. Non-RFU Environmental Control Units will be disposed of per their source, maintenance, and recoverability (S, M, and R) codes.

5. Administration and Logistics

a. Personnel

(1) MALS W/C 60C is established to provide I-Level support for MFs, MF ECUs, and associated MF ancillary equipment. W/C 60C is also responsible for all scheduled and unscheduled maintenance of the MF ancillary equipment. The Table of Organization for each MALS provides a basic "core" of personnel that hold the 6499 MOS. Various Organizational level T/Os hold additional 6499 Augmentees in support of W/C 60C.

(2) Each department, division or section using MFs will continue to perform O-Level maintenance to their associated MFs.

b. Funding Responsibilities and Cognizance

(1) The NAVAIR MF Program Branch Head has total budgeting, funding, and acquisition responsibility for all MFs and related equipment acquired in support of the NAVAIR mission. The NAVAIR MF Program Branch Head has configuration and outfitting responsibility for all MFs acquired in support of specific NAVAIR weapon system projects and funded through the appropriate program management or program coordinator office.

(2) The NAVAIR MF Program Management Office has responsibility for all MFs acquired under the MFs subline in the Common Support Equipment APN-7 (BA-7) P-I Budget Line Item. The NAVAIR MF Program Management Office has direct budgeting/funding responsibility in the Operation and Maintenance, Navy appropriation for configuration/equipment installation requirements for those MFs procured in support of the NAVAIR mission whether for a specific weapon system or a common requirement. Reference (c) authorizes the use of Aviation Fleet

Maintenance funds for organizational and intermediate level maintenance of MF equipment used in support of aircraft maintenance. Operating costs, such as those needed for engine oil, filters, and fuel for MF equipment must be budgeted and funded per TYCOM and local instructions.

c. Records Management. Records created as a result of this Order shall be managed according to National Archives and Records Administration approved dispositions per reference (j) to ensure proper maintenance, use, accessibility, and preservation, regardless of format or medium.

d. The generation, collection or distribution of personally identifiable information (PII) and management of privacy sensitive information shall be in accordance with the Privacy Act of 1974, as amended, per references (k) and (l). Any unauthorized review, use, disclosure or distribution is prohibited.

6. Command and Signal

a. Command. This Order is applicable to the Marine Corps Total Force.

b. Signal. This Order is effective date signed.



J. M. DAVIS
Deputy Commandant for Aviation

DISTRIBUTION: PCN 10214780000

Sample Mobile Facility Deployable Readiness Report

(Report Control Symbol EXEMPT)

FM XMAW(UC)//(Originating MAW)
TO CMC WASHINGTON DC AVN ASL(UC)//
CC COMMARFORXXX ALD(UC) //
COMNAVAIRSYS COM PATUXENT RIVER MD(UC)//
MAG XX(UC)// (Each MAG within the Wing)
MALS XX(UC)// (Each MALS within the Wing)
UNCLAS //N13670//
MSGID/GENADMIN/XMAW//
SUBJ/SE-4 MOBILE FACILITY DEPLOYABLE READINESS REPORT (MFDRR)//
REF/A/DOC/MCO 13670.1E/DD MMM YY//
AMPN/REF A IS THE Marine Corps ORDER FOR MANAGEMENT AND
ADMINISTRATION OF MARINE AVIATION MFS//
POC/(APPLICABLE INFO FOR NAME OF WING POC)//

RMKS/ 1. IAW REF A THE FOLLOWING MFDRR IS SUBMITTED FOR XMAW
(Applicable Wing) READ IN SEVEN (7) COLUMNS:

MOBILE FACILITIES

UNIT	%FSSD	%PSSM	%PSSI	%DSSN	NOTES
MALS-11	78%	15%	5%	2%	1, 4

TQGs

UNIT	%FSSD	%PSSM	%PSSI	%DSSN	NOTES
MALS-11	78%	15%	5%	2%	2

STATIC CONVERTERS/MMG-1As

UNIT	%FSSD	%PSSM	%PSSI	%DSSN	NOTES
MALS-11	78%	15%	5%	2%	

OTHER ANCILLARY SUPPORT EQUIPMENT

UNIT	%FSSD	%PSSM	%PSSI	%DSSN	NOTES
MALS-11	78%	15%	5%	2%	3

2. THE MFDRR CODES ABOVE ARE DEFINED AS:

(FSSD) FULL SYSTEM SUPPORT, DEPLOYABLE. THE MF AS WELL AS THE IMRL/ANCILLARY SUPPORT EQUIPMENT ARE RFI AND DEPLOYABLE, ACCORDING TO MCO 13670.1E AND NAVAIRINST 13670.1C.

(PSSM) PARTIAL SYSTEM SUPPORT, MOBILE FACILITY MAINTENANCE. MF IS NRFI AND NOT DEPLOYABLE BUT REPAIRABLE, ACCORDING TO MCO 13670.1E AND NAVAIRINST 13670.1C.

(PSSI) PARTIAL SYSTEM SUPPORT, IMRL. THE MF IS RFI AND DEPLOYABLE BUT THE IMRL IS RELOCATED TO A HARDSITE AND REMOVED FROM THE MF, ACCORDING TO MCO 13670.1E AND NAVAIRINST 13670.1C.

(DSSN) DEGRADED SYSTEM SUPPORT, NON-DEPLOYABLE. THE MF IS NRFI AND NON-DEPLOYABLE AND NOT REPAIRABLE, ACCORDING TO MCO 13670.1E AND NAVAIRINST 13670.1C.

3. NOTES:

1. (15) MFS DOWN FOR CSC INSPECTIONS.
2. (4) TQGS REQUIRE FUEL PUMPS, EI SUBMITTED.
3. (2) CDT UNITS ON ORDER.
4. (1) TUBE BENDING MACHINE NOT IN MF

USMC MF TBA by Configuration Code

DIV	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
<u>AB-02</u>																
000	S3	SCIFXX	1	1	0	0	0	0	0	0	1	0	0	0	0	0
		** Subtotal **	1	1	0	0	0	0	0	0	1	0	0	0	0	0
** <u>AB-03</u> **																
000	S3	SCIFXX	1	1	0	0	0	0	0	0	1	0	0	0	0	0
		** Subtotal **	1	1	0	0	0	0	0	0	1	0	0	0	0	0
** <u>AM-01</u> **																
000	05C	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
000	05C	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	1	0
000	05C	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
		** Subtotal **	2	1	1	1	1	1	1	1	1	0	1	1	1	0
** <u>AT-08</u> **																
000	S2	118A36	2	2	0	0	0	0	0	0	2	0	0	0	0	0
		** Subtotal **	2	2	0	0	0	0	0	0	2	0	0	0	0	0
** <u>AT-09BM</u> **																
000	210	118A36	2	2	0	0	0	0	0	0	2	0	0	0	0	0
		** Subtotal **	2	2	0	0	0	0	0	0	2	0	0	0	0	0
** <u>AT-10A</u> **																
000	210	118A36	2	2	0	0	0	0	0	0	2	0	0	0	0	0
		** Subtotal **	2	2	0	0	0	0	0	0	2	0	0	0	0	0
** <u>AT-11</u> **																
ATC	ATC	MACSXX	0	1	1	2	1	0	0	1	1	1	2	1	0	0
		** Subtotal **	0	1	1	2	1	0	0	1	1	1	2	1	0	0
** <u>AT-12</u> **																
ATC	ATC	MACSXX	0	1	1	2	1	0	0	1	1	1	2	1	0	0
		** Subtotal **	0	1	1	2	1	0	0	1	1	1	2	1	0	0
** <u>AV-01A</u> **																
600	600	CCSPFW	2	0	2	0	0	0	0	0	2	0	0	0	0	0
600	600	CCSPRW	0	0	0	0	2	2	2	2	0	0	2	0	0	0
		** Subtotal **	2	0	2	0	2	2	2	2	2	0	2	0	0	0
** <u>AV-02B</u> **																
600	600	CCSPFW	2	0	2	0	0	0	0	0	2	0	0	0	0	0
600	600	CCSPRW	0	0	0	0	2	2	2	2	0	0	2	0	0	0
		** Subtotal **	2	0	2	0	2	2	2	2	2	0	2	0	0	0
** <u>BL-01</u> **																

USMC MF TBA by Configuration Code

DIV	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
600	600	135B16	0	0	2	0	0	0	0	0	0	0	0	0	0	0
600	620	1HML09	0	0	0	0	0	0	0	0	0	0	0	0	1	0
600	620	1HML27	0	0	0	0	0	1	0	2	0	2	0	0	0	0
600	600	235C10	0	0	0	0	0	0	0	0	1	0	0	0	0	0
MP2	LPZ	2FEFW	0	0	0	0	0	0	0	0	0	0	0	0	0	2
MP2	BTN	2FERW	0	0	0	0	0	0	0	0	0	0	0	0	0	2
600	620	2HML09	0	0	0	0	0	0	0	0	0	0	0	0	1	0
600	620	2HML27	0	0	0	0	0	0	0	0	0	0	1	0	0	0
600	600	335B10	2	0	0	0	0	0	0	0	0	0	0	1	0	0
MP3	LMS	3FEFW	0	0	0	0	0	0	0	0	0	0	0	0	0	2
MP3	BBO	3FERW	0	0	0	0	0	0	0	0	0	0	0	0	0	2
600	620	3HML27	0	0	0	0	0	0	0	0	0	0	1	0	0	0
600	600	435B16	0	0	0	2	0	0	0	0	0	0	0	1	0	0
MPS	BLI	4574H	0	0	0	0	0	0	0	0	0	0	0	0	0	1
600	620	4HML27	0	0	0	0	0	0	0	2	0	0	0	0	0	0
600	600	535B16	0	1	0	0	0	0	0	0	0	0	0	0	0	0
600	620	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
900	940	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	0	0	0
600	620	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
900	940	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	0	0
600	620	T53E29	0	0	0	0	0	0	0	1	0	0	0	0	0	0
600	600	TF3531	0	0	0	0	0	0	0	0	1	0	0	0	0	0
600	620	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
600	620	TH1M39	0	0	0	0	0	0	0	0	0	0	1	0	0	0
600	620	TV8B14	0	0	0	1	0	0	0	0	0	0	0	0	0	0
600	620	WGISSX	0	0	0	0	1	0	0	0	0	0	0	0	0	0
** Subtotal **			5	3	4	5	3	3	2	7	4	4	5	3	3	9
** <u>BR-01</u> **																
700	71D	118A36	1	1	0	1	0	0	0	0	0	0	0	2	0	0
700	71D	1V8R14	1	1	0	1	0	0	0	0	0	0	0	0	0	0
** Subtotal **			2	2	0	2	0	0	0	0	0	0	0	2	0	0
** <u>BR-04A</u> **																
700	71D	CCSPFW	1	1	0	1	0	0	0	0	0	0	0	1	0	0
700	71D	CCSPRW	0	0	0	0	1	1	1	0	0	1	0	0	1	0
** Subtotal **			1	1	0	1	1	1	1	0	0	1	0	1	1	0
** <u>BR-05B</u> **																
700	71D	CCSPFW	1	1	0	1	0	0	0	0	0	0	0	1	0	0
700	71D	CCSPRW	0	0	0	0	1	1	1	0	0	1	0	0	1	0
** Subtotal **			1	1	0	1	1	1	1	0	0	1	0	1	1	0
** <u>CA-01</u> **																
600	670	CCSPFW	2	2	0	2	0	0	0	0	0	0	0	0	0	0
AIS	AIS	CCSPFW	2	2	2	2	0	0	0	0	2	0	0	2	0	0
AIS	AIS	CCSPRW	0	0	0	0	2	2	2	2	0	2	2	0	2	0

USMC MF TBA by Configuration Code

DIV	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
** Subtotal **			4	4	2	4	2	2	2	2	2	2	2	2	2	0
** CA-04 **																
600	670	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
600	670	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
** Subtotal **			1	1	1	1	1	1	1	1	1	1	1	1	1	0
** CA-07A **																
600	670	CCSPRW	0	0	0	0	0	0	1	0	0	1	1	0	0	0
** Subtotal **			0	0	0	0	0	0	1	0	0	1	1	0	0	0
** CA-08B **																
600	670	CCSPRW	0	0	0	0	0	0	1	0	0	1	1	0	0	0
** Subtotal **			0	0	0	0	0	0	1	0	0	1	1	0	0	0
** CA-09 **																
600	670	CCSPRW	0	0	0	0	0	1	1	0	0	0	1	0	0	0
** Subtotal **			0	0	0	0	0	1	1	0	0	0	1	0	0	0
** CL-01 **																
600	670	CCSPFW	2	2	2	2	0	0	0	0	2	0	0	2	0	0
600	670	CCSPRW	0	0	0	0	2	2	2	2	0	2	2	0	2	0
600	670	TV8B14	0	0	0	1	0	0	0	0	0	0	0	0	0	0
** Subtotal **			2	2	2	3	2	2	2	2	2	2	2	2	2	0
** CL-02 **																
600	670	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
600	670	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
** Subtotal **			1	1	1	1	1	1	1	1	1	1	1	1	1	0
** CL-04 **																
600	610	CCSPFW	2	2	2	2	0	0	0	0	2	0	0	2	0	0
600	670	CCSPFW	2	2	2	2	0	0	0	0	2	0	0	2	0	0
600	610	CCSPRW	0	0	0	0	2	2	2	2	0	2	2	0	2	0
600	670	CCSPRW	0	0	0	0	2	2	2	2	0	2	2	0	2	0
** Subtotal **			4	4	4	4	4	4	4	4	4	4	4	4	4	0
** CL-06 **																
600	670	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
600	670	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
** Subtotal **			1	1	1	1	1	1	1	1	1	1	1	1	1	0
** CL-07 **																
600	670	CCSPFW	4	4	3	4	0	0	0	0	3	0	0	3	0	0
600	670	CCSPRW	0	0	0	0	3	3	4	3	0	4	4	0	3	0

USMC MF TBA by Configuration Code

DIV	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
** Subtotal **			4	4	3	4	3	3	4	3	3	4	4	3	3	0
** <u>CL-09</u> **																
600	670	CCSPFW	2	2	2	2	0	0	0	0	2	0	0	2	0	0
600	670	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
600	670	IOSP14	0	0	0	2	0	0	0	0	0	0	0	0	0	0
** Subtotal **			2	2	2	4	1	1	1	1	2	1	1	2	1	0
** <u>CL-10</u> **																
600	670	CCSPFW	2	2	2	2	0	0	0	0	2	0	0	2	0	0
600	670	CCSPRW	0	0	0	0	2	2	2	2	0	2	2	0	2	0
** Subtotal **			2	2	2	2	2	2	2	2	2	2	2	2	2	0
** <u>CR-03</u> **																
ATC	ATC	MACSXX	0	2	2	4	2	0	0	2	2	2	4	2	0	0
** Subtotal **			0	2	2	4	2	0	0	2	2	2	4	2	0	0
** <u>CR-04</u> **																
600	690	CCSPFW	2	2	2	2	0	0	0	0	2	0	0	2	0	0
600	690	CCSPRW	0	0	0	0	2	2	2	2	0	2	2	0	2	0
** Subtotal **			2	2	2	2	2	2	2	2	2	2	2	2	2	0
** <u>CS-02A</u> **																
500	510	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
500	510	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
** Subtotal **			1	1	1	1	1	1	1	1	1	1	1	1	1	0
** <u>CS-03BM</u> **																
500	510	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
500	510	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
** Subtotal **			1	1	1	1	1	1	1	1	1	1	1	1	1	0
** <u>CU-01</u> **																
000	010	CCSPFW	2	2	2	2	0	0	0	0	1	0	0	2	0	0
000	020	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
400	400	CCSPFW	1	1	1	1	0	0	0	0	0	0	0	0	0	0
500	500	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
600	600	CCSPFW	2	3	3	3	0	0	0	0	2	0	0	3	0	0
700	700	CCSPFW	1	1	0	1	0	0	0	0	0	0	0	1	0	0
700	730	CCSPFW	1	1	0	1	0	0	0	0	0	0	0	1	0	0
800	800	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
000	010	CCSPRW	0	0	0	0	2	2	2	2	0	2	2	0	2	0
000	020	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
000	040	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
400	400	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
500	500	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0

USMC MF TBA by Configuration Code

DIV	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
600	600	CCSPRW	0	0	0	0	3	2	3	2	0	3	3	0	3	0
700	700	CCSPRW	0	0	0	0	1	1	1	0	0	1	0	0	1	0
700	730	CCSPRW	0	0	0	0	1	1	1	0	0	1	0	0	1	0
800	800	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
000	010	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
000	020	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
400	400	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
500	500	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
600	600	TFRS11	2	0	0	0	0	0	0	0	0	0	0	0	0	0
800	800	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			17	11	9	11	12	11	12	9	6	12	10	10	12	0
** <u>CY-01</u> **																
600	610	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
600	610	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
600	610	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			2	1	1	1	1	1	1	1	1	1	1	1	1	0
** <u>DP-03</u> **																
AIS	AIS	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
AIS	AIS	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
** Subtotal **			1	1	1	1	1	1	1	1	1	1	1	1	1	0
** <u>DP-18A</u> **																
AIS	AIS	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
AIS	AIS	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
AIS	AIS	IOSP14	0	0	0	1	0	0	0	0	0	0	0	0	0	0
AIS	AIS	IOSP16	0	0	0	0	1	0	0	0	0	0	0	0	0	0
AIS	AIS	IOSP36	0	0	0	0	0	0	0	0	0	1	0	0	0	0
AIS	AIS	IOSP41	0	0	0	0	0	0	0	0	0	0	0	1	0	0
** Subtotal **			1	1	1	2	2	1	1	1	1	2	1	2	1	0
** <u>EA-01</u> **																
ZZC	EAF	BEAFFW	1	1	1	2	0	0	0	0	1	0	0	0	0	0
ZZC	EAF	BEAFRW	0	0	0	0	1	0	1	1	0	1	1	0	0	0
MP2	SKM	EAF	0	0	0	0	0	0	0	0	0	0	0	0	0	1
MP3	WLM	EAF	0	0	0	0	0	0	0	0	0	0	0	0	0	1
ZZC	EAF	PALMXX	1	0	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			2	1	1	2	1	0	1	1	1	1	1	0	0	2
** <u>EA-02</u> **																
ZZC	EAF	BEAFFW	0	0	0	2	0	0	0	0	0	0	0	0	0	0
ZZC	EAF	BEAFRW	0	0	0	0	2	0	0	0	0	2	0	0	0	0
** Subtotal **			0	0	0	2	2	0	0	0	0	2	0	0	0	0
** <u>EB-06</u> **																

USMC MF TBA by Configuration Code

DIV	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
600	650	IOSP12	0	1	0	0	0	0	0	0	0	0	0	0	0	0
600	650	IOSP14	0	0	0	2	0	0	0	0	0	0	0	0	0	0
** Subtotal **			0	1	0	2	0	0	0	0	0	0	0	0	0	0
** <u>EB-07</u> **																
600	650	IOSP12	0	1	0	0	0	0	0	0	0	0	0	0	0	0
600	650	IOSP14	0	0	0	2	0	0	0	0	0	0	0	0	0	0
** Subtotal **			0	1	0	2	0	0	0	0	0	0	0	0	0	0
** <u>EB-08</u> **																
600	650	IOSP14	0	0	0	1	0	0	0	0	0	0	0	0	0	0
** Subtotal **			0	0	0	1	0	0	0	0	0	0	0	0	0	0
** <u>EB-09</u> **																
600	650	IOSP12	0	1	0	0	0	0	0	0	0	0	0	0	0	0
600	650	IOSP14	0	0	0	2	0	0	0	0	0	0	0	0	0	0
** Subtotal **			0	1	0	2	0	0	0	0	0	0	0	0	0	0
** <u>ED-01</u> **																
S00	CMD	F18R14	0	1	1	1	0	0	0	0	0	0	0	0	0	0
S00	CMD	F1H127	0	0	0	0	0	2	0	2	0	0	0	0	0	0
S00	CMD	F1V224	0	0	0	0	0	2	2	0	0	0	0	0	0	0
S00	CMD	F28A36	0	1	0	0	0	0	0	0	0	0	0	0	0	0
S00	CMD	F28R14	0	0	1	1	0	0	0	0	0	0	0	0	0	0
S00	CMD	F2H127	0	0	0	0	0	0	0	0	0	0	2	0	0	0
S00	CMD	F2V224	0	0	0	0	0	0	2	0	0	0	0	0	0	0
S00	CMD	F30J12	1	0	0	1	0	0	0	0	0	1	0	0	0	0
S00	CMD	F35316	0	0	0	0	0	0	0	0	0	1	0	0	0	0
S00	CMD	F38A36	0	0	0	0	0	0	0	0	2	0	0	0	0	0
S00	CMD	F38C24	0	0	0	0	0	0	0	0	1	0	0	0	0	0
S00	CMD	F3H127	0	0	0	0	0	0	0	0	0	2	0	0	0	0
S00	CMD	F3V224	0	0	0	0	2	0	0	0	0	0	0	0	0	0
S00	CMD	F45316	0	0	0	0	1	0	0	0	0	0	0	0	0	0
S00	CMD	F55316	0	0	0	0	1	0	0	0	0	0	0	0	0	0
S00	CMD	F5H127	0	0	0	0	0	0	0	0	0	0	2	0	0	0
** Subtotal **			1	2	2	3	4	4	4	2	3	4	4	0	0	0
** <u>FA-02A</u> **																
500	520	118A12	0	0	0	0	0	0	0	0	0	0	0	1	0	0
500	520	118A36	1	2	0	0	0	0	0	0	0	0	0	0	0	0
500	520	118C24	1	0	0	0	0	0	0	0	0	0	0	0	0	0
500	520	318A36	0	0	0	0	0	0	0	0	1	0	0	0	0	0
500	520	318C24	0	0	0	0	0	0	0	0	1	0	0	0	0	0
500	520	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			3	2	0	0	0	0	0	0	2	0	0	1	0	0

USMC MF TBA by Configuration Code

DIV	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
** FA-03B **																
500	520	118A12	0	0	0	0	0	0	0	0	0	0	0	1	0	0
500	520	118A36	1	2	0	0	0	0	0	0	0	0	0	0	0	0
500	520	118C24	1	0	0	0	0	0	0	0	0	0	0	0	0	0
500	520	318A36	0	0	0	0	0	0	0	0	1	0	0	0	0	0
500	520	318C24	0	0	0	0	0	0	0	0	1	0	0	0	0	0
500	520	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			3	2	0	0	0	0	0	0	2	0	0	1	0	0
** FC-05 **																
700	730	CCSPFW	1	1	0	1	0	0	0	0	0	0	0	1	0	0
700	730	CCSPRW	0	0	0	0	1	1	1	0	0	0	0	0	1	0
** Subtotal **			1	1	0	1	1	1	1	0	0	0	0	1	1	0
** FS-01 **																
MPS	BLI	4574H	0	0	0	0	0	0	0	0	0	0	0	0	0	1
400	400	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	0	0	0
500	500	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
600	600	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
700	700	CCSPFW	1	1	0	1	0	0	0	0	0	0	0	1	0	0
400	400	CCSPRW	0	0	0	0	1	0	1	1	0	1	1	0	1	0
500	500	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
600	600	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
700	700	CCSPRW	0	0	0	0	1	1	1	0	0	1	0	0	1	0
S00	CMD	F15316	0	0	0	0	0	1	0	1	0	0	0	0	0	0
S00	CMD	F18A36	1	0	0	0	0	0	0	0	0	0	0	0	0	0
S00	CMD	F18C24	1	0	0	0	0	0	0	0	0	0	0	0	0	0
S00	CMD	F18R14	0	1	1	1	0	0	0	0	0	0	0	0	0	0
S00	CMD	F1E605	0	1	0	1	0	0	0	0	0	0	0	0	0	0
S00	CMD	F1H127	0	0	0	0	0	1	0	1	0	0	0	0	0	0
S00	CMD	F1V224	0	0	0	0	0	1	1	0	0	0	0	0	0	0
S00	CMD	F25316	0	0	0	0	0	0	0	1	0	0	0	0	0	0
S00	CMD	F28A36	0	1	0	0	0	0	0	0	0	0	0	0	0	0
S00	CMD	F28R14	0	0	1	1	0	0	0	0	0	0	0	0	0	0
S00	CMD	F2E605	0	0	0	1	0	0	0	0	0	0	0	0	0	0
S00	CMD	F2H127	0	0	0	0	0	0	0	0	0	0	1	0	0	0
S00	CMD	F2V224	0	0	0	0	1	0	1	0	0	0	0	0	0	0
S00	CMD	F30J12	1	0	0	1	0	0	0	0	0	0	0	0	0	0
S00	CMD	F35316	0	0	0	0	0	0	0	0	0	1	0	0	0	0
S00	CMD	F38A36	0	0	0	0	0	0	0	0	1	0	0	0	0	0
S00	CMD	F3E605	0	0	0	1	0	0	0	0	0	0	0	0	0	0
S00	CMD	F3H127	0	0	0	0	0	0	0	0	0	1	0	0	0	0
S00	CMD	F3V224	0	0	0	0	1	0	0	0	0	1	1	0	0	0
S00	CMD	F45316	0	0	0	0	1	0	0	0	0	0	0	0	0	0
S00	CMD	F4H127	0	0	0	0	0	0	0	1	0	0	0	0	0	0
S00	CMD	F55316	0	0	0	0	1	0	0	0	0	0	0	0	0	0
S00	CMD	F5H127	0	0	0	0	0	0	0	0	0	0	1	0	0	0

USMC MF TBA by Configuration Code

DIV	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
** Subtotal **			7	7	5	10	8	6	6	7	4	7	6	3	4	1
** <u>GC-01</u> **																
600	620	1V8R14	0	1	1	1	0	0	0	0	0	0	0	0	0	0
600	620	2V8R14	0	0	1	1	0	0	0	0	0	0	0	0	0	0
** Subtotal **			0	1	2	2	0	0	0	0	0	0	0	0	0	0
** <u>GM-02A</u> **																
700	71B	118A36	1	1	0	1	0	0	0	0	0	0	0	0	0	0
700	71B	1V8R14	1	1	0	1	0	0	0	0	0	0	0	1	0	0
700	71B	CCSPRW	0	0	0	0	1	1	1	0	0	1	0	0	1	0
** Subtotal **			2	2	0	2	1	1	1	0	0	1	0	1	1	0
** <u>GM-03B</u> **																
700	71B	118A36	1	1	0	1	0	0	0	0	0	0	0	0	0	0
700	71B	1V8R14	1	1	0	1	0	0	0	0	0	0	0	1	0	0
700	71B	CCSPRW	0	0	0	0	1	1	1	0	0	1	0	0	1	0
** Subtotal **			2	2	0	2	1	1	1	0	0	1	0	1	1	0
** <u>HC-01</u> **																
500	520	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	1	0
500	520	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	0	0
500	520	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			2	1	1	1	1	1	1	1	1	1	1	1	1	0
** <u>HC-02</u> **																
500	520	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	1	0
500	520	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	0	0
500	520	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			2	1	1	1	1	1	1	1	1	1	1	1	1	0
** <u>HY-04A</u> **																
500	520	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
500	520	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
500	520	T53E29	0	0	0	0	0	0	0	1	0	0	0	0	0	0
500	520	TH1M39	0	0	0	0	0	0	0	0	0	0	1	0	0	0
500	520	TV8B14	0	0	0	1	0	0	0	0	0	0	0	0	0	0
** Subtotal **			1	1	1	2	1	1	1	2	1	1	2	1	1	0
** <u>HY-05B</u> **																
500	520	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
500	520	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
500	520	T53E29	0	0	0	0	0	0	0	1	0	0	0	0	0	0
500	520	TH1M39	0	0	0	0	0	0	0	0	0	0	1	0	0	0
500	520	TV8B14	0	0	0	1	0	0	0	0	0	0	0	0	0	0

USMC MF TBA by Configuration Code

DIV	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
** Subtotal **			1	1	1	2	1	1	1	2	1	1	2	1	1	0
** <u>HY-06C</u> **																
500	520	1V2236	0	0	0	0	0	1	2	0	0	1	1	0	0	0
500	520	3V2212	0	0	0	0	1	0	0	0	0	0	0	0	1	0
500	520	TV2226	0	0	0	0	0	0	1	0	0	0	0	0	0	0
** Subtotal **			0	0	0	0	1	1	3	0	0	1	1	0	1	0
** <u>JU-01</u> **																
500	500	118A12	0	0	0	0	0	0	0	0	0	0	0	1	0	0
000	000	118A36	1	1	0	0	0	0	0	0	1	0	0	0	0	0
500	500	118A36	1	1	0	0	0	0	0	0	0	0	0	0	0	0
600	600	118A36	1	1	0	0	0	0	0	0	1	0	0	0	0	0
S00	S00	118A36	3	0	0	0	0	0	0	0	0	0	0	0	0	0
500	500	118C24	1	0	0	0	0	0	0	0	0	0	0	0	0	0
600	600	118C24	1	0	0	0	0	0	0	0	1	0	0	1	0	0
S00	S00	118C24	3	0	0	0	0	0	0	0	0	0	0	0	0	0
800	800	130J12	0	0	0	0	0	0	0	0	0	1	0	0	0	0
S00	S00	130J12	2	0	0	2	0	0	0	0	0	2	0	0	0	0
600	600	130T12	0	0	0	0	0	0	0	0	0	0	0	1	2	0
S00	S00	146E12	0	0	0	0	0	0	0	0	0	2	2	0	0	0
600	600	153E16	0	0	0	0	1	0	0	1	0	0	0	0	0	0
S00	S00	153E16	0	0	0	0	0	2	0	2	0	0	0	0	0	0
S00	S00	1E6B05	0	1	0	1	0	0	0	0	0	0	0	0	0	0
600	600	1HML27	0	0	0	0	0	1	0	2	0	1	2	0	1	0
S00	S00	1HML27	0	0	0	0	0	3	0	3	0	0	0	0	0	0
S00	S00	1RS46E	0	0	0	0	0	0	0	0	0	0	0	0	3	0
500	500	1V2236	0	0	0	0	0	1	1	0	0	1	1	0	0	0
800	800	1V2236	0	0	0	0	0	0	1	0	0	0	0	0	0	0
S00	S00	1V2236	0	0	0	0	0	3	3	0	0	0	0	0	0	0
500	500	1V8R14	0	0	0	1	0	0	0	0	0	0	0	0	0	0
600	600	1V8R14	0	1	1	1	0	0	0	0	0	0	0	0	0	0
S00	S00	1V8R14	0	2	2	2	0	0	0	0	0	0	0	0	0	0
S00	S00	218A36	0	3	0	0	0	0	0	0	0	0	0	0	0	0
S00	S00	246E36	0	0	0	0	3	0	0	0	0	0	0	0	0	0
S00	S00	253E16	0	0	0	0	0	0	0	2	0	0	0	0	0	0
S00	S00	2E6B05	0	0	0	1	0	0	0	0	0	0	0	0	0	0
600	600	2HML27	0	0	0	0	0	0	0	0	0	0	1	0	0	0
S00	S00	2HML27	0	0	0	0	0	0	0	0	0	0	3	0	0	0
S00	S00	2V2224	0	0	0	0	0	0	3	0	0	0	0	0	0	0
600	600	2V8R14	0	0	1	1	0	0	0	0	0	0	0	0	0	0
S00	S00	2V8R14	0	0	2	2	0	0	0	0	0	0	0	0	0	0
600	600	318A36	0	0	0	0	0	0	0	0	1	0	0	0	0	0
S00	S00	318A36	0	0	0	0	0	0	0	0	3	0	0	0	0	0
500	500	318C24	0	0	0	0	0	0	0	0	1	0	0	0	0	0
S00	S00	318C24	0	0	0	0	0	0	0	0	3	0	0	0	0	0
S00	S00	346E24	0	0	0	0	0	0	0	0	0	0	3	0	0	0

USMC MF TBA by Configuration Code

DIV	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
S00	S00	353E16	0	0	0	0	2	0	0	0	0	0	0	0	0	0
S00	S00	3E6B05	0	0	0	1	0	0	0	0	0	0	0	0	0	0
S00	S00	3HML27	0	0	0	0	0	0	0	0	0	0	3	0	0	0
500	500	3V2212	0	0	0	0	1	0	0	0	0	0	0	0	1	0
S00	S00	3V2212	0	0	0	0	2	0	0	0	0	0	0	0	0	0
S00	S00	3V8R14	0	0	2	2	0	0	0	0	0	0	0	0	0	0
S00	S00	446E24	0	0	0	0	0	0	0	0	0	3	0	0	0	0
S00	S00	453E16	0	0	0	0	0	0	0	0	0	2	0	0	0	0
MPS	FLY	4574H	0	0	0	0	0	0	0	0	0	0	0	0	0	1
600	600	4HML27	0	0	0	0	0	0	0	1	0	0	0	0	0	0
S00	S00	4HML27	0	0	0	0	0	0	0	3	0	3	0	0	0	0
S00	S00	553E16	0	0	0	0	2	0	0	0	0	0	0	0	0	0
S00	S00	553EXX	0	0	0	0	2	0	0	0	0	0	0	0	0	0
S00	S00	5HML27	0	0	0	0	0	0	0	0	0	0	3	0	0	0
ZZC	EAF	BEAFFW	0	0	0	0	0	0	0	0	0	0	0	0	0	0
ZZC	EAF	BEAFRW	0	0	0	0	0	0	0	0	0	0	0	0	0	0
000	000	CCSPFW	3	3	3	3	0	0	0	0	3	0	0	3	0	0
500	500	CCSPFW	5	5	5	5	0	0	0	0	5	0	0	5	1	0
600	600	CCSPFW	12	11	12	11	0	0	0	0	12	0	0	10	0	0
700	700	CCSPFW	2	2	0	2	0	0	0	0	0	0	0	2	0	0
800	800	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
900	900	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
AIS	AIS	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
S00	S00	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
000	000	CCSPRW	0	0	0	0	3	2	3	3	0	3	3	0	3	0
400	400	CCSPRW	0	0	0	0	2	1	2	2	0	2	2	0	2	0
500	500	CCSPRW	0	0	0	0	5	5	4	5	0	5	5	0	5	0
600	600	CCSPRW	0	0	0	0	11	10	11	11	0	11	12	0	9	0
700	700	CCSPRW	0	0	0	0	2	2	2	0	0	2	0	0	1	0
800	800	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
900	900	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
AIS	AIS	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
S00	S00	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
S00	S00	F15316	0	0	0	0	0	1	0	1	0	0	0	0	0	0
S00	S00	F18A36	2	0	0	0	0	0	0	0	0	0	0	0	0	0
S00	S00	F18C24	2	0	0	0	0	0	0	0	0	0	0	0	0	0
S00	S00	F18R14	0	1	1	1	0	0	0	0	0	0	0	0	0	0
S00	S00	F1E605	0	1	0	1	0	0	0	0	0	0	0	0	0	0
S00	S00	F1H127	0	0	0	0	0	2	0	2	0	0	0	0	0	0
S00	S00	F1V224	0	0	0	0	0	2	2	0	0	0	0	0	0	0
S00	S00	F25316	0	0	0	0	0	0	0	1	0	0	0	0	0	0
S00	S00	F28A36	0	2	0	0	0	0	0	0	0	0	0	0	0	0
S00	S00	F28R14	0	0	1	1	0	0	0	0	0	0	0	0	0	0
000	000	F2E605	0	0	0	1	0	0	0	0	0	0	0	0	0	0
S00	S00	F2H127	0	0	0	0	0	0	0	0	0	0	2	0	0	0
S00	S00	F2V224	0	0	0	0	0	0	2	0	0	0	0	0	0	0
S00	S00	F30J12	1	0	0	1	0	0	0	0	0	1	0	0	0	0

USMC MF TBA by Configuration Code

DIV	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
S00	S00	F34624	0	0	0	0	0	0	0	0	0	0	2	0	0	0
S00	S00	F35316	0	0	0	0	0	0	0	0	0	1	0	0	0	0
S00	S00	F38A36	0	0	0	0	0	0	0	0	2	0	0	0	0	0
S00	S00	F38C24	0	0	0	0	0	0	0	0	2	0	0	0	0	0
S00	S00	F3E605	0	0	0	1	0	0	0	0	0	0	0	0	0	0
S00	S00	F3H127	0	0	0	0	0	0	0	0	0	2	0	0	0	0
S00	S00	F3V224	0	0	0	0	2	0	0	0	0	0	0	0	0	0
S00	S00	F44624	0	0	0	0	0	0	0	0	0	2	0	0	0	0
S00	S00	F45316	0	0	0	0	1	0	0	0	0	0	0	0	0	0
S00	S00	F46FSP	0	0	0	0	0	0	0	0	0	0	0	0	2	0
S00	S00	F4H127	0	0	0	0	0	0	0	2	0	0	0	0	0	0
S00	S00	F54636	0	0	0	0	1	0	0	0	0	0	0	0	0	0
S00	S00	F55316	0	0	0	0	1	0	0	0	0	0	0	0	0	0
S00	S00	F5H127	0	0	0	0	0	0	0	0	0	0	2	0	0	0
600	600	IOSP11	4	0	0	0	0	0	0	0	0	0	0	0	0	0
600	600	IOSP12	0	3	0	0	0	0	0	0	0	0	0	0	0	0
600	600	IOSP14	0	0	0	6	0	0	0	0	0	0	0	0	0	0
600	600	IOSP31	0	0	0	0	0	0	0	0	4	0	0	0	0	0
ATC	ATC	MACSXX	0	1	2	2	1	0	0	1	1	1	2	1	0	0
ZZC	EAF	PALMXX	1	0	0	0	0	0	0	0	0	0	0	0	0	0
000	000	SCIFXX	1	1	0	0	0	0	0	0	1	0	0	0	0	0
600	600	T53E29	0	0	0	0	0	0	0	1	0	0	0	0	0	0
000	000	TFRS11	3	0	0	0	0	0	0	0	0	0	0	0	0	0
500	500	TFRS11	4	0	0	0	0	0	0	0	0	0	0	0	0	0
600	600	TFRS11	4	0	0	0	0	0	0	0	0	0	0	0	0	0
800	800	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
900	900	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
600	600	TH1M39	0	0	0	0	0	0	0	0	0	0	1	0	0	0
500	500	TV2226	0	0	0	0	0	0	1	0	0	0	0	0	0	0
600	600	TV2226	0	0	0	0	0	0	1	0	0	0	0	0	0	0
000	000	TV8B14	0	0	0	1	0	0	0	0	0	0	0	0	0	0
500	500	TV8B14	0	0	0	1	0	0	0	0	0	0	0	0	0	0
600	600	TV8B14	0	0	0	4	0	0	0	0	0	0	0	0	0	0
ZZC	EAF	TV8B14	0	0	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			63	44	36	59	46	39	40	47	45	49	53	28	34	1
** <u>JU-09</u> **																
600	600	1E6B05	0	1	0	1	0	0	0	0	0	0	0	0	0	0
600	600	2E6B05	0	0	0	1	0	0	0	0	0	0	0	0	0	0
600	600	3E6B05	0	0	0	1	0	0	0	0	0	0	0	0	0	0
** Subtotal **			0	1	0	3	0	0	0	0	0	0	0	0	0	0
** <u>JU-10</u> **																
600	600	1E6B05	0	1	0	1	0	0	0	0	0	0	0	0	0	0
600	600	2E6B05	0	0	0	1	0	0	0	0	0	0	0	0	0	0
600	600	3E6B05	0	0	0	1	0	0	0	0	0	0	0	0	0	0
** Subtotal **			0	1	0	3	0	0	0	0	0	0	0	0	0	0

USMC MF TBA by Configuration Code

DIV	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
** <u>JU-31</u> **																
000	S3	SCIFXX	1	1	0	0	0	0	0	0	1	0	0	0	0	0
** Subtotal **			1	1	0	0	0	0	0	0	1	0	0	0	0	0
** <u>JU-32</u> **																
000	S3	SCIFXX	1	1	0	0	0	0	0	0	1	0	0	0	0	0
** Subtotal **			1	1	0	0	0	0	0	0	1	0	0	0	0	0
** <u>KA-18A</u> **																
600	600	1HML27	0	0	0	0	0	0	0	0	0	0	3	0	0	0
600	600	1V2236	0	0	0	0	2	0	0	0	0	0	0	0	0	0
600	600	CCSPFW	7	7	7	7	0	0	0	0	9	0	0	2	0	0
600	600	CCSPRW	0	0	0	0	4	3	4	4	0	3	4	0	2	0
600	600	IOSP11	6	0	0	0	0	0	0	0	0	0	0	0	0	0
600	600	IOSP12	0	2	0	0	0	0	0	0	0	0	0	0	0	0
600	600	IOSP14	0	0	0	2	0	0	0	0	0	0	0	0	0	0
600	600	IOSP31	0	0	0	0	0	0	0	0	4	0	0	0	0	0
600	600	TFRS11	6	0	0	0	0	0	0	0	0	0	0	0	0	0
600	600	TV2226	0	0	0	0	0	0	4	0	0	0	0	0	0	0
600	600	TV8B14	0	0	0	5	0	0	0	0	0	0	0	0	0	0
** Subtotal **			19	9	7	14	6	3	8	4	13	3	7	2	2	0
** <u>KA-19A</u> **																
600	650	CCSPFW	2	2	2	2	0	0	0	0	2	0	0	1	0	0
600	650	IOSP11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
600	650	IOSP14	0	0	0	2	0	0	0	0	0	0	0	0	0	0
600	650	IOSP31	0	0	0	0	0	0	0	0	1	0	0	0	0	0
600	650	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
600	650	TV8B14	0	0	0	1	0	0	0	0	0	0	0	0	0	0
** Subtotal **			4	2	2	5	0	0	0	0	3	0	0	1	0	0
** <u>KA-20B</u> **																
600	650	CCSPFW	2	2	2	2	0	0	0	0	2	0	0	1	0	0
600	650	IOSP11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
600	650	IOSP14	0	0	0	2	0	0	0	0	0	0	0	0	0	0
600	650	IOSP31	0	0	0	0	0	0	0	0	1	0	0	0	0	0
600	650	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
600	650	TV8B14	0	0	0	1	0	0	0	0	0	0	0	0	0	0
** Subtotal **			4	2	2	5	0	0	0	0	3	0	0	1	0	0
** <u>KA-31</u> **																
600	650	118A12	0	0	0	0	0	0	0	0	0	0	0	1	0	0
600	650	118A36	2	0	0	0	0	0	0	0	0	0	0	0	0	0
600	650	1E6B05	0	0	0	3	0	0	0	0	0	0	0	0	0	0
600	650	1HML27	0	0	0	0	0	0	0	0	0	0	2	0	0	0
600	650	218A36	0	1	0	0	0	0	0	0	0	0	0	0	0	0

USMC MF TBA by Configuration Code

DIV	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
600	650	2E6B05	0	0	0	3	0	0	0	0	0	0	0	0	0	0
600	650	2V8R14	0	0	0	1	0	0	0	0	0	0	0	0	0	0
600	650	318A36	0	0	0	0	0	0	0	0	4	0	0	0	0	0
600	650	3V2212	0	0	0	0	1	0	0	0	0	0	0	0	0	0
600	650	CCSPFW	3	3	7	3	0	0	0	0	3	0	0	3	0	0
600	650	CCSPRW	0	0	0	0	3	3	3	3	0	3	3	0	3	0
600	650	IOSP11	11	0	0	0	0	0	0	0	0	0	0	0	0	0
600	650	IOSP12	0	11	0	0	0	0	0	0	0	0	0	0	0	0
600	650	IOSP14	0	0	0	4	0	0	0	0	0	0	0	0	0	0
600	650	IOSP31	0	0	0	0	0	0	0	0	9	0	0	0	0	0
600	650	TV2226	0	0	0	0	0	0	1	0	0	0	0	0	0	0
** Subtotal **			16	15	7	14	4	3	4	3	16	3	5	4	3	0
** <u>MC-01</u> **																
000	020	CCSPFW	2	2	2	2	0	0	0	0	2	0	0	2	0	0
600	600	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
600	670	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
700	700	CCSPFW	1	1	0	1	0	0	0	0	0	0	0	1	0	0
000	020	CCSPRW	0	0	0	0	2	1	2	2	0	0	2	0	2	0
600	600	CCSPRW	0	0	0	0	1	0	1	1	0	0	1	0	1	0
600	670	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	1	0
700	700	CCSPRW	0	0	0	0	1	1	1	0	0	0	0	0	1	0
000	020	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
000	020	TV8B14	0	0	0	1	0	0	0	0	0	0	0	0	0	0
** Subtotal **			6	5	4	6	5	3	5	4	4	0	4	5	5	0
** <u>MM-01</u> **																
500	510	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
500	510	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	1	0
500	510	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			2	1	1	1	1	1	1	1	1	0	1	1	1	0
** <u>MM-02</u> **																
500	510	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	1	0
500	510	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	0	0
500	510	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			2	1	1	1	1	1	1	1	1	0	1	1	1	0
** <u>MM-03</u> **																
500	510	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
500	510	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	1	0
500	510	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			2	1	1	1	1	1	1	1	1	0	1	1	1	0
** <u>MM-04</u> **																
500	510	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
500	510	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	1	0

USMC MF TBA by Configuration Code

DIV	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
500	510	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			2	1	1	1	1	1	1	1	1	0	1	1	1	0
** <u>NT-06</u> **																
500	530	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
500	530	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	1	0
500	530	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			2	1	1	1	1	1	1	1	1	0	1	1	1	0
** <u>NT-07</u> **																
500	530	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
500	530	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	1	0
500	530	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			2	1	1	1	1	1	1	1	1	0	1	1	1	0
** <u>NT-08</u> **																
500	530	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
500	530	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	1	0
500	530	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			2	1	1	1	1	1	1	1	1	0	1	1	1	0
** <u>PM-01</u> **																
600	650	1E6B05	0	1	0	1	0	0	0	0	0	0	0	0	0	0
600	650	2E6B05	0	0	0	1	0	0	0	0	0	0	0	0	0	0
600	650	3E6B05	0	0	0	1	0	0	0	0	0	0	0	0	0	0
** Subtotal **			0	1	0	3	0	0	0	0	0	0	0	0	0	0
** <u>PM-02</u> **																
600	650	1V8R14	0	1	1	1	0	0	0	0	0	0	0	0	0	0
** Subtotal **			0	1	1	1	0	0	0	0	0	0	0	0	0	0
** <u>PP-01</u> **																
400	410	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	1	0
** Subtotal **			0	0	0	0	1	1	1	1	0	0	1	0	1	0
** <u>PP-03A</u> **																
400	440	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	1	0
** Subtotal **			0	0	0	0	1	1	1	1	0	0	1	0	1	0
** <u>PP-04BM</u> **																
400	440	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	1	0
** Subtotal **			0	0	0	0	1	1	1	1	0	0	1	0	1	0
** <u>PW-01</u> **																
500	500	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
500	500	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0

USMC MF TBA by Configuration Code

DIV	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
500	500	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			2	1	1	1	1	1	1	1	1	1	1	1	1	0
** <u>RR-02</u> **																
800	810	130J12	0	1	0	0	0	0	0	0	0	0	0	0	0	0
800	810	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
800	810	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			2	2	1	1	0	0	0	0	1	0	0	1	0	0
** <u>RR-03</u> **																
800	810	130J12	0	1	0	0	0	0	0	0	0	0	0	0	0	0
800	810	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
** Subtotal **			1	2	1	1	0	0	0	0	1	0	0	1	0	0
** <u>RR-04A</u> **																
800	810	1V2236	0	0	0	0	0	0	2	0	0	1	1	0	0	0
800	810	3V2212	0	0	0	0	1	1	0	0	0	0	0	0	1	0
800	810	TV2226	0	0	0	0	0	0	1	0	0	0	0	0	0	0
** Subtotal **			0	0	0	0	1	1	3	0	0	1	1	0	1	0
** <u>RR-05B</u> **																
800	810	1V2236	0	0	0	0	0	0	2	0	0	1	1	0	0	0
800	810	3V2212	0	0	0	0	1	1	0	0	0	0	0	0	1	0
800	810	TV2226	0	0	0	0	0	0	1	0	0	0	0	0	0	0
** Subtotal **			0	0	0	0	1	1	3	0	0	1	1	0	1	0
** <u>SE-01</u> **																
800	810	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
800	810	CCSPRW	0	0	0	0	1	0	1	1	0	1	1	0	1	0
800	810	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			2	1	1	1	1	0	1	1	1	1	1	1	1	0
** <u>SE-02B</u> **																
800	810	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
** Subtotal **			0	0	0	0	1	1	1	1	0	1	1	0	1	0
** <u>SE-03C</u> **																
800	810	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
** Subtotal **			0	0	0	0	1	1	1	1	0	1	1	0	1	0
** <u>SE-04B</u> **																
800	810	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
** Subtotal **			0	0	0	0	1	1	1	1	0	1	1	0	1	0
** <u>SH-06</u> **																
600	650	130J12	1	0	0	1	0	0	0	0	0	1	0	0	0	0

USMC MF TBA by Configuration Code

DIV	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
600	650	130T12	0	0	0	0	0	0	0	0	0	0	0	1	1	0
600	650	CCSPRW	0	0	0	0	2	2	0	2	0	2	2	0	1	0
** Subtotal **			1	0	0	1	2	2	0	2	0	3	2	1	2	0
** <u>SM-04B</u> **																
500	510	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
500	510	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	1	0
500	510	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			2	1	1	1	1	1	1	1	1	0	1	1	1	0
** <u>SM-05A</u> **																
500	510	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
500	510	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	1	0
500	510	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			2	1	1	1	1	1	1	1	1	0	1	1	1	0
** <u>SM-06B</u> **																
500	510	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
500	510	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	1	0
** Subtotal **			1	1	1	1	1	1	1	1	1	0	1	1	1	0
** <u>SM-07A</u> **																
500	510	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
500	510	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	1	0
** Subtotal **			1	1	1	1	1	1	1	1	1	0	1	1	1	0
** <u>SP-04</u> **																
500	520	1V8R14	0	1	1	2	0	0	0	0	0	0	0	0	0	0
** Subtotal **			0	1	1	2	0	0	0	0	0	0	0	0	0	0
** <u>ST-01</u> **																
600	610	118A36	1	1	0	0	0	0	0	0	1	0	0	0	0	0
600	620	118A36	1	1	0	0	0	0	0	0	1	0	0	0	0	0
600	650	118A36	0	1	0	0	0	0	0	0	0	0	0	0	0	0
600	610	118C24	1	0	0	0	0	0	0	0	1	0	0	1	0	0
600	620	118C24	1	0	0	0	0	0	0	0	1	0	0	1	0	0
600	610	130T12	0	0	0	0	0	0	0	0	0	0	0	3	3	0
600	620	130T12	0	0	0	0	0	0	0	0	0	0	0	1	1	0
600	620	146E36	0	0	0	0	1	0	0	0	0	1	1	0	0	0
600	620	153E16	0	0	0	0	1	1	0	2	0	1	0	0	0	0
600	610	1E6B05	0	2	0	2	0	0	0	0	0	0	0	0	0	0
600	620	1E6B05	0	1	0	1	0	0	0	0	0	0	0	0	0	0
600	620	1HML27	0	0	0	0	0	1	0	2	0	1	1	0	0	0
600	620	1RS53E	0	0	0	0	0	0	0	0	0	0	0	0	1	0
600	610	1V8R14	0	1	1	1	0	0	0	0	0	0	0	0	0	0
600	620	1V8R14	0	1	1	1	0	0	0	0	0	0	0	0	0	0

USMC MF TBA by Configuration Code

DIV	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
600	620	253E16	0	0	0	0	1	0	0	0	0	0	0	0	0	0
600	610	2E6B05	0	0	0	2	0	0	0	0	0	0	0	0	0	0
600	620	2E6B05	0	0	0	1	0	0	0	0	0	0	0	0	0	0
600	620	2HML27	0	0	0	0	0	0	0	0	0	0	1	0	0	0
600	610	2V8R14	0	0	1	1	0	0	0	0	0	0	0	0	0	0
600	620	2V8R14	0	0	1	1	0	0	0	0	0	0	0	0	0	0
600	610	3E6B05	0	0	0	2	0	0	0	0	0	0	0	0	0	0
600	620	3E6B05	0	0	0	1	0	0	0	0	0	0	0	0	0	0
500	520	CCSPFW	2	2	2	2	0	0	0	0	2	0	0	2	0	0
600	610	CCSPFW	3	1	1	1	0	0	0	0	1	0	0	1	0	0
600	620	CCSPFW	3	2	2	2	0	0	0	0	2	0	0	2	0	0
600	650	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
600	690	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
500	520	CCSPRW	0	0	0	0	0	0	0	0	0	0	0	0	5	0
600	610	CCSPRW	0	0	0	0	3	3	2	3	0	3	3	0	3	0
600	620	CCSPRW	0	0	0	0	3	2	2	2	0	2	3	0	2	0
600	650	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	2	0
600	690	CCSPRW	0	0	0	0	3	1	1	1	0	1	3	0	1	0
600	610	T53E29	0	0	0	0	0	0	0	2	0	0	0	0	0	0
600	620	T53E29	0	0	0	0	0	0	0	1	0	0	0	0	0	0
500	520	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
600	610	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
600	620	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
600	650	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
600	610	TH1M39	0	0	0	0	0	0	0	0	0	0	1	0	0	0
600	620	TH1M39	0	0	0	0	0	0	0	0	0	0	1	0	0	0
500	520	TV8B14	0	0	0	1	0	0	0	0	0	0	0	0	0	0
600	610	TV8B14	0	0	0	6	0	0	0	0	0	0	0	0	0	0
600	620	TV8B14	0	0	0	3	0	0	0	0	0	0	0	0	0	0
** Subtotal **			18	15	11	30	13	9	6	14	11	10	15	13	18	0
** <u>SU-01</u> **																
S00	CMD	118A36	1	0	0	0	0	0	0	0	0	0	0	0	0	0
S00	RMD	118C24	1	0	0	0	0	0	0	0	0	0	0	0	0	0
S00	RMD	130J12	1	0	0	1	0	0	0	0	0	1	0	0	0	0
S00	RMD	1V8R14	0	1	0	1	0	0	0	0	0	0	0	0	0	0
S00	RMD	253E16	0	0	0	0	0	0	0	1	0	0	0	0	0	0
S00	RMD	2HML27	0	0	0	0	0	0	0	0	0	0	2	0	0	0
S00	RMD	2V2224	0	0	0	0	0	0	1	0	0	0	0	0	0	0
S00	RMD	318C24	0	0	0	0	0	0	0	0	1	0	0	0	0	0
S00	RMD	353E16	0	0	0	0	1	0	0	0	0	0	0	0	0	0
S00	RMD	3HML27	0	0	0	0	0	0	0	0	0	0	2	0	0	0
S00	RMD	3V2212	0	0	0	0	1	0	0	0	0	0	0	0	0	0
S00	RMD	453E16	0	0	0	0	0	0	0	0	0	0	0	0	0	0
S00	RMD	4HML27	0	0	0	0	0	0	0	1	0	1	0	0	0	0
S00	RMD	553E16	0	0	0	0	1	0	0	0	0	0	0	0	0	0
S00	RMD	553EXX	0	0	0	0	1	0	0	0	0	0	0	0	0	0

USMC MF TBA by Configuration Code

DIV	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
000	05C	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
000	05D	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
600	600	CCSPFW	4	4	4	4	0	0	0	0	4	0	0	3	0	0
S00	RMD	CCSPFW	1	2	1	1	0	0	0	0	1	0	0	0	0	0
000	05C	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
000	05D	CCSPRW	0	0	0	0	1	0	1	1	0	1	1	0	1	0
600	600	CCSPRW	0	0	0	0	4	4	3	3	0	4	4	0	4	0
600	650	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
S00	RMD	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
S00	RMD	F15316	0	0	0	0	0	1	0	1	0	0	0	0	0	0
S00	RMD	F18R14	0	1	1	1	0	0	0	0	0	0	0	0	0	0
S00	RMD	F1H127	0	0	0	0	0	2	0	1	0	0	0	0	0	0
S00	RMD	F1V224	0	0	0	0	0	2	1	0	0	0	0	0	0	0
S00	RMD	F25316	0	0	0	0	0	0	0	1	0	0	0	0	0	0
S00	RMD	F2H127	0	0	0	0	0	0	0	0	0	0	3	0	0	0
S00	RMD	F2V224	0	0	0	0	0	0	1	0	0	0	0	0	0	0
S00	RMD	F30J12	1	0	0	1	0	0	0	0	0	1	0	0	0	0
S00	RMD	F35316	0	0	0	0	0	0	0	0	0	1	0	0	0	0
S00	RMD	F38A36	0	0	0	0	0	0	0	0	1	0	0	0	0	0
S00	RMD	F38C24	0	0	0	0	0	0	0	0	1	0	0	0	0	0
S00	RMD	F3H127	0	0	0	0	0	0	0	0	0	1	0	0	0	0
S00	RMD	F3V224	0	0	0	0	1	0	0	0	0	0	0	0	0	0
600	600	IOSP14	0	0	0	4	0	0	0	0	0	0	0	0	0	0
000	05C	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
000	05C	TV8B14	0	0	0	2	0	0	0	0	0	0	0	0	0	0
** Subtotal **			12	10	8	17	13	12	10	12	10	13	15	5	8	0
** <u>SU-02</u> **																
S00	CMD	118A36	3	0	0	0	0	0	0	0	0	0	0	0	0	0
S00	CMD	118C24	3	0	0	0	0	0	0	0	0	0	0	0	0	0
S00	CMD	130J12	1	0	0	1	0	0	0	0	0	2	0	0	0	0
S00	CMD	153E16	0	0	0	0	0	1	0	2	0	0	0	0	0	0
S00	CMD	1E6B05	0	1	0	1	0	0	0	0	0	0	0	0	0	0
S00	CMD	1HML27	0	0	0	0	0	1	0	3	0	0	0	0	0	0
S00	CMD	1RS46E	0	0	0	0	0	0	0	0	0	0	0	0	1	0
S00	CMD	1V2236	0	0	0	0	0	1	1	0	0	0	0	0	0	0
S00	CMD	1V8R14	0	1	1	1	0	0	0	0	0	0	0	0	0	0
S00	CMD	218A36	0	1	0	0	0	0	0	0	0	0	0	0	0	0
S00	CMD	246E36	0	0	0	0	1	0	0	0	0	0	0	0	0	0
S00	CMD	2E6B05	0	0	0	1	0	0	0	0	0	0	0	0	0	0
S00	CMD	2HML27	0	0	0	0	0	0	0	0	0	0	3	0	0	0
S00	CMD	2V2224	0	0	0	0	0	0	1	0	0	0	0	0	0	0
S00	CMD	2V8R14	0	0	1	1	0	0	0	0	0	0	0	0	0	0
S00	CMD	318A36	0	0	0	0	0	0	0	0	1	0	0	0	0	0
S00	CMD	318C24	0	0	0	0	0	0	0	0	1	0	0	0	0	0
S00	CMD	353E16	0	0	0	0	1	0	0	0	0	0	0	0	0	0
S00	CMD	3HML27	0	0	0	0	0	0	0	0	0	0	3	0	0	0

USMC MF TBA by Configuration Code

DIV	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
S00	CMD	3V2212	0	0	0	0	1	0	0	0	0	0	0	0	0	0
S00	CMD	3V8R14	0	0	1	1	0	0	0	0	0	0	0	0	0	0
S00	CMD	453E16	0	0	0	0	0	0	0	0	0	2	0	0	0	0
S00	CMD	4HML27	0	0	0	0	0	0	0	2	0	3	0	0	0	0
S00	CMD	553E16	0	0	0	0	1	0	0	0	0	0	0	0	0	0
S00	CMD	553EXX	0	0	0	0	1	0	0	0	0	0	0	0	0	0
S00	CMD	5HML27	0	0	0	0	0	0	0	0	0	0	3	0	0	0
S00	CMD	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
S00	CMD	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
S00	CMD	F1E605	0	1	0	1	0	0	0	0	0	0	0	0	0	0
S00	CMD	F2E605	0	0	0	1	0	0	0	0	0	0	0	0	0	0
** Subtotal **			8	5	4	9	6	4	3	8	3	8	10	1	2	0
** <u>SU-03</u> **																
600	650	118C24	0	0	0	0	0	0	0	0	1	0	0	1	0	0
S00	CMD	153E16	0	0	0	0	0	1	0	0	0	0	0	0	0	0
ZZC	EAF	BEAFFW	0	0	0	0	0	0	0	0	0	0	0	0	0	0
ZZC	EAF	BEAFRW	0	0	0	0	0	0	0	0	0	0	0	0	0	0
600	600	CCSPFW	1	0	1	1	0	0	0	0	0	0	0	1	0	0
600	60C	CCSPFW	1	1	1	1	0	0	0	0	0	0	0	0	0	0
700	700	CCSPFW	1	1	0	1	0	0	0	0	0	0	0	1	0	0
AIS	AIS	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
400	410	CCSPRW	0	0	0	0	1	0	1	1	0	1	1	0	1	0
600	600	CCSPRW	0	0	0	0	1	0	0	1	0	1	0	0	0	0
600	60C	CCSPRW	0	0	0	0	1	0	0	0	0	0	1	0	0	0
700	700	CCSPRW	0	0	0	0	1	1	1	0	0	1	0	0	1	0
AIS	AIS	CCSPRW	0	0	0	0	1	0	1	1	0	1	1	0	1	0
600	600	IOSP14	0	0	0	1	0	0	0	0	0	0	0	0	0	0
600	670	IOSP14	0	0	0	1	0	0	0	0	0	0	0	0	0	0
ATC	ATC	MACSXX	0	1	1	2	1	0	0	1	1	1	2	0	0	0
MPS	BLI	MPSXXX	0	0	0	0	0	0	0	0	0	0	0	0	0	3
MPS	FLY	MPSXXX	0	0	0	0	0	0	0	0	0	0	0	0	0	3
** Subtotal **			4	4	4	8	6	2	3	4	3	5	5	4	3	6
** <u>SU-04</u> **																
S00	SRD	1HML27	0	0	0	0	0	2	0	2	0	0	0	0	0	0
** Subtotal **			0	0	0	0	0	2	0	2	0	0	0	0	0	0
** <u>SU-05</u> **																
S00	SAD	118A36	1	0	0	0	0	0	0	0	0	0	0	0	0	0
S00	SRD	118A36	1	0	0	0	0	0	0	0	0	0	0	0	0	0
S00	SAD	118C24	1	0	0	0	0	0	0	0	0	0	0	0	0	0
S00	SRD	118C24	1	0	0	0	0	0	0	0	0	0	0	0	0	0
S00	SAD	1HML27	0	0	0	0	0	1	0	1	0	0	0	0	0	0
S00	SRD	1RS46E	0	0	0	0	0	0	0	0	0	0	0	0	2	0
S00	CMD	1V2236	0	0	0	0	0	1	1	0	0	0	0	0	0	0
S00	RMD	1V2236	0	0	0	0	0	1	1	0	0	0	0	0	0	0

USMC MF TBA by Configuration Code

DIV	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
S00	SAD	1V2236	0	0	0	0	0	1	1	0	0	0	0	0	0	0
S00	CMD	218A36	0	1	0	0	0	0	0	0	0	0	0	0	0	0
S00	RMD	218A36	0	1	0	0	0	0	0	0	0	0	0	0	0	0
S00	SRD	218A36	0	1	0	0	0	0	0	0	0	0	0	0	0	0
S00	CMD	246E36	0	0	0	0	1	0	0	0	0	0	0	0	0	0
S00	RMD	246E36	0	0	0	0	1	0	0	0	0	0	0	0	0	0
S00	SAD	246E36	0	0	0	0	1	0	0	0	0	0	0	0	0	0
S00	SAD	2HML27	0	0	0	0	0	0	0	0	0	0	1	0	0	0
S00	SRD	2HML27	0	0	0	0	0	0	0	0	0	0	2	0	0	0
S00	SRD	2V2224	0	0	0	0	0	0	2	0	0	0	0	0	0	0
S00	CMD	318A36	0	0	0	0	0	0	0	0	1	0	0	0	0	0
S00	RMD	318A36	0	0	0	0	0	0	0	0	1	0	0	0	0	0
S00	SAD	318A36	0	0	0	0	0	0	0	0	1	0	0	0	0	0
S00	SRD	318C24	0	0	0	0	0	0	0	0	1	0	0	0	0	0
S00	SAD	3HML27	0	0	0	0	0	0	0	0	0	0	1	0	0	0
S00	SRD	3HML27	0	0	0	0	0	0	0	0	0	0	2	0	0	0
S00	SAD	446E24	0	0	0	0	0	0	0	0	0	0	0	0	0	0
S00	SAD	4HML27	0	0	0	0	0	0	0	1	0	0	0	0	0	0
S00	SRD	4HML27	0	0	0	0	0	0	0	1	0	0	0	0	0	0
S00	SAD	5HML27	0	0	0	0	0	0	0	0	0	0	1	0	0	0
600	600	CCSPFW	2	0	2	0	0	0	0	0	2	0	0	0	0	0
600	60C	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
600	600	CCSPRW	0	0	0	0	2	2	2	2	0	0	2	0	0	0
600	60C	CCSPRW	0	0	0	0	1	1	1	0	0	0	1	0	1	0
600	60C	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			8	4	3	1	6	7	8	5	7	0	10	1	3	0
** <u>SU-08</u> **																
000	05A	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
000	05A	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
** Subtotal **			1	1	1	1	1	1	1	1	1	1	1	1	1	0
** <u>SU-12</u> **																
S00	CMD	118A36	1	0	0	0	0	0	0	0	0	0	0	0	0	0
S00	CMD	118C24	1	0	0	0	0	0	0	0	0	0	0	0	0	0
S00	CMD	130J12	1	0	0	1	0	0	0	0	0	1	0	0	0	0
S00	RMD	130J12	2	0	0	2	0	0	0	0	0	2	0	0	0	0
S00	CMD	153E16	0	0	0	0	0	1	0	1	0	0	0	0	0	0
S00	RMD	153E16	0	0	0	0	0	0	0	1	0	0	0	0	0	0
S00	RMD	1E6B05	0	1	0	1	0	0	0	0	0	0	0	0	0	0
S00	CMD	1HML27	0	0	0	0	0	1	0	1	0	0	0	0	0	0
S00	RMD	1HML27	0	0	0	0	0	0	0	1	0	0	0	0	0	0
S00	CMD	1V2236	0	0	0	0	0	1	1	0	0	0	0	0	0	0
S00	RMD	1V2236	0	0	0	0	0	4	1	0	0	0	0	0	0	0
S00	CMD	1V8R14	0	1	0	1	0	0	0	0	0	0	0	0	0	0
S00	RMD	1V8R14	0	2	2	2	0	0	0	0	0	0	0	0	0	0
MP2	LPZ	218A12	0	0	0	0	0	0	0	0	0	0	0	0	0	1

USMC MF TBA by Configuration Code

DIV	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
MP2	SSR	218C12	0	0	0	0	0	0	0	0	0	0	0	0	0	1
MP2	LPZ	218D12	0	0	0	0	0	0	0	0	0	0	0	0	0	1
MP2	BTN	222B12	0	0	0	0	0	0	0	0	0	0	0	0	0	1
MP2	BTN	230J15	0	0	0	0	0	0	0	0	0	0	0	0	0	1
MP2	BTN	253E08	0	0	0	0	0	0	0	0	0	0	0	0	0	1
S00	CMD	253E16	0	0	0	0	0	0	0	1	0	0	0	0	0	0
S00	RMD	253E16	0	0	0	0	0	0	0	1	0	0	0	0	0	0
MP2	LPZ	2E6B05	0	0	0	0	0	0	0	0	0	0	0	0	0	1
MP2	LPZ	2FEFW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
MP2	SEAY	2H53E8	0	0	0	0	0	0	0	0	0	0	0	0	0	1
S00	CMD	2HML27	0	0	0	0	0	0	0	0	0	0	2	0	0	0
S00	RMD	2HML27	0	0	0	0	0	0	0	0	0	0	3	0	0	0
MP2	SEAY	2HML9A	0	0	0	0	0	0	0	0	0	0	0	0	0	1
MP2	SEAY	2HML9B	0	0	0	0	0	0	0	0	0	0	0	0	0	1
MP2	BTN	2HML9C	0	0	0	0	0	0	0	0	0	0	0	0	0	1
MP2	SEAY	2M2212	0	0	0	0	0	0	0	0	0	0	0	0	0	1
MP2	SEAY	2V2212	0	0	0	0	0	0	0	0	0	0	0	0	0	1
S00	CMD	2V2224	0	0	0	0	0	0	1	0	0	0	0	0	0	0
S00	RMD	2V2224	0	0	0	0	0	0	1	0	0	0	0	0	0	0
MP2	SSR	2V8B05	0	0	0	0	0	0	0	0	0	0	0	0	0	1
MP2	SSR	2V8B09	0	0	0	0	0	0	0	0	0	0	0	0	0	1
MP3	LMS	318A12	0	0	0	0	0	0	0	0	0	0	0	0	0	1
S00	CMD	318A36	0	0	0	0	0	0	0	0	2	0	0	0	0	0
S00	RMD	318A36	0	0	0	0	0	0	0	0	1	0	0	0	0	0
MP3	DHL	318C12	0	0	0	0	0	0	0	0	0	0	0	0	0	1
S00	CMD	318C24	0	0	0	0	0	0	0	0	1	0	0	0	0	0
S00	RMD	318C24	0	0	0	0	0	0	0	0	1	0	0	0	0	0
MP3	LMS	318D12	0	0	0	0	0	0	0	0	0	0	0	0	0	1
MP3	BBO	322B12	0	0	0	0	0	0	0	0	0	0	0	0	0	1
MP3	BBO	330J15	0	0	0	0	0	0	0	0	0	0	0	0	0	1
MP3	BBO	353E08	0	0	0	0	0	0	0	0	0	0	0	0	0	1
S00	CMD	353E16	0	0	0	0	1	0	0	0	0	0	0	0	0	0
S00	RMD	353E16	0	0	0	0	2	0	0	0	0	0	0	0	0	0
MP3	LMS	3E6B05	0	0	0	0	0	0	0	0	0	0	0	0	0	1
MP3	PLU	3H53E8	0	0	0	0	0	0	0	0	0	0	0	0	0	1
S00	CMD	3HML27	0	0	0	0	0	0	0	0	0	0	2	0	0	0
S00	RMD	3HML27	0	0	0	0	0	0	0	0	0	0	2	0	0	0
MP3	PLU	3HML9A	0	0	0	0	0	0	0	0	0	0	0	0	0	1
MP3	PLU	3HML9B	0	0	0	0	0	0	0	0	0	0	0	0	0	1
MP3	BBO	3HML9C	0	0	0	0	0	0	0	0	0	0	0	0	0	1
MP3	PLU	3M2212	0	0	0	0	0	0	0	0	0	0	0	0	0	1
MP3	PLU	3V2212	0	0	0	0	0	0	0	0	0	0	0	0	0	1
S00	CMD	3V2212	0	0	0	0	1	0	0	0	0	0	0	0	0	0
S00	RMD	3V2212	0	0	0	0	2	0	0	0	0	0	0	0	0	0
MP3	DHL	3V8B05	0	0	0	0	0	0	0	0	0	0	0	0	0	1
MP3	DHL	3V8B09	0	0	0	0	0	0	0	0	0	0	0	0	0	1
S00	RMD	3V8R14	0	0	2	2	0	0	0	0	0	0	0	0	0	0

USMC MF TBA by Configuration Code

DIV	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
S00	CMD	453E16	0	0	0	0	0	0	0	0	0	1	0	0	0	0
S00	RMD	453E16	0	0	0	0	0	0	0	0	0	2	0	0	0	0
MPS	BLI	4574H	0	0	0	0	0	0	0	0	0	0	0	0	0	1
MPS	FLY	4574H	0	0	0	0	0	0	0	0	0	0	0	0	0	3
S00	CMD	4HML27	0	0	0	0	0	0	0	1	0	2	0	0	0	0
S00	RMD	4HML27	0	0	0	0	0	0	0	1	0	3	0	0	0	0
S00	CMD	553E16	0	0	0	0	1	0	0	0	0	0	0	0	0	0
S00	RMD	553E16	0	0	0	0	1	0	0	0	0	0	0	0	0	0
S00	CMD	553EXX	0	0	0	0	1	0	0	0	0	0	0	0	0	0
S00	RMD	553EXX	0	0	0	0	1	0	0	0	0	0	0	0	0	0
S00	CMD	5HML27	0	0	0	0	0	0	0	0	0	0	2	0	0	0
S00	RMD	5HML27	0	0	0	0	0	0	0	0	0	0	2	0	0	0
000	05A	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
S00	CMD	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	0	0	0
S00	RMD	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	0	0	0
000	05A	CCSPRW	0	0	0	0	1	0	1	1	0	1	1	0	1	0
400	440	CCSPRW	0	0	0	0	1	0	1	1	0	1	1	0	1	0
S00	CMD	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	3	0
S00	RMD	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	3	0
S00	CMD	F15316	0	0	0	0	0	1	0	1	0	0	0	0	0	0
S00	RMD	F15316	0	0	0	0	0	1	0	1	0	0	0	0	0	0
S00	RMD	F18A36	1	0	0	0	0	0	0	0	0	0	0	0	0	0
S00	RMD	F18C24	2	0	0	0	0	0	0	0	0	0	0	0	0	0
S00	CMD	F18R14	0	1	1	1	0	0	0	0	0	0	0	0	0	0
S00	RMD	F18R14	0	1	1	0	0	0	0	0	0	0	0	0	0	0
S00	RMD	F1E605	0	1	0	1	0	0	0	0	0	0	0	0	0	0
S00	CMD	F1H127	0	0	0	0	0	1	0	1	0	0	0	0	0	0
S00	RMD	F1H127	0	0	0	0	0	2	0	1	0	0	0	0	0	0
S00	CMD	F1V224	0	0	0	0	0	1	1	0	0	0	0	0	0	0
S00	RMD	F1V224	0	0	0	0	0	2	1	0	0	0	0	0	0	0
S00	CMD	F25316	0	0	0	0	0	0	0	1	0	0	0	0	0	0
S00	RMD	F25316	0	0	0	0	0	0	0	1	0	0	0	0	0	0
S00	RMD	F28A36	0	1	0	0	0	0	0	0	0	0	0	0	0	0
S00	CMD	F2H127	0	0	0	0	0	0	0	0	0	0	1	0	0	0
S00	RMD	F2H127	0	0	0	0	0	0	0	0	0	0	2	0	0	0
S00	CMD	F2V224	0	0	0	0	0	0	1	0	0	0	0	0	0	0
S00	RMD	F2V224	0	0	0	0	0	0	1	0	0	0	0	0	0	0
S00	CMD	F30J12	1	0	0	1	0	0	0	0	0	1	0	0	0	0
S00	RMD	F30J12	1	0	0	1	0	0	0	0	0	1	0	0	0	0
S00	CMD	F35316	0	0	0	0	0	0	0	0	0	1	0	0	0	0
S00	RMD	F35316	0	0	0	0	0	0	0	0	0	1	0	0	0	0
S00	CMD	F38A36	0	0	0	0	0	0	0	0	1	0	0	0	0	0
S00	RMD	F38A36	0	0	0	0	0	0	0	0	1	0	0	0	0	0
S00	CMD	F38C24	0	0	0	0	0	0	0	0	1	0	0	0	0	0
S00	RMD	F38C24	0	0	0	0	0	0	0	0	1	0	0	0	0	0
S00	CMD	F3H127	0	0	0	0	0	0	0	0	0	1	0	0	0	0
S00	RMD	F3H127	0	0	0	0	0	0	0	0	0	2	0	0	0	0
S00	CMD	F3V224	0	0	0	0	1	0	0	0	0	0	0	0	0	0

USMC MF TBA by Configuration Code

DIV	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
S00	RMD	F3V224	0	0	0	0	1	0	0	0	0	0	0	0	0	0
S00	CMD	F45316	0	0	0	0	1	0	0	0	0	0	0	0	0	0
S00	CMD	F4H127	0	0	0	0	0	0	0	1	0	0	0	0	0	0
S00	RMD	F4H127	0	0	0	0	0	0	0	1	0	0	0	0	0	0
S00	CMD	F5H127	0	0	0	0	0	0	0	0	0	0	1	0	0	0
S00	RMD	F5H127	0	0	0	0	0	0	0	0	0	0	2	0	0	0
600	670	IOSP14	0	0	0	1	0	0	0	0	0	0	0	0	0	0
000	05A	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			14	11	9	17	17	17	12	20	12	22	23	1	8	35
** <u>SW-02</u> **																
800	820	118A36	1	1	0	0	0	0	0	0	1	0	0	1	0	0
800	820	118C24	1	1	0	0	0	0	0	0	1	0	0	0	0	0
800	820	1HML27	0	0	0	0	0	0	0	2	0	0	1	0	2	0
800	820	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
800	820	TH1M39	0	0	0	0	0	0	0	0	0	0	1	0	0	0
** Subtotal **			3	2	0	0	0	0	0	2	2	0	2	1	2	0
** <u>TB-01</u> **																
500	520	CCSPRW	0	0	0	0	1	1	0	2	0	1	0	0	0	0
** Subtotal **			0	0	0	0	1	1	0	2	0	1	0	0	0	0
** <u>TB-02</u> **																
500	520	1V2236	0	0	0	0	0	1	2	0	0	1	1	0	0	0
500	520	3V2212	0	0	0	0	1	0	0	0	0	0	0	0	1	0
500	520	TV2226	0	0	0	0	0	0	1	0	0	0	0	0	0	0
** Subtotal **			0	0	0	0	1	1	3	0	0	1	1	0	1	0
** <u>TB-03A</u> **																
500	520	CCSPFW	2	1	1	2	0	0	0	0	1	0	0	1	0	0
500	520	TFRS39	0	0	0	0	0	0	0	0	0	0	1	0	0	0
** Subtotal **			2	1	1	2	0	0	0	0	1	0	1	1	0	0
** <u>TB-04B</u> **																
500	520	CCSPFW	2	1	1	2	0	0	0	0	1	0	0	1	0	0
500	520	TFRS39	0	0	0	0	0	0	0	0	0	0	1	0	0	0
** Subtotal **			2	1	1	2	0	0	0	0	1	0	1	1	0	0
** <u>TL-01</u> **																
000	040	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
600	670	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
000	040	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	1	0
600	670	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	1	0
** Subtotal **			2	2	2	2	2	2	2	2	2	0	2	2	2	0
** <u>TR-01</u> **																

USMC MF TBA by Configuration Code

DIV	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
400	400	118A12	0	0	0	0	0	0	0	0	0	0	0	1	0	0
400	400	118A36	1	1	0	0	0	0	0	0	0	0	0	0	0	0
400	400	118C24	1	0	0	0	0	0	0	0	0	0	0	0	0	0
400	400	1E6B05	0	1	0	1	0	0	0	0	0	0	0	0	0	0
400	400	2E6B05	0	0	0	1	0	0	0	0	0	0	0	0	0	0
400	400	3E6B05	0	0	0	1	0	0	0	0	0	0	0	0	0	0
000	05D	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
500	500	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
600	600	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
000	05D	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
400	440	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
500	500	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
600	600	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
000	05D	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
600	600	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			7	5	3	6	4	4	4	4	3	4	4	4	4	0
** <u>TT-02</u> **																
600	620	1HML27	0	0	0	0	0	1	0	2	0	1	1	0	1	0
600	620	2HML27	0	0	0	0	0	0	0	0	0	0	1	0	0	0
** Subtotal **			0	0	0	0	0	1	0	2	0	1	2	0	1	0
** <u>TT-03A</u> **																
600	620	1HML27	0	0	0	0	0	1	0	2	0	1	1	0	1	0
600	620	2HML27	0	0	0	0	0	0	0	0	0	0	1	0	0	0
** Subtotal **			0	0	0	0	0	1	0	2	0	1	2	0	1	0
** <u>TT-04B</u> **																
600	620	1HML27	0	0	0	0	0	1	0	2	0	1	1	0	1	0
600	620	2HML27	0	0	0	0	0	0	0	0	0	0	1	0	0	0
** Subtotal **			0	0	0	0	0	1	0	2	0	1	2	0	1	0
** <u>TW-05A</u> **																
MP2	LPZ	2FEFW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
MP2	BTN	2FERW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
MP3	LMS	3FEFW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
MP3	BBO	3FERW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
MPS	FLY	4574H	0	0	0	0	0	0	0	0	0	0	0	0	0	1
500	510	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
500	510	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	1	0
** Subtotal **			1	1	1	1	1	1	1	1	1	0	1	1	1	5
** <u>TW-06B</u> **																
MP2	LPZ	2FEFW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
MP2	BTN	2FERW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
MP3	LMS	3FEFW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
MP3	BBO	3FERW	0	0	0	0	0	0	0	0	0	0	0	0	0	1

USMC MF TBA by Configuration Code

DIV	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
MPS	FLY	4574H	0	0	0	0	0	0	0	0	0	0	0	0	0	1
500	510	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
500	510	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	1	0
** Subtotal **			1	1	1	1	1	1	1	1	1	0	1	1	1	5
** <u>VD-05A</u> **																
600	620	CCSPRW	0	0	0	0	0	0	1	1	0	1	1	0	0	0
600	620	T53E29	0	0	0	0	0	0	0	1	0	0	0	0	0	0
600	620	TH1M39	0	0	0	0	0	0	0	0	0	0	1	0	0	0
** Subtotal **			0	0	0	0	0	0	1	2	0	1	2	0	0	0
** <u>VD-06B</u> **																
600	620	CCSPRW	0	0	0	0	0	0	1	1	0	1	1	0	0	0
600	620	T53E29	0	0	0	0	0	0	0	1	0	0	0	0	0	0
600	620	TH1M39	0	0	0	0	0	0	0	0	0	0	1	0	0	0
** Subtotal **			0	0	0	0	0	0	1	2	0	1	2	0	0	0
** <u>VD-07A</u> **																
600	620	130T12	0	0	0	0	0	0	0	0	0	0	0	0	1	0
600	620	153E16	0	0	0	0	1	0	0	0	0	0	0	0	0	0
600	620	318C24	0	0	0	0	0	0	0	0	1	0	0	0	0	0
600	620	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
600	620	CCSPRW	0	0	0	0	0	1	0	0	0	0	0	0	0	0
600	620	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
600	620	TV8B14	0	0	0	1	0	0	0	0	0	0	0	0	0	0
** Subtotal **			2	1	1	2	1	1	0	0	2	0	0	1	1	0
** <u>VD-08B</u> **																
600	620	130T12	0	0	0	0	0	0	0	0	0	0	0	0	1	0
600	620	153E16	0	0	0	0	1	0	0	0	0	0	0	0	0	0
600	620	318C24	0	0	0	0	0	0	0	0	1	0	0	0	0	0
600	620	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
600	620	CCSPRW	0	0	0	0	0	1	0	0	0	0	0	0	0	0
600	620	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
600	620	TV8B14	0	0	0	1	0	0	0	0	0	0	0	0	0	0
** Subtotal **			2	1	1	2	1	1	0	0	2	0	0	1	1	0
** <u>WC-02</u> **																
000	030	CCSPFW	2	2	2	2	0	0	0	0	2	0	0	2	0	0
000	040	CCSPFW	2	2	2	2	0	0	0	0	2	0	0	2	0	0
000	030	CCSPRW	0	0	0	0	2	0	2	2	0	0	2	0	2	0
000	040	CCSPRW	0	0	0	0	2	1	1	2	0	0	2	0	2	0
000	030	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
000	040	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			6	4	4	4	4	1	3	4	4	0	4	4	4	0
** <u>WC-08</u> **																

USMC MF TBA by Configuration Code

DIV	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
900	910	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
900	930	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
900	940	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
900	910	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	1	0
900	930	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	1	0
900	940	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	1	0
900	910	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
900	940	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			5	3	3	3	3	3	3	3	3	0	3	3	3	0
** <u>WC-12A</u> **																
600	60C	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
600	60C	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
** Subtotal **			1	1	1	1	1	1	1	1	1	1	1	1	1	0
** <u>WC-13BM</u> **																
600	60C	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
600	60C	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
** Subtotal **			1	1	1	1	1	1	1	1	1	1	1	1	1	0
** <u>WJ-06</u> **																
ATC	ATC	MACSXX	0	1	2	2	1	0	0	1	1	1	1	1	1	0
** Subtotal **			0	1	2	2	1	0	0	1	1	1	1	1	1	0
** <u>WL-04A</u> **																
500	510	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
500	510	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	1	0
500	510	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			2	1	1	1	1	1	1	1	1	0	1	1	1	0
** <u>WL-05A</u> **																
500	510	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
500	510	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	1	0
500	510	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			2	1	1	1	1	1	1	1	1	0	1	1	1	0
** <u>WR-01</u> **																
600	690	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	0	0	0
600	690	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	0	0
** Subtotal **			1	1	1	1	1	1	1	1	1	1	1	0	0	0
Total 343			265	201	344	245	212	219	245	244	210	281	168	192	64	

14 MAR 2016

USMC MF TBA by Contingency Support Package

CONFIG	DIV	BR	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
** 118A12 **																
FA-02A	500	520	0	0	0	0	0	0	0	0	0	0	0	1	0	0
FA-03B	500	520	0	0	0	0	0	0	0	0	0	0	0	1	0	0
JU-01	500	500	0	0	0	0	0	0	0	0	0	0	0	1	0	0
KA-31	600	650	0	0	0	0	0	0	0	0	0	0	0	1	0	0
TR-01	400	400	0	0	0	0	0	0	0	0	0	0	0	1	0	0
** Subtotal **			0	0	0	0	0	0	0	0	0	0	0	5	0	0
** 118A36 **																
AT-08	000	S2	2	2	0	0	0	0	0	0	2	0	0	0	0	0
AT-09BM	000	210	2	2	0	0	0	0	0	0	2	0	0	0	0	0
AT-10A	000	210	2	2	0	0	0	0	0	0	2	0	0	0	0	0
BR-01	700	71D	1	1	0	1	0	0	0	0	0	0	0	2	0	0
FA-02A	500	520	1	2	0	0	0	0	0	0	0	0	0	0	0	0
FA-03B	500	520	1	2	0	0	0	0	0	0	0	0	0	0	0	0
GM-02A	700	71B	1	1	0	1	0	0	0	0	0	0	0	0	0	0
GM-03B	700	71B	1	1	0	1	0	0	0	0	0	0	0	0	0	0
JU-01	S00	S00	3	0	0	0	0	0	0	0	0	0	0	0	0	0
JU-01	600	600	1	1	0	0	0	0	0	0	1	0	0	0	0	0
JU-01	500	500	1	1	0	0	0	0	0	0	0	0	0	0	0	0
JU-01	000	000	1	1	0	0	0	0	0	0	1	0	0	0	0	0
KA-31	600	650	2	0	0	0	0	0	0	0	0	0	0	0	0	0
ST-01	600	610	1	1	0	0	0	0	0	0	1	0	0	0	0	0
ST-01	600	620	1	1	0	0	0	0	0	0	1	0	0	0	0	0
ST-01	600	650	0	1	0	0	0	0	0	0	0	0	0	0	0	0
SU-01	S00	CMD	1	0	0	0	0	0	0	0	0	0	0	0	0	0
SU-02	S00	CMD	3	0	0	0	0	0	0	0	0	0	0	0	0	0
SU-05	S00	SAD	1	0	0	0	0	0	0	0	0	0	0	0	0	0
SU-05	S00	SRD	1	0	0	0	0	0	0	0	0	0	0	0	0	0
SU-12	S00	CMD	1	0	0	0	0	0	0	0	0	0	0	0	0	0
SW-02	800	820	1	1	0	0	0	0	0	0	1	0	0	1	0	0
TR-01	400	400	1	1	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			30	21	0	3	0	0	0	0	11	0	0	3	0	0
** 118C24 **																
FA-02A	500	520	1	0	0	0	0	0	0	0	0	0	0	0	0	0
FA-03B	500	520	1	0	0	0	0	0	0	0	0	0	0	0	0	0
JU-01	S00	S00	3	0	0	0	0	0	0	0	0	0	0	0	0	0
JU-01	600	600	1	0	0	0	0	0	0	0	1	0	0	1	0	0
JU-01	500	500	1	0	0	0	0	0	0	0	0	0	0	0	0	0
ST-01	600	610	1	0	0	0	0	0	0	0	1	0	0	1	0	0
ST-01	600	620	1	0	0	0	0	0	0	0	1	0	0	1	0	0
SU-01	S00	RMD	1	0	0	0	0	0	0	0	0	0	0	0	0	0
SU-02	S00	CMD	3	0	0	0	0	0	0	0	0	0	0	0	0	0
SU-03	600	650	0	0	0	0	0	0	0	0	1	0	0	1	0	0
SU-05	S00	SAD	1	0	0	0	0	0	0	0	0	0	0	0	0	0

USMC MF TBA by Contingency Support Package

CONFIG	DIV	BR	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
SU-05	S00	SRD	1	0	0	0	0	0	0	0	0	0	0	0	0	0
SU-12	S00	CMD	1	0	0	0	0	0	0	0	0	0	0	0	0	0
SW-02	800	820	1	1	0	0	0	0	0	0	1	0	0	0	0	0
TR-01	400	400	1	0	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			18	1	0	0	0	0	0	0	5	0	0	4	0	0
** <u>130J12</u> **																
JU-01	S00	S00	2	0	0	2	0	0	0	0	0	2	0	0	0	0
JU-01	800	800	0	0	0	0	0	0	0	0	0	1	0	0	0	0
RR-02	800	810	0	1	0	0	0	0	0	0	0	0	0	0	0	0
RR-03	800	810	0	1	0	0	0	0	0	0	0	0	0	0	0	0
SH-06	600	650	1	0	0	1	0	0	0	0	0	1	0	0	0	0
SU-01	S00	RMD	1	0	0	1	0	0	0	0	0	1	0	0	0	0
SU-02	S00	CMD	1	0	0	1	0	0	0	0	0	2	0	0	0	0
SU-12	S00	CMD	1	0	0	1	0	0	0	0	0	1	0	0	0	0
SU-12	S00	RMD	2	0	0	2	0	0	0	0	0	2	0	0	0	0
** Subtotal **			8	2	0	8	0	0	0	0	0	10	0	0	0	0
** <u>130T12</u> **																
JU-01	600	600	0	0	0	0	0	0	0	0	0	0	0	1	2	0
SH-06	600	650	0	0	0	0	0	0	0	0	0	0	0	1	1	0
ST-01	600	610	0	0	0	0	0	0	0	0	0	0	0	3	3	0
ST-01	600	620	0	0	0	0	0	0	0	0	0	0	0	1	1	0
VD-07A	600	620	0	0	0	0	0	0	0	0	0	0	0	0	1	0
VD-08B	600	620	0	0	0	0	0	0	0	0	0	0	0	0	1	0
** Subtotal **			0	0	0	0	0	0	0	0	0	0	0	6	9	0
** <u>135B16</u> **																
BL-01	600	600	0	0	2	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			0	0	2	0	0	0	0	0	0	0	0	0	0	0
** <u>146E12</u> **																
JU-01	S00	S00	0	0	0	0	0	0	0	0	0	2	2	0	0	0
** Subtotal **			0	0	0	0	0	0	0	0	0	2	2	0	0	0
** <u>146E36</u> **																
ST-01	600	620	0	0	0	0	1	0	0	0	0	1	1	0	0	0
** Subtotal **			0	0	0	0	1	0	0	0	0	1	1	0	0	0
** <u>153E16</u> **																
JU-01	S00	S00	0	0	0	0	0	2	0	2	0	0	0	0	0	0
JU-01	600	600	0	0	0	0	1	0	0	1	0	0	0	0	0	0
ST-01	600	620	0	0	0	0	1	1	0	2	0	1	0	0	0	0
SU-02	S00	CMD	0	0	0	0	0	1	0	2	0	0	0	0	0	0
SU-03	S00	CMD	0	0	0	0	0	1	0	0	0	0	0	0	0	0

USMC MF TBA by Contingency Support Package

CONFIG	DIV	BR	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
SU-12	S00	CMD	0	0	0	0	0	1	0	1	0	0	0	0	0	0
SU-12	S00	RMD	0	0	0	0	0	0	0	1	0	0	0	0	0	0
VD-07A	600	620	0	0	0	0	1	0	0	0	0	0	0	0	0	0
VD-08B	600	620	0	0	0	0	1	0	0	0	0	0	0	0	0	0
** Subtotal **			0	0	0	0	4	6	0	9	0	1	0	0	0	0
** <u>1E6B05</u> **																
JU-01	S00	S00	0	1	0	1	0	0	0	0	0	0	0	0	0	0
JU-09	600	600	0	1	0	1	0	0	0	0	0	0	0	0	0	0
JU-10	600	600	0	1	0	1	0	0	0	0	0	0	0	0	0	0
KA-31	600	650	0	0	0	3	0	0	0	0	0	0	0	0	0	0
PM-01	600	650	0	1	0	1	0	0	0	0	0	0	0	0	0	0
ST-01	600	610	0	2	0	2	0	0	0	0	0	0	0	0	0	0
ST-01	600	620	0	1	0	1	0	0	0	0	0	0	0	0	0	0
SU-02	S00	CMD	0	1	0	1	0	0	0	0	0	0	0	0	0	0
SU-12	S00	RMD	0	1	0	1	0	0	0	0	0	0	0	0	0	0
TR-01	400	400	0	1	0	1	0	0	0	0	0	0	0	0	0	0
** Subtotal **			0	10	0	13	0	0	0	0	0	0	0	0	0	0
** <u>1HML09</u> **																
BL-01	600	620	0	0	0	0	0	0	0	0	0	0	0	0	1	0
** Subtotal **			0	0	0	0	0	0	0	0	0	0	0	0	1	0
** <u>1HML27</u> **																
BL-01	600	620	0	0	0	0	0	1	0	2	0	2	0	0	0	0
JU-01	S00	S00	0	0	0	0	0	3	0	3	0	0	0	0	0	0
JU-01	600	600	0	0	0	0	0	1	0	2	0	1	2	0	1	0
KA-18A	600	600	0	0	0	0	0	0	0	0	0	0	3	0	0	0
KA-31	600	650	0	0	0	0	0	0	0	0	0	0	2	0	0	0
ST-01	600	620	0	0	0	0	0	1	0	2	0	1	1	0	0	0
SU-02	S00	CMD	0	0	0	0	0	1	0	3	0	0	0	0	0	0
SU-04	S00	SRD	0	0	0	0	0	2	0	2	0	0	0	0	0	0
SU-05	S00	SAD	0	0	0	0	0	1	0	1	0	0	0	0	0	0
SU-12	S00	CMD	0	0	0	0	0	1	0	1	0	0	0	0	0	0
SU-12	S00	RMD	0	0	0	0	0	0	0	1	0	0	0	0	0	0
SW-02	800	820	0	0	0	0	0	0	0	2	0	0	1	0	2	0
TT-02	600	620	0	0	0	0	0	1	0	2	0	1	1	0	1	0
TT-03A	600	620	0	0	0	0	0	1	0	2	0	1	1	0	1	0
TT-04B	600	620	0	0	0	0	0	1	0	2	0	1	1	0	1	0
** Subtotal **			0	0	0	0	0	14	0	25	0	7	12	0	6	0
** <u>1RS46E</u> **																
JU-01	S00	S00	0	0	0	0	0	0	0	0	0	0	0	0	3	0
SU-02	S00	CMD	0	0	0	0	0	0	0	0	0	0	0	0	1	0
SU-05	S00	SRD	0	0	0	0	0	0	0	0	0	0	0	0	2	0

USMC MF TBA by Contingency Support Package

CONFIG	DIV	BR	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
** Subtotal **			0	0	0	0	0	0	0	0	0	0	0	0	6	0
** <u>1RS53E</u> **																
ST-01	600	620	0	0	0	0	0	0	0	0	0	0	0	0	1	0
** Subtotal **			0	0	0	0	0	0	0	0	0	0	0	0	1	0
** <u>1V2236</u> **																
HY-06C	500	520	0	0	0	0	0	1	2	0	0	1	1	0	0	0
JU-01	S00	S00	0	0	0	0	0	3	3	0	0	0	0	0	0	0
JU-01	800	800	0	0	0	0	0	0	1	0	0	0	0	0	0	0
JU-01	500	500	0	0	0	0	0	1	1	0	0	1	1	0	0	0
KA-18A	600	600	0	0	0	0	2	0	0	0	0	0	0	0	0	0
RR-04A	800	810	0	0	0	0	0	0	2	0	0	1	1	0	0	0
RR-05B	800	810	0	0	0	0	0	0	2	0	0	1	1	0	0	0
SU-02	S00	CMD	0	0	0	0	0	1	1	0	0	0	0	0	0	0
SU-05	S00	CMD	0	0	0	0	0	1	1	0	0	0	0	0	0	0
SU-05	S00	RMD	0	0	0	0	0	1	1	0	0	0	0	0	0	0
SU-05	S00	SAD	0	0	0	0	0	1	1	0	0	0	0	0	0	0
SU-12	S00	CMD	0	0	0	0	0	1	1	0	0	0	0	0	0	0
SU-12	S00	RMD	0	0	0	0	0	4	1	0	0	0	0	0	0	0
TB-02	500	520	0	0	0	0	0	1	2	0	0	1	1	0	0	0
** Subtotal **			0	0	0	0	2	15	19	0	0	5	5	0	0	0
** <u>1V8R14</u> **																
BR-01	700	71D	1	1	0	1	0	0	0	0	0	0	0	0	0	0
GC-01	600	620	0	1	1	1	0	0	0	0	0	0	0	0	0	0
GM-02A	700	71B	1	1	0	1	0	0	0	0	0	0	0	1	0	0
GM-03B	700	71B	1	1	0	1	0	0	0	0	0	0	0	1	0	0
JU-01	S00	S00	0	2	2	2	0	0	0	0	0	0	0	0	0	0
JU-01	600	600	0	1	1	1	0	0	0	0	0	0	0	0	0	0
JU-01	500	500	0	0	0	1	0	0	0	0	0	0	0	0	0	0
PM-02	600	650	0	1	1	1	0	0	0	0	0	0	0	0	0	0
SP-04	500	520	0	1	1	2	0	0	0	0	0	0	0	0	0	0
ST-01	600	610	0	1	1	1	0	0	0	0	0	0	0	0	0	0
ST-01	600	620	0	1	1	1	0	0	0	0	0	0	0	0	0	0
SU-01	S00	RMD	0	1	0	1	0	0	0	0	0	0	0	0	0	0
SU-02	S00	CMD	0	1	1	1	0	0	0	0	0	0	0	0	0	0
SU-12	S00	CMD	0	1	0	1	0	0	0	0	0	0	0	0	0	0
SU-12	S00	RMD	0	2	2	2	0	0	0	0	0	0	0	0	0	0
** Subtotal **			3	16	11	18	0	0	0	0	0	0	0	2	0	0
** <u>218A12</u> **																
SU-12	MP2	LPZ	0	0	0	0	0	0	0	0	0	0	0	0	0	1
** Subtotal **			0	0	0	0	0	0	0	0	0	0	0	0	0	1

USMC MF TBA by Contingency Support Package

CONFIG	DIV	BR	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
** <u>218A36</u> **																
JU-01	S00	S00	0	3	0	0	0	0	0	0	0	0	0	0	0	0
KA-31	600	650	0	1	0	0	0	0	0	0	0	0	0	0	0	0
SU-02	S00	CMD	0	1	0	0	0	0	0	0	0	0	0	0	0	0
SU-05	S00	CMD	0	1	0	0	0	0	0	0	0	0	0	0	0	0
SU-05	S00	RMD	0	1	0	0	0	0	0	0	0	0	0	0	0	0
SU-05	S00	SRD	0	1	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			0	8	0	0	0	0	0	0	0	0	0	0	0	0
** <u>218C12</u> **																
SU-12	MP2	SSR	0	0	0	0	0	0	0	0	0	0	0	0	0	1
** Subtotal **			0	0	0	0	0	0	0	0	0	0	0	0	0	1
** <u>218D12</u> **																
SU-12	MP2	LPZ	0	0	0	0	0	0	0	0	0	0	0	0	0	1
** Subtotal **			0	0	0	0	0	0	0	0	0	0	0	0	0	1
** <u>222B12</u> **																
SU-12	MP2	BTN	0	0	0	0	0	0	0	0	0	0	0	0	0	1
** Subtotal **			0	0	0	0	0	0	0	0	0	0	0	0	0	1
** <u>230J15</u> **																
SU-12	MP2	BTN	0	0	0	0	0	0	0	0	0	0	0	0	0	1
** Subtotal **			0	0	0	0	0	0	0	0	0	0	0	0	0	1
** <u>235C10</u> **																
BL-01	600	600	0	0	0	0	0	0	0	0	1	0	0	0	0	0
** Subtotal **			0	0	0	0	0	0	0	0	1	0	0	0	0	0
** <u>246E36</u> **																
JU-01	S00	S00	0	0	0	0	3	0	0	0	0	0	0	0	0	0
SU-02	S00	CMD	0	0	0	0	1	0	0	0	0	0	0	0	0	0
SU-05	S00	CMD	0	0	0	0	1	0	0	0	0	0	0	0	0	0
SU-05	S00	RMD	0	0	0	0	1	0	0	0	0	0	0	0	0	0
SU-05	S00	SAD	0	0	0	0	1	0	0	0	0	0	0	0	0	0
** Subtotal **			0	0	0	0	7	0	0	0	0	0	0	0	0	0
** <u>253E08</u> **																
SU-12	MP2	BTN	0	0	0	0	0	0	0	0	0	0	0	0	0	1
** Subtotal **			0	0	0	0	0	0	0	0	0	0	0	0	0	1
** <u>253E16</u> **																
JU-01	S00	S00	0	0	0	0	0	0	0	2	0	0	0	0	0	0
ST-01	600	620	0	0	0	0	1	0	0	0	0	0	0	0	0	0

USMC MF TBA by Contingency Support Package

CONFIG	DIV	BR	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
SU-01	S00	RMD	0	0	0	0	0	0	0	1	0	0	0	0	0	0
SU-12	S00	CMD	0	0	0	0	0	0	0	1	0	0	0	0	0	0
SU-12	S00	RMD	0	0	0	0	0	0	0	1	0	0	0	0	0	0
** Subtotal **			0	0	0	0	1	0	0	5	0	0	0	0	0	0
** <u>2E6B05</u> **																
JU-01	S00	S00	0	0	0	1	0	0	0	0	0	0	0	0	0	0
JU-09	600	600	0	0	0	1	0	0	0	0	0	0	0	0	0	0
JU-10	600	600	0	0	0	1	0	0	0	0	0	0	0	0	0	0
KA-31	600	650	0	0	0	3	0	0	0	0	0	0	0	0	0	0
PM-01	600	650	0	0	0	1	0	0	0	0	0	0	0	0	0	0
ST-01	600	610	0	0	0	2	0	0	0	0	0	0	0	0	0	0
ST-01	600	620	0	0	0	1	0	0	0	0	0	0	0	0	0	0
SU-02	S00	CMD	0	0	0	1	0	0	0	0	0	0	0	0	0	0
SU-12	MP2	LPZ	0	0	0	0	0	0	0	0	0	0	0	0	0	1
TR-01	400	400	0	0	0	1	0	0	0	0	0	0	0	0	0	0
** Subtotal **			0	0	0	12	0	0	0	0	0	0	0	0	0	1
** <u>2FEFW</u> **																
BL-01	MP2	LPZ	0	0	0	0	0	0	0	0	0	0	0	0	0	2
SU-12	MP2	LPZ	0	0	0	0	0	0	0	0	0	0	0	0	0	1
TW-05A	MP2	LPZ	0	0	0	0	0	0	0	0	0	0	0	0	0	1
TW-06B	MP2	LPZ	0	0	0	0	0	0	0	0	0	0	0	0	0	1
** Subtotal **			0	0	0	0	0	0	0	0	0	0	0	0	0	5
** <u>2FERW</u> **																
BL-01	MP2	BTN	0	0	0	0	0	0	0	0	0	0	0	0	0	2
TW-05A	MP2	BTN	0	0	0	0	0	0	0	0	0	0	0	0	0	1
TW-06B	MP2	BTN	0	0	0	0	0	0	0	0	0	0	0	0	0	1
** Subtotal **			0	0	0	0	0	0	0	0	0	0	0	0	0	4
** <u>2H53E8</u> **																
SU-12	MP2	SEAY	0	0	0	0	0	0	0	0	0	0	0	0	0	1
** Subtotal **			0	0	0	0	0	0	0	0	0	0	0	0	0	1
** <u>2HML09</u> **																
BL-01	600	620	0	0	0	0	0	0	0	0	0	0	0	0	1	0
** Subtotal **			0	0	0	0	0	0	0	0	0	0	0	0	1	0
** <u>2HML27</u> **																
BL-01	600	620	0	0	0	0	0	0	0	0	0	0	1	0	0	0
JU-01	S00	S00	0	0	0	0	0	0	0	0	0	0	3	0	0	0
JU-01	600	600	0	0	0	0	0	0	0	0	0	0	1	0	0	0
ST-01	600	620	0	0	0	0	0	0	0	0	0	0	1	0	0	0
SU-01	S00	RMD	0	0	0	0	0	0	0	0	0	0	2	0	0	0

USMC MF TBA by Contingency Support Package

CONFIG	DIV	BR	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
SU-02	S00	CMD	0	0	0	0	0	0	0	0	0	0	3	0	0	0
SU-05	S00	SAD	0	0	0	0	0	0	0	0	0	0	1	0	0	0
SU-05	S00	SRD	0	0	0	0	0	0	0	0	0	0	2	0	0	0
SU-12	S00	CMD	0	0	0	0	0	0	0	0	0	0	2	0	0	0
SU-12	S00	RMD	0	0	0	0	0	0	0	0	0	0	3	0	0	0
TT-02	600	620	0	0	0	0	0	0	0	0	0	0	1	0	0	0
TT-03A	600	620	0	0	0	0	0	0	0	0	0	0	1	0	0	0
TT-04B	600	620	0	0	0	0	0	0	0	0	0	0	1	0	0	0
** Subtotal **			0	0	0	0	0	0	0	0	0	0	22	0	0	0
** <u>2HML9A</u> **																
SU-12	MP2	SEAY	0	0	0	0	0	0	0	0	0	0	0	0	0	1
** Subtotal **			0	0	0	0	0	0	0	0	0	0	0	0	0	1
** <u>2HML9B</u> **																
SU-12	MP2	SEAY	0	0	0	0	0	0	0	0	0	0	0	0	0	1
** Subtotal **			0	0	0	0	0	0	0	0	0	0	0	0	0	1
** <u>2HML9C</u> **																
SU-12	MP2	BTN	0	0	0	0	0	0	0	0	0	0	0	0	0	1
** Subtotal **			0	0	0	0	0	0	0	0	0	0	0	0	0	1
** <u>2M2212</u> **																
SU-12	MP2	SEAY	0	0	0	0	0	0	0	0	0	0	0	0	0	1
** Subtotal **			0	0	0	0	0	0	0	0	0	0	0	0	0	1
** <u>2V2212</u> **																
SU-12	MP2	SEAY	0	0	0	0	0	0	0	0	0	0	0	0	0	1
** Subtotal **			0	0	0	0	0	0	0	0	0	0	0	0	0	1
** <u>2V2224</u> **																
JU-01	S00	S00	0	0	0	0	0	0	3	0	0	0	0	0	0	0
SU-01	S00	RMD	0	0	0	0	0	0	1	0	0	0	0	0	0	0
SU-02	S00	CMD	0	0	0	0	0	0	1	0	0	0	0	0	0	0
SU-05	S00	SRD	0	0	0	0	0	0	2	0	0	0	0	0	0	0
SU-12	S00	CMD	0	0	0	0	0	0	1	0	0	0	0	0	0	0
SU-12	S00	RMD	0	0	0	0	0	0	1	0	0	0	0	0	0	0
** Subtotal **			0	0	0	0	0	0	9	0	0	0	0	0	0	0
** <u>2V8B05</u> **																
SU-12	MP2	SSR	0	0	0	0	0	0	0	0	0	0	0	0	0	1
** Subtotal **			0	0	0	0	0	0	0	0	0	0	0	0	0	1

USMC MF TBA by Contingency Support Package

CONFIG	DIV	BR	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
** <u>2V8B09</u> **																
SU-12	MP2	SSR	0	0	0	0	0	0	0	0	0	0	0	0	0	1
** Subtotal **			0	0	0	0	0	0	0	0	0	0	0	0	0	1
** <u>2V8R14</u> **																
GC-01	600	620	0	0	1	1	0	0	0	0	0	0	0	0	0	0
JU-01	S00	S00	0	0	2	2	0	0	0	0	0	0	0	0	0	0
JU-01	600	600	0	0	1	1	0	0	0	0	0	0	0	0	0	0
KA-31	600	650	0	0	0	1	0	0	0	0	0	0	0	0	0	0
ST-01	600	610	0	0	1	1	0	0	0	0	0	0	0	0	0	0
ST-01	600	620	0	0	1	1	0	0	0	0	0	0	0	0	0	0
SU-02	S00	CMD	0	0	1	1	0	0	0	0	0	0	0	0	0	0
** Subtotal **			0	0	7	8	0	0	0	0	0	0	0	0	0	0
** <u>318A12</u> **																
SU-12	MP3	LMS	0	0	0	0	0	0	0	0	0	0	0	0	0	1
** Subtotal **			0	0	0	0	0	0	0	0	0	0	0	0	0	1
** <u>318A36</u> **																
FA-02A	500	520	0	0	0	0	0	0	0	0	1	0	0	0	0	0
FA-03B	500	520	0	0	0	0	0	0	0	0	1	0	0	0	0	0
JU-01	S00	S00	0	0	0	0	0	0	0	0	3	0	0	0	0	0
JU-01	600	600	0	0	0	0	0	0	0	0	1	0	0	0	0	0
KA-31	600	650	0	0	0	0	0	0	0	0	4	0	0	0	0	0
SU-02	S00	CMD	0	0	0	0	0	0	0	0	1	0	0	0	0	0
SU-05	S00	CMD	0	0	0	0	0	0	0	0	1	0	0	0	0	0
SU-05	S00	RMD	0	0	0	0	0	0	0	0	1	0	0	0	0	0
SU-05	S00	SAD	0	0	0	0	0	0	0	0	1	0	0	0	0	0
SU-12	S00	CMD	0	0	0	0	0	0	0	0	2	0	0	0	0	0
SU-12	S00	RMD	0	0	0	0	0	0	0	0	1	0	0	0	0	0
** Subtotal **			0	0	0	0	0	0	0	0	17	0	0	0	0	0
** <u>318C12</u> **																
SU-12	MP3	DHL	0	0	0	0	0	0	0	0	0	0	0	0	0	1
** Subtotal **			0	0	0	0	0	0	0	0	0	0	0	0	0	1
** <u>318C24</u> **																
FA-02A	500	520	0	0	0	0	0	0	0	0	1	0	0	0	0	0
FA-03B	500	520	0	0	0	0	0	0	0	0	1	0	0	0	0	0
JU-01	S00	S00	0	0	0	0	0	0	0	0	3	0	0	0	0	0
JU-01	500	500	0	0	0	0	0	0	0	0	1	0	0	0	0	0
SU-01	S00	RMD	0	0	0	0	0	0	0	0	1	0	0	0	0	0
SU-02	S00	CMD	0	0	0	0	0	0	0	0	1	0	0	0	0	0
SU-05	S00	SRD	0	0	0	0	0	0	0	0	1	0	0	0	0	0
SU-12	S00	CMD	0	0	0	0	0	0	0	0	1	0	0	0	0	0

14 MAR 2016

USMC MF TBA by Contingency Support Package

CONFIG	DIV	BR	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
SU-12	S00	RMD	0	0	0	0	0	0	0	0	1	0	0	0	0	0
VD-07A	600	620	0	0	0	0	0	0	0	0	1	0	0	0	0	0
VD-08B	600	620	0	0	0	0	0	0	0	0	1	0	0	0	0	0
** Subtotal **			0	0	0	0	0	0	0	0	13	0	0	0	0	0
** <u>318D12</u> **																
SU-12	MP3	LMS	0	0	0	0	0	0	0	0	0	0	0	0	0	1
** Subtotal **			0	0	0	0	0	0	0	0	0	0	0	0	0	1
** <u>322B12</u> **																
SU-12	MP3	BBO	0	0	0	0	0	0	0	0	0	0	0	0	0	1
** Subtotal **			0	0	0	0	0	0	0	0	0	0	0	0	0	1
** <u>330J15</u> **																
SU-12	MP3	BBO	0	0	0	0	0	0	0	0	0	0	0	0	0	1
** Subtotal **			0	0	0	0	0	0	0	0	0	0	0	0	0	1
** <u>335B10</u> **																
BL-01	600	600	2	0	0	0	0	0	0	0	0	0	0	1	0	0
** Subtotal **			2	0	0	0	0	0	0	0	0	0	0	1	0	0
** <u>346E24</u> **																
JU-01	S00	S00	0	0	0	0	0	0	0	0	0	0	3	0	0	0
** Subtotal **			0	0	0	0	0	0	0	0	0	0	3	0	0	0
** <u>353E08</u> **																
SU-12	MP3	BBO	0	0	0	0	0	0	0	0	0	0	0	0	0	1
** Subtotal **			0	0	0	0	0	0	0	0	0	0	0	0	0	1
** <u>353E16</u> **																
JU-01	S00	S00	0	0	0	0	2	0	0	0	0	0	0	0	0	0
SU-01	S00	RMD	0	0	0	0	1	0	0	0	0	0	0	0	0	0
SU-02	S00	CMD	0	0	0	0	1	0	0	0	0	0	0	0	0	0
SU-12	S00	CMD	0	0	0	0	1	0	0	0	0	0	0	0	0	0
SU-12	S00	RMD	0	0	0	0	2	0	0	0	0	0	0	0	0	0
** Subtotal **			0	0	0	0	7	0	0	0	0	0	0	0	0	0
** <u>3E6B05</u> **																
JU-01	S00	S00	0	0	0	1	0	0	0	0	0	0	0	0	0	0
JU-09	600	600	0	0	0	1	0	0	0	0	0	0	0	0	0	0
JU-10	600	600	0	0	0	1	0	0	0	0	0	0	0	0	0	0
PM-01	600	650	0	0	0	1	0	0	0	0	0	0	0	0	0	0
ST-01	600	610	0	0	0	2	0	0	0	0	0	0	0	0	0	0
ST-01	600	620	0	0	0	1	0	0	0	0	0	0	0	0	0	0

USMC MF TBA by Contingency Support Package

CONFIG	DIV	BR	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
SU-12	MP3	LMS	0	0	0	0	0	0	0	0	0	0	0	0	0	1
TR-01	400	400	0	0	0	1	0	0	0	0	0	0	0	0	0	0
** Subtotal **			0	0	0	8	0	0	0	0	0	0	0	0	0	1
** <u>3FEFW</u> **																
BL-01	MP3	LMS	0	0	0	0	0	0	0	0	0	0	0	0	0	2
TW-05A	MP3	LMS	0	0	0	0	0	0	0	0	0	0	0	0	0	1
TW-06B	MP3	LMS	0	0	0	0	0	0	0	0	0	0	0	0	0	1
** Subtotal **			0	0	0	0	0	0	0	0	0	0	0	0	0	4
** <u>3FERW</u> **																
BL-01	MP3	BBO	0	0	0	0	0	0	0	0	0	0	0	0	0	2
TW-05A	MP3	BBO	0	0	0	0	0	0	0	0	0	0	0	0	0	1
TW-06B	MP3	BBO	0	0	0	0	0	0	0	0	0	0	0	0	0	1
** Subtotal **			0	0	0	0	0	0	0	0	0	0	0	0	0	4
** <u>3H53E8</u> **																
SU-12	MP3	PLU	0	0	0	0	0	0	0	0	0	0	0	0	0	1
** Subtotal **			0	0	0	0	0	0	0	0	0	0	0	0	0	1
** <u>3HML27</u> **																
BL-01	600	620	0	0	0	0	0	0	0	0	0	0	1	0	0	0
JU-01	S00	S00	0	0	0	0	0	0	0	0	0	0	3	0	0	0
SU-01	S00	RMD	0	0	0	0	0	0	0	0	0	0	2	0	0	0
SU-02	S00	CMD	0	0	0	0	0	0	0	0	0	0	3	0	0	0
SU-05	S00	SAD	0	0	0	0	0	0	0	0	0	0	1	0	0	0
SU-05	S00	SRD	0	0	0	0	0	0	0	0	0	0	2	0	0	0
SU-12	S00	CMD	0	0	0	0	0	0	0	0	0	0	2	0	0	0
SU-12	S00	RMD	0	0	0	0	0	0	0	0	0	0	2	0	0	0
** Subtotal **			0	0	0	0	0	0	0	0	0	0	16	0	0	0
** <u>3HML9A</u> **																
SU-12	MP3	PLU	0	0	0	0	0	0	0	0	0	0	0	0	0	1
** Subtotal **			0	0	0	0	0	0	0	0	0	0	0	0	0	1
** <u>3HML9B</u> **																
SU-12	MP3	PLU	0	0	0	0	0	0	0	0	0	0	0	0	0	1
** Subtotal **			0	0	0	0	0	0	0	0	0	0	0	0	0	1
** <u>3HML9C</u> **																
SU-12	MP3	BBO	0	0	0	0	0	0	0	0	0	0	0	0	0	1
** Subtotal **			0	0	0	0	0	0	0	0	0	0	0	0	0	1

USMC MF TBA by Contingency Support Package

CONFIG	DIV	BR	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
** <u>3M2212</u> **																
SU-12	MP3	PLU	0	0	0	0	0	0	0	0	0	0	0	0	0	1
** Subtotal **			0	0	0	0	0	0	0	0	0	0	0	0	0	1
** <u>3V2212</u> **																
HY-06C	500	520	0	0	0	0	1	0	0	0	0	0	0	0	1	0
JU-01	S00	S00	0	0	0	0	2	0	0	0	0	0	0	0	0	0
JU-01	500	500	0	0	0	0	1	0	0	0	0	0	0	0	1	0
KA-31	600	650	0	0	0	0	1	0	0	0	0	0	0	0	0	0
RR-04A	800	810	0	0	0	0	1	1	0	0	0	0	0	0	1	0
RR-05B	800	810	0	0	0	0	1	1	0	0	0	0	0	0	1	0
SU-01	S00	RMD	0	0	0	0	1	0	0	0	0	0	0	0	0	0
SU-02	S00	CMD	0	0	0	0	1	0	0	0	0	0	0	0	0	0
SU-12	S00	CMD	0	0	0	0	1	0	0	0	0	0	0	0	0	0
SU-12	S00	RMD	0	0	0	0	2	0	0	0	0	0	0	0	0	0
SU-12	MP3	PLU	0	0	0	0	0	0	0	0	0	0	0	0	0	1
TB-02	500	520	0	0	0	0	1	0	0	0	0	0	0	0	1	0
** Subtotal **			0	0	0	0	13	2	0	0	0	0	0	0	5	1
** <u>3V8B05</u> **																
SU-12	MP3	DHL	0	0	0	0	0	0	0	0	0	0	0	0	0	1
** Subtotal **			0	0	0	0	0	0	0	0	0	0	0	0	0	1
** <u>3V8B09</u> **																
SU-12	MP3	DHL	0	0	0	0	0	0	0	0	0	0	0	0	0	1
** Subtotal **			0	0	0	0	0	0	0	0	0	0	0	0	0	1
** <u>3V8R14</u> **																
JU-01	S00	S00	0	0	2	2	0	0	0	0	0	0	0	0	0	0
SU-02	S00	CMD	0	0	1	1	0	0	0	0	0	0	0	0	0	0
SU-12	S00	RMD	0	0	2	2	0	0	0	0	0	0	0	0	0	0
** Subtotal **			0	0	5	5	0	0	0	0	0	0	0	0	0	0
** <u>435B16</u> **																
BL-01	600	600	0	0	0	2	0	0	0	0	0	0	0	1	0	0
** Subtotal **			0	0	0	2	0	0	0	0	0	0	0	1	0	0
** <u>446E24</u> **																
JU-01	S00	S00	0	0	0	0	0	0	0	0	0	3	0	0	0	0
SU-05	S00	SAD	0	0	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			0	0	0	0	0	0	0	0	0	3	0	0	0	0
** <u>453E16</u> **																
JU-01	S00	S00	0	0	0	0	0	0	0	0	0	2	0	0	0	0

USMC MF TBA by Contingency Support Package

CONFIG	DIV	BR	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
SU-01	S00	RMD	0	0	0	0	0	0	0	0	0	0	0	0	0	0
SU-02	S00	CMD	0	0	0	0	0	0	0	0	0	2	0	0	0	0
SU-12	S00	CMD	0	0	0	0	0	0	0	0	0	1	0	0	0	0
SU-12	S00	RMD	0	0	0	0	0	0	0	0	0	2	0	0	0	0
** Subtotal **			0	0	0	0	0	0	0	0	0	7	0	0	0	0
** <u>4574H</u> **																
BL-01	MPS	BLI	0	0	0	0	0	0	0	0	0	0	0	0	0	1
FS-01	MPS	BLI	0	0	0	0	0	0	0	0	0	0	0	0	0	1
JU-01	MPS	FLY	0	0	0	0	0	0	0	0	0	0	0	0	0	1
SU-12	MPS	BLI	0	0	0	0	0	0	0	0	0	0	0	0	0	1
SU-12	MPS	FLY	0	0	0	0	0	0	0	0	0	0	0	0	0	3
TW-05A	MPS	FLY	0	0	0	0	0	0	0	0	0	0	0	0	0	1
TW-06B	MPS	FLY	0	0	0	0	0	0	0	0	0	0	0	0	0	1
** Subtotal **			0	0	0	0	0	0	0	0	0	0	0	0	0	9
** <u>4HML27</u> **																
BL-01	600	620	0	0	0	0	0	0	0	2	0	0	0	0	0	0
JU-01	S00	S00	0	0	0	0	0	0	0	3	0	3	0	0	0	0
JU-01	600	600	0	0	0	0	0	0	0	1	0	0	0	0	0	0
SU-01	S00	RMD	0	0	0	0	0	0	0	1	0	1	0	0	0	0
SU-02	S00	CMD	0	0	0	0	0	0	0	2	0	3	0	0	0	0
SU-05	S00	SAD	0	0	0	0	0	0	0	1	0	0	0	0	0	0
SU-05	S00	SRD	0	0	0	0	0	0	0	1	0	0	0	0	0	0
SU-12	S00	CMD	0	0	0	0	0	0	0	1	0	2	0	0	0	0
SU-12	S00	RMD	0	0	0	0	0	0	0	1	0	3	0	0	0	0
** Subtotal **			0	0	0	0	0	0	0	13	0	12	0	0	0	0
** <u>535B16</u> **																
BL-01	600	600	0	1	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			0	1	0	0	0	0	0	0	0	0	0	0	0	0
** <u>553E16</u> **																
JU-01	S00	S00	0	0	0	0	2	0	0	0	0	0	0	0	0	0
SU-01	S00	RMD	0	0	0	0	1	0	0	0	0	0	0	0	0	0
SU-02	S00	CMD	0	0	0	0	1	0	0	0	0	0	0	0	0	0
SU-12	S00	CMD	0	0	0	0	1	0	0	0	0	0	0	0	0	0
SU-12	S00	RMD	0	0	0	0	1	0	0	0	0	0	0	0	0	0
** Subtotal **			0	0	0	0	6	0	0	0	0	0	0	0	0	0
** <u>553EXX</u> **																
JU-01	S00	S00	0	0	0	0	2	0	0	0	0	0	0	0	0	0
SU-01	S00	RMD	0	0	0	0	1	0	0	0	0	0	0	0	0	0
SU-02	S00	CMD	0	0	0	0	1	0	0	0	0	0	0	0	0	0
SU-12	S00	CMD	0	0	0	0	1	0	0	0	0	0	0	0	0	0

USMC MF TBA by Contingency Support Package

CONFIG	DIV	BR	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
SU-12	S00	RMD	0	0	0	0	1	0	0	0	0	0	0	0	0	0
** Subtotal **			0	0	0	0	6	0	0	0	0	0	0	0	0	0
** <u>5HML27</u> **																
JU-01	S00	S00	0	0	0	0	0	0	0	0	0	0	3	0	0	0
SU-02	S00	CMD	0	0	0	0	0	0	0	0	0	0	3	0	0	0
SU-05	S00	SAD	0	0	0	0	0	0	0	0	0	0	1	0	0	0
SU-12	S00	CMD	0	0	0	0	0	0	0	0	0	0	2	0	0	0
SU-12	S00	RMD	0	0	0	0	0	0	0	0	0	0	2	0	0	0
** Subtotal **			0	0	0	0	0	0	0	0	0	0	11	0	0	0
** <u>BEAFFW</u> **																
EA-01	ZZC	EAF	1	1	1	2	0	0	0	0	1	0	0	0	0	0
EA-02	ZZC	EAF	0	0	0	2	0	0	0	0	0	0	0	0	0	0
JU-01	ZZC	EAF	0	0	0	0	0	0	0	0	0	0	0	0	0	0
SU-03	ZZC	EAF	0	0	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			1	1	1	4	0	0	0	0	1	0	0	0	0	0
** <u>BEAFRW</u> **																
EA-01	ZZC	EAF	0	0	0	0	1	0	1	1	0	1	1	0	0	0
EA-02	ZZC	EAF	0	0	0	0	2	0	0	0	0	2	0	0	0	0
JU-01	ZZC	EAF	0	0	0	0	0	0	0	0	0	0	0	0	0	0
SU-03	ZZC	EAF	0	0	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			0	0	0	0	3	0	1	1	0	3	1	0	0	0
** <u>CCSPFW</u> **																
AM-01	000	05C	1	1	1	1	0	0	0	0	1	0	0	1	0	0
AV-01A	600	600	2	0	2	0	0	0	0	0	2	0	0	0	0	0
AV-02B	600	600	2	0	2	0	0	0	0	0	2	0	0	0	0	0
BL-01	900	940	1	1	1	1	0	0	0	0	1	0	0	0	0	0
BL-01	600	620	1	1	1	1	0	0	0	0	1	0	0	1	0	0
BR-04A	700	71D	1	1	0	1	0	0	0	0	0	0	0	1	0	0
BR-05B	700	71D	1	1	0	1	0	0	0	0	0	0	0	1	0	0
CA-01	AIS	AIS	2	2	2	2	0	0	0	0	2	0	0	2	0	0
CA-01	600	670	2	2	0	2	0	0	0	0	0	0	0	0	0	0
CA-04	600	670	1	1	1	1	0	0	0	0	1	0	0	1	0	0
CL-01	600	670	2	2	2	2	0	0	0	0	2	0	0	2	0	0
CL-02	600	670	1	1	1	1	0	0	0	0	1	0	0	1	0	0
CL-04	600	610	2	2	2	2	0	0	0	0	2	0	0	2	0	0
CL-04	600	670	2	2	2	2	0	0	0	0	2	0	0	2	0	0
CL-06	600	670	1	1	1	1	0	0	0	0	1	0	0	1	0	0
CL-07	600	670	4	4	3	4	0	0	0	0	3	0	0	3	0	0
CL-09	600	670	2	2	2	2	0	0	0	0	2	0	0	2	0	0
CL-10	600	670	2	2	2	2	0	0	0	0	2	0	0	2	0	0
CR-04	600	690	2	2	2	2	0	0	0	0	2	0	0	2	0	0
CS-02A	500	510	1	1	1	1	0	0	0	0	1	0	0	1	0	0

14 MAR 2016

USMC MF TBA by Contingency Support Package

CONFIG	DIV	BR	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
CS-03BM	500	510	1	1	1	1	0	0	0	0	1	0	0	1	0	0
CU-01	800	800	1	1	1	1	0	0	0	0	1	0	0	1	0	0
CU-01	700	700	1	1	0	1	0	0	0	0	0	0	0	1	0	0
CU-01	700	730	1	1	0	1	0	0	0	0	0	0	0	1	0	0
CU-01	600	600	2	3	3	3	0	0	0	0	2	0	0	3	0	0
CU-01	500	500	1	1	1	1	0	0	0	0	1	0	0	1	0	0
CU-01	400	400	1	1	1	1	0	0	0	0	0	0	0	0	0	0
CU-01	000	010	2	2	2	2	0	0	0	0	1	0	0	2	0	0
CU-01	000	020	1	1	1	1	0	0	0	0	1	0	0	1	0	0
CY-01	600	610	1	1	1	1	0	0	0	0	1	0	0	1	0	0
DP-03	AIS	AIS	1	1	1	1	0	0	0	0	1	0	0	1	0	0
DP-18A	AIS	AIS	1	1	1	1	0	0	0	0	1	0	0	1	0	0
FC-05	700	730	1	1	0	1	0	0	0	0	0	0	0	1	0	0
FS-01	700	700	1	1	0	1	0	0	0	0	0	0	0	1	0	0
FS-01	600	600	1	1	1	1	0	0	0	0	1	0	0	1	0	0
FS-01	500	500	1	1	1	1	0	0	0	0	1	0	0	1	0	0
FS-01	400	400	1	1	1	1	0	0	0	0	1	0	0	0	0	0
HC-01	500	520	1	1	1	1	0	0	0	0	1	0	0	1	1	0
HC-02	500	520	1	1	1	1	0	0	0	0	1	0	0	1	1	0
HY-04A	500	520	1	1	1	1	0	0	0	0	1	0	0	1	0	0
HY-05B	500	520	1	1	1	1	0	0	0	0	1	0	0	1	0	0
JU-01	S00	S00	1	1	1	1	0	0	0	0	1	0	0	1	0	0
JU-01	AIS	AIS	1	1	1	1	0	0	0	0	1	0	0	1	0	0
JU-01	900	900	1	1	1	1	0	0	0	0	1	0	0	1	0	0
JU-01	800	800	1	1	1	1	0	0	0	0	1	0	0	1	0	0
JU-01	700	700	2	2	0	2	0	0	0	0	0	0	0	2	0	0
JU-01	600	600	12	11	12	11	0	0	0	0	12	0	0	10	0	0
JU-01	500	500	5	5	5	5	0	0	0	0	5	0	0	5	1	0
JU-01	000	000	3	3	3	3	0	0	0	0	3	0	0	3	0	0
KA-18A	600	600	7	7	7	7	0	0	0	0	9	0	0	2	0	0
KA-19A	600	650	2	2	2	2	0	0	0	0	2	0	0	1	0	0
KA-20B	600	650	2	2	2	2	0	0	0	0	2	0	0	1	0	0
KA-31	600	650	3	3	7	3	0	0	0	0	3	0	0	3	0	0
MC-01	700	700	1	1	0	1	0	0	0	0	0	0	0	1	0	0
MC-01	600	600	1	1	1	1	0	0	0	0	1	0	0	1	0	0
MC-01	600	670	1	1	1	1	0	0	0	0	1	0	0	1	0	0
MC-01	000	020	2	2	2	2	0	0	0	0	2	0	0	2	0	0
MM-01	500	510	1	1	1	1	0	0	0	0	1	0	0	1	0	0
MM-02	500	510	1	1	1	1	0	0	0	0	1	0	0	1	1	0
MM-03	500	510	1	1	1	1	0	0	0	0	1	0	0	1	0	0
MM-04	500	510	1	1	1	1	0	0	0	0	1	0	0	1	0	0
NT-06	500	530	1	1	1	1	0	0	0	0	1	0	0	1	0	0
NT-07	500	530	1	1	1	1	0	0	0	0	1	0	0	1	0	0
NT-08	500	530	1	1	1	1	0	0	0	0	1	0	0	1	0	0
PW-01	500	500	1	1	1	1	0	0	0	0	1	0	0	1	0	0
RR-02	800	810	1	1	1	1	0	0	0	0	1	0	0	1	0	0
RR-03	800	810	1	1	1	1	0	0	0	0	1	0	0	1	0	0
SE-01	800	810	1	1	1	1	0	0	0	0	1	0	0	1	0	0

14 MAR 2016

USMC MF TBA by Contingency Support Package

CONFIG	DIV	BR	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
SM-04B	500	510	1	1	1	1	0	0	0	0	1	0	0	1	0	0
SM-05A	500	510	1	1	1	1	0	0	0	0	1	0	0	1	0	0
SM-06B	500	510	1	1	1	1	0	0	0	0	1	0	0	1	0	0
SM-07A	500	510	1	1	1	1	0	0	0	0	1	0	0	1	0	0
ST-01	600	610	3	1	1	1	0	0	0	0	1	0	0	1	0	0
ST-01	600	620	3	2	2	2	0	0	0	0	2	0	0	2	0	0
ST-01	600	650	1	1	1	1	0	0	0	0	1	0	0	1	0	0
ST-01	600	690	1	1	1	1	0	0	0	0	1	0	0	1	0	0
ST-01	500	520	2	2	2	2	0	0	0	0	2	0	0	2	0	0
SU-01	S00	RMD	1	2	1	1	0	0	0	0	1	0	0	0	0	0
SU-01	600	600	4	4	4	4	0	0	0	0	4	0	0	3	0	0
SU-01	000	05C	1	1	1	1	0	0	0	0	1	0	0	1	0	0
SU-01	000	05D	1	1	1	1	0	0	0	0	1	0	0	1	0	0
SU-02	S00	CMD	1	1	1	1	0	0	0	0	1	0	0	1	0	0
SU-03	AIS	AIS	1	1	1	1	0	0	0	0	1	0	0	1	0	0
SU-03	700	700	1	1	0	1	0	0	0	0	0	0	0	1	0	0
SU-03	600	600	1	0	1	1	0	0	0	0	0	0	0	1	0	0
SU-03	600	60C	1	1	1	1	0	0	0	0	0	0	0	0	0	0
SU-05	600	600	2	0	2	0	0	0	0	0	2	0	0	0	0	0
SU-05	600	60C	1	1	1	1	0	0	0	0	1	0	0	1	0	0
SU-08	000	05A	1	1	1	1	0	0	0	0	1	0	0	1	0	0
SU-12	S00	CMD	1	1	1	1	0	0	0	0	1	0	0	0	0	0
SU-12	S00	RMD	1	1	1	1	0	0	0	0	1	0	0	0	0	0
SU-12	000	05A	1	1	1	1	0	0	0	0	1	0	0	1	0	0
TB-03A	500	520	2	1	1	2	0	0	0	0	1	0	0	1	0	0
TB-04B	500	520	2	1	1	2	0	0	0	0	1	0	0	1	0	0
TL-01	600	670	1	1	1	1	0	0	0	0	1	0	0	1	0	0
TL-01	000	040	1	1	1	1	0	0	0	0	1	0	0	1	0	0
TR-01	600	600	1	1	1	1	0	0	0	0	1	0	0	1	0	0
TR-01	500	500	1	1	1	1	0	0	0	0	1	0	0	1	0	0
TR-01	000	05D	1	1	1	1	0	0	0	0	1	0	0	1	0	0
TW-05A	500	510	1	1	1	1	0	0	0	0	1	0	0	1	0	0
TW-06B	500	510	1	1	1	1	0	0	0	0	1	0	0	1	0	0
VD-07A	600	620	1	1	1	1	0	0	0	0	1	0	0	1	0	0
VD-08B	600	620	1	1	1	1	0	0	0	0	1	0	0	1	0	0
WC-02	000	030	2	2	2	2	0	0	0	0	2	0	0	2	0	0
WC-02	000	040	2	2	2	2	0	0	0	0	2	0	0	2	0	0
WC-08	900	910	1	1	1	1	0	0	0	0	1	0	0	1	0	0
WC-08	900	930	1	1	1	1	0	0	0	0	1	0	0	1	0	0
WC-08	900	940	1	1	1	1	0	0	0	0	1	0	0	1	0	0
WC-12A	600	60C	1	1	1	1	0	0	0	0	1	0	0	1	0	0
WC-13BM	600	60C	1	1	1	1	0	0	0	0	1	0	0	1	0	0
WL-04A	500	510	1	1	1	1	0	0	0	0	1	0	0	1	0	0
WL-05A	500	510	1	1	1	1	0	0	0	0	1	0	0	1	0	0
WR-01	600	690	1	1	1	1	0	0	0	0	1	0	0	0	0	0
** Subtotal **			170	159	157	161	0	0	0	0	150	0	0	139	4	0

14 MAR 2016

USMC MF TBA by Contingency Support Package

CONFIG	DIV	BR	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
** CCSPRW **																
AM-01	000	05C	0	0	0	0	1	1	1	1	0	0	1	0	1	0
AV-01A	600	600	0	0	0	0	2	2	2	2	0	0	2	0	0	0
AV-02B	600	600	0	0	0	0	2	2	2	2	0	0	2	0	0	0
BL-01	900	940	0	0	0	0	1	1	1	1	0	1	1	0	0	0
BL-01	600	620	0	0	0	0	1	1	1	1	0	1	1	0	1	0
BR-04A	700	71D	0	0	0	0	1	1	1	0	0	1	0	0	1	0
BR-05B	700	71D	0	0	0	0	1	1	1	0	0	1	0	0	1	0
CA-01	AIS	AIS	0	0	0	0	2	2	2	2	0	2	2	0	2	0
CA-04	600	670	0	0	0	0	1	1	1	1	0	1	1	0	1	0
CA-07A	600	670	0	0	0	0	0	0	1	0	0	1	1	0	0	0
CA-08B	600	670	0	0	0	0	0	0	1	0	0	1	1	0	0	0
CA-09	600	670	0	0	0	0	0	1	1	0	0	0	1	0	0	0
CL-01	600	670	0	0	0	0	2	2	2	2	0	2	2	0	2	0
CL-02	600	670	0	0	0	0	1	1	1	1	0	1	1	0	1	0
CL-04	600	610	0	0	0	0	2	2	2	2	0	2	2	0	2	0
CL-04	600	670	0	0	0	0	2	2	2	2	0	2	2	0	2	0
CL-06	600	670	0	0	0	0	1	1	1	1	0	1	1	0	1	0
CL-07	600	670	0	0	0	0	3	3	4	3	0	4	4	0	3	0
CL-09	600	670	0	0	0	0	1	1	1	1	0	1	1	0	1	0
CL-10	600	670	0	0	0	0	2	2	2	2	0	2	2	0	2	0
CR-04	600	690	0	0	0	0	2	2	2	2	0	2	2	0	2	0
CS-02A	500	510	0	0	0	0	1	1	1	1	0	1	1	0	1	0
CS-03BM	500	510	0	0	0	0	1	1	1	1	0	1	1	0	1	0
CU-01	800	800	0	0	0	0	1	1	1	1	0	1	1	0	1	0
CU-01	700	700	0	0	0	0	1	1	1	0	0	1	0	0	1	0
CU-01	700	730	0	0	0	0	1	1	1	0	0	1	0	0	1	0
CU-01	600	600	0	0	0	0	3	2	3	2	0	3	3	0	3	0
CU-01	500	500	0	0	0	0	1	1	1	1	0	1	1	0	1	0
CU-01	400	400	0	0	0	0	1	1	1	1	0	1	1	0	1	0
CU-01	000	010	0	0	0	0	2	2	2	2	0	2	2	0	2	0
CU-01	000	020	0	0	0	0	1	1	1	1	0	1	1	0	1	0
CU-01	000	040	0	0	0	0	1	1	1	1	0	1	1	0	1	0
CY-01	600	610	0	0	0	0	1	1	1	1	0	1	1	0	1	0
DP-03	AIS	AIS	0	0	0	0	1	1	1	1	0	1	1	0	1	0
DP-18A	AIS	AIS	0	0	0	0	1	1	1	1	0	1	1	0	1	0
FC-05	700	730	0	0	0	0	1	1	1	0	0	0	0	0	1	0
FS-01	700	700	0	0	0	0	1	1	1	0	0	1	0	0	1	0
FS-01	600	600	0	0	0	0	1	1	1	1	0	1	1	0	1	0
FS-01	500	500	0	0	0	0	1	1	1	1	0	1	1	0	1	0
FS-01	400	400	0	0	0	0	1	0	1	1	0	1	1	0	1	0
GM-02A	700	71B	0	0	0	0	1	1	1	0	0	1	0	0	1	0
GM-03B	700	71B	0	0	0	0	1	1	1	0	0	1	0	0	1	0
HC-01	500	520	0	0	0	0	1	1	1	1	0	1	1	0	0	0
HC-02	500	520	0	0	0	0	1	1	1	1	0	1	1	0	0	0
HY-04A	500	520	0	0	0	0	1	1	1	1	0	1	1	0	1	0
HY-05B	500	520	0	0	0	0	1	1	1	1	0	1	1	0	1	0

14 MAR 2016

USMC MF TBA by Contingency Support Package

CONFIG	DIV	BR	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
JU-01	S00	S00	0	0	0	0	1	1	1	1	0	1	1	0	1	0
JU-01	AIS	AIS	0	0	0	0	1	1	1	1	0	1	1	0	1	0
JU-01	900	900	0	0	0	0	1	1	1	1	0	1	1	0	1	0
JU-01	800	800	0	0	0	0	1	1	1	1	0	1	1	0	1	0
JU-01	700	700	0	0	0	0	2	2	2	0	0	2	0	0	1	0
JU-01	600	600	0	0	0	0	11	10	11	11	0	11	12	0	9	0
JU-01	500	500	0	0	0	0	5	5	4	5	0	5	5	0	5	0
JU-01	400	400	0	0	0	0	2	1	2	2	0	2	2	0	2	0
JU-01	000	000	0	0	0	0	3	2	3	3	0	3	3	0	3	0
KA-18A	600	600	0	0	0	0	4	3	4	4	0	3	4	0	2	0
KA-31	600	650	0	0	0	0	3	3	3	3	0	3	3	0	3	0
MC-01	700	700	0	0	0	0	1	1	1	0	0	0	0	0	1	0
MC-01	600	600	0	0	0	0	1	0	1	1	0	0	1	0	1	0
MC-01	600	670	0	0	0	0	1	1	1	1	0	0	1	0	1	0
MC-01	000	020	0	0	0	0	2	1	2	2	0	0	2	0	2	0
MM-01	500	510	0	0	0	0	1	1	1	1	0	0	1	0	1	0
MM-02	500	510	0	0	0	0	1	1	1	1	0	0	1	0	0	0
MM-03	500	510	0	0	0	0	1	1	1	1	0	0	1	0	1	0
MM-04	500	510	0	0	0	0	1	1	1	1	0	0	1	0	1	0
NT-06	500	530	0	0	0	0	1	1	1	1	0	0	1	0	1	0
NT-07	500	530	0	0	0	0	1	1	1	1	0	0	1	0	1	0
NT-08	500	530	0	0	0	0	1	1	1	1	0	0	1	0	1	0
PP-01	400	410	0	0	0	0	1	1	1	1	0	0	1	0	1	0
PP-03A	400	440	0	0	0	0	1	1	1	1	0	0	1	0	1	0
PP-04BM	400	440	0	0	0	0	1	1	1	1	0	0	1	0	1	0
PW-01	500	500	0	0	0	0	1	1	1	1	0	1	1	0	1	0
SE-01	800	810	0	0	0	0	1	0	1	1	0	1	1	0	1	0
SE-02B	800	810	0	0	0	0	1	1	1	1	0	1	1	0	1	0
SE-03C	800	810	0	0	0	0	1	1	1	1	0	1	1	0	1	0
SE-04B	800	810	0	0	0	0	1	1	1	1	0	1	1	0	1	0
SH-06	600	650	0	0	0	0	2	2	0	2	0	2	2	0	1	0
SM-04B	500	510	0	0	0	0	1	1	1	1	0	0	1	0	1	0
SM-05A	500	510	0	0	0	0	1	1	1	1	0	0	1	0	1	0
SM-06B	500	510	0	0	0	0	1	1	1	1	0	0	1	0	1	0
SM-07A	500	510	0	0	0	0	1	1	1	1	0	0	1	0	1	0
ST-01	600	610	0	0	0	0	3	3	2	3	0	3	3	0	3	0
ST-01	600	620	0	0	0	0	3	2	2	2	0	2	3	0	2	0
ST-01	600	650	0	0	0	0	1	1	1	1	0	1	1	0	2	0
ST-01	600	690	0	0	0	0	3	1	1	1	0	1	3	0	1	0
ST-01	500	520	0	0	0	0	0	0	0	0	0	0	0	0	5	0
SU-01	S00	RMD	0	0	0	0	1	1	1	1	0	1	1	0	1	0
SU-01	600	600	0	0	0	0	4	4	3	3	0	4	4	0	4	0
SU-01	600	650	0	0	0	0	1	1	1	1	0	1	1	0	1	0
SU-01	000	05C	0	0	0	0	1	1	1	1	0	1	1	0	1	0
SU-01	000	05D	0	0	0	0	1	0	1	1	0	1	1	0	1	0
SU-02	S00	CMD	0	0	0	0	1	1	1	1	0	1	1	0	1	0
SU-03	AIS	AIS	0	0	0	0	1	0	1	1	0	1	1	0	1	0

USMC MF TBA by Contingency Support Package

CONFIG	DIV	BR	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
SU-03	700	700	0	0	0	0	1	1	1	0	0	1	0	0	1	0
SU-03	600	600	0	0	0	0	1	0	0	1	0	1	0	0	0	0
SU-03	600	60C	0	0	0	0	1	0	0	0	0	0	1	0	0	0
SU-03	400	410	0	0	0	0	1	0	1	1	0	1	1	0	1	0
SU-05	600	600	0	0	0	0	2	2	2	2	0	0	2	0	0	0
SU-05	600	60C	0	0	0	0	1	1	1	0	0	0	1	0	1	0
SU-08	000	05A	0	0	0	0	1	1	1	1	0	1	1	0	1	0
SU-12	S00	CMD	0	0	0	0	1	1	1	1	0	1	1	0	3	0
SU-12	S00	RMD	0	0	0	0	1	1	1	1	0	1	1	0	3	0
SU-12	400	440	0	0	0	0	1	0	1	1	0	1	1	0	1	0
SU-12	000	05A	0	0	0	0	1	0	1	1	0	1	1	0	1	0
TB-01	500	520	0	0	0	0	1	1	0	2	0	1	0	0	0	0
TL-01	600	670	0	0	0	0	1	1	1	1	0	0	1	0	1	0
TL-01	000	040	0	0	0	0	1	1	1	1	0	0	1	0	1	0
TR-01	600	600	0	0	0	0	1	1	1	1	0	1	1	0	1	0
TR-01	500	500	0	0	0	0	1	1	1	1	0	1	1	0	1	0
TR-01	400	440	0	0	0	0	1	1	1	1	0	1	1	0	1	0
TR-01	000	05D	0	0	0	0	1	1	1	1	0	1	1	0	1	0
TW-05A	500	510	0	0	0	0	1	1	1	1	0	0	1	0	1	0
TW-06B	500	510	0	0	0	0	1	1	1	1	0	0	1	0	1	0
VD-05A	600	620	0	0	0	0	0	0	1	1	0	1	1	0	0	0
VD-06B	600	620	0	0	0	0	0	0	1	1	0	1	1	0	0	0
VD-07A	600	620	0	0	0	0	0	1	0	0	0	0	0	0	0	0
VD-08B	600	620	0	0	0	0	0	1	0	0	0	0	0	0	0	0
WC-02	000	030	0	0	0	0	2	0	2	2	0	0	2	0	2	0
WC-02	000	040	0	0	0	0	2	1	1	2	0	0	2	0	2	0
WC-08	900	910	0	0	0	0	1	1	1	1	0	0	1	0	1	0
WC-08	900	930	0	0	0	0	1	1	1	1	0	0	1	0	1	0
WC-08	900	940	0	0	0	0	1	1	1	1	0	0	1	0	1	0
WC-12A	600	60C	0	0	0	0	1	1	1	1	0	1	1	0	1	0
WC-13BM	600	60C	0	0	0	0	1	1	1	1	0	1	1	0	1	0
WL-04A	500	510	0	0	0	0	1	1	1	1	0	0	1	0	1	0
WL-05A	500	510	0	0	0	0	1	1	1	1	0	0	1	0	1	0
WR-01	600	690	0	0	0	0	1	1	1	1	0	1	1	0	0	0
** Subtotal **			0	0	0	0	169	150	163	153	0	128	162	0	156	0
** EAF **																
EA-01	MP3	WLM	0	0	0	0	0	0	0	0	0	0	0	0	0	1
EA-01	MP2	SKM	0	0	0	0	0	0	0	0	0	0	0	0	0	1
** Subtotal **			0	0	0	0	0	0	0	0	0	0	0	0	0	2
** F15316 **																
FS-01	S00	CMD	0	0	0	0	0	1	0	1	0	0	0	0	0	0
JU-01	S00	S00	0	0	0	0	0	1	0	1	0	0	0	0	0	0
SU-01	S00	RMD	0	0	0	0	0	1	0	1	0	0	0	0	0	0
SU-12	S00	CMD	0	0	0	0	0	1	0	1	0	0	0	0	0	0
SU-12	S00	RMD	0	0	0	0	0	1	0	1	0	0	0	0	0	0

USMC MF TBA by Contingency Support Package

CONFIG	DIV	BR	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
** Subtotal **			0	0	0	0	0	5	0	5	0	0	0	0	0	0
** <u>F18A36</u> **																
FS-01	S00	CMD	1	0	0	0	0	0	0	0	0	0	0	0	0	0
JU-01	S00	S00	2	0	0	0	0	0	0	0	0	0	0	0	0	0
SU-12	S00	RMD	1	0	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			4	0	0	0	0	0	0	0	0	0	0	0	0	0
** <u>F18C24</u> **																
FS-01	S00	CMD	1	0	0	0	0	0	0	0	0	0	0	0	0	0
JU-01	S00	S00	2	0	0	0	0	0	0	0	0	0	0	0	0	0
SU-12	S00	RMD	2	0	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			5	0	0	0	0	0	0	0	0	0	0	0	0	0
** <u>F18R14</u> **																
ED-01	S00	CMD	0	1	1	1	0	0	0	0	0	0	0	0	0	0
FS-01	S00	CMD	0	1	1	1	0	0	0	0	0	0	0	0	0	0
JU-01	S00	S00	0	1	1	1	0	0	0	0	0	0	0	0	0	0
SU-01	S00	RMD	0	1	1	1	0	0	0	0	0	0	0	0	0	0
SU-12	S00	CMD	0	1	1	1	0	0	0	0	0	0	0	0	0	0
SU-12	S00	RMD	0	1	1	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			0	6	6	5	0	0	0	0	0	0	0	0	0	0
** <u>F1E605</u> **																
FS-01	S00	CMD	0	1	0	1	0	0	0	0	0	0	0	0	0	0
JU-01	S00	S00	0	1	0	1	0	0	0	0	0	0	0	0	0	0
SU-02	S00	CMD	0	1	0	1	0	0	0	0	0	0	0	0	0	0
SU-12	S00	RMD	0	1	0	1	0	0	0	0	0	0	0	0	0	0
** Subtotal **			0	4	0	4	0	0	0	0	0	0	0	0	0	0
** <u>F1H127</u> **																
ED-01	S00	CMD	0	0	0	0	0	2	0	2	0	0	0	0	0	0
FS-01	S00	CMD	0	0	0	0	0	1	0	1	0	0	0	0	0	0
JU-01	S00	S00	0	0	0	0	0	2	0	2	0	0	0	0	0	0
SU-01	S00	RMD	0	0	0	0	0	2	0	1	0	0	0	0	0	0
SU-12	S00	CMD	0	0	0	0	0	1	0	1	0	0	0	0	0	0
SU-12	S00	RMD	0	0	0	0	0	2	0	1	0	0	0	0	0	0
** Subtotal **			0	0	0	0	0	10	0	8	0	0	0	0	0	0
** <u>F1V224</u> **																
ED-01	S00	CMD	0	0	0	0	0	2	2	0	0	0	0	0	0	0
FS-01	S00	CMD	0	0	0	0	0	1	1	0	0	0	0	0	0	0
JU-01	S00	S00	0	0	0	0	0	2	2	0	0	0	0	0	0	0
SU-01	S00	RMD	0	0	0	0	0	2	1	0	0	0	0	0	0	0
SU-12	S00	CMD	0	0	0	0	0	1	1	0	0	0	0	0	0	0

USMC MF TBA by Contingency Support Package

CONFIG	DIV	BR	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
SU-12	S00	RMD	0	0	0	0	0	2	1	0	0	0	0	0	0	0
** Subtotal **			0	0	0	0	0	10	8	0	0	0	0	0	0	0
** <u>F25316</u> **																
FS-01	S00	CMD	0	0	0	0	0	0	0	1	0	0	0	0	0	0
JU-01	S00	S00	0	0	0	0	0	0	0	1	0	0	0	0	0	0
SU-01	S00	RMD	0	0	0	0	0	0	0	1	0	0	0	0	0	0
SU-12	S00	CMD	0	0	0	0	0	0	0	1	0	0	0	0	0	0
SU-12	S00	RMD	0	0	0	0	0	0	0	1	0	0	0	0	0	0
** Subtotal **			0	0	0	0	0	0	0	5	0	0	0	0	0	0
** <u>F28A36</u> **																
ED-01	S00	CMD	0	1	0	0	0	0	0	0	0	0	0	0	0	0
FS-01	S00	CMD	0	1	0	0	0	0	0	0	0	0	0	0	0	0
JU-01	S00	S00	0	2	0	0	0	0	0	0	0	0	0	0	0	0
SU-12	S00	RMD	0	1	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			0	5	0	0	0	0	0	0	0	0	0	0	0	0
** <u>F28R14</u> **																
ED-01	S00	CMD	0	0	1	1	0	0	0	0	0	0	0	0	0	0
FS-01	S00	CMD	0	0	1	1	0	0	0	0	0	0	0	0	0	0
JU-01	S00	S00	0	0	1	1	0	0	0	0	0	0	0	0	0	0
** Subtotal **			0	0	3	3	0	0	0	0	0	0	0	0	0	0
** <u>F2E605</u> **																
FS-01	S00	CMD	0	0	0	1	0	0	0	0	0	0	0	0	0	0
JU-01	000	000	0	0	0	1	0	0	0	0	0	0	0	0	0	0
SU-02	S00	CMD	0	0	0	1	0	0	0	0	0	0	0	0	0	0
** Subtotal **			0	0	0	3	0	0	0	0	0	0	0	0	0	0
** <u>F2H127</u> **																
ED-01	S00	CMD	0	0	0	0	0	0	0	0	0	0	2	0	0	0
FS-01	S00	CMD	0	0	0	0	0	0	0	0	0	0	1	0	0	0
JU-01	S00	S00	0	0	0	0	0	0	0	0	0	0	2	0	0	0
SU-01	S00	RMD	0	0	0	0	0	0	0	0	0	0	3	0	0	0
SU-12	S00	CMD	0	0	0	0	0	0	0	0	0	0	1	0	0	0
SU-12	S00	RMD	0	0	0	0	0	0	0	0	0	0	2	0	0	0
** Subtotal **			0	0	0	0	0	0	0	0	0	0	11	0	0	0
** <u>F2V224</u> **																
ED-01	S00	CMD	0	0	0	0	0	0	2	0	0	0	0	0	0	0
FS-01	S00	CMD	0	0	0	0	1	0	1	0	0	0	0	0	0	0
JU-01	S00	S00	0	0	0	0	0	0	2	0	0	0	0	0	0	0
SU-01	S00	RMD	0	0	0	0	0	0	1	0	0	0	0	0	0	0
SU-12	S00	CMD	0	0	0	0	0	0	1	0	0	0	0	0	0	0

USMC MF TBA by Contingency Support Package

CONFIG	DIV	BR	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
SU-12	S00	RMD	0	0	0	0	0	0	1	0	0	0	0	0	0	0
** Subtotal **			0	0	0	0	1	0	8	0	0	0	0	0	0	0
** F30J12 **																
ED-01	S00	CMD	1	0	0	1	0	0	0	0	0	1	0	0	0	0
FS-01	S00	CMD	1	0	0	1	0	0	0	0	0	0	0	0	0	0
JU-01	S00	S00	1	0	0	1	0	0	0	0	0	1	0	0	0	0
SU-01	S00	RMD	1	0	0	1	0	0	0	0	0	1	0	0	0	0
SU-12	S00	CMD	1	0	0	1	0	0	0	0	0	1	0	0	0	0
SU-12	S00	RMD	1	0	0	1	0	0	0	0	0	1	0	0	0	0
** Subtotal **			6	0	0	6	0	0	0	0	0	5	0	0	0	0
** F34624 **																
JU-01	S00	S00	0	0	0	0	0	0	0	0	0	0	2	0	0	0
** Subtotal **			0	0	0	0	0	0	0	0	0	0	2	0	0	0
** F35316 **																
ED-01	S00	CMD	0	0	0	0	0	0	0	0	0	1	0	0	0	0
FS-01	S00	CMD	0	0	0	0	0	0	0	0	0	1	0	0	0	0
JU-01	S00	S00	0	0	0	0	0	0	0	0	0	1	0	0	0	0
SU-01	S00	RMD	0	0	0	0	0	0	0	0	0	1	0	0	0	0
SU-12	S00	CMD	0	0	0	0	0	0	0	0	0	1	0	0	0	0
SU-12	S00	RMD	0	0	0	0	0	0	0	0	0	1	0	0	0	0
** Subtotal **			0	0	0	0	0	0	0	0	0	6	0	0	0	0
** F38A36 **																
ED-01	S00	CMD	0	0	0	0	0	0	0	0	2	0	0	0	0	0
FS-01	S00	CMD	0	0	0	0	0	0	0	0	1	0	0	0	0	0
JU-01	S00	S00	0	0	0	0	0	0	0	0	2	0	0	0	0	0
SU-01	S00	RMD	0	0	0	0	0	0	0	0	1	0	0	0	0	0
SU-12	S00	CMD	0	0	0	0	0	0	0	0	1	0	0	0	0	0
SU-12	S00	RMD	0	0	0	0	0	0	0	0	1	0	0	0	0	0
** Subtotal **			0	0	0	0	0	0	0	0	8	0	0	0	0	0
** F38C24 **																
ED-01	S00	CMD	0	0	0	0	0	0	0	0	1	0	0	0	0	0
JU-01	S00	S00	0	0	0	0	0	0	0	0	2	0	0	0	0	0
SU-01	S00	RMD	0	0	0	0	0	0	0	0	1	0	0	0	0	0
SU-12	S00	CMD	0	0	0	0	0	0	0	0	1	0	0	0	0	0
SU-12	S00	RMD	0	0	0	0	0	0	0	0	1	0	0	0	0	0
** Subtotal **			0	0	0	0	0	0	0	0	6	0	0	0	0	0
** F3E605 **																
FS-01	S00	CMD	0	0	0	1	0	0	0	0	0	0	0	0	0	0
JU-01	S00	S00	0	0	0	1	0	0	0	0	0	0	0	0	0	0

USMC MF TBA by Contingency Support Package

CONFIG	DIV	BR	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
** Subtotal **			0	0	0	2	0	0	0	0	0	0	0	0	0	0
** <u>F3H127</u> **																
ED-01	S00	CMD	0	0	0	0	0	0	0	0	0	2	0	0	0	0
FS-01	S00	CMD	0	0	0	0	0	0	0	0	0	1	0	0	0	0
JU-01	S00	S00	0	0	0	0	0	0	0	0	0	2	0	0	0	0
SU-01	S00	RMD	0	0	0	0	0	0	0	0	0	1	0	0	0	0
SU-12	S00	CMD	0	0	0	0	0	0	0	0	0	1	0	0	0	0
SU-12	S00	RMD	0	0	0	0	0	0	0	0	0	2	0	0	0	0
** Subtotal **			0	0	0	0	0	0	0	0	0	9	0	0	0	0
** <u>F3V224</u> **																
ED-01	S00	CMD	0	0	0	0	2	0	0	0	0	0	0	0	0	0
FS-01	S00	CMD	0	0	0	0	1	0	0	0	0	1	1	0	0	0
JU-01	S00	S00	0	0	0	0	2	0	0	0	0	0	0	0	0	0
SU-01	S00	RMD	0	0	0	0	1	0	0	0	0	0	0	0	0	0
SU-12	S00	CMD	0	0	0	0	1	0	0	0	0	0	0	0	0	0
SU-12	S00	RMD	0	0	0	0	1	0	0	0	0	0	0	0	0	0
** Subtotal **			0	0	0	0	8	0	0	0	0	1	1	0	0	0
** <u>F44624</u> **																
JU-01	S00	S00	0	0	0	0	0	0	0	0	0	2	0	0	0	0
** Subtotal **			0	0	0	0	0	0	0	0	0	2	0	0	0	0
** <u>F45316</u> **																
ED-01	S00	CMD	0	0	0	0	1	0	0	0	0	0	0	0	0	0
FS-01	S00	CMD	0	0	0	0	1	0	0	0	0	0	0	0	0	0
JU-01	S00	S00	0	0	0	0	1	0	0	0	0	0	0	0	0	0
SU-12	S00	CMD	0	0	0	0	1	0	0	0	0	0	0	0	0	0
** Subtotal **			0	0	0	0	4	0	0	0	0	0	0	0	0	0
** <u>F46FSP</u> **																
JU-01	S00	S00	0	0	0	0	0	0	0	0	0	0	0	0	2	0
** Subtotal **			0	0	0	0	0	0	0	0	0	0	0	0	2	0
** <u>F4H127</u> **																
FS-01	S00	CMD	0	0	0	0	0	0	0	1	0	0	0	0	0	0
JU-01	S00	S00	0	0	0	0	0	0	0	2	0	0	0	0	0	0
SU-12	S00	CMD	0	0	0	0	0	0	0	1	0	0	0	0	0	0
SU-12	S00	RMD	0	0	0	0	0	0	0	1	0	0	0	0	0	0
** Subtotal **			0	0	0	0	0	0	0	5	0	0	0	0	0	0
** <u>F54636</u> **																
JU-01	S00	S00	0	0	0	0	1	0	0	0	0	0	0	0	0	0

USMC MF TBA by Contingency Support Package

CONFIG	DIV	BR	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
** Subtotal **			0	0	0	0	1	0	0	0	0	0	0	0	0	0
** <u>F55316</u> **																
ED-01	S00	CMD	0	0	0	0	1	0	0	0	0	0	0	0	0	0
FS-01	S00	CMD	0	0	0	0	1	0	0	0	0	0	0	0	0	0
JU-01	S00	S00	0	0	0	0	1	0	0	0	0	0	0	0	0	0
** Subtotal **			0	0	0	0	3	0	0	0	0	0	0	0	0	0
** <u>F5H127</u> **																
ED-01	S00	CMD	0	0	0	0	0	0	0	0	0	0	2	0	0	0
FS-01	S00	CMD	0	0	0	0	0	0	0	0	0	0	1	0	0	0
JU-01	S00	S00	0	0	0	0	0	0	0	0	0	0	2	0	0	0
SU-12	S00	CMD	0	0	0	0	0	0	0	0	0	0	1	0	0	0
SU-12	S00	RMD	0	0	0	0	0	0	0	0	0	0	2	0	0	0
** Subtotal **			0	0	0	0	0	0	0	0	0	0	8	0	0	0
** <u>IOSP11</u> **																
JU-01	600	600	4	0	0	0	0	0	0	0	0	0	0	0	0	0
KA-18A	600	600	6	0	0	0	0	0	0	0	0	0	0	0	0	0
KA-19A	600	650	1	0	0	0	0	0	0	0	0	0	0	0	0	0
KA-20B	600	650	1	0	0	0	0	0	0	0	0	0	0	0	0	0
KA-31	600	650	11	0	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			23	0	0	0	0	0	0	0	0	0	0	0	0	0
** <u>IOSP12</u> **																
EB-06	600	650	0	1	0	0	0	0	0	0	0	0	0	0	0	0
EB-07	600	650	0	1	0	0	0	0	0	0	0	0	0	0	0	0
EB-09	600	650	0	1	0	0	0	0	0	0	0	0	0	0	0	0
JU-01	600	600	0	3	0	0	0	0	0	0	0	0	0	0	0	0
KA-18A	600	600	0	2	0	0	0	0	0	0	0	0	0	0	0	0
KA-31	600	650	0	11	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			0	19	0	0	0	0	0	0	0	0	0	0	0	0
** <u>IOSP14</u> **																
CL-09	600	670	0	0	0	2	0	0	0	0	0	0	0	0	0	0
DP-18A	AIS	AIS	0	0	0	1	0	0	0	0	0	0	0	0	0	0
EB-06	600	650	0	0	0	2	0	0	0	0	0	0	0	0	0	0
EB-07	600	650	0	0	0	2	0	0	0	0	0	0	0	0	0	0
EB-08	600	650	0	0	0	1	0	0	0	0	0	0	0	0	0	0
EB-09	600	650	0	0	0	2	0	0	0	0	0	0	0	0	0	0
JU-01	600	600	0	0	0	6	0	0	0	0	0	0	0	0	0	0
KA-18A	600	600	0	0	0	2	0	0	0	0	0	0	0	0	0	0
KA-19A	600	650	0	0	0	2	0	0	0	0	0	0	0	0	0	0
KA-20B	600	650	0	0	0	2	0	0	0	0	0	0	0	0	0	0
KA-31	600	650	0	0	0	4	0	0	0	0	0	0	0	0	0	0

USMC MF TBA by Contingency Support Package

CONFIG	DIV	BR	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
SU-01	600	600	0	0	0	4	0	0	0	0	0	0	0	0	0	0
SU-03	600	600	0	0	0	1	0	0	0	0	0	0	0	0	0	0
SU-03	600	670	0	0	0	1	0	0	0	0	0	0	0	0	0	0
SU-12	600	670	0	0	0	1	0	0	0	0	0	0	0	0	0	0
** Subtotal **			0	0	0	33	0	0	0	0	0	0	0	0	0	0
** <u>IOSP16</u> **																
DP-18A	AIS	AIS	0	0	0	0	1	0	0	0	0	0	0	0	0	0
** Subtotal **			0	0	0	0	1	0	0	0	0	0	0	0	0	0
** <u>IOSP31</u> **																
JU-01	600	600	0	0	0	0	0	0	0	0	4	0	0	0	0	0
KA-18A	600	600	0	0	0	0	0	0	0	0	4	0	0	0	0	0
KA-19A	600	650	0	0	0	0	0	0	0	0	1	0	0	0	0	0
KA-20B	600	650	0	0	0	0	0	0	0	0	1	0	0	0	0	0
KA-31	600	650	0	0	0	0	0	0	0	0	9	0	0	0	0	0
** Subtotal **			0	0	0	0	0	0	0	0	19	0	0	0	0	0
** <u>IOSP36</u> **																
DP-18A	AIS	AIS	0	0	0	0	0	0	0	0	0	1	0	0	0	0
** Subtotal **			0	0	0	0	0	0	0	0	0	1	0	0	0	0
** <u>IOSP41</u> **																
DP-18A	AIS	AIS	0	0	0	0	0	0	0	0	0	0	0	1	0	0
** Subtotal **			0	0	0	0	0	0	0	0	0	0	0	1	0	0
** <u>MACSXX</u> **																
AT-11	ATC	ATC	0	1	1	2	1	0	0	1	1	1	2	1	0	0
AT-12	ATC	ATC	0	1	1	2	1	0	0	1	1	1	2	1	0	0
CR-03	ATC	ATC	0	2	2	4	2	0	0	2	2	2	4	2	0	0
JU-01	ATC	ATC	0	1	2	2	1	0	0	1	1	1	2	1	0	0
SU-03	ATC	ATC	0	1	1	2	1	0	0	1	1	1	2	0	0	0
WJ-06	ATC	ATC	0	1	2	2	1	0	0	1	1	1	1	1	1	0
** Subtotal **			0	7	9	14	7	0	0	7	7	7	13	6	1	0
** <u>MPSXXX</u> **																
SU-03	MPS	BLI	0	0	0	0	0	0	0	0	0	0	0	0	0	3
SU-03	MPS	FLY	0	0	0	0	0	0	0	0	0	0	0	0	0	3
** Subtotal **			0	0	0	0	0	0	0	0	0	0	0	0	0	6
** <u>PALMXX</u> **																
EA-01	ZZC	EAF	1	0	0	0	0	0	0	0	0	0	0	0	0	0
JU-01	ZZC	EAF	1	0	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			2	0	0	0	0	0	0	0	0	0	0	0	0	0

USMC MF TBA by Contingency Support Package

CONFIG	DIV	BR	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
** SCIFXX **																
AB-02	000	S3	1	1	0	0	0	0	0	0	1	0	0	0	0	0
AB-03	000	S3	1	1	0	0	0	0	0	0	1	0	0	0	0	0
JU-01	000	000	1	1	0	0	0	0	0	0	1	0	0	0	0	0
JU-31	000	S3	1	1	0	0	0	0	0	0	1	0	0	0	0	0
JU-32	000	S3	1	1	0	0	0	0	0	0	1	0	0	0	0	0
** Subtotal **			5	5	0	0	0	0	0	0	5	0	0	0	0	0
** T53E29 **																
BL-01	600	620	0	0	0	0	0	0	0	1	0	0	0	0	0	0
HY-04A	500	520	0	0	0	0	0	0	0	1	0	0	0	0	0	0
HY-05B	500	520	0	0	0	0	0	0	0	1	0	0	0	0	0	0
JU-01	600	600	0	0	0	0	0	0	0	1	0	0	0	0	0	0
ST-01	600	610	0	0	0	0	0	0	0	2	0	0	0	0	0	0
ST-01	600	620	0	0	0	0	0	0	0	1	0	0	0	0	0	0
VD-05A	600	620	0	0	0	0	0	0	0	1	0	0	0	0	0	0
VD-06B	600	620	0	0	0	0	0	0	0	1	0	0	0	0	0	0
** Subtotal **			0	0	0	0	0	0	0	9	0	0	0	0	0	0
** TF3531 **																
BL-01	600	600	0	0	0	0	0	0	0	0	1	0	0	0	0	0
** Subtotal **			0	0	0	0	0	0	0	0	1	0	0	0	0	0
** TFRS11 **																
AM-01	000	05C	1	0	0	0	0	0	0	0	0	0	0	0	0	0
BL-01	600	620	1	0	0	0	0	0	0	0	0	0	0	0	0	0
CU-01	800	800	1	0	0	0	0	0	0	0	0	0	0	0	0	0
CU-01	600	600	2	0	0	0	0	0	0	0	0	0	0	0	0	0
CU-01	500	500	1	0	0	0	0	0	0	0	0	0	0	0	0	0
CU-01	400	400	1	0	0	0	0	0	0	0	0	0	0	0	0	0
CU-01	000	010	1	0	0	0	0	0	0	0	0	0	0	0	0	0
CU-01	000	020	1	0	0	0	0	0	0	0	0	0	0	0	0	0
CY-01	600	610	1	0	0	0	0	0	0	0	0	0	0	0	0	0
FA-02A	500	520	1	0	0	0	0	0	0	0	0	0	0	0	0	0
FA-03B	500	520	1	0	0	0	0	0	0	0	0	0	0	0	0	0
HC-01	500	520	1	0	0	0	0	0	0	0	0	0	0	0	0	0
HC-02	500	520	1	0	0	0	0	0	0	0	0	0	0	0	0	0
JU-01	900	900	1	0	0	0	0	0	0	0	0	0	0	0	0	0
JU-01	800	800	1	0	0	0	0	0	0	0	0	0	0	0	0	0
JU-01	600	600	4	0	0	0	0	0	0	0	0	0	0	0	0	0
JU-01	500	500	4	0	0	0	0	0	0	0	0	0	0	0	0	0
JU-01	000	000	3	0	0	0	0	0	0	0	0	0	0	0	0	0
KA-18A	600	600	6	0	0	0	0	0	0	0	0	0	0	0	0	0
KA-19A	600	650	1	0	0	0	0	0	0	0	0	0	0	0	0	0
KA-20B	600	650	1	0	0	0	0	0	0	0	0	0	0	0	0	0
MC-01	000	020	1	0	0	0	0	0	0	0	0	0	0	0	0	0

USMC MF TBA by Contingency Support Package

CONFIG	DIV	BR	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
MM-01	500	510	1	0	0	0	0	0	0	0	0	0	0	0	0	0
MM-02	500	510	1	0	0	0	0	0	0	0	0	0	0	0	0	0
MM-03	500	510	1	0	0	0	0	0	0	0	0	0	0	0	0	0
MM-04	500	510	1	0	0	0	0	0	0	0	0	0	0	0	0	0
NT-06	500	530	1	0	0	0	0	0	0	0	0	0	0	0	0	0
NT-07	500	530	1	0	0	0	0	0	0	0	0	0	0	0	0	0
NT-08	500	530	1	0	0	0	0	0	0	0	0	0	0	0	0	0
PW-01	500	500	1	0	0	0	0	0	0	0	0	0	0	0	0	0
RR-02	800	810	1	0	0	0	0	0	0	0	0	0	0	0	0	0
SE-01	800	810	1	0	0	0	0	0	0	0	0	0	0	0	0	0
SM-04B	500	510	1	0	0	0	0	0	0	0	0	0	0	0	0	0
SM-05A	500	510	1	0	0	0	0	0	0	0	0	0	0	0	0	0
ST-01	600	610	1	0	0	0	0	0	0	0	0	0	0	0	0	0
ST-01	600	620	1	0	0	0	0	0	0	0	0	0	0	0	0	0
ST-01	600	650	1	0	0	0	0	0	0	0	0	0	0	0	0	0
ST-01	500	520	1	0	0	0	0	0	0	0	0	0	0	0	0	0
SU-01	000	05C	1	0	0	0	0	0	0	0	0	0	0	0	0	0
SU-05	600	60C	1	0	0	0	0	0	0	0	0	0	0	0	0	0
SU-12	000	05A	1	0	0	0	0	0	0	0	0	0	0	0	0	0
SW-02	800	820	1	0	0	0	0	0	0	0	0	0	0	0	0	0
TR-01	600	600	1	0	0	0	0	0	0	0	0	0	0	0	0	0
TR-01	000	05D	1	0	0	0	0	0	0	0	0	0	0	0	0	0
VD-07A	600	620	1	0	0	0	0	0	0	0	0	0	0	0	0	0
VD-08B	600	620	1	0	0	0	0	0	0	0	0	0	0	0	0	0
WC-02	000	030	1	0	0	0	0	0	0	0	0	0	0	0	0	0
WC-02	000	040	1	0	0	0	0	0	0	0	0	0	0	0	0	0
WC-08	900	910	1	0	0	0	0	0	0	0	0	0	0	0	0	0
WC-08	900	940	1	0	0	0	0	0	0	0	0	0	0	0	0	0
WL-04A	500	510	1	0	0	0	0	0	0	0	0	0	0	0	0	0
WL-05A	500	510	1	0	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			66	0	0	0	0	0	0	0	0	0	0	0	0	0
** TFRS39 **																
TB-03A	500	520	0	0	0	0	0	0	0	0	0	0	1	0	0	0
TB-04B	500	520	0	0	0	0	0	0	0	0	0	0	1	0	0	0
** Subtotal **			0	0	0	0	0	0	0	0	0	0	2	0	0	0
** TH1M39 **																
BL-01	600	620	0	0	0	0	0	0	0	0	0	0	1	0	0	0
HY-04A	500	520	0	0	0	0	0	0	0	0	0	0	1	0	0	0
HY-05B	500	520	0	0	0	0	0	0	0	0	0	0	1	0	0	0
JU-01	600	600	0	0	0	0	0	0	0	0	0	0	1	0	0	0
ST-01	600	610	0	0	0	0	0	0	0	0	0	0	1	0	0	0
ST-01	600	620	0	0	0	0	0	0	0	0	0	0	1	0	0	0
SW-02	800	820	0	0	0	0	0	0	0	0	0	0	1	0	0	0
VD-05A	600	620	0	0	0	0	0	0	0	0	0	0	1	0	0	0
VD-06B	600	620	0	0	0	0	0	0	0	0	0	0	1	0	0	0

USMC MF TBA by Contingency Support Package

CONFIG	DIV	BR	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
** Subtotal **			0	0	0	0	0	0	0	0	0	0	9	0	0	0
** <u>TV2226</u> **																
HY-06C	500	520	0	0	0	0	0	0	1	0	0	0	0	0	0	0
JU-01	600	600	0	0	0	0	0	0	1	0	0	0	0	0	0	0
JU-01	500	500	0	0	0	0	0	0	1	0	0	0	0	0	0	0
KA-18A	600	600	0	0	0	0	0	0	4	0	0	0	0	0	0	0
KA-31	600	650	0	0	0	0	0	0	1	0	0	0	0	0	0	0
RR-04A	800	810	0	0	0	0	0	0	1	0	0	0	0	0	0	0
RR-05B	800	810	0	0	0	0	0	0	1	0	0	0	0	0	0	0
TB-02	500	520	0	0	0	0	0	0	1	0	0	0	0	0	0	0
** Subtotal **			0	0	0	0	0	0	11	0	0	0	0	0	0	0
** <u>TV8B14</u> **																
BL-01	600	620	0	0	0	1	0	0	0	0	0	0	0	0	0	0
CL-01	600	670	0	0	0	1	0	0	0	0	0	0	0	0	0	0
HY-04A	500	520	0	0	0	1	0	0	0	0	0	0	0	0	0	0
HY-05B	500	520	0	0	0	1	0	0	0	0	0	0	0	0	0	0
JU-01	ZZC	EAF	0	0	0	0	0	0	0	0	0	0	0	0	0	0
JU-01	600	600	0	0	0	4	0	0	0	0	0	0	0	0	0	0
JU-01	500	500	0	0	0	1	0	0	0	0	0	0	0	0	0	0
JU-01	000	000	0	0	0	1	0	0	0	0	0	0	0	0	0	0
KA-18A	600	600	0	0	0	5	0	0	0	0	0	0	0	0	0	0
KA-19A	600	650	0	0	0	1	0	0	0	0	0	0	0	0	0	0
KA-20B	600	650	0	0	0	1	0	0	0	0	0	0	0	0	0	0
MC-01	000	020	0	0	0	1	0	0	0	0	0	0	0	0	0	0
ST-01	600	610	0	0	0	6	0	0	0	0	0	0	0	0	0	0
ST-01	600	620	0	0	0	3	0	0	0	0	0	0	0	0	0	0
ST-01	500	520	0	0	0	1	0	0	0	0	0	0	0	0	0	0
SU-01	000	05C	0	0	0	2	0	0	0	0	0	0	0	0	0	0
VD-07A	600	620	0	0	0	1	0	0	0	0	0	0	0	0	0	0
VD-08B	600	620	0	0	0	1	0	0	0	0	0	0	0	0	0	0
** Subtotal **			0	0	0	32	0	0	0	0	0	0	0	0	0	0
** <u>WGISSX</u> **																
BL-01	600	620	0	0	0	0	1	0	0	0	0	0	0	0	0	0
** Subtotal **			0	0	0	0	1	0	0	0	0	0	0	0	0	0
Total			343	265	201	344	245	212	219	245	244	210	281	168	192	64

USMC MF TBA by Division

CONFIG	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
	**	000														
AB-02	S3	SCIFXX	1	1	0	0	0	0	0	0	1	0	0	0	0	0
AB-03	S3	SCIFXX	1	1	0	0	0	0	0	0	1	0	0	0	0	0
AM-01	05C	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
AM-01	05C	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	1	0
AM-01	05C	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
AT-08	S2	118A36	2	2	0	0	0	0	0	0	2	0	0	0	0	0
AT-09BM	210	118A36	2	2	0	0	0	0	0	0	2	0	0	0	0	0
AT-10A	210	118A36	2	2	0	0	0	0	0	0	2	0	0	0	0	0
CU-01	040	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
CU-01	020	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
CU-01	020	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
CU-01	020	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
CU-01	010	CCSPFW	2	2	2	2	0	0	0	0	1	0	0	2	0	0
CU-01	010	CCSPRW	0	0	0	0	2	2	2	2	0	2	2	0	2	0
CU-01	010	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
JU-01	000	118A36	1	1	0	0	0	0	0	0	1	0	0	0	0	0
JU-01	000	CCSPFW	3	3	3	3	0	0	0	0	3	0	0	3	0	0
JU-01	000	CCSPRW	0	0	0	0	3	2	3	3	0	3	3	0	3	0
JU-01	000	F2E605	0	0	0	1	0	0	0	0	0	0	0	0	0	0
JU-01	000	SCIFXX	1	1	0	0	0	0	0	0	1	0	0	0	0	0
JU-01	000	TFRS11	3	0	0	0	0	0	0	0	0	0	0	0	0	0
JU-01	000	TV8B14	0	0	0	1	0	0	0	0	0	0	0	0	0	0
JU-31	S3	SCIFXX	1	1	0	0	0	0	0	0	1	0	0	0	0	0
JU-32	S3	SCIFXX	1	1	0	0	0	0	0	0	1	0	0	0	0	0
MC-01	020	CCSPFW	2	2	2	2	0	0	0	0	2	0	0	2	0	0
MC-01	020	CCSPRW	0	0	0	0	2	1	2	2	0	0	2	0	2	0
MC-01	020	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
MC-01	020	TV8B14	0	0	0	1	0	0	0	0	0	0	0	0	0	0
SU-01	05D	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
SU-01	05D	CCSPRW	0	0	0	0	1	0	1	1	0	1	1	0	1	0
SU-01	05C	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
SU-01	05C	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
SU-01	05C	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
SU-01	05C	TV8B14	0	0	0	2	0	0	0	0	0	0	0	0	0	0
SU-08	05A	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
SU-08	05A	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
SU-12	05A	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
SU-12	05A	CCSPRW	0	0	0	0	1	0	1	1	0	1	1	0	1	0
SU-12	05A	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
TL-01	040	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
TL-01	040	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	1	0

USMC MF TBA by Division

CONFIG	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
TR-01	05D	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
TR-01	05D	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
TR-01	05D	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
WC-02	040	CCSPFW	2	2	2	2	0	0	0	0	2	0	0	2	0	0
WC-02	040	CCSPRW	0	0	0	0	2	1	1	2	0	0	2	0	2	0
WC-02	040	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
WC-02	030	CCSPFW	2	2	2	2	0	0	0	0	2	0	0	2	0	0
WC-02	030	CCSPRW	0	0	0	0	2	0	2	2	0	0	2	0	2	0
WC-02	030	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			43	31	19	24	20	13	19	20	30	12	20	19	20	0
** 400 **																
CU-01	400	CCSPFW	1	1	1	1	0	0	0	0	0	0	0	0	0	0
CU-01	400	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
CU-01	400	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
FS-01	400	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	0	0	0
FS-01	400	CCSPRW	0	0	0	0	1	0	1	1	0	1	1	0	1	0
JU-01	400	CCSPRW	0	0	0	0	2	1	2	2	0	2	2	0	2	0
PP-01	410	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	1	0
PP-03A	440	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	1	0
PP-04BM	440	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	1	0
SU-03	410	CCSPRW	0	0	0	0	1	0	1	1	0	1	1	0	1	0
SU-12	440	CCSPRW	0	0	0	0	1	0	1	1	0	1	1	0	1	0
TR-01	440	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
TR-01	400	118A12	0	0	0	0	0	0	0	0	0	0	0	1	0	0
TR-01	400	118A36	1	1	0	0	0	0	0	0	0	0	0	0	0	0
TR-01	400	118C24	1	0	0	0	0	0	0	0	0	0	0	0	0	0
TR-01	400	1E6B05	0	1	0	1	0	0	0	0	0	0	0	0	0	0
TR-01	400	2E6B05	0	0	0	1	0	0	0	0	0	0	0	0	0	0
TR-01	400	3E6B05	0	0	0	1	0	0	0	0	0	0	0	0	0	0
** Subtotal **			5	4	2	5	10	6	10	10	1	7	10	1	10	0
** 500 **																
CS-02A	510	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
CS-02A	510	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
CS-03BM	510	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
CS-03BM	510	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
CU-01	500	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
CU-01	500	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
CU-01	500	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
FA-02A	520	118A12	0	0	0	0	0	0	0	0	0	0	0	1	0	0
FA-02A	520	118A36	1	2	0	0	0	0	0	0	0	0	0	0	0	0
FA-02A	520	118C24	1	0	0	0	0	0	0	0	0	0	0	0	0	0

USMC MF TBA by Division

CONFIG	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
FA-02A	520	318A36	0	0	0	0	0	0	0	0	1	0	0	0	0	0
FA-02A	520	318C24	0	0	0	0	0	0	0	0	1	0	0	0	0	0
FA-02A	520	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
FA-03B	520	118A12	0	0	0	0	0	0	0	0	0	0	0	1	0	0
FA-03B	520	118A36	1	2	0	0	0	0	0	0	0	0	0	0	0	0
FA-03B	520	118C24	1	0	0	0	0	0	0	0	0	0	0	0	0	0
FA-03B	520	318A36	0	0	0	0	0	0	0	0	1	0	0	0	0	0
FA-03B	520	318C24	0	0	0	0	0	0	0	0	1	0	0	0	0	0
FA-03B	520	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
FS-01	500	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
FS-01	500	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
HC-01	520	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	1	0
HC-01	520	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	0	0
HC-01	520	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
HC-02	520	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	1	0
HC-02	520	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	0	0
HC-02	520	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
HY-04A	520	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
HY-04A	520	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
HY-04A	520	T53E29	0	0	0	0	0	0	0	1	0	0	0	0	0	0
HY-04A	520	TH1M39	0	0	0	0	0	0	0	0	0	0	1	0	0	0
HY-04A	520	TV8B14	0	0	0	1	0	0	0	0	0	0	0	0	0	0
HY-05B	520	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
HY-05B	520	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
HY-05B	520	T53E29	0	0	0	0	0	0	0	1	0	0	0	0	0	0
HY-05B	520	TH1M39	0	0	0	0	0	0	0	0	0	0	1	0	0	0
HY-05B	520	TV8B14	0	0	0	1	0	0	0	0	0	0	0	0	0	0
HY-06C	520	1V2236	0	0	0	0	0	1	2	0	0	1	1	0	0	0
HY-06C	520	3V2212	0	0	0	0	1	0	0	0	0	0	0	0	1	0
HY-06C	520	TV2226	0	0	0	0	0	0	1	0	0	0	0	0	0	0
JU-01	500	118A12	0	0	0	0	0	0	0	0	0	0	0	1	0	0
JU-01	500	118A36	1	1	0	0	0	0	0	0	0	0	0	0	0	0
JU-01	500	118C24	1	0	0	0	0	0	0	0	0	0	0	0	0	0
JU-01	500	1V2236	0	0	0	0	0	1	1	0	0	1	1	0	0	0
JU-01	500	1V8R14	0	0	0	1	0	0	0	0	0	0	0	0	0	0
JU-01	500	318C24	0	0	0	0	0	0	0	0	1	0	0	0	0	0
JU-01	500	3V2212	0	0	0	0	1	0	0	0	0	0	0	0	1	0
JU-01	500	CCSPFW	5	5	5	5	0	0	0	0	5	0	0	5	1	0
JU-01	500	CCSPRW	0	0	0	0	5	5	4	5	0	5	5	0	5	0
JU-01	500	TFRS11	4	0	0	0	0	0	0	0	0	0	0	0	0	0
JU-01	500	TV2226	0	0	0	0	0	0	1	0	0	0	0	0	0	0
JU-01	500	TV8B14	0	0	0	1	0	0	0	0	0	0	0	0	0	0
MM-01	510	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0

USMC MF TBA by Division

CONFIG	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
MM-01	510	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	1	0
MM-01	510	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
MM-02	510	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	1	0
MM-02	510	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	0	0
MM-02	510	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
MM-03	510	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
MM-03	510	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	1	0
MM-03	510	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
MM-04	510	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
MM-04	510	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	1	0
MM-04	510	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
NT-06	530	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
NT-06	530	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	1	0
NT-06	530	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
NT-07	530	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
NT-07	530	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	1	0
NT-07	530	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
NT-08	530	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
NT-08	530	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	1	0
NT-08	530	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
PW-01	500	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
PW-01	500	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
PW-01	500	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
SM-04B	510	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
SM-04B	510	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	1	0
SM-04B	510	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
SM-05A	510	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
SM-05A	510	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	1	0
SM-05A	510	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
SM-06B	510	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
SM-06B	510	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	1	0
SM-07A	510	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
SM-07A	510	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	1	0
SP-04	520	1V8R14	0	1	1	2	0	0	0	0	0	0	0	0	0	0
ST-01	520	CCSPFW	2	2	2	2	0	0	0	0	2	0	0	2	0	0
ST-01	520	CCSPRW	0	0	0	0	0	0	0	0	0	0	0	0	5	0
ST-01	520	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
ST-01	520	TV8B14	0	0	0	1	0	0	0	0	0	0	0	0	0	0
TB-01	520	CCSPRW	0	0	0	0	1	1	0	2	0	1	0	0	0	0
TB-02	520	1V2236	0	0	0	0	0	1	2	0	0	1	1	0	0	0
TB-02	520	3V2212	0	0	0	0	1	0	0	0	0	0	0	0	1	0
TB-02	520	TV2226	0	0	0	0	0	0	1	0	0	0	0	0	0	0
TB-03A	520	CCSPFW	2	1	1	2	0	0	0	0	1	0	0	1	0	0

USMC MF TBA by Division

CONFIG	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
TB-03A	520	TFRS39	0	0	0	0	0	0	0	0	0	0	1	0	0	0
TB-04B	520	CCSPFW	2	1	1	2	0	0	0	0	1	0	0	1	0	0
TB-04B	520	TFRS39	0	0	0	0	0	0	0	0	0	0	1	0	0	0
TR-01	500	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
TR-01	500	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
TW-05A	510	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
TW-05A	510	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	1	0
TW-06B	510	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
TW-06B	510	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	1	0
WL-04A	510	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
WL-04A	510	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	1	0
WL-04A	510	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
WL-05A	510	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
WL-05A	510	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	1	0
WL-05A	510	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			64	40	35	43	34	34	37	34	39	19	37	37	39	0
** 600 **																
AV-01A	600	CCSPFW	2	0	2	0	0	0	0	0	2	0	0	0	0	0
AV-01A	600	CCSPRW	0	0	0	0	2	2	2	2	0	0	2	0	0	0
AV-02B	600	CCSPFW	2	0	2	0	0	0	0	0	2	0	0	0	0	0
AV-02B	600	CCSPRW	0	0	0	0	2	2	2	2	0	0	2	0	0	0
BL-01	620	1HML09	0	0	0	0	0	0	0	0	0	0	0	0	1	0
BL-01	620	1HML27	0	0	0	0	0	1	0	2	0	2	0	0	0	0
BL-01	620	2HML09	0	0	0	0	0	0	0	0	0	0	0	0	1	0
BL-01	620	2HML27	0	0	0	0	0	0	0	0	0	0	1	0	0	0
BL-01	620	3HML27	0	0	0	0	0	0	0	0	0	0	1	0	0	0
BL-01	620	4HML27	0	0	0	0	0	0	0	2	0	0	0	0	0	0
BL-01	620	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
BL-01	620	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
BL-01	620	T53E29	0	0	0	0	0	0	0	1	0	0	0	0	0	0
BL-01	620	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
BL-01	620	TH1M39	0	0	0	0	0	0	0	0	0	0	1	0	0	0
BL-01	620	TV8B14	0	0	0	1	0	0	0	0	0	0	0	0	0	0
BL-01	620	WGISSX	0	0	0	0	1	0	0	0	0	0	0	0	0	0
BL-01	600	135B16	0	0	2	0	0	0	0	0	0	0	0	0	0	0
BL-01	600	235C10	0	0	0	0	0	0	0	0	1	0	0	0	0	0
BL-01	600	335B10	2	0	0	0	0	0	0	0	0	0	0	1	0	0
BL-01	600	435B16	0	0	0	2	0	0	0	0	0	0	0	1	0	0
BL-01	600	535B16	0	1	0	0	0	0	0	0	0	0	0	0	0	0
BL-01	600	TF3531	0	0	0	0	0	0	0	0	1	0	0	0	0	0
CA-01	670	CCSPFW	2	2	0	2	0	0	0	0	0	0	0	0	0	0
CA-04	670	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0

USMC MF TBA by Division

CONFIG	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
CA-04	670	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
CA-07A	670	CCSPRW	0	0	0	0	0	0	1	0	0	1	1	0	0	0
CA-08B	670	CCSPRW	0	0	0	0	0	0	1	0	0	1	1	0	0	0
CA-09	670	CCSPRW	0	0	0	0	0	1	1	0	0	0	1	0	0	0
CL-01	670	CCSPFW	2	2	2	2	0	0	0	0	2	0	0	2	0	0
CL-01	670	CCSPRW	0	0	0	0	2	2	2	2	0	2	2	0	2	0
CL-01	670	TV8B14	0	0	0	1	0	0	0	0	0	0	0	0	0	0
CL-02	670	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
CL-02	670	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
CL-04	670	CCSPFW	2	2	2	2	0	0	0	0	2	0	0	2	0	0
CL-04	670	CCSPRW	0	0	0	0	2	2	2	2	0	2	2	0	2	0
CL-04	610	CCSPFW	2	2	2	2	0	0	0	0	2	0	0	2	0	0
CL-04	610	CCSPRW	0	0	0	0	2	2	2	2	0	2	2	0	2	0
CL-06	670	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
CL-06	670	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
CL-07	670	CCSPFW	4	4	3	4	0	0	0	0	3	0	0	3	0	0
CL-07	670	CCSPRW	0	0	0	0	3	3	4	3	0	4	4	0	3	0
CL-09	670	CCSPFW	2	2	2	2	0	0	0	0	2	0	0	2	0	0
CL-09	670	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
CL-09	670	IOSP14	0	0	0	2	0	0	0	0	0	0	0	0	0	0
CL-10	670	CCSPFW	2	2	2	2	0	0	0	0	2	0	0	2	0	0
CL-10	670	CCSPRW	0	0	0	0	2	2	2	2	0	2	2	0	2	0
CR-04	690	CCSPFW	2	2	2	2	0	0	0	0	2	0	0	2	0	0
CR-04	690	CCSPRW	0	0	0	0	2	2	2	2	0	2	2	0	2	0
CU-01	600	CCSPFW	2	3	3	3	0	0	0	0	2	0	0	3	0	0
CU-01	600	CCSPRW	0	0	0	0	3	2	3	2	0	3	3	0	3	0
CU-01	600	TFRS11	2	0	0	0	0	0	0	0	0	0	0	0	0	0
CY-01	610	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
CY-01	610	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
CY-01	610	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
EB-06	650	IOSP12	0	1	0	0	0	0	0	0	0	0	0	0	0	0
EB-06	650	IOSP14	0	0	0	2	0	0	0	0	0	0	0	0	0	0
EB-07	650	IOSP12	0	1	0	0	0	0	0	0	0	0	0	0	0	0
EB-07	650	IOSP14	0	0	0	2	0	0	0	0	0	0	0	0	0	0
EB-08	650	IOSP14	0	0	0	1	0	0	0	0	0	0	0	0	0	0
EB-09	650	IOSP12	0	1	0	0	0	0	0	0	0	0	0	0	0	0
EB-09	650	IOSP14	0	0	0	2	0	0	0	0	0	0	0	0	0	0
FS-01	600	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
FS-01	600	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
GC-01	620	1V8R14	0	1	1	1	0	0	0	0	0	0	0	0	0	0
GC-01	620	2V8R14	0	0	1	1	0	0	0	0	0	0	0	0	0	0
JU-01	600	118A36	1	1	0	0	0	0	0	0	1	0	0	0	0	0
JU-01	600	118C24	1	0	0	0	0	0	0	0	1	0	0	1	0	0

USMC MF TBA by Division

CONFIG	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
JU-01	600	130T12	0	0	0	0	0	0	0	0	0	0	0	1	2	0
JU-01	600	153E16	0	0	0	0	1	0	0	1	0	0	0	0	0	0
JU-01	600	1HML27	0	0	0	0	0	1	0	2	0	1	2	0	1	0
JU-01	600	1V8R14	0	1	1	1	0	0	0	0	0	0	0	0	0	0
JU-01	600	2HML27	0	0	0	0	0	0	0	0	0	0	1	0	0	0
JU-01	600	2V8R14	0	0	1	1	0	0	0	0	0	0	0	0	0	0
JU-01	600	318A36	0	0	0	0	0	0	0	0	1	0	0	0	0	0
JU-01	600	4HML27	0	0	0	0	0	0	0	1	0	0	0	0	0	0
JU-01	600	CCSPFW	12	11	12	11	0	0	0	0	12	0	0	10	0	0
JU-01	600	CCSPRW	0	0	0	0	11	10	11	11	0	11	12	0	9	0
JU-01	600	IOSP11	4	0	0	0	0	0	0	0	0	0	0	0	0	0
JU-01	600	IOSP12	0	3	0	0	0	0	0	0	0	0	0	0	0	0
JU-01	600	IOSP14	0	0	0	6	0	0	0	0	0	0	0	0	0	0
JU-01	600	IOSP31	0	0	0	0	0	0	0	0	4	0	0	0	0	0
JU-01	600	T53E29	0	0	0	0	0	0	0	1	0	0	0	0	0	0
JU-01	600	TFRS11	4	0	0	0	0	0	0	0	0	0	0	0	0	0
JU-01	600	TH1M39	0	0	0	0	0	0	0	0	0	0	1	0	0	0
JU-01	600	TV2226	0	0	0	0	0	0	1	0	0	0	0	0	0	0
JU-01	600	TV8B14	0	0	0	4	0	0	0	0	0	0	0	0	0	0
JU-09	600	1E6B05	0	1	0	1	0	0	0	0	0	0	0	0	0	0
JU-09	600	2E6B05	0	0	0	1	0	0	0	0	0	0	0	0	0	0
JU-09	600	3E6B05	0	0	0	1	0	0	0	0	0	0	0	0	0	0
JU-10	600	1E6B05	0	1	0	1	0	0	0	0	0	0	0	0	0	0
JU-10	600	2E6B05	0	0	0	1	0	0	0	0	0	0	0	0	0	0
JU-10	600	3E6B05	0	0	0	1	0	0	0	0	0	0	0	0	0	0
KA-18A	600	1HML27	0	0	0	0	0	0	0	0	0	0	3	0	0	0
KA-18A	600	1V2236	0	0	0	0	2	0	0	0	0	0	0	0	0	0
KA-18A	600	CCSPFW	7	7	7	7	0	0	0	0	9	0	0	2	0	0
KA-18A	600	CCSPRW	0	0	0	0	4	3	4	4	0	3	4	0	2	0
KA-18A	600	IOSP11	6	0	0	0	0	0	0	0	0	0	0	0	0	0
KA-18A	600	IOSP12	0	2	0	0	0	0	0	0	0	0	0	0	0	0
KA-18A	600	IOSP14	0	0	0	2	0	0	0	0	0	0	0	0	0	0
KA-18A	600	IOSP31	0	0	0	0	0	0	0	0	4	0	0	0	0	0
KA-18A	600	TFRS11	6	0	0	0	0	0	0	0	0	0	0	0	0	0
KA-18A	600	TV2226	0	0	0	0	0	0	4	0	0	0	0	0	0	0
KA-18A	600	TV8B14	0	0	0	5	0	0	0	0	0	0	0	0	0	0
KA-19A	650	CCSPFW	2	2	2	2	0	0	0	0	2	0	0	1	0	0
KA-19A	650	IOSP11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
KA-19A	650	IOSP14	0	0	0	2	0	0	0	0	0	0	0	0	0	0
KA-19A	650	IOSP31	0	0	0	0	0	0	0	0	1	0	0	0	0	0
KA-19A	650	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
KA-19A	650	TV8B14	0	0	0	1	0	0	0	0	0	0	0	0	0	0
KA-20B	650	CCSPFW	2	2	2	2	0	0	0	0	2	0	0	1	0	0

USMC MF TBA by Division

CONFIG	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
KA-20B	650	IOSP11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
KA-20B	650	IOSP14	0	0	0	2	0	0	0	0	0	0	0	0	0	0
KA-20B	650	IOSP31	0	0	0	0	0	0	0	0	1	0	0	0	0	0
KA-20B	650	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
KA-20B	650	TV8B14	0	0	0	1	0	0	0	0	0	0	0	0	0	0
KA-31	650	118A12	0	0	0	0	0	0	0	0	0	0	0	1	0	0
KA-31	650	118A36	2	0	0	0	0	0	0	0	0	0	0	0	0	0
KA-31	650	1E6B05	0	0	0	3	0	0	0	0	0	0	0	0	0	0
KA-31	650	1HML27	0	0	0	0	0	0	0	0	0	0	2	0	0	0
KA-31	650	218A36	0	1	0	0	0	0	0	0	0	0	0	0	0	0
KA-31	650	2E6B05	0	0	0	3	0	0	0	0	0	0	0	0	0	0
KA-31	650	2V8R14	0	0	0	1	0	0	0	0	0	0	0	0	0	0
KA-31	650	318A36	0	0	0	0	0	0	0	0	4	0	0	0	0	0
KA-31	650	3V2212	0	0	0	0	1	0	0	0	0	0	0	0	0	0
KA-31	650	CCSPFW	3	3	7	3	0	0	0	0	3	0	0	3	0	0
KA-31	650	CCSPRW	0	0	0	0	3	3	3	3	0	3	3	0	3	0
KA-31	650	IOSP11	11	0	0	0	0	0	0	0	0	0	0	0	0	0
KA-31	650	IOSP12	0	11	0	0	0	0	0	0	0	0	0	0	0	0
KA-31	650	IOSP14	0	0	0	4	0	0	0	0	0	0	0	0	0	0
KA-31	650	IOSP31	0	0	0	0	0	0	0	0	9	0	0	0	0	0
KA-31	650	TV2226	0	0	0	0	0	0	1	0	0	0	0	0	0	0
MC-01	670	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
MC-01	670	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	1	0
MC-01	600	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
MC-01	600	CCSPRW	0	0	0	0	1	0	1	1	0	0	1	0	1	0
PM-01	650	1E6B05	0	1	0	1	0	0	0	0	0	0	0	0	0	0
PM-01	650	2E6B05	0	0	0	1	0	0	0	0	0	0	0	0	0	0
PM-01	650	3E6B05	0	0	0	1	0	0	0	0	0	0	0	0	0	0
PM-02	650	1V8R14	0	1	1	1	0	0	0	0	0	0	0	0	0	0
SH-06	650	130J12	1	0	0	1	0	0	0	0	0	1	0	0	0	0
SH-06	650	130T12	0	0	0	0	0	0	0	0	0	0	0	1	1	0
SH-06	650	CCSPRW	0	0	0	0	2	2	0	2	0	2	2	0	1	0
ST-01	690	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
ST-01	690	CCSPRW	0	0	0	0	3	1	1	1	0	1	3	0	1	0
ST-01	650	118A36	0	1	0	0	0	0	0	0	0	0	0	0	0	0
ST-01	650	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
ST-01	650	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	2	0
ST-01	650	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
ST-01	620	118A36	1	1	0	0	0	0	0	0	1	0	0	0	0	0
ST-01	620	118C24	1	0	0	0	0	0	0	0	1	0	0	1	0	0
ST-01	620	130T12	0	0	0	0	0	0	0	0	0	0	0	1	1	0
ST-01	620	146E36	0	0	0	0	1	0	0	0	0	1	1	0	0	0
ST-01	620	153E16	0	0	0	0	1	1	0	2	0	1	0	0	0	0

USMC MF TBA by Division

CONFIG	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
ST-01	620	1E6B05	0	1	0	1	0	0	0	0	0	0	0	0	0	0
ST-01	620	1HML27	0	0	0	0	0	1	0	2	0	1	1	0	0	0
ST-01	620	1RS53E	0	0	0	0	0	0	0	0	0	0	0	0	1	0
ST-01	620	1V8R14	0	1	1	1	0	0	0	0	0	0	0	0	0	0
ST-01	620	253E16	0	0	0	0	1	0	0	0	0	0	0	0	0	0
ST-01	620	2E6B05	0	0	0	1	0	0	0	0	0	0	0	0	0	0
ST-01	620	2HML27	0	0	0	0	0	0	0	0	0	0	1	0	0	0
ST-01	620	2V8R14	0	0	1	1	0	0	0	0	0	0	0	0	0	0
ST-01	620	3E6B05	0	0	0	1	0	0	0	0	0	0	0	0	0	0
ST-01	620	CCSPFW	3	2	2	2	0	0	0	0	2	0	0	2	0	0
ST-01	620	CCSPRW	0	0	0	0	3	2	2	2	0	2	3	0	2	0
ST-01	620	T53E29	0	0	0	0	0	0	0	1	0	0	0	0	0	0
ST-01	620	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
ST-01	620	TH1M39	0	0	0	0	0	0	0	0	0	0	1	0	0	0
ST-01	620	TV8B14	0	0	0	3	0	0	0	0	0	0	0	0	0	0
ST-01	610	118A36	1	1	0	0	0	0	0	0	1	0	0	0	0	0
ST-01	610	118C24	1	0	0	0	0	0	0	0	1	0	0	1	0	0
ST-01	610	130T12	0	0	0	0	0	0	0	0	0	0	0	3	3	0
ST-01	610	1E6B05	0	2	0	2	0	0	0	0	0	0	0	0	0	0
ST-01	610	1V8R14	0	1	1	1	0	0	0	0	0	0	0	0	0	0
ST-01	610	2E6B05	0	0	0	2	0	0	0	0	0	0	0	0	0	0
ST-01	610	2V8R14	0	0	1	1	0	0	0	0	0	0	0	0	0	0
ST-01	610	3E6B05	0	0	0	2	0	0	0	0	0	0	0	0	0	0
ST-01	610	CCSPFW	3	1	1	1	0	0	0	0	1	0	0	1	0	0
ST-01	610	CCSPRW	0	0	0	0	3	3	2	3	0	3	3	0	3	0
ST-01	610	T53E29	0	0	0	0	0	0	0	2	0	0	0	0	0	0
ST-01	610	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
ST-01	610	TH1M39	0	0	0	0	0	0	0	0	0	0	1	0	0	0
ST-01	610	TV8B14	0	0	0	6	0	0	0	0	0	0	0	0	0	0
SU-01	650	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
SU-01	600	CCSPFW	4	4	4	4	0	0	0	0	4	0	0	3	0	0
SU-01	600	CCSPRW	0	0	0	0	4	4	3	3	0	4	4	0	4	0
SU-01	600	IOSP14	0	0	0	4	0	0	0	0	0	0	0	0	0	0
SU-03	670	IOSP14	0	0	0	1	0	0	0	0	0	0	0	0	0	0
SU-03	650	118C24	0	0	0	0	0	0	0	0	1	0	0	1	0	0
SU-03	60C	CCSPFW	1	1	1	1	0	0	0	0	0	0	0	0	0	0
SU-03	60C	CCSPRW	0	0	0	0	1	0	0	0	0	0	1	0	0	0
SU-03	600	CCSPFW	1	0	1	1	0	0	0	0	0	0	0	1	0	0
SU-03	600	CCSPRW	0	0	0	0	1	0	0	1	0	1	0	0	0	0
SU-03	600	IOSP14	0	0	0	1	0	0	0	0	0	0	0	0	0	0
SU-05	60C	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
SU-05	60C	CCSPRW	0	0	0	0	1	1	1	0	0	0	1	0	1	0
SU-05	60C	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0

USMC MF TBA by Division

CONFIG	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
SU-05	600	CCSPFW	2	0	2	0	0	0	0	0	2	0	0	0	0	0
SU-05	600	CCSPRW	0	0	0	0	2	2	2	2	0	0	2	0	0	0
SU-12	670	IOSP14	0	0	0	1	0	0	0	0	0	0	0	0	0	0
TL-01	670	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
TL-01	670	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	1	0
TR-01	600	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
TR-01	600	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
TR-01	600	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
TT-02	620	1HML27	0	0	0	0	0	1	0	2	0	1	1	0	1	0
TT-02	620	2HML27	0	0	0	0	0	0	0	0	0	0	1	0	0	0
TT-03A	620	1HML27	0	0	0	0	0	1	0	2	0	1	1	0	1	0
TT-03A	620	2HML27	0	0	0	0	0	0	0	0	0	0	1	0	0	0
TT-04B	620	1HML27	0	0	0	0	0	1	0	2	0	1	1	0	1	0
TT-04B	620	2HML27	0	0	0	0	0	0	0	0	0	0	1	0	0	0
VD-05A	620	CCSPRW	0	0	0	0	0	0	1	1	0	1	1	0	0	0
VD-05A	620	T53E29	0	0	0	0	0	0	0	1	0	0	0	0	0	0
VD-05A	620	TH1M39	0	0	0	0	0	0	0	0	0	0	1	0	0	0
VD-06B	620	CCSPRW	0	0	0	0	0	0	1	1	0	1	1	0	0	0
VD-06B	620	T53E29	0	0	0	0	0	0	0	1	0	0	0	0	0	0
VD-06B	620	TH1M39	0	0	0	0	0	0	0	0	0	0	1	0	0	0
VD-07A	620	130T12	0	0	0	0	0	0	0	0	0	0	0	0	1	0
VD-07A	620	153E16	0	0	0	0	1	0	0	0	0	0	0	0	0	0
VD-07A	620	318C24	0	0	0	0	0	0	0	0	1	0	0	0	0	0
VD-07A	620	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
VD-07A	620	CCSPRW	0	0	0	0	0	1	0	0	0	0	0	0	0	0
VD-07A	620	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
VD-07A	620	TV8B14	0	0	0	1	0	0	0	0	0	0	0	0	0	0
VD-08B	620	130T12	0	0	0	0	0	0	0	0	0	0	0	0	1	0
VD-08B	620	153E16	0	0	0	0	1	0	0	0	0	0	0	0	0	0
VD-08B	620	318C24	0	0	0	0	0	0	0	0	1	0	0	0	0	0
VD-08B	620	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
VD-08B	620	CCSPRW	0	0	0	0	0	1	0	0	0	0	0	0	0	0
VD-08B	620	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
VD-08B	620	TV8B14	0	0	0	1	0	0	0	0	0	0	0	0	0	0
WC-12A	60C	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
WC-12A	60C	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
WC-13BM	60C	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
WC-13BM	60C	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
WR-01	690	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	0	0	0
WR-01	690	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	0	0
** Subtotal **			139	108	92	166	84	75	77	94	111	74	105	72	74	0

** 700 **

USMC MF TBA by Division

CONFIG	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
BR-01	71D	118A36	1	1	0	1	0	0	0	0	0	0	0	2	0	0
BR-01	71D	1V8R14	1	1	0	1	0	0	0	0	0	0	0	0	0	0
BR-04A	71D	CCSPFW	1	1	0	1	0	0	0	0	0	0	0	1	0	0
BR-04A	71D	CCSPRW	0	0	0	0	1	1	1	0	0	1	0	0	1	0
BR-05B	71D	CCSPFW	1	1	0	1	0	0	0	0	0	0	0	1	0	0
BR-05B	71D	CCSPRW	0	0	0	0	1	1	1	0	0	1	0	0	1	0
CU-01	730	CCSPFW	1	1	0	1	0	0	0	0	0	0	0	1	0	0
CU-01	730	CCSPRW	0	0	0	0	1	1	1	0	0	1	0	0	1	0
CU-01	700	CCSPFW	1	1	0	1	0	0	0	0	0	0	0	1	0	0
CU-01	700	CCSPRW	0	0	0	0	1	1	1	0	0	1	0	0	1	0
FC-05	730	CCSPFW	1	1	0	1	0	0	0	0	0	0	0	1	0	0
FC-05	730	CCSPRW	0	0	0	0	1	1	1	0	0	0	0	0	1	0
FS-01	700	CCSPFW	1	1	0	1	0	0	0	0	0	0	0	1	0	0
FS-01	700	CCSPRW	0	0	0	0	1	1	1	0	0	1	0	0	1	0
GM-02A	71B	118A36	1	1	0	1	0	0	0	0	0	0	0	0	0	0
GM-02A	71B	1V8R14	1	1	0	1	0	0	0	0	0	0	0	1	0	0
GM-02A	71B	CCSPRW	0	0	0	0	1	1	1	0	0	1	0	0	1	0
GM-03B	71B	118A36	1	1	0	1	0	0	0	0	0	0	0	0	0	0
GM-03B	71B	1V8R14	1	1	0	1	0	0	0	0	0	0	0	1	0	0
GM-03B	71B	CCSPRW	0	0	0	0	1	1	1	0	0	1	0	0	1	0
JU-01	700	CCSPFW	2	2	0	2	0	0	0	0	0	0	0	2	0	0
JU-01	700	CCSPRW	0	0	0	0	2	2	2	0	0	2	0	0	1	0
MC-01	700	CCSPFW	1	1	0	1	0	0	0	0	0	0	0	1	0	0
MC-01	700	CCSPRW	0	0	0	0	1	1	1	0	0	0	0	0	1	0
SU-03	700	CCSPFW	1	1	0	1	0	0	0	0	0	0	0	1	0	0
SU-03	700	CCSPRW	0	0	0	0	1	1	1	0	0	1	0	0	1	0
** Subtotal **			16	16	0	16	12	12	12	0	0	10	0	14	11	0
**	<u>800</u>	**														
CU-01	800	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
CU-01	800	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
CU-01	800	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
JU-01	800	130J12	0	0	0	0	0	0	0	0	0	1	0	0	0	0
JU-01	800	1V2236	0	0	0	0	0	0	1	0	0	0	0	0	0	0
JU-01	800	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
JU-01	800	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
JU-01	800	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
RR-02	810	130J12	0	1	0	0	0	0	0	0	0	0	0	0	0	0
RR-02	810	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
RR-02	810	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
RR-03	810	130J12	0	1	0	0	0	0	0	0	0	0	0	0	0	0
RR-03	810	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
RR-04A	810	1V2236	0	0	0	0	0	0	2	0	0	1	1	0	0	0

USMC MF TBA by Division

CONFIG	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
RR-04A	810	3V2212	0	0	0	0	1	1	0	0	0	0	0	0	1	0
RR-04A	810	TV2226	0	0	0	0	0	0	1	0	0	0	0	0	0	0
RR-05B	810	1V2236	0	0	0	0	0	0	2	0	0	1	1	0	0	0
RR-05B	810	3V2212	0	0	0	0	1	1	0	0	0	0	0	0	1	0
RR-05B	810	TV2226	0	0	0	0	0	0	1	0	0	0	0	0	0	0
SE-01	810	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
SE-01	810	CCSPRW	0	0	0	0	1	0	1	1	0	1	1	0	1	0
SE-01	810	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
SE-02B	810	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
SE-03C	810	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
SE-04B	810	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
SW-02	820	118A36	1	1	0	0	0	0	0	0	1	0	0	1	0	0
SW-02	820	118C24	1	1	0	0	0	0	0	0	1	0	0	0	0	0
SW-02	820	1HML27	0	0	0	0	0	0	0	2	0	0	1	0	2	0
SW-02	820	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
SW-02	820	TH1M39	0	0	0	0	0	0	0	0	0	0	1	0	0	0
** Subtotal **			12	9	5	5	8	7	13	8	7	9	10	6	10	0
** 900 **																
BL-01	940	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	0	0	0
BL-01	940	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	0	0
JU-01	900	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
JU-01	900	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
JU-01	900	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
WC-08	940	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
WC-08	940	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	1	0
WC-08	940	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
WC-08	930	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
WC-08	930	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	1	0
WC-08	910	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
WC-08	910	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	1	0
WC-08	910	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			8	5	5	5	5	5	5	5	5	2	5	4	4	0
** AIS **																
CA-01	AIS	CCSPFW	2	2	2	2	0	0	0	0	2	0	0	2	0	0
CA-01	AIS	CCSPRW	0	0	0	0	2	2	2	2	0	2	2	0	2	0
DP-03	AIS	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
DP-03	AIS	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
DP-18A	AIS	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
DP-18A	AIS	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
DP-18A	AIS	IOSP14	0	0	0	1	0	0	0	0	0	0	0	0	0	0
DP-18A	AIS	IOSP16	0	0	0	0	1	0	0	0	0	0	0	0	0	0

USMC MF TBA by Division

CONFIG	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
DP-18A	AIS	IOSP36	0	0	0	0	0	0	0	0	0	1	0	0	0	0
DP-18A	AIS	IOSP41	0	0	0	0	0	0	0	0	0	0	0	1	0	0
JU-01	AIS	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
JU-01	AIS	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
SU-03	AIS	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
SU-03	AIS	CCSPRW	0	0	0	0	1	0	1	1	0	1	1	0	1	0
** Subtotal **			6	6	6	7	7	5	6	6	6	7	6	7	6	0
** <u>ATC</u> **																
AT-11	ATC	MACSXX	0	1	1	2	1	0	0	1	1	1	2	1	0	0
AT-12	ATC	MACSXX	0	1	1	2	1	0	0	1	1	1	2	1	0	0
CR-03	ATC	MACSXX	0	2	2	4	2	0	0	2	2	2	4	2	0	0
JU-01	ATC	MACSXX	0	1	2	2	1	0	0	1	1	1	2	1	0	0
SU-03	ATC	MACSXX	0	1	1	2	1	0	0	1	1	1	2	0	0	0
WJ-06	ATC	MACSXX	0	1	2	2	1	0	0	1	1	1	1	1	1	0
** Subtotal **			0	7	9	14	7	0	0	7	7	7	13	6	1	0
** <u>MP2</u> **																
BL-01	LPZ	2FEFW	0	0	0	0	0	0	0	0	0	0	0	0	0	2
BL-01	BTN	2FERW	0	0	0	0	0	0	0	0	0	0	0	0	0	2
EA-01	SKM	EAF	0	0	0	0	0	0	0	0	0	0	0	0	0	1
SU-12	SSR	218C12	0	0	0	0	0	0	0	0	0	0	0	0	0	1
SU-12	SSR	2V8B05	0	0	0	0	0	0	0	0	0	0	0	0	0	1
SU-12	SSR	2V8B09	0	0	0	0	0	0	0	0	0	0	0	0	0	1
SU-12	SEAY	2H53E8	0	0	0	0	0	0	0	0	0	0	0	0	0	1
SU-12	SEAY	2HML9A	0	0	0	0	0	0	0	0	0	0	0	0	0	1
SU-12	SEAY	2HML9B	0	0	0	0	0	0	0	0	0	0	0	0	0	1
SU-12	SEAY	2M2212	0	0	0	0	0	0	0	0	0	0	0	0	0	1
SU-12	SEAY	2V2212	0	0	0	0	0	0	0	0	0	0	0	0	0	1
SU-12	LPZ	218A12	0	0	0	0	0	0	0	0	0	0	0	0	0	1
SU-12	LPZ	218D12	0	0	0	0	0	0	0	0	0	0	0	0	0	1
SU-12	LPZ	2E6B05	0	0	0	0	0	0	0	0	0	0	0	0	0	1
SU-12	LPZ	2FEFW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
SU-12	BTN	222B12	0	0	0	0	0	0	0	0	0	0	0	0	0	1
SU-12	BTN	230J15	0	0	0	0	0	0	0	0	0	0	0	0	0	1
SU-12	BTN	253E08	0	0	0	0	0	0	0	0	0	0	0	0	0	1
SU-12	BTN	2HML9C	0	0	0	0	0	0	0	0	0	0	0	0	0	1
TW-05A	LPZ	2FEFW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
TW-05A	BTN	2FERW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
TW-06B	LPZ	2FEFW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
TW-06B	BTN	2FERW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
** Subtotal **			0	0	0	0	0	0	0	0	0	0	0	0	0	25

USMC MF TBA by Division

CONFIG	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
** MP3 **																
BL-01	LMS	3FEFW	0	0	0	0	0	0	0	0	0	0	0	0	0	2
BL-01	BBO	3FERW	0	0	0	0	0	0	0	0	0	0	0	0	0	2
EA-01	WLM	EAF	0	0	0	0	0	0	0	0	0	0	0	0	0	1
SU-12	PLU	3H53E8	0	0	0	0	0	0	0	0	0	0	0	0	0	1
SU-12	PLU	3HML9A	0	0	0	0	0	0	0	0	0	0	0	0	0	1
SU-12	PLU	3HML9B	0	0	0	0	0	0	0	0	0	0	0	0	0	1
SU-12	PLU	3M2212	0	0	0	0	0	0	0	0	0	0	0	0	0	1
SU-12	PLU	3V2212	0	0	0	0	0	0	0	0	0	0	0	0	0	1
SU-12	LMS	318A12	0	0	0	0	0	0	0	0	0	0	0	0	0	1
SU-12	LMS	318D12	0	0	0	0	0	0	0	0	0	0	0	0	0	1
SU-12	LMS	3E6B05	0	0	0	0	0	0	0	0	0	0	0	0	0	1
SU-12	DHL	318C12	0	0	0	0	0	0	0	0	0	0	0	0	0	1
SU-12	DHL	3V8B05	0	0	0	0	0	0	0	0	0	0	0	0	0	1
SU-12	DHL	3V8B09	0	0	0	0	0	0	0	0	0	0	0	0	0	1
SU-12	BBO	322B12	0	0	0	0	0	0	0	0	0	0	0	0	0	1
SU-12	BBO	330J15	0	0	0	0	0	0	0	0	0	0	0	0	0	1
SU-12	BBO	353E08	0	0	0	0	0	0	0	0	0	0	0	0	0	1
SU-12	BBO	3HML9C	0	0	0	0	0	0	0	0	0	0	0	0	0	1
TW-05A	LMS	3FEFW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
TW-05A	BBO	3FERW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
TW-06B	LMS	3FEFW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
TW-06B	BBO	3FERW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
** Subtotal **			0	0	0	0	0	0	0	0	0	0	0	0	0	24
** MPS **																
BL-01	BLI	4574H	0	0	0	0	0	0	0	0	0	0	0	0	0	1
FS-01	BLI	4574H	0	0	0	0	0	0	0	0	0	0	0	0	0	1
JU-01	FLY	4574H	0	0	0	0	0	0	0	0	0	0	0	0	0	1
SU-03	FLY	MPSXXX	0	0	0	0	0	0	0	0	0	0	0	0	0	3
SU-03	BLI	MPSXXX	0	0	0	0	0	0	0	0	0	0	0	0	0	3
SU-12	FLY	4574H	0	0	0	0	0	0	0	0	0	0	0	0	0	3
SU-12	BLI	4574H	0	0	0	0	0	0	0	0	0	0	0	0	0	1
TW-05A	FLY	4574H	0	0	0	0	0	0	0	0	0	0	0	0	0	1
TW-06B	FLY	4574H	0	0	0	0	0	0	0	0	0	0	0	0	0	1
** Subtotal **			0	0	0	0	0	0	0	0	0	0	0	0	0	15
** S00 **																
ED-01	CMD	F18R14	0	1	1	1	0	0	0	0	0	0	0	0	0	0
ED-01	CMD	F1H127	0	0	0	0	0	2	0	2	0	0	0	0	0	0
ED-01	CMD	F1V224	0	0	0	0	0	2	2	0	0	0	0	0	0	0
ED-01	CMD	F28A36	0	1	0	0	0	0	0	0	0	0	0	0	0	0

USMC MF TBA by Division

CONFIG	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
ED-01	CMD	F28R14	0	0	1	1	0	0	0	0	0	0	0	0	0	0
ED-01	CMD	F2H127	0	0	0	0	0	0	0	0	0	0	2	0	0	0
ED-01	CMD	F2V224	0	0	0	0	0	0	2	0	0	0	0	0	0	0
ED-01	CMD	F30J12	1	0	0	1	0	0	0	0	0	1	0	0	0	0
ED-01	CMD	F35316	0	0	0	0	0	0	0	0	0	1	0	0	0	0
ED-01	CMD	F38A36	0	0	0	0	0	0	0	0	2	0	0	0	0	0
ED-01	CMD	F38C24	0	0	0	0	0	0	0	0	1	0	0	0	0	0
ED-01	CMD	F3H127	0	0	0	0	0	0	0	0	0	2	0	0	0	0
ED-01	CMD	F3V224	0	0	0	0	2	0	0	0	0	0	0	0	0	0
ED-01	CMD	F45316	0	0	0	0	1	0	0	0	0	0	0	0	0	0
ED-01	CMD	F55316	0	0	0	0	1	0	0	0	0	0	0	0	0	0
ED-01	CMD	F5H127	0	0	0	0	0	0	0	0	0	0	2	0	0	0
FS-01	CMD	F15316	0	0	0	0	0	1	0	1	0	0	0	0	0	0
FS-01	CMD	F18A36	1	0	0	0	0	0	0	0	0	0	0	0	0	0
FS-01	CMD	F18C24	1	0	0	0	0	0	0	0	0	0	0	0	0	0
FS-01	CMD	F18R14	0	1	1	1	0	0	0	0	0	0	0	0	0	0
FS-01	CMD	F1E605	0	1	0	1	0	0	0	0	0	0	0	0	0	0
FS-01	CMD	F1H127	0	0	0	0	0	1	0	1	0	0	0	0	0	0
FS-01	CMD	F1V224	0	0	0	0	0	1	1	0	0	0	0	0	0	0
FS-01	CMD	F25316	0	0	0	0	0	0	0	1	0	0	0	0	0	0
FS-01	CMD	F28A36	0	1	0	0	0	0	0	0	0	0	0	0	0	0
FS-01	CMD	F28R14	0	0	1	1	0	0	0	0	0	0	0	0	0	0
FS-01	CMD	F2E605	0	0	0	1	0	0	0	0	0	0	0	0	0	0
FS-01	CMD	F2H127	0	0	0	0	0	0	0	0	0	0	1	0	0	0
FS-01	CMD	F2V224	0	0	0	0	1	0	1	0	0	0	0	0	0	0
FS-01	CMD	F30J12	1	0	0	1	0	0	0	0	0	0	0	0	0	0
FS-01	CMD	F35316	0	0	0	0	0	0	0	0	0	1	0	0	0	0
FS-01	CMD	F38A36	0	0	0	0	0	0	0	0	1	0	0	0	0	0
FS-01	CMD	F3E605	0	0	0	1	0	0	0	0	0	0	0	0	0	0
FS-01	CMD	F3H127	0	0	0	0	0	0	0	0	0	1	0	0	0	0
FS-01	CMD	F3V224	0	0	0	0	1	0	0	0	0	1	1	0	0	0
FS-01	CMD	F45316	0	0	0	0	1	0	0	0	0	0	0	0	0	0
FS-01	CMD	F4H127	0	0	0	0	0	0	0	1	0	0	0	0	0	0
FS-01	CMD	F55316	0	0	0	0	1	0	0	0	0	0	0	0	0	0
FS-01	CMD	F5H127	0	0	0	0	0	0	0	0	0	0	1	0	0	0
JU-01	S00	118A36	3	0	0	0	0	0	0	0	0	0	0	0	0	0
JU-01	S00	118C24	3	0	0	0	0	0	0	0	0	0	0	0	0	0
JU-01	S00	130J12	2	0	0	2	0	0	0	0	0	2	0	0	0	0
JU-01	S00	146E12	0	0	0	0	0	0	0	0	0	2	2	0	0	0
JU-01	S00	153E16	0	0	0	0	0	2	0	2	0	0	0	0	0	0
JU-01	S00	1E6B05	0	1	0	1	0	0	0	0	0	0	0	0	0	0
JU-01	S00	1HML27	0	0	0	0	0	3	0	3	0	0	0	0	0	0
JU-01	S00	1RS46E	0	0	0	0	0	0	0	0	0	0	0	0	3	0

USMC MF TBA by Division

CONFIG	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
JU-01	S00	1V2236	0	0	0	0	0	3	3	0	0	0	0	0	0	0
JU-01	S00	1V8R14	0	2	2	2	0	0	0	0	0	0	0	0	0	0
JU-01	S00	218A36	0	3	0	0	0	0	0	0	0	0	0	0	0	0
JU-01	S00	246E36	0	0	0	0	3	0	0	0	0	0	0	0	0	0
JU-01	S00	253E16	0	0	0	0	0	0	0	2	0	0	0	0	0	0
JU-01	S00	2E6B05	0	0	0	1	0	0	0	0	0	0	0	0	0	0
JU-01	S00	2HML27	0	0	0	0	0	0	0	0	0	0	3	0	0	0
JU-01	S00	2V2224	0	0	0	0	0	0	3	0	0	0	0	0	0	0
JU-01	S00	2V8R14	0	0	2	2	0	0	0	0	0	0	0	0	0	0
JU-01	S00	318A36	0	0	0	0	0	0	0	0	3	0	0	0	0	0
JU-01	S00	318C24	0	0	0	0	0	0	0	0	3	0	0	0	0	0
JU-01	S00	346E24	0	0	0	0	0	0	0	0	0	0	3	0	0	0
JU-01	S00	353E16	0	0	0	0	2	0	0	0	0	0	0	0	0	0
JU-01	S00	3E6B05	0	0	0	1	0	0	0	0	0	0	0	0	0	0
JU-01	S00	3HML27	0	0	0	0	0	0	0	0	0	0	3	0	0	0
JU-01	S00	3V2212	0	0	0	0	2	0	0	0	0	0	0	0	0	0
JU-01	S00	3V8R14	0	0	2	2	0	0	0	0	0	0	0	0	0	0
JU-01	S00	446E24	0	0	0	0	0	0	0	0	0	3	0	0	0	0
JU-01	S00	453E16	0	0	0	0	0	0	0	0	0	2	0	0	0	0
JU-01	S00	4HML27	0	0	0	0	0	0	0	3	0	3	0	0	0	0
JU-01	S00	553E16	0	0	0	0	2	0	0	0	0	0	0	0	0	0
JU-01	S00	553EXX	0	0	0	0	2	0	0	0	0	0	0	0	0	0
JU-01	S00	5HML27	0	0	0	0	0	0	0	0	0	0	3	0	0	0
JU-01	S00	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
JU-01	S00	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
JU-01	S00	F15316	0	0	0	0	0	1	0	1	0	0	0	0	0	0
JU-01	S00	F18A36	2	0	0	0	0	0	0	0	0	0	0	0	0	0
JU-01	S00	F18C24	2	0	0	0	0	0	0	0	0	0	0	0	0	0
JU-01	S00	F18R14	0	1	1	1	0	0	0	0	0	0	0	0	0	0
JU-01	S00	F1E605	0	1	0	1	0	0	0	0	0	0	0	0	0	0
JU-01	S00	F1H127	0	0	0	0	0	2	0	2	0	0	0	0	0	0
JU-01	S00	F1V224	0	0	0	0	0	2	2	0	0	0	0	0	0	0
JU-01	S00	F25316	0	0	0	0	0	0	0	1	0	0	0	0	0	0
JU-01	S00	F28A36	0	2	0	0	0	0	0	0	0	0	0	0	0	0
JU-01	S00	F28R14	0	0	1	1	0	0	0	0	0	0	0	0	0	0
JU-01	S00	F2H127	0	0	0	0	0	0	0	0	0	0	2	0	0	0
JU-01	S00	F2V224	0	0	0	0	0	0	2	0	0	0	0	0	0	0
JU-01	S00	F30J12	1	0	0	1	0	0	0	0	0	1	0	0	0	0
JU-01	S00	F34624	0	0	0	0	0	0	0	0	0	0	2	0	0	0
JU-01	S00	F35316	0	0	0	0	0	0	0	0	0	1	0	0	0	0
JU-01	S00	F38A36	0	0	0	0	0	0	0	0	2	0	0	0	0	0
JU-01	S00	F38C24	0	0	0	0	0	0	0	0	2	0	0	0	0	0
JU-01	S00	F3E605	0	0	0	1	0	0	0	0	0	0	0	0	0	0

USMC MF TBA by Division

CONFIG	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
JU-01	S00	F3H127	0	0	0	0	0	0	0	0	0	2	0	0	0	0
JU-01	S00	F3V224	0	0	0	0	2	0	0	0	0	0	0	0	0	0
JU-01	S00	F44624	0	0	0	0	0	0	0	0	0	2	0	0	0	0
JU-01	S00	F45316	0	0	0	0	1	0	0	0	0	0	0	0	0	0
JU-01	S00	F46FSP	0	0	0	0	0	0	0	0	0	0	0	0	2	0
JU-01	S00	F4H127	0	0	0	0	0	0	0	2	0	0	0	0	0	0
JU-01	S00	F54636	0	0	0	0	1	0	0	0	0	0	0	0	0	0
JU-01	S00	F55316	0	0	0	0	1	0	0	0	0	0	0	0	0	0
JU-01	S00	F5H127	0	0	0	0	0	0	0	0	0	0	2	0	0	0
SU-01	RMD	118C24	1	0	0	0	0	0	0	0	0	0	0	0	0	0
SU-01	RMD	130J12	1	0	0	1	0	0	0	0	0	1	0	0	0	0
SU-01	RMD	1V8R14	0	1	0	1	0	0	0	0	0	0	0	0	0	0
SU-01	RMD	253E16	0	0	0	0	0	0	0	1	0	0	0	0	0	0
SU-01	RMD	2HML27	0	0	0	0	0	0	0	0	0	0	2	0	0	0
SU-01	RMD	2V2224	0	0	0	0	0	0	1	0	0	0	0	0	0	0
SU-01	RMD	318C24	0	0	0	0	0	0	0	0	1	0	0	0	0	0
SU-01	RMD	353E16	0	0	0	0	1	0	0	0	0	0	0	0	0	0
SU-01	RMD	3HML27	0	0	0	0	0	0	0	0	0	0	2	0	0	0
SU-01	RMD	3V2212	0	0	0	0	1	0	0	0	0	0	0	0	0	0
SU-01	RMD	453E16	0	0	0	0	0	0	0	0	0	0	0	0	0	0
SU-01	RMD	4HML27	0	0	0	0	0	0	0	1	0	1	0	0	0	0
SU-01	RMD	553E16	0	0	0	0	1	0	0	0	0	0	0	0	0	0
SU-01	RMD	553EXX	0	0	0	0	1	0	0	0	0	0	0	0	0	0
SU-01	RMD	CCSPFW	1	2	1	1	0	0	0	0	1	0	0	0	0	0
SU-01	RMD	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
SU-01	RMD	F15316	0	0	0	0	0	1	0	1	0	0	0	0	0	0
SU-01	RMD	F18R14	0	1	1	1	0	0	0	0	0	0	0	0	0	0
SU-01	RMD	F1H127	0	0	0	0	0	2	0	1	0	0	0	0	0	0
SU-01	RMD	F1V224	0	0	0	0	0	2	1	0	0	0	0	0	0	0
SU-01	RMD	F25316	0	0	0	0	0	0	0	1	0	0	0	0	0	0
SU-01	RMD	F2H127	0	0	0	0	0	0	0	0	0	0	3	0	0	0
SU-01	RMD	F2V224	0	0	0	0	0	0	1	0	0	0	0	0	0	0
SU-01	RMD	F30J12	1	0	0	1	0	0	0	0	0	1	0	0	0	0
SU-01	RMD	F35316	0	0	0	0	0	0	0	0	0	1	0	0	0	0
SU-01	RMD	F38A36	0	0	0	0	0	0	0	0	1	0	0	0	0	0
SU-01	RMD	F38C24	0	0	0	0	0	0	0	0	1	0	0	0	0	0
SU-01	RMD	F3H127	0	0	0	0	0	0	0	0	0	1	0	0	0	0
SU-01	RMD	F3V224	0	0	0	0	1	0	0	0	0	0	0	0	0	0
SU-01	CMD	118A36	1	0	0	0	0	0	0	0	0	0	0	0	0	0
SU-02	CMD	118A36	3	0	0	0	0	0	0	0	0	0	0	0	0	0
SU-02	CMD	118C24	3	0	0	0	0	0	0	0	0	0	0	0	0	0
SU-02	CMD	130J12	1	0	0	1	0	0	0	0	0	2	0	0	0	0
SU-02	CMD	153E16	0	0	0	0	0	1	0	2	0	0	0	0	0	0

USMC MF TBA by Division

CONFIG	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
SU-02	CMD	1E6B05	0	1	0	1	0	0	0	0	0	0	0	0	0	0
SU-02	CMD	1HML27	0	0	0	0	0	1	0	3	0	0	0	0	0	0
SU-02	CMD	1RS46E	0	0	0	0	0	0	0	0	0	0	0	0	1	0
SU-02	CMD	1V2236	0	0	0	0	0	1	1	0	0	0	0	0	0	0
SU-02	CMD	1V8R14	0	1	1	1	0	0	0	0	0	0	0	0	0	0
SU-02	CMD	218A36	0	1	0	0	0	0	0	0	0	0	0	0	0	0
SU-02	CMD	246E36	0	0	0	0	1	0	0	0	0	0	0	0	0	0
SU-02	CMD	2E6B05	0	0	0	1	0	0	0	0	0	0	0	0	0	0
SU-02	CMD	2HML27	0	0	0	0	0	0	0	0	0	0	3	0	0	0
SU-02	CMD	2V2224	0	0	0	0	0	0	1	0	0	0	0	0	0	0
SU-02	CMD	2V8R14	0	0	1	1	0	0	0	0	0	0	0	0	0	0
SU-02	CMD	318A36	0	0	0	0	0	0	0	0	1	0	0	0	0	0
SU-02	CMD	318C24	0	0	0	0	0	0	0	0	1	0	0	0	0	0
SU-02	CMD	353E16	0	0	0	0	1	0	0	0	0	0	0	0	0	0
SU-02	CMD	3HML27	0	0	0	0	0	0	0	0	0	0	3	0	0	0
SU-02	CMD	3V2212	0	0	0	0	1	0	0	0	0	0	0	0	0	0
SU-02	CMD	3V8R14	0	0	1	1	0	0	0	0	0	0	0	0	0	0
SU-02	CMD	453E16	0	0	0	0	0	0	0	0	0	2	0	0	0	0
SU-02	CMD	4HML27	0	0	0	0	0	0	0	2	0	3	0	0	0	0
SU-02	CMD	553E16	0	0	0	0	1	0	0	0	0	0	0	0	0	0
SU-02	CMD	553EXX	0	0	0	0	1	0	0	0	0	0	0	0	0	0
SU-02	CMD	5HML27	0	0	0	0	0	0	0	0	0	0	3	0	0	0
SU-02	CMD	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
SU-02	CMD	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
SU-02	CMD	F1E605	0	1	0	1	0	0	0	0	0	0	0	0	0	0
SU-02	CMD	F2E605	0	0	0	1	0	0	0	0	0	0	0	0	0	0
SU-03	CMD	153E16	0	0	0	0	0	1	0	0	0	0	0	0	0	0
SU-04	SRD	1HML27	0	0	0	0	0	2	0	2	0	0	0	0	0	0
SU-05	SRD	118A36	1	0	0	0	0	0	0	0	0	0	0	0	0	0
SU-05	SRD	118C24	1	0	0	0	0	0	0	0	0	0	0	0	0	0
SU-05	SRD	1RS46E	0	0	0	0	0	0	0	0	0	0	0	0	2	0
SU-05	SRD	218A36	0	1	0	0	0	0	0	0	0	0	0	0	0	0
SU-05	SRD	2HML27	0	0	0	0	0	0	0	0	0	0	2	0	0	0
SU-05	SRD	2V2224	0	0	0	0	0	0	2	0	0	0	0	0	0	0
SU-05	SRD	318C24	0	0	0	0	0	0	0	0	1	0	0	0	0	0
SU-05	SRD	3HML27	0	0	0	0	0	0	0	0	0	0	2	0	0	0
SU-05	SRD	4HML27	0	0	0	0	0	0	0	1	0	0	0	0	0	0
SU-05	SAD	118A36	1	0	0	0	0	0	0	0	0	0	0	0	0	0
SU-05	SAD	118C24	1	0	0	0	0	0	0	0	0	0	0	0	0	0
SU-05	SAD	1HML27	0	0	0	0	0	1	0	1	0	0	0	0	0	0
SU-05	SAD	1V2236	0	0	0	0	0	1	1	0	0	0	0	0	0	0
SU-05	SAD	246E36	0	0	0	0	1	0	0	0	0	0	0	0	0	0
SU-05	SAD	2HML27	0	0	0	0	0	0	0	0	0	0	1	0	0	0

USMC MF TBA by Division

CONFIG	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
SU-05	SAD	318A36	0	0	0	0	0	0	0	0	1	0	0	0	0	0
SU-05	SAD	3HML27	0	0	0	0	0	0	0	0	0	0	1	0	0	0
SU-05	SAD	446E24	0	0	0	0	0	0	0	0	0	0	0	0	0	0
SU-05	SAD	4HML27	0	0	0	0	0	0	0	1	0	0	0	0	0	0
SU-05	SAD	5HML27	0	0	0	0	0	0	0	0	0	0	1	0	0	0
SU-05	RMD	1V2236	0	0	0	0	0	1	1	0	0	0	0	0	0	0
SU-05	RMD	218A36	0	1	0	0	0	0	0	0	0	0	0	0	0	0
SU-05	RMD	246E36	0	0	0	0	1	0	0	0	0	0	0	0	0	0
SU-05	RMD	318A36	0	0	0	0	0	0	0	0	1	0	0	0	0	0
SU-05	CMD	1V2236	0	0	0	0	0	1	1	0	0	0	0	0	0	0
SU-05	CMD	218A36	0	1	0	0	0	0	0	0	0	0	0	0	0	0
SU-05	CMD	246E36	0	0	0	0	1	0	0	0	0	0	0	0	0	0
SU-05	CMD	318A36	0	0	0	0	0	0	0	0	1	0	0	0	0	0
SU-12	RMD	130J12	2	0	0	2	0	0	0	0	0	2	0	0	0	0
SU-12	RMD	153E16	0	0	0	0	0	0	0	1	0	0	0	0	0	0
SU-12	RMD	1E6B05	0	1	0	1	0	0	0	0	0	0	0	0	0	0
SU-12	RMD	1HML27	0	0	0	0	0	0	0	1	0	0	0	0	0	0
SU-12	RMD	1V2236	0	0	0	0	0	4	1	0	0	0	0	0	0	0
SU-12	RMD	1V8R14	0	2	2	2	0	0	0	0	0	0	0	0	0	0
SU-12	RMD	253E16	0	0	0	0	0	0	0	1	0	0	0	0	0	0
SU-12	RMD	2HML27	0	0	0	0	0	0	0	0	0	0	3	0	0	0
SU-12	RMD	2V2224	0	0	0	0	0	0	1	0	0	0	0	0	0	0
SU-12	RMD	318A36	0	0	0	0	0	0	0	0	1	0	0	0	0	0
SU-12	RMD	318C24	0	0	0	0	0	0	0	0	1	0	0	0	0	0
SU-12	RMD	353E16	0	0	0	0	2	0	0	0	0	0	0	0	0	0
SU-12	RMD	3HML27	0	0	0	0	0	0	0	0	0	0	2	0	0	0
SU-12	RMD	3V2212	0	0	0	0	2	0	0	0	0	0	0	0	0	0
SU-12	RMD	3V8R14	0	0	2	2	0	0	0	0	0	0	0	0	0	0
SU-12	RMD	453E16	0	0	0	0	0	0	0	0	0	2	0	0	0	0
SU-12	RMD	4HML27	0	0	0	0	0	0	0	1	0	3	0	0	0	0
SU-12	RMD	553E16	0	0	0	0	1	0	0	0	0	0	0	0	0	0
SU-12	RMD	553EXX	0	0	0	0	1	0	0	0	0	0	0	0	0	0
SU-12	RMD	5HML27	0	0	0	0	0	0	0	0	0	0	2	0	0	0
SU-12	RMD	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	0	0	0
SU-12	RMD	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	3	0
SU-12	RMD	F15316	0	0	0	0	0	1	0	1	0	0	0	0	0	0
SU-12	RMD	F18A36	1	0	0	0	0	0	0	0	0	0	0	0	0	0
SU-12	RMD	F18C24	2	0	0	0	0	0	0	0	0	0	0	0	0	0
SU-12	RMD	F18R14	0	1	1	0	0	0	0	0	0	0	0	0	0	0
SU-12	RMD	F1E605	0	1	0	1	0	0	0	0	0	0	0	0	0	0
SU-12	RMD	F1H127	0	0	0	0	0	2	0	1	0	0	0	0	0	0
SU-12	RMD	F1V224	0	0	0	0	0	2	1	0	0	0	0	0	0	0
SU-12	RMD	F25316	0	0	0	0	0	0	0	1	0	0	0	0	0	0

USMC MF TBA by Division

CONFIG	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
SU-12	RMD	F28A36	0	1	0	0	0	0	0	0	0	0	0	0	0	0
SU-12	RMD	F2H127	0	0	0	0	0	0	0	0	0	0	2	0	0	0
SU-12	RMD	F2V224	0	0	0	0	0	0	1	0	0	0	0	0	0	0
SU-12	RMD	F30J12	1	0	0	1	0	0	0	0	0	1	0	0	0	0
SU-12	RMD	F35316	0	0	0	0	0	0	0	0	0	1	0	0	0	0
SU-12	RMD	F38A36	0	0	0	0	0	0	0	0	1	0	0	0	0	0
SU-12	RMD	F38C24	0	0	0	0	0	0	0	0	1	0	0	0	0	0
SU-12	RMD	F3H127	0	0	0	0	0	0	0	0	0	2	0	0	0	0
SU-12	RMD	F3V224	0	0	0	0	1	0	0	0	0	0	0	0	0	0
SU-12	RMD	F4H127	0	0	0	0	0	0	0	1	0	0	0	0	0	0
SU-12	RMD	F5H127	0	0	0	0	0	0	0	0	0	0	2	0	0	0
SU-12	CMD	118A36	1	0	0	0	0	0	0	0	0	0	0	0	0	0
SU-12	CMD	118C24	1	0	0	0	0	0	0	0	0	0	0	0	0	0
SU-12	CMD	130J12	1	0	0	1	0	0	0	0	0	1	0	0	0	0
SU-12	CMD	153E16	0	0	0	0	0	1	0	1	0	0	0	0	0	0
SU-12	CMD	1HML27	0	0	0	0	0	1	0	1	0	0	0	0	0	0
SU-12	CMD	1V2236	0	0	0	0	0	1	1	0	0	0	0	0	0	0
SU-12	CMD	1V8R14	0	1	0	1	0	0	0	0	0	0	0	0	0	0
SU-12	CMD	253E16	0	0	0	0	0	0	0	1	0	0	0	0	0	0
SU-12	CMD	2HML27	0	0	0	0	0	0	0	0	0	0	2	0	0	0
SU-12	CMD	2V2224	0	0	0	0	0	0	1	0	0	0	0	0	0	0
SU-12	CMD	318A36	0	0	0	0	0	0	0	0	2	0	0	0	0	0
SU-12	CMD	318C24	0	0	0	0	0	0	0	0	1	0	0	0	0	0
SU-12	CMD	353E16	0	0	0	0	1	0	0	0	0	0	0	0	0	0
SU-12	CMD	3HML27	0	0	0	0	0	0	0	0	0	0	2	0	0	0
SU-12	CMD	3V2212	0	0	0	0	1	0	0	0	0	0	0	0	0	0
SU-12	CMD	453E16	0	0	0	0	0	0	0	0	0	1	0	0	0	0
SU-12	CMD	4HML27	0	0	0	0	0	0	0	1	0	2	0	0	0	0
SU-12	CMD	553E16	0	0	0	0	1	0	0	0	0	0	0	0	0	0
SU-12	CMD	553EXX	0	0	0	0	1	0	0	0	0	0	0	0	0	0
SU-12	CMD	5HML27	0	0	0	0	0	0	0	0	0	0	2	0	0	0
SU-12	CMD	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	0	0	0
SU-12	CMD	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	3	0
SU-12	CMD	F15316	0	0	0	0	0	1	0	1	0	0	0	0	0	0
SU-12	CMD	F18R14	0	1	1	1	0	0	0	0	0	0	0	0	0	0
SU-12	CMD	F1H127	0	0	0	0	0	1	0	1	0	0	0	0	0	0
SU-12	CMD	F1V224	0	0	0	0	0	1	1	0	0	0	0	0	0	0
SU-12	CMD	F25316	0	0	0	0	0	0	0	1	0	0	0	0	0	0
SU-12	CMD	F2H127	0	0	0	0	0	0	0	0	0	0	1	0	0	0
SU-12	CMD	F2V224	0	0	0	0	0	0	1	0	0	0	0	0	0	0
SU-12	CMD	F30J12	1	0	0	1	0	0	0	0	0	1	0	0	0	0
SU-12	CMD	F35316	0	0	0	0	0	0	0	0	0	1	0	0	0	0
SU-12	CMD	F38A36	0	0	0	0	0	0	0	0	1	0	0	0	0	0

USMC MF TBA by Division

CONFIG	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
SU-12	CMD	F38C24	0	0	0	0	0	0	0	0	1	0	0	0	0	0
SU-12	CMD	F3H127	0	0	0	0	0	0	0	0	0	1	0	0	0	0
SU-12	CMD	F3V224	0	0	0	0	1	0	0	0	0	0	0	0	0	0
SU-12	CMD	F45316	0	0	0	0	1	0	0	0	0	0	0	0	0	0
SU-12	CMD	F4H127	0	0	0	0	0	0	0	1	0	0	0	0	0	0
SU-12	CMD	F5H127	0	0	0	0	0	0	0	0	0	0	1	0	0	0
** Subtotal **			47	38	27	55	55	55	39	60	37	60	74	2	17	0
** <u>ZZC</u> **																
EA-01	EAF	BEAFFW	1	1	1	2	0	0	0	0	1	0	0	0	0	0
EA-01	EAF	BEAFRW	0	0	0	0	1	0	1	1	0	1	1	0	0	0
EA-01	EAF	PALMXX	1	0	0	0	0	0	0	0	0	0	0	0	0	0
EA-02	EAF	BEAFFW	0	0	0	2	0	0	0	0	0	0	0	0	0	0
EA-02	EAF	BEAFRW	0	0	0	0	2	0	0	0	0	2	0	0	0	0
JU-01	EAF	BEAFFW	0	0	0	0	0	0	0	0	0	0	0	0	0	0
JU-01	EAF	BEAFRW	0	0	0	0	0	0	0	0	0	0	0	0	0	0
JU-01	EAF	PALMXX	1	0	0	0	0	0	0	0	0	0	0	0	0	0
JU-01	EAF	TV8B14	0	0	0	0	0	0	0	0	0	0	0	0	0	0
SU-03	EAF	BEAFFW	0	0	0	0	0	0	0	0	0	0	0	0	0	0
SU-03	EAF	BEAFRW	0	0	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			3	1	1	4	3	0	1	1	1	3	1	0	0	0
Total			343	265	201	344	245	212	219	245	244	210	281	168	192	64

USMC MF TBA Support Equipment by Configuration Code

DIV	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
** <u>ANCILLARY</u> **																
600	60C	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
600	60C	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
** Subtotal **			1	1	1	1	1	1	1	1	1	1	1	1	1	0
** <u>CDT</u> **																
600	60C	CCSPFW	2	2	2	2	0	0	0	0	2	0	0	2	0	0
600	60C	CCSPRW	0	0	0	0	2	2	2	2	0	2	2	0	2	0
600	60C	HMXXXX	0	0	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			2	2	2	2	2	2	2	2	2	2	2	2	2	0
** <u>E-TOOL</u> **																
600	60C	CCSPFW	3	3	3	3	0	0	0	0	3	0	0	3	0	0
600	60C	CCSPRW	0	0	0	0	3	2	3	3	0	3	3	0	3	0
MPS	BLI	4574H	0	0	0	0	0	0	0	0	0	0	0	0	0	2
** Subtotal **			3	3	3	3	3	2	3	3	3	3	3	3	3	2
** <u>LOAD BANK</u> **																
600	60C	CCSPFW	6	6	6	6	0	0	0	0	6	0	0	5	0	0
600	60C	CCSPRW	0	0	0	0	4	2	4	4	0	4	4	0	4	0
MPS	BLI	4574H	0	0	0	0	0	0	0	0	0	0	0	0	0	2
** Subtotal **			6	6	6	6	4	2	4	4	6	4	4	5	4	2
** <u>MEP-807A</u> **																
600	60C	CCSPFW	12	12	12	12	0	0	0	0	12	0	0	12	0	0
600	60C	CCSPRW	0	0	0	0	5	5	5	5	0	5	5	0	5	0
600	60C	PALMXX	1	0	0	0	0	0	0	0	0	0	0	0	0	0
MP2	BTN	2FERW	0	0	0	0	0	0	0	0	0	0	0	0	0	4
MP2	LPZ	2FEFW	0	0	0	0	0	0	0	0	0	0	0	0	0	3
MP2	SEY	2FERW	0	0	0	0	0	0	0	0	0	0	0	0	0	4
MP2	SSR	2FEFW	0	0	0	0	0	0	0	0	0	0	0	0	0	3
MP3	BBO	3FERW	0	0	0	0	0	0	0	0	0	0	0	0	0	4
MP3	DHL	3FEFW	0	0	0	0	0	0	0	0	0	0	0	0	0	3
MP3	LMS	3FEFW	0	0	0	0	0	0	0	0	0	0	0	0	0	3
MP3	PLU	3FERW	0	0	0	0	0	0	0	0	0	0	0	0	0	4
MPS	FLY	4574H	0	0	0	0	0	0	0	0	0	0	0	0	0	1
ZZB	WX	MACSXX	4	2	2	4	2	0	2	0	2	2	2	0	0	0
** Subtotal **			17	14	14	16	7	5	7	5	14	7	7	12	5	29
** <u>MEP-809A</u> **																
600	60C	CCSPFW	18	18	18	18	0	0	0	0	18	0	0	18	0	0
600	60C	CCSPRW	0	0	0	0	14	7	14	14	0	14	14	0	14	0
** Subtotal **			18	18	18	18	14	7	14	14	18	14	14	18	14	0
** <u>PW-BX</u> **																
600	60C	CCSPFW	5	5	5	5	0	0	0	0	5	0	0	3	0	0

14 MAR 2016

USMC MF TBA Support Equipment by Configuration Code

DIV	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
600	60C	CCSPRW	0	0	0	0	4	4	4	4	0	4	4	0	4	0
** Subtotal **			5	5	5	5	4	4	4	4	5	4	4	3	4	0
** <u>RECLAMATOR</u> **																
600	60C	CCSPFW	3	3	3	3	0	0	0	0	3	0	0	3	0	0
600	60C	CCSPRW	0	0	0	0	3	3	3	3	0	3	3	0	3	0
** Subtotal **			3	3	3	3	3	3	3	3	3	3	3	3	3	0
** <u>SMFC</u> **																
600	60C	CCSPFW	6	7	6	10	0	0	0	0	8	0	0	5	0	2
600	60C	CCSPRW	0	0	0	0	6	3	4	4	0	7	5	0	3	2
** Subtotal **			6	7	6	10	6	3	4	4	8	7	5	5	3	4
Total			61	59	58	64	44	29	42	40	60	45	43	52	39	37

Mobile Facility/Ancillary Equipment/Administrative Note
Cross Reference

CODE	CONFIGURATION
AB-02	AIRCREW BRIEF/DEBRIEF MF #1
AB-03	AIRCREW BRIEF/DEBRIEF MF #2
AM-01	IMRL MANAGEMENT
AT-08	SQUADRON GROUND SYSTEM
AT-09BM	ATARS POD MAINTENANCE
AT-10A	ATARS PALLET MAINTENANCE
AT-11	EQUIPMENT MAINTENANCE/ATC
AT-12	ADMINISTRATIVE SUPPORT/ATC
AV-01A	600 DIVISION AVO/AVC MF A
AV-02B	600 DIVISION AVO/AVC MF B
BL-01	BATTERY MAINTENANCE SUPPORT FACILITY (REPLACES LA-01 AND NB-03)
BR-01	BRU-33A MAINTENANCE
BR-04A	BRU-33 MF A MAINTENANCE
BR-05B	BRU-33 MF B MAINTENANCE
CA-01	ELECTRO-MECHANICAL
CA-04	PHYSICAL MECHANICAL CALIBRATION
CA-07A	OPTICAL/DIMENSIONAL CALIBRATION MF A
CA-08B	OPTICAL/DIMENSIONAL CALIBRATION MF B
CA-09	PHYSICAL DIMENSIONAL CALIBRATION
CL-01	"I" LEVEL CAL PHASES A, B, C, D
CL-02	"I" LEVEL CAL PHASES E, F
CL-04	TEST EQUIPMENT REPAIR
CL-06	CALIBRATION MANAGEMENT
CL-07	TEST EQUIPMENT STAGING
CL-09	AIMS/TACAN CALIBRATION
CL-10	PHYSICAL DIMENSIONAL CALIB
CR-03	MICRO MINIATURE REPAIR/ATC
CR-04	MICRO MINIATURE REPAIR
CS-02A	COMPOSITE REPAIR/METAL SHOP MF A
CS-03BM	COMPOSITE REPAIR/METAL SHOP MF B MODIFIED
CU-01	MANAGEMENT CONTROL
CY-01	COMMUNICATION SECURITY MAINTENANCE
DP-03	SUPPLY ADP MGMT CENTER
DP-18A	NTCSS
EA-01	EAF MECHANICAL
EA-02	EAF ELECTRICAL
EB-06	EA6B RFI POOL

Mobile Facility/Ancillary Equipment/Administrative Note
Cross Reference

CODE	CONFIGURATION
EB-07	EA6B ANTENNA, RF HEAD POOL
EB-08	EA6B RECEIVER, AWP/AWM
EB-09	EA6B TRANSMITTER, AWP/AWM
ED-01	AVIATION SUPPLY FISP (FUTURE)
FA-02A	SERVO CYLINDER T/S MF A
FA-03B	SERVO CYLINDER T/S MF B
FC-05	FOSAMS
FS-01	FLAMMABLE STORAGE
GC-01	GENERATOR CONTROL UNIT T/S
GM-02A	ORD REPAIR MF A
GM-03B	ORD REPAIR MF B
HC-01	HYDRAULIC COMPONENT ASSEMBLY
HC-02	HYDRAULIC COMPONENT DISASSEMBLY
HY-04A	HYDRAULIC TEST SET A/F27T-10 MF A
HY-05B	HYDRAULIC TEST SET A/F27T-10 MF B
HY-06C	MV-22 LANDING GEAR TEST FIXTURE
JU-01	INTEGRATION UNIT, STANDARD
JU-09	INTEGRATION UNIT, EA6B #1
JU-10	INTEGRATION UNIT, EA6B #2
JU-31	INU, F-18 BRIEF/DEBRIEF
JU-32	INU, F-18 TRAINING UNIT # 1
KA-18A	CASS RT TEST STATION (USMC)
KA-19A	CASS HI POWER SOMF A
KA-20B	CASS HI POWER SOMF B
KA-31	OTPS STORAGE, REAPLCED ALL PREVIOUS TPS SUPPORT CONFIGS
LA-01	LEAD ACID BATTERY (REPLACED BY BL-01)
MC-01	MAINT/PRODUCTION CONTROL
MM-01	MACHINE SHOP , GRINDER
MM-02	MACHINE SHOP, MILLING MACHINE
MM-03	MACHINE SHOP, LATHE
MM-04	MACHINE SHOP, DRILLING
NT-06	NON-DESTRUCT TEST
NT-07	XRAY PROCESSOR
NT-08	MAGNETIC PARTICLE MF
PM-01	COUNTERMEASURES CHAFF DISPENSER POD MAINT
PM-02	UNIVERSAL POD MAINTENANCE
PP-01	POWER PLANTS

Mobile Facility/Ancillary Equipment/Administrative Note
Cross Reference

CODE	CONFIGURATION
PP-03A	POWER PLANTS MF A
PP-04BM	POWER PLANTS MF B MODIFIED
PW-01	Power Washer/Aqueous parts washer
RR-02	OXYGEN REPAIR
RR-03	ABO ANNALYZER
RR-04A	OXYGEN TEST/REPAIR (RW) MFA
RR-05B	OXYGEN TEST/REPAIR (RW) MFB
SE-01	SURVIVAL EQUIPMENT #1
SE-02B	SURVIVAL EQUIPMENT #2
SE-03C	SURVIVAL EQUIPMENT #3
SE-04B	SURVIVAL EQUIPMENT #4
SH-06	A/C SURVIVABILITY EQUIPMENT
SM-04B	SHEET METAL SHOP 1 MF B
SM-05A	SHEET METAL SHOP 1 MF A
SM-06B	SHEET METAL SHOP 2 MF B
SM-07A	SHEET METAL SHOP 2 MF A
SP-04	NOAP (NAVAL OIL ANALYSIS PROGRAM) MF
ST-01	STANDARD MF
SU-01	AVIATION SUPPLY, SHELVES
SU-02	AVIATION SUPPLY, CABINETS
SU-03	AVIATION SUPPLY
SU-04	AVIATION SUPPLY, TECH EDIT
SU-05	AVIATION SUPPLY, SUPPORT CENTER
SU-08	AVIATION SUPPLY, SHIPPING/RECEIVING
SU-12	AVIATION SUPPLY, BULK STORAGE
SW-02	NITROGEN RECEIVER FILL/REPAIR
TB-01	TUBE BENDER MF (REPLACED BY TB-03A/04B IN F/W MALS)
TB-02	MV-22 TUBE BENDER MF
TB-03A	TUBE BENDERS (5FT), CVN/MALS MF A
TB-04B	TUBE BENDERS (5FT), CVN/MALS MF B
TL-01	TECH LIBRARY
TR-01	TOOL ROOM
TT-02	TURRET TEST SUPPORT
TT-03A	TURRET TEST MF A
TT-04B	TURRET TEST MF B
TW-05A	ACFT TIRE/WHEEL BUILD-UP MF A
TW-06B	ACFT TIRE/WHEEL BUILD-UP MF B

Mobile Facility/Ancillary Equipment/Administrative Note
Cross Reference

CODE	CONFIGURATION
VD-05A	ACFT ENGINE COMPONENT TEST STAND (RW)
VD-06B	ACFT ENGINE COMPONENT TEST STAND (RW)
VD-07A	ACFT ENGINE COMPONENT TEST STAND (FW)
VD-08B	ACFT ENGINE COMPONENT TEST STAND (FW)
WC-02	QUALITY ASSURANCE
WC-08	SUPPORT EQUIPMENT MAINT
WC-12A	WORK CENTER 60C MF A
WC-13BM	WORK CENTER 60C MF B-MOD
WJ-06	METROLOGY MF
WL-04A	WELDING SHOP MF A
WL-05A	WELDING SHOP MF B
WR-01	WIRE REPAIR
ANCILLARY	ANCILLARY MF
CDT	COMPLEXING/DECOMPLEXING TOOL
E-TOOL	TACTICAL QUIET GENERATOR TROUBLESHOOTING COMPUTER
LOAD BANK	RESISTIVE LOAD BANK, LPH200
MEP-807A	GENERATOR, TACTICAL QUIET 100KW
MEP-809A	GENERATOR, TACTICAL QUIET 200KW
SMFC	STATIC MOBILE FREQUENCY CONVERTER
PW-BX	POWER DISTRIBUTION BOX& ASSOCIATED ANCILLARY EQUIPMENT
RECLAMATOR	REFRIGERANT RECOVERY/RECYCLING UNIT

Mobile Facility/Ancillary Equipment/Administrative Note
Cross Reference

NAME	DESCRIPTION
118A12	12 A/C F/A-18A PCSP
118A36	36 A/C F/A-18A PCSP
118C24	24 A/C F/A-18C PCSP
130J12	12 A/C KC-130J PCSP
130T12	12 A/C KC-130T PCSP
135B16	16 A/C F-35B PCSP
146E12	12 A/C CH-46E PCSP
146E36	36 A/C CH-46E PCSP
153E16	16 A/C CH-53E PCSP
1E6B05	5 A/C EA-6B PCSP
1HML09	9 A/C H-1 PCSP 4 TH MAW
1HML27	27 A/C 9 UH-1N/18 AH-1W PCSP
1RS46E	X A/C CH-46E PCSP 4 TH MAW
1RS53E	X A/C CH-53E PCSP 4 TH MAW
1V2236	36 A/C V-22 PCSP
1V8R14	14 A/C AV-8B PCSP
2130J2	XX A/C KC-130J PCSP
218A12	12 A/C F/A-18A PCSP (2ND PKG ON SITE)
218A36	36 A/C F/A-18A PCSP (2ND PKG ON SITE)
218C12	12 A/C F/A-18C PCSP (2ND PKG ON SITE)
218D12	12 A/C F/A-18D PCSP (2ND PKG ON SITE)
235C10	10 A/C F-35C PCSP (2ND PKG ON SITE)
222B12	12 A/C V-22B PCSP (2ND PKG ON SITE)
253E08	8 A/C CH-53E PCSP (2ND PKG ON SITE)
246E36	36 A/C CH-46E PCSP (2ND PKG ON SITE)
253D10	10 A/C CH-53D PCSP (2ND PKG ON SITE)
253E16	16 A/C CH-53E PCSP (2ND PKG ON SITE)
2E6B05	5 A/C EA-6B PCSP (2ND PKG ON SITE)
2FEFW	F/W CSP (2ND PKG ON SITE)
2FERW	R/W CSP (2ND PKG ON SITE)
2H53E8	8 A/C CH-53E PCSP (2ND PKG ON SITE)
2HML09	9 A/C H-1 PCSP 4 TH MAW (2ND PKG ON SITE)
2HML9A	9 A/C H-1 PCSP 4 TH MAW (2ND PKG ON SITE)
2HML9B	9 A/C H-1 PCSP 4 TH MAW (2ND PKG ON SITE)
2HML9C	9 A/C H-1 PCSP 4 TH MAW (2ND PKG ON SITE)
2HML27	27 A/C 9 UH-1N/18 AH-1W PCSP (2ND PKG ON SITE)

Mobile Facility/Ancillary Equipment/Administrative Note
Cross Reference

NAME	DESCRIPTION
2M2212	12 A/C MV-22 PCSP (2ND PKG ON SITE)
2RS46E	X A/C CH-46E PCSP 4 TH MAW (2ND PKG ON SITE)
2V2212	12 A/C MV-22 PCSP (2ND PKG ON SITE)
2V2224	24 A/C V-22 PCSP (2ND PKG ON SITE)
2V8B05	5 A/C AV-8B PCSP (2ND PKG ON SITE)
2V8B09	9 A/C AV-8B PCSP (2ND PKG ON SITE)
2V8R14	14 A/C AV-8B PCSP (2ND PKG ON SITE)
318A12	12 A/C F/A-18A PCSP (3RD PKG ON SITE)
318A36	36 A/C F/A-18A PCSP (3RD PKG ON SITE)
318C12	12 A/C F/A-18C PCSP (3RD PKG ON SITE)
318C24	24 A/C F/A-18C PCSP (3RD PKG ON SITE)
318D12	12 A/C F/A-18D PCSP (3RD PKG ON SITE)
322B12	12 A/C MV-22B PCSP (3RD PKG ON SITE)
330J15	5 A/C C-130J PCSP (3RD PKG ON SITE)
335B10	10 A/C F-35B PCSP (3RD PKG ON SITE)
346E24	24 A/C CH-46E PCSP (3RD PKG ON SITE)
353E08	8 A/C CH-53E PCSP (3RD PKG ON SITE)
353E16	16 A/C CH-53E PCSP (3RD PKG ON SITE)
3E6B05	5 A/C EA-6B PCSP (3RD PKG ON SITE)
3FEFW	F/W CSP (3RD PKG ON SITE)
3FERW	R/W CSP (3RD PKG ON SITE)
3H53E8	8 A/C CH-53E PCSP (3RD PKG ON SITE)
3HML9A	XX UH-1N/18 AH-1W PCSP (3RD PKG ON SITE)
3HML9B	XX UH-1N/18 AH-1W PCSP (3RD PKG ON SITE)
3HML9C	XX UH-1N/18 AH-1W PCSP (3RD PKG ON SITE)
3HML27	27 A/C 9 UH-1N/18 AH-1W PCSP (3RD PKG ON SITE)
3M2212	12 A/C MV-22 PCSP (3RD PKG ON SITE)
3V2212	12 A/C V-22 PCSP (3RD PKG ON SITE)
3V8B05	5 A/C AV-8B PCSP (3RD PKG ON SITE)
3V8B09	9 A/C AV-8B PCSP (3RD PKG ON SITE)
3V8R14	14 A/C AV-8B PCSP (3RD PKG ON SITE)
435B16	16 A/C F-35B PCSP (4TH PKG ON SITE)
446E24	24 A/C CH-46E PCSP (4TH PKG ON SITE)
453E16	16 A/C CH-53D PCSP (4TH PKG ON SITE)
4574H	(4TH PKG ON SITE)
4HML27	27 A/C H-1 PCSP 4 TH MAW (4TH PKG ON SITE)
535B16	16 A/C F-35B PCSP (5TH PKG ON SITE)

Mobile Facility/Ancillary Equipment/Administrative Note
Cross Reference

NAME	DESCRIPTION
553E16	16 A/C CH-53E PCSP (5TH PKG ON SITE)
553EXX	XX A/C CH-53E PCSP (5TH PKG ON SITE)
5HML27	27 A/C H-1 PCSP (5TH PKG ON SITE)
BEAFFW	EAF F/W PCSP
BEAFRW	EAF R/W PCSP
CCSPFW	COMMON CSP FOR A FIXED WING MALS
CCSPRW	COMMON CSP FOR A ROTARY WING MALS
EAF	EXPEDITIONARY AIR FIELD
F15316	FISP, 16 A/C CH-53E
F18A36	FISP, 36 A/C F/A-18A
F18C24	FISP, 24 A/C F/A-18C
F18R14	FISP, 14 A/C AV-8B
F1E605	FISP, 5 A/C EA-6B
F1H127	FISP, 27 A/C 9 UH-1N/18 AH-1W
F1V224	FISP, 24 A/C MV-22
F25316	FISP, 16 A/C CH-53E (2ND PKG ON SITE)
F28A36	FISP, 36 A/C F/A-18A (2ND PKG ON SITE)
F28R14	FISP, 14 A/C AV-8B (2ND PKG ON SITE)
F2E605	FISP, 5 A/C EA-6B (2ND PKG ON SITE)
F2H127	FISP, 27 A/C 9 UH-1N/18 AH-1W (2ND PKG ON SITE)
F2V224	FISP, 24 A/C MV-22 (2ND PKG ON SITE)
F30J12	FISP, 12 A/C KC-130J (3RD PKG ON SITE)
F34624	FISP, 24 A/C CH-46E (3RD PKG ON SITE)
F35316	FISP, 16 A/C CH-53E (3RD PKG ON SITE)
F38A36	FISP, 36 A/C F/A-18A (3RD PKG ON SITE)
F38C24	FISP, 24 A/C F/A-18C (3RD PKG ON SITE)
F3E605	FISP, 5 A/C EA-6B (3RD PKG ON SITE)
F3H127	FISP, 27 A/C 9 UH-1N/18 AH-1W (3RD PKG ON SITE)
F3V224	FISP, 24 A/C MV-22 (3RD PKG ON SITE)
F44624	FISP, 24 A/C CH-46E (3RD PKG ON SITE)
F45316	FISP, 16 A/C CH-53E (3RD PKG ON SITE)
F46FSP	FISP, XX A/C CH-46E (4TH PKG ON SITE)
F4H127	FISP, 27 A/C 9 UH-1N/18 AH-1W (4TH PKG ON SITE)
F54636	FISP, 36 A/C CH-46E (5TH PKG ON SITE)
F55316	FISP, 16 A/C CH-53E (5TH PKG ON SITE)
F5H127	FISP, 27 A/C 9 UH-1N/18 AH-1W (5TH PKG ON SITE)
IOSPXX	FOLLOW-ON SUPPORT IDENTIFIED BY ACTIVITY I.E. FOSP11, FOSP12,

Mobile Facility/Ancillary Equipment/Administrative Note
Cross Reference

NAME	DESCRIPTION
	FOSP13, ETC.
T53E29	TRAINING CH53E MALS 29
TF3531	TRAINING SQUADRON ALLOWANCE A/C F-35 MALS 31
TFRS11	TRAINING SQUADRON ALLOWANCE FRS MALS 11
TFRS39	TRAINING SQUADRON ALLOWANCE FRS MALS 39
TH1M39	TRAINING SQUADRON ALLOWANCE A/C UH-1N/18 AH-1W MALS 39
TV2226	TRAINING SQUADRON ALLOWANCE A/C MV-22B MALS 26
TV8B14	TRAINING SQUADRON ALLOWANCE A/C AV-8B MALS 14
MACSXX	MARINE AIR CONTROL SQUADRON
PALMXX	EAF, AGSE 29 PALM
SCIFXX	IDENTIFIES EQUIPMENT ADMINISTRATIVELY CONTROLLED BY THE INDICATED ACTIVITY BUT OPERATIONALLY CONTROLLED BY CMC
WGISSX	INTERIM SUPPORT ALLOWANCE (ISAL)

ADMINISTRATIVE NOTES

(A) Whenever the integration units are calculated within a package, the allowance is 1 JU-01 per 6 MFs rated. If there are any additional MFs after the quantity is determined, an additional asset will be authorized when 4 units are rated. Example: If you have 10 MFs authorized you will be authorized 2 JU-01's or equivalent.

(B) The SU-12 is replacing the TL-01 and TR-01 configurations by attrition. Units can utilize their own equipment to configure the SU-12 to meet a tool room or tech library configuration.

Sample MF User O-Level Maintenance Syllabus

Name _____ Rank _____ W/C / MOS _____

The following training is required for all personnel performing maintenance actions and quality assurance inspections on MFs (i.e. EAF, Weather and MCAS) that have mobile facility allocations in accordance with (IAW) enclosure (6) of MCO 13670.1E. The Mobile Facility Coordinator (MFC) shall maintain a copy of this training track in W/C 60C for all trained personnel currently assigned to the MALS or a unit that receives MF support from the MALS (i.e., EAF, Weather, and MACS) that do not have an active ASM account.

Periodic Maintenance (PM) Training

Training will be conducted by a W/C 60C CDI on proper procedures for completion of the MF and ECU PM. During this training, the work will be conducted by the MF user with the W/C 60C CDI providing instruction. Training will be hands on training using a MF and NAVAIR-19-600-152-6-2 or NAVAIR 19-600-141-6-2 as a training aid.

7	Day MF PM	MCN _____	Date _____	CDI _____
30	Day MF PM	MCN _____	Date _____	CDI _____
90	Day MF PM	MCN _____	Date _____	CDI _____
180	Day MF PM	MCN _____	Date _____	CDI _____
360	Day MF PM	MCN _____	Date _____	CDI _____
90	Day ECU PM	MCN _____	Date _____	CDI _____
360	Day ECU PM	MCN _____	Date _____	CDI _____

Periodic Maintenance Performance

The MF user will perform the MF PM without W/C 60C instruction. The W/C 60C CDI will ensure proper performance of PM upon completion.

7	Day MF PM	MCN _____	Date _____	CDI _____
30	Day MF PM	MCN _____	Date _____	CDI _____
90	Day MF PM	MCN _____	Date _____	CDI _____
180	Day MF PM	MCN _____	Date _____	CDI _____
360	Day MF PM	MCN _____	Date _____	CDI _____
90	Day ECU PM	MCN _____	Date _____	CDI _____
360	Day ECU PM	MCN _____	Date _____	CDI _____

MF User O-Level Maintenance Qualification

Name _____ Rank _____ W/C / MOS _____

Corrosion Prevention/Treatment

Corrosion prevention/treatment training will be provided to the MF user by a W/C 60C CDI. This training will stress the importance of *PROPER* corrosion prevention and treatment of the MF. Forklift pockets, rivets, emergency exit thumbscrews, and the seams between MF structural beams and MF walls will be given special attention during this training as these areas are most susceptible to a corrosive failure. Training will be hands on training using a MF as a training aid.

Date Training Provided _____

Training Provided By _____

Convention for Safe Container (CSC) Introduction

The MF user will receive an introduction to the CSC program from a certified CSC inspector. This training will familiarize the MF user with the purpose of the CSC program as well as common CSC failures that occur with MFs. The MF user should be able to identify structural issues that could result in failing the CSC inspection and identify these issues to W/C 60C. This introduction will not be a substitute for the AMMO-43 Intermodal Dry Cargo Container/CSC Re-inspection Course and will not certify the MF user as a CSC inspector. Training will be hands on training using a MF and MIL-HDBK-138B as a training aid.

Date Training Provided _____

Training Provided By _____

Mobile Facility Preparation for Shipping

To prevent damage to the MF and contents during shipment, MF users will receive training from a W/C 60C CDI on the proper way to prepare a MF for shipping. This training will be hands on training using a MF and the AG-360-IIN-000 as a training aid.

Date Training Provided _____

Training Provided By _____