



DEPARTMENT OF THE NAVY
HEADQUARTERS UNITED STATES MARINE CORPS
3000 MARINE CORPS PENTAGON
WASHINGTON DC 20350-3000

MCO 13670.1G
ASL
21 MAY 2018

MARINE CORPS ORDER 13670.1G

From: Commandant of the Marine Corps
To: Distribution List

Subj: MANAGEMENT AND ADMINISTRATION OF UNITED STATES MARINE
CORPS MOBILE FACILITY (MF) PROGRAM AND RELATED EQUIPMENT

Ref: (a) DTR 4500.9-R, "Defense Transportation Regulations,"
May 2014
(b) MIL-STD-3037
(c) COMNAVAIRFORINST 4790.2C
(d) MCTP 3-20A
(e) NAVAIRINST 13670.1C
(f) NAVAIR 17-1-125
(g) NAVAIR 19-25-177
(h) AG-360MF-IIN-000
(i) AG-360MF-CCD-000
(j) SECNAV M-5210.1
(k) 5 U.S.C. 552a
(l) SECNAVINST 5211.5E
(m) MCO 3000.13A
(n) CNAP/CNAL 13650.3

Encl: (1) Mobile Facility Deployment Readiness Code Matrix
(2) USMC MF TBA by Configuration Code
(3) USMC MF TBA by Contingency Support Package
(4) USMC MF TBA by Division
(5) USMC MF TBA Support Equipment by Configuration Code
(6) Mobile Facility/Ancillary Equipment/Administrative
Note Cross Reference
(7) MF User O-Level Maintenance Syllabus
(8) Sample MF Program Manager Appointment Letter

1. Situation. To promulgate policies, procedures, and guidance regarding the management and administration of Mobile Facilities (MFs) and related equipment assigned to United States Marine Corps (USMC) commands.

2. Cancellation. MCO 13670.1F.

DISTRIBUTION STATEMENT A: Approved for public release;
distribution is unlimited.

3. Mission. To provide Marine Corps Forces with deployable and environmentally controlled shelters for aircraft logistic support in tactical and garrison environments. All MFs and ancillary equipment will be managed, utilized and maintained in accordance with references (a) through (n) and policies set forth in this order. Successful execution of this program relies heavily on proper management at all levels, but mission accomplishment requires appropriate actions at the user levels.

4. Execution

a. Commander's Intent and Concept of Operations

(1) Commander's Intent. Ensure the readiness of all MFs and ancillary equipment by providing support and sustainment in accordance with established policies and procedures.

(2) Concept of Operations. This program must be conducted on multiple levels.

(a) Headquarters Marine Corps (HQMC). The Aviation Support Logistics Avionics section (ASL-34) provides oversight and guidance to subordinate elements. ASL-34 also acts as the liaison and establishes the MF program requirements, on behalf of the Deputy Commandant of Aviation (DC AVN), to the U.S. Navy Naval Air Systems Command (NAVAIR) MF Program Manager.

(b) Marine Forces (MARFORs). The MARFOR Aviation Logistics Division (ALD) Avionics section provides oversight and guidance to subordinate elements. The MARFOR also acts as the liaison for subordinate units to HQMC (ASL-34) and the NAVAIR MF Program Manager.

(c) Marine Aircraft Wing (MAW). The MAW ALD Avionics Branch manages all MFs and ancillary equipment and coordinates the distribution of MF assets between higher and lower echelons.

(d) Marine Aviation Logistics Squadron (MALS). The MALS Avionics Officer (AVO) is responsible for the day-to-day operation, deployment readiness reporting, and maintenance and management of all MF assets within the Marine Aircraft Group (MAG), to include supported units, such as Marine Wing Support Squadron (MWSS) and the Marine Air Control Squadron (MACS).

(e) Supported Units/Training Commands. The Commanding Officer/Officer-in-Charge (CO/OIC) of supported units

using MF assets, must work in concert with the MALS AVO to ensure the successful execution of the MF program.

b. Subordinate Element Missions

(1) Headquarters Marine Corps (HQMC) Aviation Logistics Squadron (ASL)

(a) Responsible for the management and the coordination of the U.S. Marine Corps MF program.

(b) Serve as the Table of Basic Allowance (TBA) program sponsor who publishes the MFs and associated ancillary equipment requirements in support of Marine Corps Aviation.

(c) Collaborate with the MARFORs and the NAVAIR MF Program Office for production priorities, MF TBA requirements, and incorporation. Continual review of the TBA will address any updates. The Mobile Facility Tool (MFTool) will provide a realtime reflection of the current TBA requirement. Changes for the next Marine Corps Order/TBA revision will be due by 30 September annually.

(2) Marine Forces (MARFORs)

(a) Responsible for the management and the coordination of the MARFOR MF program in accordance with references (a) through (n) and policies set forth in this Order.

(b) Assign, in writing, the MARFOR MF Coordinator (MFC).

(c) Require the MARFOR MFC to be a certified International Convention for Safe Containers (CSC) inspector.

(d) Publish an MF inspection schedule via naval message to ensure the MAW MF Program is inspected by the MARFOR MFC biennially using the current Computerized Self Evaluation (CSEC) checklist, Department of Defense Readiness Reporting System Marine Corps (DRRS-MC), and MFTool reports.

(e) Forward biennial inspection results in naval message format to Commandant of the Marine Corps (CMC AVN ASL WASHINGTON DC).

(f) Maintain file copies of the MF biennial inspection for a minimum of two years per reference (j).

(g) Upon MF survey approval, monitor MF disposition in accordance with this Order.

(h) Deliver consolidated TBA inputs and production prioritization in email format to ASL-34B annually NLT 1 March. Coordinate with the other MARFORs to establish requirements and production priorities prior to final submission to ASL-34B.

(3) Marine Aircraft Wing (MAW)

(a) Responsible for the management and coordination of the MF program in accordance with references (a) through (n) and policies set forth in this Order.

(b) Assign, in writing, a MAW MFC. The MAW MFC shall provide training and oversight to the MALS MFC during T-AVB exercises.

(c) Ensure that the MAW MFC is a certified CSC inspector.

(d) Ensure the best possible MF deployable posture is maintained using assets within the MAW, through close coordination with MARFOR Aviation Logistics Department, Avionics (ALD-E) and strict adherence to the CSC program.

(e) Ensure timely and accurate submission of MF reports as required.

(f) Ensure that the MAW MFC accompanies the MARFOR MFC during the biennial MARFOR inspection of the MAW.

(g) Ensure that the MALS programs are inspected by the MAW MFC annually using the current CSEC checklist. On biennial years where MARFOR inspects the MALS, the MAW MFC is only responsible to perform a follow-up inspection on those discrepancy areas noted during the MARFOR inspection. Inspection results shall be forward DC AVN (CMC AVN ASL WASHINGTON DC) in naval message format via the MARFOR.

(h) Inform MARFOR ALD-E of changes in status of MF program equipment as they occur.

(i) Maintain file copies of the MF annual inspection for a minimum of two years per reference (j).

(j) Upon MF survey approval, ensure MF is disposed of per this Order.

(k) Review MF readiness via DRRS and MFTool on a monthly basis.

(4) Marine Aviation Logistics Squadron (MALS)

(a) Manage the local MF program, to include all divisions within MALS, deployed and deploying units, and other supported units with MF requirements, in accordance with references (a) through (n) and policies set forth in this Order.

(b) Assign, in writing work center (W/C) 60C Staff Non-Commissioned Officer-in-Charge (SNCOIC) as the MALS MFC.

(c) Ensure the MALS MFC holds the 6499 Military Occupational Specialty (MOS) and is a certified CSC inspector.

(d) Ensure the MALS MFC conducts periodic (quarterly) site visits to supported units to assist in management of the MF program.

(e) Ensure the best possible MF deployable posture through close coordination with the MAW MFC and strict adherence to the CSC program.

(f) Ensure that at least four members of the unit are certified CSC reinspectors and all CSC reinspectors are designated by the AVO via the MFC. Newly qualified 6499 Marines who receive initial CSC training at the school house will need to demonstrate to the MFC and Chain of Command proficiency and competence in the execution of CSC reinspection as per reference (b). Once this rapport has been established, the MFC may recommend locally the Marine be qualified through online AMMO-43-DL CSC Container Re-inspection course and designated as a CSC inspector.

(g) Ensure the established training tracks are being utilized to qualify user (i.e., department, division and section) personnel in MF Organizational Level (O-Level) maintenance in accordance with enclosure (7). Selected user personnel shall be trained to the level necessary to perform collateral duty inspections (i.e., scheduled maintenance and corrosion control). This training will be documented in the Collateral Duty Inspector (CDI) syllabus and miscellaneous sections, respectively, of the individual's training record.

Training will be conducted by W/C 60C CDIs. The MALS MFC shall retain training records for personnel that do not have active Advanced Skills Management (ASM) accounts.

(h) Ensure that Logbook and Inventory Records (LIRs) or electronic LIR (E-LIR) and OPNAV 4790/51, "Support Equipment Custody and Maintenance History Record" are maintained by the Aircraft Maintenance Administration Specialist (6046) Marine in W/C 60C in accordance with references (c) and (j).

(i) Ensure program audits on W/C 60C are conducted as required by reference (c).

(j) Ensure receipt and transfer messages that are required by this Order are prepared and submitted in accordance with reference (c). Receipt and transfer messages shall be maintained for a minimum of one year per reference (j).

(k) Maintain file copies of the MF annual inventory for a minimum of two years per reference (j).

(l) Submit MF disposition/survey requests in accordance with reference (c), as required. Upon survey approval, prepare MF for disposal per this Order. MF disposition/survey approvals shall be maintained for a minimum of two years per reference (j).

(m) AVO and MFC shall coordinate with the squadron's Operations Officer and report MF readiness (MF organic, non-Individual Material Readiness List (IMRL) items) utilizing DRRS-MC per reference (m). Additionally, report MF, IMRL, and associated ancillary gear status via MFTool utilizing the code matrix provided in enclosure (1) on a continuous basis.

(5) Supported Units Commanding Officer/Officer-in-Charge (CO/OIC)

(a) Assign, in writing, a Mobile Facilities Program Manager (MFPM). An example assignment letter is provided in enclosure (8).

1. The MFPM will be directly responsible to the CO/OIC for implementation, coordination, and management of the unit's MF program in accordance with references (a) through (n) and policies set forth in this Order.

2. The MFPM will be the liaison between their unit and the MALS MFC providing I-Level support.

(b) Ensure that the MFPM accompanies the supporting MALS MFC during site visits.

(c) Ensure the best possible MF deployable posture through close coordination with the MALS MFC and strict adherence to the CSC program.

(d) Ensure that the CSC inspections are kept current on all active MFs. The supporting MALS CSC inspector will be used for CSC program required re-inspections.

(e) Enforce a comprehensive MF maintenance program, per applicable references and this Order, to provide maximum support with an emphasis on readiness. This will be accomplished by performing all user-related maintenance actions and by coordinating with the supporting MALS W/C 60C for those repair actions requiring support.

(f) Ensure that a minimum of two personnel per section are trained to a level necessary to perform limited MF QA inspections (e.g., scheduled maintenance and corrosion control). The supporting MALS W/C 60C will provide the training necessary to qualify user personnel in MF O-Level maintenance. For non-maintenance sections / W/Cs (e.g., Production Control, IMRL, ALIMs, and Supply) W/C 60C will coordinate with QA to assign a production W/C representative to perform the CDI function of each maintenance action, (e.g., W/C 51A CDIs will perform the CDI function for the Hazardous Materials W/C).

(g) Maintain a current MFTool inventory database of all MF equipment supported by the MALS.

(h) Report all MF movement, inventory, readiness and updates to the supporting MALS MFC.

c. Coordinating Instructions

(1) Mobile Facilities Coordinator (MFC). The MFC at the MAW and MALS level shall be a Staff Noncommissioned Officer that holds the 6499 MOS. The MFC shall maintain a copy of this Order and be familiar and comply with references (a) through (n) and policies set forth in this Order. The MFC shall ensure that the subject line of all naval messages regarding MF program equipment begins with "SE-4 MOBILE FACILITY (MF)."

(2) International Convention for Safe Containers (CSC). MFs are military dry cargo intermodal containers constructed to International Organization for Standardization (ISO) standards and support multiple modes of handling and transportation. MFs are required to meet ISO container and international shipping standards. All active MFs must comply with international regulations governing intermodal dry cargo containers. MFs, therefore, require certification under the CSC Program.

(a) Every active MF is required to have a CSC inspection data plate permanently attached. The data plate will display the next CSC inspection due date.

(b) Inspections are conducted in accordance with reference (b).

(c) MFs that fail a CSC inspection or whose CSC inspection due date has lapsed will be considered a CSC failure and are, therefore, non-deployable until such time that the material condition of the MF has been restored to a passing condition and/or re-certified.

(d) CSC Inspectors can be initially certified and recertified by completing the AMMO-43-DL CSC Container Re-inspection Course. available at link: <https://www.nko.navy.mil>; click Navy eLearning link; search Navy Training Course Catalog. Each CSC Inspector shall maintain a copy of their AMMO-43-DL course completion certificate within the MALS MFC turnover jacket.

(3) Movement Control. The term movement applies to deployments, transfers, and temporary loans. Movement control is a high impact issue because it has a direct effect on inventory control. All movement must be approved prior to execution and must be reported to the MF Program Office via naval message, citing the approval authority, to facilitate inventory control. As with all matters pertaining to MFs and ancillary equipment, movement must be coordinated through the MALS MFC.

(a) Intra-MAW movement must be approved by MAW ALD Avionics. Intra-MAW movement is defined as any movement where the MF/equipment will remain in the custody of a MALS, or supported unit, assigned to MAW.

(b) Any movement of MFs and/or ancillary equipment outside Continental United States (with the exceptions of intra-

MAW movement within 1ST MAW, and the Marine Expeditionary Unit Aviation Combat Element (ACE) onboard ship) must be approved by the MARFOR.

(c) Inter-MAW movement, when the MF/equipment will be in the physical custody of a unit not within the MAW, must be approved by the MARFOR.

(d) Movement of MFs housing hard-mounted IMRL equipment outside of the parent MALS must be approved by the IMRL Type Commander (TYCOM) Commander, Naval Air Forces/Commander, Navy Air Force Reserve as well as the appropriate MF authority.

(e) Prior to movement, the MFs must be prepared in accordance with reference (h) and inspected in accordance with reference (b). MF must have a minimum of six months remaining on the CSC inspection due date at the time of shipment or transfer. A conditional inspection will be performed prior to shipment and annotated on the Naval message to ensure the MF is still within CSC standards.

(f) No MF will be transferred with equipment shortages unless approved by the MARFOR. All shortages will be annotated on the transfer naval message and in the LIR or E-LIR.

(g) Authorized modes of transportation are: air-ride truck, ship, or air (when operational considerations require urgent delivery). Rail transportation is not authorized. Note: Air louvers must be opened during air transport to prevent over-pressurization of MFs.

(h) All documentation of movement controls will be maintained per reference (j) as appropriate.

(i) Execute the transfer of all MFs or MF SE within 60 days of receiving authorization from the MAW, MARFOR or MFPO.

(4) Inventory Control. A current inventory of all assigned MF program equipment will be maintained by the MFC using the MFTool database. This format will be used to submit the annual inventory report. Each MALS inventory will include all MF program equipment used by supported units (MWSS, ATC, etc).

(a) Report any changes to the MF inventory database, as they occur, to the next higher echelon.

(b) As MFs are received, they will be assigned to a specific Contingency Support Package, Division, W/C / Branch based on the Configuration Code, needs of the unit, and consideration for older MFs that have reached their service life. To assist in this task, utilize the MF TBA, enclosure (2). Utilize transfer/acceptance checklist located in reference (c).

(c) All receipts and transfers of MFs or ancillary equipment will be reported via naval message within 24 hours of transfer and four working days from receipt.

(d) Receipt, transfer and disposition/survey messages, and inventories, for all MF TBA equipment will be submitted by the supporting MALS to the MF Program Office via the respective chain of command.

(e) MF transactions, such as receipts, transfers, rework, and surveys, will be annotated in the "REMARKS" column of the inventory report by entering the date-time-group (DTG) and the originating activity of the message directing the action.

(f) Units or organizations that do not have a defined MF requirement contained within enclosures (2) through (5) or Type/Model/Series Weapons System Planning Document will not be assigned MFs, unless specifically authorized by DC AVN (ASL-34).

(g) Units that possess MFs within their inventory that are no longer authorized due to TBA requirements change must request disposition via the MAW and MARFOR.

(h) Maximum effort shall be made to utilize the Tactical Quiet Generator (TQG) storage facility on Marine Corps Base Albany in an effort to reduce fleet maintenance and increase TQG readiness. A minimum amount of TQGs should be retained for training purposes at each MALS. Each MARFOR should determine the appropriate quantity of TQGs required at each MALS to accommodate this training.

(i) MARFOR and MAW MFCs will verify the accuracy of each unit's readiness, utilizing MFTool and DRRS, during their annual/biennial inspections.

(5) Maintenance. Maintenance concepts and maintenance management systems for MF program ancillary equipment (e.g.,

TQGs, Load Banks, Power Distribution Boxes, and all other SE in support of the MF) are the same as delineated in reference (c) for Support Equipment. MFs and related equipment, in use or in storage, will be maintained in a state of operational readiness, in accordance with references (c), (f) and (g) and as further defined within this Order. The MF container itself is a facility and not Support Equipment. Any similarities with the Support Equipment program are in an effort to properly manage inventory and readiness. All scheduled maintenance pertaining to MFs and all CNAF 4790/51 records shall be maintained utilizing reference (c).

(a) O-Level maintenance will be performed by the MF user (i.e., sections and W/Cs to which the MFs were assigned according to the TBA). O-Level maintenance involves conducting the Preventive Maintenance (PM) Inspections on the Environmental Control Unit (ECU) and MF, keeping the ECU filters clean and unobstructed, keeping the inside and outside of MFs clean, changing light bulbs, keeping hinges lubricated and corrosion free, touch up painting, corrosion control and surface corrosion repair. There is no special qualification required for touch up painting on a MF. Use of power tools are authorized locally by the MFC as deemed necessary in the performance of O-Level corrosion control. The SNCOIC of W/C 60C will determine if severe levels of corrosion requiring the use of power tools will be classified as O-Level or I-Level maintenance. The NCOIC of W/C 60C has the final determination on the level of repair for any issue in question.

(b) The term I-Level within the MF program refers to that level of maintenance performed by the MALS W/C 60C. I-Level involves all maintenance, beyond that of the O-Level, necessary to return an MF or ECU to ready-for-use (RFU) condition, to include the incorporation of applicable Technical Directives (TDs) and maintenance beyond touch up painting. There is no special qualification, beyond the basic 6499 MOS graduation, required to paint a MF and all painting will be performed as outlined in reference (g). I-Level maintenance is provided by the supporting MALS for all supported users.

(c) W/C 60C is responsible for all maintenance requirements, to include TDs, corrosion control and surface corrosion repair on the MF program ancillary equipment, (e.g., Complexing/Decomplexing Tools (CDTs), generators, frequency converters, and scaffolding).

(d) ECU access panels and doors, if removed while complexed, will be stored in an area protected from the elements. A remark will be annotated in the LIR/E-LIR shortages section as to the whereabouts of the removed items, and they will be serialized to the MF they belong to in a manner which is easily removable. Side opening MF panels will be properly stored in accordance with reference (g) in a manner that will not cause damage to the panel. CDTs and generators (not required for periodic use) shall be preserved and properly stored when not in use.

(e) In garrison, MF generators and associated equipment, that are not in a state of preservation will be operated at a minimum one hour per month, or as local regulations permit, to prevent generator down time and provide operator training.

(f) MF generator/ancillary equipment rework shall be requested, via naval message, in accordance with reference (c).

(g) The alteration or modification of an MF from its original configuration or intended use, is strictly prohibited unless authorized by the MF Program Office. The temporary addition or relocation of original internal MF equipment requires approval from the MALS AVO and all changes will be documented in the LIR/E-LIR.

(h) Requests for transferring IMRL intended to be mounted in an MF to another facility will be submitted to the MARFOR via naval message, and info the MF Program Office and HQMC ASL-34B (CMC AVN ASL WASHINGTON DC). Should IMRL intended to be mounted in an MF need to be replaced, new assets shall be requested per reference (n) and coordinated via the MARFOR to ensure MF compatibility with replacement assets. Any previous transactions that resulted in IMRL/SE that was relocated, surveyed, missing, or has been replaced with an asset not compatible with the original MF configuration should be reported to the MARFOR for MF disposition and TBA adjustment.

(6) Mobilie Facility (MF) Complexes. There are many factors to consider when complexing MFs, such as power requirements, fire and safety regulations, and overall size limitations. Additionally, ensure all local, state, and federal environmental regulations are followed, to include painting restrictions, oil/water separators, hazardous material containment, emissions, etc. All regulations, requirements, and restrictions for MF complexes are provided in reference (h).

(7) Equipment Disposition Requests

(a) Notify the MAW and MARFOR within 30 days of determination that an MF has been deemed a CSC failure and beyond economical repair. Unless another solution is available, the MAW or MARFOR shall direct the MF be added by serial number to the next FY Prioritization List. The MF shall remain in place until replacement and disposition are received from the NAVAIR MF Program Office, unless otherwise directed.

(b) Disposition requests for all other scenarios not covered by this instruction and all ancillary equipment will be submitted via naval message, in accordance with reference (c). Final disposition/survey of all assets not being retained, redistributed, or repurposed will be provided by the NAVAIR MF Program Office.

(c) If MF survey disposition is approved, surveyed MFs must be sent to the Defense Reutilization and Marketing Office (DRMO) in accordance with local instructions. A completed copy of DD 1348-1A, "Issue Release/Receipt Document" must be forwarded to NAVAIR's MF Program Office. Any request for retention of surveyed MFs must be submitted via Naval message to HQMC DC AVN ASL-34 (CMC AVN ASL WASHINGTON DC) and endorsed by the respective MAW and MARFOR, for approval. Upon approval, contact the nearest DRMO to complete the DD 1348-1A to avoid any unnecessary transportation disposal costs.

(d) No surveyed MF will be physically attached, or electrically connected to, an active MF or MF complex.

(e) Surveyed MFs, which are electrically connected to separate power sources other than active MFs, must remain in their original electrical configuration to include proper grounding per reference (h).

(f) Once an MF has been approved for survey, the following will be complied with by the surveying activity:

1. Permanently remove or paint over all MF markings or decals as applicable and remove the CSC data plate.

2. Clearly stencil "SURVEYED-NOT FOR EMBARK" in six-inch red letters, centered on both side walls and centered above the doors on both ends. Stencil the DTG of the MF Program NAVAIR authorization message in six-inch red letters centered below the SURVEYED markings on both side walls of the MF.

3. All butting kits, walkways, ECUs, and fire bottles will be removed from a surveyed MF prior to its disposition. Should a surveyed MF be connected to a power source, a fire bottle must be maintained within the MF.

4. Complete Receipt/Transfer/Survey procedures as per reference (e).

(g) Surveyed MFs will not have equipment installed for which a "SHORTAGE" is noted in any active (non-surveyed) MF.

(h) Surveyed MFs are not deployable and cannot be stacked or hoisted via ISO corners.

(i) An ECU is not an integral part of an MF; therefore, the ECU will not be disposed of with the MF. No RFU ECU will be placed in a surveyed MF if an active MF requires one. W/C 60C will maintain a signed custody card on each ECU being used in a surveyed MF. All scheduled and unscheduled maintenance will continue on every active ECU. Non-RFU ECUs will be disposed of per their source, maintenance, and recoverability (S, M, and R) codes.

5. Administration and Logistics

a. Personnel

(1) MALS W/C 60C is established to provide I-Level support for MFs, MF ECUs, and associated MF ancillary equipment. W/C 60C is also responsible for all scheduled and unscheduled maintenance of the MF ancillary equipment. The Table of Organization for each MALS provides a basic "core" of personnel that hold the 6499 MOS. Various Organizational level T/Os hold additional 6499 augmentees in support of W/C 60C.

(2) Each department, division, or section using MFs will continue to perform O-Level maintenance to their associated MFs.

b. Funding Responsibilities and Cognizance

(1) The NAVAIR MF Program Branch Head has total budgeting, funding, and acquisition responsibility for all MFs and related equipment acquired in support of the NAVAIR mission. The NAVAIR MF Program Branch Head has configuration and outfitting responsibility for all MFs acquired in support of specific NAVAIR weapon system projects and funded through the appropriate program management or program coordinator office.

(2) The NAVAIR MF Program Management Office has responsibility for all MFs acquired under the MFs subline in the Common Support Equipment APN-7 (BA-7) P-I Budget Line Item. The NAVAIR MF Program Management Office has direct budgeting/funding responsibility in the Operation and Maintenance, Navy appropriation for configuration/equipment installation requirements for those MFs procured in support of the NAVAIR mission whether for a specific weapon system or a common requirement. Reference (c) authorizes the use of Aviation Fleet Maintenance funds for organizational and intermediate level maintenance of MF equipment used in support of aircraft maintenance. Operating costs, such as those needed for engine oil, filters, and fuel for MF equipment must be budgeted and funded per TYCOM and local instructions.


c. Records created as a result of this Order shall be managed according to National Archives and Records Administration approved dispositions per reference (j) to ensure proper maintenance, use, accessibility and preservation, regardless of format or medium.

d. Privacy Act. Any misuse or unauthorized disclosure of Personally Identifiable Information (PII) may result in both civil and criminal penalties. The DON recognizes that the privacy of an individual is a personal and fundamental right that shall be respected and protected. The DON's need to collect, use, maintain, or disseminate PII about individuals for purposes of discharging its statutory responsibilities will be balanced against the individuals' right to be protected against unwarranted invasion of privacy. All collection, use, maintenance, or dissemination of PII will be in accordance with the Privacy Act of 1974, as amended (reference (k) and implemented per reference (l)).

6. Command and Signal

a. Command. This Order is applicable to the Marine Corps Total Force.

b. Signal. This Order is effective date signed.



S. R. RUDDER
Deputy Commandant for Aviation

DISTRIBUTION: PCN 10214780000

Mobile Facility Deployment Readiness Code Matrix

1ST Position - Deployability

D	DEPLOYABLE
R	NON-DEPLOYABLE, CORRECTABLE
L	LIMITED DEPLOYABILITY
N	NON-DEPLOYABLE, SURVEY CANDIDATE, OBSOLETE, PAST SERVICE LIFE

2ND Position - MF Condition

C	CSC CURRENT
R	REPAIRABLE, CSC FAILURE
N	NON-REPAIRABLE, CSC FAILURE
O	CSC OVERDUE

3RD Position - MF Equipment

A	ALL INSTALLED (COUNTERS, CHAIRS, ETC...)
P	PARTIALLY INSTALLED, MF PERFORMS INTENDED FUNCTION
M	MISSING ITEMS INHIBIT FUNCTION OF MF

4TH Position - IMRL

F	ALL IMRL INSTALLED
P	PARTIAL IMRL INSTALLED, CAN PERFORM LIMITED INTENDED FUNCTION
N	NOT INSTALLED, BUT AVAILABLE TO RE-INSTALL
M	MISSING OR REPLACED WITH IMRL THAT CANNOT BE INSTALLED (SIZE, POWER, ETC...)
X	NO IMRL ASSOCIATED WITH MF CONFIGURATION

USMC MF TBA by Configuration Code

DIV	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
** <u>AB-02</u> **																
000	S3	SCIFXX	1	1	0	0	0	0	0	0	1	0	0	0	0	0
** Subtotal **			1	1	0	0	0	0	0	0	1	0	0	0	0	0
** <u>AB-03</u> **																
000	S3	SCIFXX	1	1	0	0	0	0	0	0	1	0	0	0	0	0
** Subtotal **			1	1	0	0	0	0	0	0	1	0	0	0	0	0
** <u>AM-01</u> **																
000	05C	CCSPFW	0	1	1	0	0	0	0	0	1	0	0	0	0	0
000	05C	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	1	0
000	05C	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			1	1	1	0	1	1	1	1	1	0	1	0	1	0
** <u>AT-08</u> **																
000	S2	118A36	2	2	0	0	0	0	0	0	2	0	0	0	0	0
** Subtotal **			2	2	0	0	0	0	0	0	2	0	0	0	0	0
** <u>AT-09BM</u> **																
000	210	118A36	2	2	0	0	0	0	0	0	2	0	0	0	0	0
** Subtotal **			2	2	0	0	0	0	0	0	2	0	0	0	0	0
** <u>AT-10A</u> **																
000	210	118A36	2	2	0	0	0	0	0	0	2	0	0	0	0	0
** Subtotal **			2	2	0	0	0	0	0	0	2	0	0	0	0	0
** <u>AT-11</u> **																
ATC	ATC	MACSXX	0	1	1	2	1	0	0	1	1	1	2	1	0	0
** Subtotal **			0	1	1	2	1	0	0	1	1	1	2	1	0	0
** <u>AT-12</u> **																
ATC	ATC	MACSXX	0	1	1	2	1	0	0	1	1	1	2	1	0	0
** Subtotal **			0	1	1	2	1	0	0	1	1	1	2	1	0	0
** <u>AV-01A</u> **																
600	600	CCSPFW	2	0	2	0	0	0	0	0	2	0	0	0	0	0
600	600	CCSPRW	0	0	0	0	2	2	2	2	0	0	2	0	0	0
** Subtotal **			2	0	2	0	2	2	2	2	2	0	2	0	0	0
** <u>AV-02B</u> **																
600	600	CCSPFW	2	0	2	0	0	0	0	0	2	0	0	0	0	0
600	600	CCSPRW	0	0	0	0	2	2	2	2	0	0	2	0	0	0
** Subtotal **			2	0	2	0	2	2	2	2	2	0	2	0	0	0

USMC MF TBA by Configuration Code

DIV	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
** <u>BL-01</u> **																
600	600	135B16	0	0	2	0	0	0	0	0	0	0	0	0	0	0
600	620	1HML09	0	0	0	0	0	0	0	0	0	0	0	0	1	0
600	620	1HML27	0	0	0	0	0	1	0	2	0	2	0	0	0	0
600	600	235C10	0	0	0	0	0	0	0	0	1	0	0	0	0	0
MP2	LPZ	2FEFW	0	0	0	0	0	0	0	0	0	0	0	0	0	2
MP2	CRF	2FERW	0	0	0	0	0	0	0	0	0	0	0	0	0	2
600	620	2HML09	0	0	0	0	0	0	0	0	0	0	0	0	1	0
600	620	2HML27	0	0	0	0	0	0	0	0	0	0	1	0	0	0
600	600	335B10	2	0	0	0	0	0	0	0	0	0	0	1	0	0
MP3	LMS	3FEFW	0	0	0	0	0	0	0	0	0	0	0	0	0	2
MP3	CRF	3FERW	0	0	0	0	0	0	0	0	0	0	0	0	0	2
600	620	3HML27	0	0	0	0	0	0	0	0	0	0	1	0	0	0
600	600	435B16	0	0	0	2	0	0	0	0	0	0	0	1	0	0
600	620	4HML27	0	0	0	0	0	0	0	2	0	0	0	0	0	0
600	600	535B16	0	1	0	0	0	0	0	0	0	0	0	0	0	0
600	620	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
900	940	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	0	0	0
600	620	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
900	940	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
MPS	BLI	MPSBLI	0	0	0	0	0	0	0	0	0	0	0	0	0	1
600	620	T53E29	0	0	0	0	0	0	0	1	0	0	0	0	0	0
600	600	TF3531	0	0	0	0	0	0	0	0	1	0	0	0	0	0
600	620	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
600	620	TH1M39	0	0	0	0	0	0	0	0	0	0	1	0	0	0
600	620	TV8B14	0	0	0	1	0	0	0	0	0	0	0	0	0	0
600	620	WGISSX	0	0	0	0	1	0	0	0	0	0	0	0	0	0
** Subtotal **			5	3	4	5	3	3	2	7	4	4	5	3	4	9
** <u>BR-01</u> **																
700	71D	118A36	1	1	0	0	0	0	0	0	1	0	0	1	0	0
700	71D	1HML27	0	0	0	0	0	0	0	1	0	0	0	0	1	0
700	71D	1V8R14	0	0	1	1	0	0	0	0	0	0	0	0	0	0
** Subtotal **			1	1	1	1	0	0	0	1	1	0	0	1	1	0
** <u>BR-04A</u> **																
700	71D	CCSPFW	1	1	0	1	0	0	0	0	0	0	0	1	0	0
700	71D	CCSPRW	0	0	0	0	1	1	1	0	0	1	0	0	1	0
** Subtotal **			1	1	0	1	1	1	1	0	0	1	0	1	1	0
** <u>BR-05B</u> **																
700	71D	CCSPFW	1	1	0	1	0	0	0	0	0	0	0	1	0	0
700	71D	CCSPRW	0	0	0	0	1	1	1	0	0	1	0	0	1	0
** Subtotal **			1	1	0	1	1	1	1	0	0	1	0	1	1	0

USMC MF TBA by Configuration Code

DIV	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
** CA-01 **																
600	670	CCSPFW	2	2	0	2	0	0	0	0	0	0	0	0	0	0
** Subtotal **			2	2	0	2	0	0	0	0	0	0	0	0	0	0
** CA-04 **																
600	670	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
600	670	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
** Subtotal **			1	1	1	1	1	1	1	1	1	1	1	1	1	0
** CA-07A **																
600	670	CCSPRW	0	0	0	0	0	0	1	0	0	1	1	0	0	0
** Subtotal **			0	0	0	0	0	0	1	0	0	1	1	0	0	0
** CA-08B **																
600	670	CCSPRW	0	0	0	0	0	0	1	0	0	1	1	0	0	0
** Subtotal **			0	0	0	0	0	0	1	0	0	1	1	0	0	0
** CA-09 **																
600	670	CCSPRW	0	0	0	0	0	1	1	0	0	0	1	0	0	0
** Subtotal **			0	0	0	0	0	1	1	0	0	0	1	0	0	0
** CL-01 **																
600	670	CCSPFW	2	2	2	2	0	0	0	0	2	0	0	2	0	0
600	670	CCSPRW	0	0	0	0	2	2	2	2	0	2	2	0	2	0
600	670	TV8B14	0	0	0	1	0	0	0	0	0	0	0	0	0	0
** Subtotal **			2	2	2	3	2	2	2	2	2	2	2	2	2	0
** CL-02 **																
600	670	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
600	670	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
** Subtotal **			1	1	1	1	1	1	1	1	1	1	1	1	1	0
** CL-04 **																
600	610	CCSPFW	2	2	2	2	0	0	0	0	2	0	0	2	0	0
600	670	CCSPFW	2	2	2	2	0	0	0	0	2	0	0	2	0	0
600	610	CCSPRW	0	0	0	0	2	2	2	2	0	2	2	0	2	0
600	670	CCSPRW	0	0	0	0	2	2	2	2	0	2	2	0	2	0
** Subtotal **			4	4	4	4	4	4	4	4	4	4	4	4	4	0
** CL-06 **																
600	670	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	0	0	0
600	670	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
** Subtotal **			1	1	1	1	1	1	1	1	1	1	1	0	1	0
** CL-09 **																
600	670	CCSPFW	2	2	2	2	0	0	0	0	2	0	0	2	0	0

USMC MF TBA by Configuration Code

DIV	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
600	670	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
600	670	IOSP14	0	0	0	2	0	0	0	0	0	0	0	0	0	0
** Subtotal **			2	2	2	4	1	1	1	1	2	1	1	2	1	0
** <u>CL-10</u> **																
600	670	CCSPFW	2	2	2	2	0	0	0	0	2	0	0	2	0	0
600	670	CCSPRW	0	0	0	0	2	2	2	2	0	2	2	0	2	0
** Subtotal **			2	2	2	2	2	2	2	2	2	2	2	2	2	0
** <u>CR-03</u> **																
ATC	ATC	MACSXX	0	2	2	2	2	0	0	2	2	2	4	2	0	0
** Subtotal **			0	2	2	2	2	0	0	2	2	2	4	2	0	0
** <u>CR-04</u> **																
600	690	CCSPFW	2	2	2	2	0	0	0	0	2	0	0	2	0	0
600	690	CCSPRW	0	0	0	0	2	2	2	2	0	2	2	0	2	0
** Subtotal **			2	2	2	2	2	2	2	2	2	2	2	2	2	0
** <u>CS-02A</u> **																
500	510	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
500	510	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
** Subtotal **			1	1	1	1	1	1	1	1	1	1	1	1	1	0
** <u>CS-03BM</u> **																
500	510	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
500	510	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
** Subtotal **			1	1	1	1	1	1	1	1	1	1	1	1	1	0
** <u>CU-01</u> **																
MP2	LPZ	2FEFW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
MP2	SSR	2FEFW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
MP2	SEAY	2FERW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
MP2	WLM	2FERW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
MP3	DHL	3FEFW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
MP3	LMS	3FEFW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
MP3	BBO	3FERW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
MP3	PLU	3FERW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
000	010	CCSPFW	2	2	2	2	0	0	0	0	1	0	0	2	0	0
000	020	CCSPFW	1	1	1	3	0	0	0	0	3	0	0	1	0	0
000	030	CCSPFW	0	0	0	1	0	0	0	0	0	0	0	0	0	0
000	040	CCSPFW	1	0	0	0	0	0	0	0	0	0	0	1	0	0
000	05C	CCSPFW	1	0	0	1	0	0	0	0	0	0	0	1	0	0
400	400	CCSPFW	1	1	1	1	0	0	0	0	0	0	0	0	0	0
500	500	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
600	600	CCSPFW	3	3	3	3	0	0	0	0	2	0	0	4	0	0
600	670	CCSPFW	0	0	0	0	0	0	0	0	0	0	0	1	0	0
700	700	CCSPFW	1	1	0	1	0	0	0	0	0	0	0	1	0	0

USMC MF TBA by Configuration Code

DIV	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
700	730	CCSPFW	1	1	0	1	0	0	0	0	0	0	0	1	0	0
800	800	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
900	930	CCSPFW	0	0	0	0	0	0	0	0	0	0	0	1	0	0
900	940	CCSPFW	0	0	0	1	0	0	0	0	1	0	0	0	0	0
000	010	CCSPRW	0	0	0	0	2	2	2	2	0	2	2	0	2	0
000	020	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
000	040	CCSPRW	0	0	0	0	2	1	2	1	0	1	1	0	1	0
400	400	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
500	500	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
600	600	CCSPRW	0	0	0	0	3	3	3	2	0	3	3	0	3	0
700	700	CCSPRW	0	0	0	0	1	1	1	0	0	1	0	0	1	0
700	730	CCSPRW	0	0	0	0	1	1	1	0	0	1	0	0	1	0
800	800	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
900	910	CCSPRW	0	0	0	0	0	0	0	0	0	0	0	0	1	0
900	940	CCSPRW	0	0	0	0	0	0	0	1	0	0	0	0	0	0
AIS	AIS	CCSPRW	0	0	0	0	0	1	0	0	0	0	0	0	0	0
MPS	FLY	MPSFLY	0	0	0	0	0	0	0	0	0	0	0	0	0	1
000	010	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
000	020	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
400	400	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
500	500	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
600	600	TFRS11	2	0	0	0	0	0	0	0	0	0	0	0	0	0
800	800	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			20	11	9	16	13	13	13	10	9	12	10	15	13	9
** <u>CY-01</u> **																
600	610	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
600	610	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
600	610	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			2	1	1	1	1	1	1	1	1	1	1	1	1	0
** <u>DP-03</u> **																
AIS	AIS	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
AIS	AIS	CCSPRW	0	0	0	0	1	0	1	1	0	1	1	0	1	0
** Subtotal **			1	1	1	1	1	0	1	1	1	1	1	1	1	0
** <u>DP-18A</u> **																
AIS	AIS	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
AIS	AIS	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
AIS	AIS	IOSP14	0	0	0	1	0	0	0	0	0	0	0	0	0	0
AIS	AIS	IOSP16	0	0	0	0	1	0	0	0	0	0	0	0	0	0
AIS	AIS	IOSP36	0	0	0	0	0	0	0	0	0	1	0	0	0	0
AIS	AIS	IOSP41	0	0	0	0	0	0	0	0	0	0	0	1	0	0
** Subtotal **			1	1	1	2	2	1	1	1	1	2	1	2	1	0
** <u>EA-01</u> **																
ZZC	EAF	BEAFFW	1	1	1	2	0	0	0	0	1	0	0	0	0	0

USMC MF TBA by Configuration Code

DIV	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
ZZC	EAF	BEAFRW	0	0	0	0	1	0	1	1	0	1	1	0	0	0
MP2	SKM	EAF	0	0	0	0	0	0	0	0	0	0	0	0	0	1
MP3	BTN	EAF	0	0	0	0	0	0	0	0	0	0	0	0	0	1
ZZC	EAF	PALMXX	1	0	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			2	1	1	2	1	0	1	1	1	1	1	0	0	2
** <u>EA-02</u> **																
ZZC	EAF	BEAFFW	0	0	0	2	0	0	0	0	0	0	0	0	0	0
ZZC	EAF	BEAFRW	0	0	0	0	2	0	0	0	0	2	0	0	0	0
** Subtotal **			0	0	0	2	2	0	0	0	0	2	0	0	0	0
** <u>EB-06</u> **																
600	650	IOSP12	0	1	0	0	0	0	0	0	0	0	0	0	0	0
600	650	IOSP14	0	0	0	2	0	0	0	0	0	0	0	0	0	0
** Subtotal **			0	1	0	2	0	0	0	0	0	0	0	0	0	0
** <u>EB-07</u> **																
600	650	IOSP12	0	1	0	0	0	0	0	0	0	0	0	0	0	0
600	650	IOSP14	0	0	0	2	0	0	0	0	0	0	0	0	0	0
** Subtotal **			0	1	0	2	0	0	0	0	0	0	0	0	0	0
** <u>EB-08</u> **																
600	650	IOSP14	0	0	0	1	0	0	0	0	0	0	0	0	0	0
** Subtotal **			0	0	0	1	0	0	0	0	0	0	0	0	0	0
** <u>EB-09</u> **																
600	650	IOSP12	0	1	0	0	0	0	0	0	0	0	0	0	0	0
600	650	IOSP14	0	0	0	2	0	0	0	0	0	0	0	0	0	0
** Subtotal **			0	1	0	2	0	0	0	0	0	0	0	0	0	0
** <u>ED-01</u> **																
S00	S00	F11812	2	0	0	0	0	0	0	0	0	0	0	0	0	0
S00	S00	F11824	2	0	0	0	0	0	0	0	0	0	0	0	0	0
S00	S00	F15316	0	0	0	0	0	0	0	2	0	0	0	0	0	0
S00	S00	F1KJ09	2	0	0	0	0	0	0	0	0	0	0	0	0	0
S00	S00	F1V212	0	0	0	0	2	2	2	0	0	2	2	0	0	0
S00	S00	F1V816	0	0	0	2	0	0	0	0	0	0	0	0	0	0
S00	S00	F1YZ27	0	0	0	0	0	2	0	2	0	2	2	0	0	0
S00	S00	F21812	0	0	0	0	0	0	0	0	2	0	0	0	0	0
S00	S00	F21824	0	0	0	0	0	0	0	0	2	0	0	0	0	0
S00	S00	F25316	0	0	0	0	0	0	0	2	0	0	0	0	0	0
S00	S00	F2KJ09	0	2	0	0	0	0	0	0	0	0	0	0	0	0
S00	S00	F2V212	0	0	0	0	2	0	2	0	0	0	0	0	0	0
S00	S00	F2V816	0	0	0	2	0	0	0	0	0	0	0	0	0	0
S00	S00	F2YZ27	0	0	0	0	0	0	0	2	0	0	2	0	0	0
S00	S00	F31824	0	2	0	0	0	0	0	0	0	0	0	0	0	0
S00	S00	F35316	0	0	0	0	0	2	0	0	0	0	0	0	0	0

21 MAY 2018

USMC MF TBA by Configuration Code

DIV	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
S00	S00	F3KJ09	0	0	0	2	0	0	0	0	0	0	0	0	0	0
S00	S00	F3V816	0	0	2	0	0	0	0	0	0	0	0	0	0	0
S00	S00	F45316	0	0	0	0	2	0	0	0	0	0	0	0	0	0
S00	S00	F4V816	0	0	2	0	0	0	0	0	0	0	0	0	0	0
S00	S00	F55316	0	0	0	0	0	0	0	0	0	2	0	0	0	0
S00	S00	MSA	0	0	0	0	0	0	4	0	0	0	0	0	0	0
** Subtotal **			6	4	4	6	6	6	8	8	4	6	6	0	0	0
** <u>FA-02A</u> **																
500	520	118A12	0	0	0	0	0	0	0	0	0	0	0	1	0	0
500	520	118A36	1	2	0	0	0	0	0	0	0	0	0	0	0	0
500	520	118C24	1	0	0	0	0	0	0	0	0	0	0	0	0	0
500	520	318A36	0	0	0	0	0	0	0	0	1	0	0	0	0	0
500	520	318C24	0	0	0	0	0	0	0	0	1	0	0	0	0	0
** Subtotal **			2	2	0	0	0	0	0	0	2	0	0	1	0	0
** <u>FA-03B</u> **																
500	520	118A12	0	0	0	0	0	0	0	0	0	0	0	1	0	0
500	520	118A36	1	2	0	0	0	0	0	0	0	0	0	0	0	0
500	520	118C24	1	0	0	0	0	0	0	0	0	0	0	0	0	0
500	520	318A36	0	0	0	0	0	0	0	0	1	0	0	0	0	0
500	520	318C24	0	0	0	0	0	0	0	0	1	0	0	0	0	0
** Subtotal **			2	2	0	0	0	0	0	0	2	0	0	1	0	0
** <u>FC-05</u> **																
700	730	CCSPFW	1	1	0	1	0	0	0	0	0	0	0	1	0	0
700	730	CCSPRW	0	0	0	0	1	1	1	0	0	0	0	0	1	0
** Subtotal **			1	1	0	1	1	1	1	0	0	0	0	1	1	0
** <u>FS-01</u> **																
400	400	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	0	0	0
500	500	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
600	600	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
700	700	CCSPFW	1	1	0	1	0	0	0	0	0	0	0	1	0	0
400	400	CCSPRW	0	0	0	0	1	0	1	1	0	1	1	0	1	0
500	500	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
600	600	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
700	700	CCSPRW	0	0	0	0	1	1	1	0	0	1	0	0	1	0
S00	S00	F11812	1	0	0	0	0	0	0	0	0	0	0	0	0	0
S00	S00	F11824	1	0	0	0	0	0	0	0	0	0	0	0	0	0
S00	S00	F15316	0	0	0	0	0	0	0	1	0	0	0	0	0	0
S00	S00	F1KJ09	1	0	0	0	0	0	0	0	0	0	0	0	0	0
S00	S00	F1V212	0	0	0	0	1	1	1	0	0	1	1	0	0	0
S00	S00	F1V816	0	0	0	1	0	0	0	0	0	0	0	0	0	0
S00	S00	F1YZ27	0	0	0	0	0	1	0	1	0	1	1	0	0	0
S00	S00	F21812	0	0	0	0	0	0	0	0	1	0	0	0	0	0
S00	S00	F21824	0	0	0	0	0	0	0	0	1	0	0	0	0	0

USMC MF TBA by Configuration Code

DIV	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
S00	S00	F25316	0	0	0	0	0	0	0	1	0	0	0	0	0	0
S00	S00	F2KJ09	0	1	0	0	0	0	0	0	0	0	0	0	0	0
S00	S00	F2V212	0	0	0	0	1	0	1	0	0	0	0	0	0	0
S00	S00	F2V816	0	0	0	1	0	0	0	0	0	0	0	0	0	0
S00	S00	F2YZ27	0	0	0	0	0	0	0	1	0	0	1	0	0	0
S00	S00	F31824	0	1	0	0	0	0	0	0	0	0	0	0	0	0
S00	S00	F35316	0	0	0	0	0	1	0	0	0	0	0	0	0	0
S00	S00	F3KJ09	0	0	0	1	0	0	0	0	0	0	0	0	0	0
S00	S00	F3V816	0	0	1	0	0	0	0	0	0	0	0	0	0	0
S00	S00	F45316	0	0	0	0	1	0	0	0	0	0	0	0	0	0
S00	S00	F4V816	0	0	1	0	0	0	0	0	0	0	0	0	0	0
S00	S00	F55316	0	0	0	0	0	0	0	0	0	1	0	0	0	0
MPS	BLI	MPSBLI	0	0	0	0	0	0	0	0	0	0	0	0	0	1
S00	S00	MSA	1	1	1	1	1	1	1	1	1	1	1	0	1	0
** Subtotal **			8	7	6	8	8	7	7	8	6	8	7	3	5	1
** <u>GC-01</u> **																
600	620	1V8R14	0	1	1	1	0	0	0	0	0	0	0	0	0	0
600	620	2V8R14	0	0	1	1	0	0	0	0	0	0	0	0	0	0
** Subtotal **			0	1	2	2	0	0	0	0	0	0	0	0	0	0
** <u>GM-02A</u> **																
700	71B	118A36	1	1	0	0	0	0	0	0	1	0	0	1	0	0
700	71B	1V8R14	0	1	1	1	0	0	0	0	0	0	0	0	0	0
700	71B	CCSPRW	0	0	0	0	1	1	1	0	0	1	0	0	1	0
** Subtotal **			1	2	1	1	1	1	1	0	1	1	0	1	1	0
** <u>GM-03B</u> **																
700	71B	118A36	1	1	0	0	0	0	0	0	1	0	0	1	0	0
700	71B	1V8R14	0	1	1	1	0	0	0	0	0	0	0	0	0	0
700	71B	CCSPRW	0	0	0	0	1	1	1	0	0	1	0	0	1	0
** Subtotal **			1	2	1	1	1	1	1	0	1	1	0	1	1	0
** <u>HC-01</u> **																
500	520	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	1	0
500	520	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	0	0
500	520	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			2	1	1	1	1	1	1	1	1	1	1	1	1	0
** <u>HC-02</u> **																
500	520	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	1	0
500	520	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	0	0
500	520	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			2	1	1	1	1	1	1	1	1	1	1	1	1	0

USMC MF TBA by Configuration Code

DIV	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
** HY-06C **																
500	520	1V2236	0	0	0	0	0	1	1	0	0	1	1	0	0	0
500	520	3V2212	0	0	0	0	1	0	0	0	0	0	0	0	1	0
500	520	TV2226	0	0	0	0	0	0	1	0	0	0	0	0	0	0
** Subtotal **			0	0	0	0	1	1	2	0	0	1	1	0	1	0
** HY-07A **																
500	520	CCSPFW	1	1	0	1	0	0	0	0	1	0	0	1	0	0
500	520	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
500	520	T53E29	0	0	0	0	0	0	0	1	0	0	0	0	0	0
500	520	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
500	520	TV8B14	0	0	0	1	0	0	0	0	0	0	0	0	0	0
** Subtotal **			2	1	0	2	1	1	1	2	1	1	1	1	1	0
** HY-08B **																
500	520	CCSPFW	1	1	0	1	0	0	0	0	1	0	0	1	0	0
500	520	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
500	520	T53E29	0	0	0	0	0	0	0	1	0	0	0	0	0	0
500	520	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
500	520	TV8B14	0	0	0	1	0	0	0	0	0	0	0	0	0	0
** Subtotal **			2	1	0	2	1	1	1	2	1	1	1	1	1	0
** JU-01 **																
500	500	118A12	0	0	0	0	0	0	0	0	0	0	0	1	0	0
000	000	118A36	1	1	0	0	0	0	0	0	1	0	0	0	0	0
500	500	118A36	1	1	0	0	0	0	0	0	0	0	0	0	0	0
600	600	118A36	1	1	0	0	0	0	0	0	1	0	0	0	0	0
500	500	118C24	1	0	0	0	0	0	0	0	0	0	0	0	0	0
600	600	118C24	1	0	0	0	0	0	0	0	1	0	0	1	0	0
800	800	130J12	0	1	0	0	0	0	0	0	0	0	0	0	0	0
600	600	130T12	0	0	0	0	0	0	0	0	0	0	0	1	2	0
600	600	153E16	0	0	0	0	1	0	0	1	0	0	0	0	0	0
600	600	1HML27	0	0	0	0	0	1	0	2	0	1	2	0	1	0
500	500	1V2236	0	0	0	0	0	1	1	0	0	1	1	0	0	0
800	800	1V2236	0	0	0	0	0	0	1	0	0	0	0	0	0	0
500	500	1V8R14	0	0	0	1	0	0	0	0	0	0	0	0	0	0
600	600	1V8R14	0	1	1	1	0	0	0	0	0	0	0	0	0	0
MP2	LPZ	2FEFW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
MP2	SSR	2FEFW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
MP2	SEAY	2FERW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
MP2	WLM	2FERW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
600	600	2HML27	0	0	0	0	0	0	0	0	0	0	1	0	0	0
600	600	2V8R14	0	0	1	1	0	0	0	0	0	0	0	0	0	0
600	600	318A36	0	0	0	0	0	0	0	0	1	0	0	0	0	0
500	500	318C24	0	0	0	0	0	0	0	0	1	0	0	0	0	0
MP3	DHL	3FEFW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
MP3	LMS	3FEFW	0	0	0	0	0	0	0	0	0	0	0	0	0	1

21 MAY 2018

USMC MF TBA by Configuration Code

DIV	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
MP3	BBO	3FERW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
MP3	PLU	3FERW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
500	500	3V2212	0	0	0	0	1	0	0	0	0	0	0	0	1	0
600	600	4HML27	0	0	0	0	0	0	0	1	0	0	0	0	0	0
000	000	CCSPFW	3	3	3	4	0	0	0	0	3	0	0	3	0	0
500	500	CCSPFW	5	5	5	5	0	0	0	0	5	0	0	5	1	0
600	600	CCSPFW	12	11	12	11	0	0	0	0	12	0	0	10	0	0
700	700	CCSPFW	2	2	0	2	0	0	0	0	0	0	0	2	0	0
800	800	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
900	900	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
AIS	AIS	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
000	000	CCSPRW	0	0	0	0	3	2	3	3	0	3	3	0	3	0
400	400	CCSPRW	0	0	0	0	2	1	2	2	0	2	2	0	2	0
500	500	CCSPRW	0	0	0	0	5	5	4	5	0	5	5	0	5	0
600	600	CCSPRW	0	0	0	0	11	10	11	11	0	11	12	0	9	0
700	700	CCSPRW	0	0	0	0	2	2	2	1	0	2	0	0	1	0
800	800	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
900	900	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
AIS	AIS	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
S00	S00	F11812	1	0	0	0	0	0	0	0	0	0	0	0	0	0
S00	S00	F11824	1	0	0	0	0	0	0	0	0	0	0	0	0	0
S00	S00	F15316	0	0	0	0	0	0	0	1	0	0	0	0	0	0
S00	S00	F1KJ09	1	0	0	0	0	0	0	0	0	0	0	0	0	0
S00	S00	F1V212	0	0	0	0	1	1	1	0	0	1	1	0	0	0
S00	S00	F1V816	0	0	0	1	0	0	0	0	0	0	0	0	0	0
S00	S00	F1YZ27	0	0	0	0	0	1	0	1	0	1	1	0	0	0
S00	S00	F21812	0	0	0	0	0	0	0	0	1	0	0	0	0	0
S00	S00	F21824	0	0	0	0	0	0	0	0	1	0	0	0	0	0
S00	S00	F25316	0	0	0	0	0	0	0	1	0	0	0	0	0	0
S00	S00	F2KJ09	0	1	0	0	0	0	0	0	0	0	0	0	0	0
S00	S00	F2V212	0	0	0	0	1	0	1	0	0	0	0	0	0	0
S00	S00	F2V816	0	0	0	1	0	0	0	0	0	0	0	0	0	0
S00	S00	F2YZ27	0	0	0	0	0	0	0	1	0	0	1	0	0	0
S00	S00	F31824	0	1	0	0	0	0	0	0	0	0	0	0	0	0
S00	S00	F35316	0	0	0	0	0	1	0	0	0	0	0	0	0	0
S00	S00	F3KJ09	0	0	0	1	0	0	0	0	0	0	0	0	0	0
S00	S00	F3V816	0	0	1	0	0	0	0	0	0	0	0	0	0	0
S00	S00	F45316	0	0	0	0	1	0	0	0	0	0	0	0	0	0
S00	S00	F4V816	0	0	1	0	0	0	0	0	0	0	0	0	0	0
S00	S00	F55316	0	0	0	0	0	0	0	0	0	1	0	0	0	0
600	600	IOSP11	4	0	0	0	0	0	0	0	0	0	0	0	0	0
600	600	IOSP12	0	3	0	0	0	0	0	0	0	0	0	0	0	0
600	600	IOSP14	0	0	0	6	0	0	0	0	0	0	0	0	0	0
600	600	IOSP31	0	0	0	0	0	0	0	0	4	0	0	0	0	0
ATC	ATC	MACSXX	0	1	2	2	1	0	0	1	1	1	2	1	0	0
MPS	FLY	MPSFLY	0	0	0	0	0	0	0	0	0	0	0	0	0	1
S00	S00	MSA	2	2	2	2	2	2	2	2	2	2	2	0	2	0
ZZC	EAF	PALMXX	1	0	0	0	0	0	0	0	0	0	0	0	0	0

USMC MF TBA by Configuration Code

DIV	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
000	000	SCIFXX	1	1	0	0	0	0	0	0	1	0	0	0	0	0
600	600	T53E29	0	0	0	0	0	0	0	1	0	0	0	0	0	0
000	000	TFRS11	3	0	0	0	0	0	0	0	0	0	0	0	0	0
500	500	TFRS11	4	0	0	0	0	0	0	0	0	0	0	0	0	0
600	600	TFRS11	4	0	0	0	0	0	0	0	0	0	0	0	0	0
800	800	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
900	900	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
600	600	TH1M39	0	0	0	0	0	0	0	0	0	1	0	0	0	0
500	500	TV2226	0	0	0	0	0	1	0	0	0	0	0	0	0	0
600	600	TV2226	0	0	0	0	0	1	0	0	0	0	0	0	0	0
000	000	TV8B14	0	0	0	1	0	0	0	0	0	0	0	0	0	0
600	600	TV8B14	0	0	0	4	0	0	0	0	0	0	0	0	0	0
** Subtotal **			54	38	31	46	34	30	33	37	38	34	37	27	30	9
** <u>JU-09</u> **																
600	600	1E6B05	0	1	0	1	0	0	0	0	0	0	0	0	0	0
600	600	2E6B05	0	0	0	1	0	0	0	0	0	0	0	0	0	0
600	600	3E6B05	0	0	0	1	0	0	0	0	0	0	0	0	0	0
** Subtotal **			0	1	0	3	0	0	0	0	0	0	0	0	0	0
** <u>JU-10</u> **																
600	600	1E6B05	0	1	0	1	0	0	0	0	0	0	0	0	0	0
600	600	2E6B05	0	0	0	1	0	0	0	0	0	0	0	0	0	0
600	600	3E6B05	0	0	0	1	0	0	0	0	0	0	0	0	0	0
** Subtotal **			0	1	0	3	0	0	0	0	0	0	0	0	0	0
** <u>JU-31</u> **																
000	S3	SCIFXX	1	1	0	0	0	0	0	0	1	0	0	0	0	0
** Subtotal **			1	1	0	0	0	0	0	0	1	0	0	0	0	0
** <u>JU-32</u> **																
000	S3	SCIFXX	1	1	0	0	0	0	0	0	1	0	0	0	0	0
** Subtotal **			1	1	0	0	0	0	0	0	1	0	0	0	0	0
** <u>KA-18A</u> **																
600	600	1HML27	0	0	0	0	0	0	0	0	0	3	0	0	0	0
600	600	1V2236	0	0	0	0	2	0	0	0	0	0	0	0	0	0
600	600	CCSPFW	7	7	5	7	0	0	0	0	8	0	0	2	0	0
600	600	CCSPRW	0	0	0	0	4	3	4	4	0	3	4	0	2	0
600	600	IOSP11	3	0	0	0	0	0	0	0	0	0	0	0	0	0
600	600	IOSP12	0	2	0	0	0	0	0	0	0	0	0	0	0	0
600	600	IOSP14	0	0	0	1	0	0	0	0	0	0	0	0	0	0
600	600	IOSP31	0	0	0	0	0	0	0	0	4	0	0	0	0	0
600	600	TFRS11	6	0	0	0	0	0	0	0	0	0	0	0	0	0
600	600	TV2226	0	0	0	0	0	0	3	0	0	0	0	0	0	0
600	600	TV8B14	0	0	0	5	0	0	0	0	0	0	0	0	0	0
** Subtotal **			16	9	5	13	6	3	7	4	12	3	7	2	2	0

USMC MF TBA by Configuration Code

DIV	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
** KA-19A **																
600	650	CCSPFW	2	2	2	2	0	0	0	0	2	0	0	1	0	0
600	650	IOSP11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
600	650	IOSP14	0	0	0	2	0	0	0	0	0	0	0	0	0	0
600	650	IOSP31	0	0	0	0	0	0	0	0	1	0	0	0	0	0
600	650	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
600	650	TV8B14	0	0	0	1	0	0	0	0	0	0	0	0	0	0
** Subtotal **			4	2	2	5	0	0	0	0	3	0	0	1	0	0
** KA-20B **																
600	650	CCSPFW	2	2	2	2	0	0	0	0	2	0	0	1	0	0
600	650	IOSP11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
600	650	IOSP14	0	0	0	2	0	0	0	0	0	0	0	0	0	0
600	650	IOSP31	0	0	0	0	0	0	0	0	1	0	0	0	0	0
600	650	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
600	650	TV8B14	0	0	0	1	0	0	0	0	0	0	0	0	0	0
** Subtotal **			4	2	2	5	0	0	0	0	3	0	0	1	0	0
** KA-31 **																
600	650	118A12	0	0	0	0	0	0	0	0	0	0	0	1	0	0
600	650	118A36	2	0	0	0	0	0	0	0	0	0	0	0	0	0
600	650	1E6B05	0	0	0	3	0	0	0	0	0	0	0	0	0	0
600	650	1HML27	0	0	0	0	0	0	0	0	0	0	2	0	0	0
600	650	218A36	0	1	0	0	0	0	0	0	0	0	0	0	0	0
600	650	2E6B05	0	0	0	3	0	0	0	0	0	0	0	0	0	0
600	650	318A36	0	0	0	0	0	0	0	0	4	0	0	0	0	0
600	650	3V2212	0	0	0	0	1	0	0	0	0	0	0	0	0	0
600	650	CCSPFW	3	3	3	3	0	0	0	0	3	0	0	3	0	0
600	650	CCSPRW	0	0	0	0	3	3	3	3	0	3	3	0	3	0
600	650	IOSP11	11	0	0	0	0	0	0	0	0	0	0	0	0	0
600	650	IOSP12	0	11	0	0	0	0	0	0	0	0	0	0	0	0
600	650	IOSP14	0	0	0	4	0	0	0	0	0	0	0	0	0	0
600	650	IOSP31	0	0	0	0	0	0	0	0	9	0	0	0	0	0
600	650	TV2226	0	0	0	0	0	0	1	0	0	0	0	0	0	0
** Subtotal **			16	15	3	13	4	3	4	3	16	3	5	4	3	0
** MC-01 **																
000	020	CCSPFW	2	2	2	0	0	0	0	0	0	0	0	2	0	0
600	600	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	0	0	0
600	670	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
700	700	CCSPFW	1	1	0	1	0	0	0	0	0	0	0	1	0	0
000	020	CCSPRW	0	0	0	0	2	1	2	2	0	0	2	0	2	0
600	600	CCSPRW	0	0	0	0	1	0	1	1	0	0	1	0	1	0
600	670	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	1	0
700	700	CCSPRW	0	0	0	0	1	1	1	0	0	0	0	0	1	0
000	020	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
000	020	TV8B14	0	0	0	1	0	0	0	0	0	0	0	0	0	0

USMC MF TBA by Configuration Code

DIV	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
** Subtotal **			6	5	4	4	5	3	5	4	2	0	4	4	5	0
** <u>MM-01</u> **																
500	510	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
500	510	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	0	0
500	510	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			2	1	1	1	1	1	1	1	1	0	1	1	0	0
** <u>MM-02</u> **																
500	510	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	1	0
500	510	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	0	0
500	510	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			2	1	1	1	1	1	1	1	1	0	1	1	1	0
** <u>MM-03</u> **																
500	510	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	1	0
500	510	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	0	0
500	510	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			2	1	1	1	1	1	1	1	1	0	1	1	1	0
** <u>MM-04</u> **																
500	510	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	1	0
500	510	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	0	0
500	510	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			2	1	1	1	1	1	1	1	1	0	1	1	1	0
** <u>NT-06</u> **																
500	530	CCSPFW	0	1	0	0	0	0	0	0	0	0	0	0	0	0
500	530	CCSPRW	0	0	0	0	1	0	1	0	0	0	1	0	0	0
** Subtotal **			0	1	0	0	1	0	1	0	0	0	1	0	0	0
** <u>NT-08</u> **																
500	530	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
500	530	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	1	0
500	530	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			2	1	1	1	1	1	1	1	1	0	1	1	1	0
** <u>PM-01</u> **																
600	650	1E6B05	0	1	0	1	0	0	0	0	0	0	0	0	0	0
600	650	2E6B05	0	0	0	1	0	0	0	0	0	0	0	0	0	0
600	650	3E6B05	0	0	0	1	0	0	0	0	0	0	0	0	0	0
** Subtotal **			0	1	0	3	0	0	0	0	0	0	0	0	0	0
** <u>PM-02</u> **																
600	650	1V8R14	0	1	1	1	0	0	0	0	0	0	0	0	0	0

USMC MF TBA by Configuration Code

DIV	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
** Subtotal **			0	1	1	1	0	0	0	0	0	0	0	0	0	0
** <u>PP-01</u> **																
400	410	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	1	0
** Subtotal **			0	0	0	0	1	1	1	1	0	0	1	0	1	0
** <u>PP-03A</u> **																
400	440	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	1	0
** Subtotal **			0	0	0	0	1	1	1	1	0	0	1	0	1	0
** <u>PP-04BM</u> **																
400	440	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	1	0
** Subtotal **			0	0	0	0	1	1	1	1	0	0	1	0	1	0
** <u>PW-01</u> **																
500	500	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
500	500	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
500	500	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			2	1	1	1	1	1	1	1	1	1	1	1	1	0
** <u>RR-02</u> **																
800	810	130J12	0	1	0	0	0	0	0	0	0	0	0	0	0	0
800	810	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
800	810	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			2	2	1	1	0	0	0	0	1	0	0	1	0	0
** <u>RR-03</u> **																
800	810	130J12	0	1	0	0	0	0	0	0	0	0	0	0	0	0
800	810	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
** Subtotal **			1	2	1	1	0	0	0	0	1	0	0	1	0	0
** <u>RR-04A</u> **																
800	810	1V2236	0	0	0	0	0	0	2	0	0	1	1	0	0	0
800	810	3V2212	0	0	0	0	1	1	0	0	0	0	0	0	1	0
800	810	TV2226	0	0	0	0	0	0	1	0	0	0	0	0	0	0
** Subtotal **			0	0	0	0	1	1	3	0	0	1	1	0	1	0
** <u>RR-05B</u> **																
800	810	1V2236	0	0	0	0	0	0	2	0	0	1	1	0	0	0
800	810	3V2212	0	0	0	0	1	1	0	0	0	0	0	0	1	0
800	810	TV2226	0	0	0	0	0	0	1	0	0	0	0	0	0	0
** Subtotal **			0	0	0	0	1	1	3	0	0	1	1	0	1	0
** <u>RR-06BM</u> **																
800	810	1V2236	0	0	0	0	0	0	2	0	0	1	1	0	0	0
800	810	3V2212	0	0	0	0	1	1	0	0	0	0	0	0	1	0

USMC MF TBA by Configuration Code

DIV	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
800	810	TV2226	0	0	0	0	0	0	1	0	0	0	0	0	0	0
** Subtotal **			0	0	0	0	1	1	3	0	0	1	1	0	1	0
** SE-01 **																
800	810	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
800	810	CCSPRW	0	0	0	0	1	0	1	1	0	1	1	0	1	0
800	810	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			2	1	1	1	1	0	1	1	1	1	1	1	1	0
** SE-02B **																
800	810	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
** Subtotal **			0	0	0	0	1	1	1	1	0	1	1	0	1	0
** SE-03C **																
800	810	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
** Subtotal **			0	0	0	0	1	1	1	1	0	1	1	0	1	0
** SE-04B **																
800	810	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
** Subtotal **			0	0	0	0	1	1	1	1	0	1	1	0	1	0
** SH-06 **																
600	650	130J12	1	1	0	1	0	0	0	0	0	0	0	0	0	0
600	650	130T12	0	0	0	0	0	0	0	0	0	0	0	1	1	0
600	650	CCSPRW	0	0	0	0	0	2	0	2	0	2	2	0	1	0
** Subtotal **			1	1	0	1	0	2	0	2	0	2	2	1	2	0
** SM-04B **																
500	510	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
500	510	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	1	0
500	510	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			2	1	1	1	1	1	1	1	1	0	1	1	1	0
** SM-05A **																
500	510	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
500	510	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	1	0
500	510	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			2	1	1	1	1	1	1	1	1	0	1	1	1	0
** SM-06B **																
500	510	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
500	510	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	1	0
** Subtotal **			1	1	1	1	1	1	1	1	1	0	1	1	1	0
** SM-07A **																
500	510	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0

USMC MF TBA by Configuration Code

DIV	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
500	510	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	1	0
** Subtotal **			1	1	1	1	1	1	1	1	1	0	1	1	1	0
** <u>SP-04</u> **																
500	520	135B16	1	0	0	0	0	0	0	0	0	0	0	0	0	0
500	520	1V8R14	0	1	1	2	0	0	0	0	0	0	0	0	0	0
500	520	CCSPRW	0	0	0	0	1	0	0	1	0	0	0	0	0	0
** Subtotal **			1	1	1	2	1	0	0	1	0	0	0	0	0	0
** <u>ST-01</u> **																
600	610	118A36	1	1	0	0	0	0	0	0	1	0	0	0	0	0
600	620	118A36	1	1	0	0	0	0	0	0	1	0	0	0	0	0
600	650	118A36	0	1	0	0	0	0	0	0	0	0	0	0	0	0
600	610	118C24	1	0	0	0	0	0	0	0	1	0	0	1	0	0
600	620	118C24	1	0	0	0	0	0	0	0	1	0	0	1	0	0
600	610	130T12	0	0	0	0	0	0	0	0	0	0	0	3	3	0
600	620	130T12	0	0	0	0	0	0	0	0	0	0	0	1	1	0
600	620	153E16	0	0	0	0	1	1	0	2	0	1	0	0	0	0
600	610	1E6B05	0	2	0	2	0	0	0	0	0	0	0	0	0	0
600	620	1E6B05	0	1	0	1	0	0	0	0	0	0	0	0	0	0
600	620	1HML27	0	0	0	0	0	1	0	2	0	1	1	0	0	0
600	620	1RS53E	0	0	0	0	0	0	0	0	0	0	0	0	1	0
600	610	1V8R14	0	1	1	1	0	0	0	0	0	0	0	0	0	0
600	620	1V8R14	0	1	1	1	0	0	0	0	0	0	0	0	0	0
600	620	253E16	0	0	0	0	1	0	0	0	0	0	0	0	0	0
600	610	2E6B05	0	0	0	2	0	0	0	0	0	0	0	0	0	0
600	620	2E6B05	0	0	0	1	0	0	0	0	0	0	0	0	0	0
MP2	LPZ	2FEFW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
MP2	SSR	2FEFW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
MP2	SEAY	2FERW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
MP2	WLM	2FERW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
600	620	2HML27	0	0	0	0	0	0	0	0	0	0	1	0	0	0
600	610	2V8R14	0	0	1	1	0	0	0	0	0	0	0	0	0	0
600	620	2V8R14	0	0	1	1	0	0	0	0	0	0	0	0	0	0
600	610	3E6B05	0	0	0	2	0	0	0	0	0	0	0	0	0	0
600	620	3E6B05	0	0	0	1	0	0	0	0	0	0	0	0	0	0
MP3	DHL	3FEFW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
MP3	LMS	3FEFW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
MP3	BBO	3FERW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
MP3	PLU	3FERW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
500	520	CCSPFW	2	2	2	2	0	0	0	0	2	0	0	2	0	0
600	610	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
600	620	CCSPFW	2	2	2	2	0	0	0	0	2	0	0	2	0	0
600	650	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
600	690	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
AIS	AIS	CCSPFW	2	2	2	2	0	0	0	0	2	0	0	2	0	0
500	520	CCSPRW	0	0	0	0	0	0	0	0	0	0	0	0	5	0

21 MAY 2018

USMC MF TBA by Configuration Code

DIV	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
600	610	CCSPRW	0	0	0	0	3	3	2	3	0	3	3	0	3	0
600	620	CCSPRW	0	0	0	0	2	2	2	2	0	2	2	0	2	0
600	650	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	2	0
600	690	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
AIS	AIS	CCSPRW	0	0	0	0	2	2	2	2	0	2	2	0	2	0
MPS	FLY	MPSFLY	0	0	0	0	0	0	0	0	0	0	0	0	0	1
600	610	T53E29	0	0	0	0	0	0	0	2	0	0	0	0	0	0
600	620	T53E29	0	0	0	0	0	0	0	1	0	0	0	0	0	0
500	520	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
600	610	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
600	620	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
600	650	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
600	610	TH1M39	0	0	0	0	0	0	0	0	0	0	1	0	0	0
600	620	TH1M39	0	0	0	0	0	0	0	0	0	0	1	0	0	0
500	520	TV8B14	0	0	0	1	0	0	0	0	0	0	0	0	0	0
600	610	TV8B14	0	0	0	6	0	0	0	0	0	0	0	0	0	0
600	620	TV8B14	0	0	0	3	0	0	0	0	0	0	0	0	0	0
** Subtotal **			17	17	13	32	11	11	8	16	13	11	13	15	20	9
** <u>SU-01</u> **																
000	05C	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
000	05D	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
600	600	CCSPFW	4	4	4	4	0	0	0	0	4	0	0	3	0	0
600	670	CCSPFW	4	4	3	4	0	0	0	0	3	0	0	3	0	0
000	05C	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
000	05D	CCSPRW	0	0	0	0	1	0	1	1	0	1	1	0	1	0
600	600	CCSPRW	0	0	0	0	4	4	3	3	0	4	4	0	4	0
600	650	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
600	670	CCSPRW	0	0	0	0	3	3	4	3	0	4	4	0	3	0
S00	S00	F11812	2	0	0	0	0	0	0	0	0	0	0	0	0	0
S00	S00	F11824	2	0	0	0	0	0	0	0	0	0	0	0	0	0
S00	S00	F15316	0	0	0	0	0	0	0	2	0	0	0	0	0	0
S00	S00	F1KJ09	2	0	0	0	0	0	0	0	0	0	0	0	0	0
S00	S00	F1V212	0	0	0	0	2	2	2	0	0	2	2	0	0	0
S00	S00	F1V816	0	0	0	2	0	0	0	0	0	0	0	0	0	0
S00	S00	F1YZ27	0	0	0	0	0	2	0	2	0	2	2	0	0	0
S00	S00	F21812	0	0	0	0	0	0	0	0	2	0	0	0	0	0
S00	S00	F21824	0	0	0	0	0	0	0	0	2	0	0	0	0	0
S00	S00	F25316	0	0	0	0	0	0	0	2	0	0	0	0	0	0
S00	S00	F2KJ09	0	2	0	0	0	0	0	0	0	0	0	0	0	0
S00	S00	F2V212	0	0	0	0	2	0	2	0	0	0	0	0	0	0
S00	S00	F2V816	0	0	0	2	0	0	0	0	0	0	0	0	0	0
S00	S00	F2YZ27	0	0	0	0	0	0	0	2	0	0	2	0	0	0
S00	S00	F31824	0	2	0	0	0	0	0	0	0	0	0	0	0	0
S00	S00	F35316	0	0	0	0	0	2	0	0	0	0	0	0	0	0
S00	S00	F3KJ09	0	0	0	2	0	0	0	0	0	0	0	0	0	0
S00	S00	F3V816	0	0	2	0	0	0	0	0	0	0	0	0	0	0

USMC MF TBA by Configuration Code

DIV	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
S00	S00	F45316	0	0	0	0	2	0	0	0	0	0	0	0	0	0
S00	S00	F4V816	0	0	2	0	0	0	0	0	0	0	0	0	0	0
S00	S00	F55316	0	0	0	0	0	0	0	0	0	2	0	0	0	0
600	600	IOSP14	0	0	0	4	0	0	0	0	0	0	0	0	0	0
S00	S00	MSA	2	1	2	2	2	1	2	2	2	1	2	0	2	0
000	05C	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
000	05C	TV8B14	0	0	0	2	0	0	0	0	0	0	0	0	0	0
** Subtotal **			19	15	15	24	18	16	16	19	15	18	19	8	12	0
** <u>SU-02</u> **																
S00	S00	MSA	4	2	4	4	4	2	2	4	4	2	4	0	4	0
** Subtotal **			4	2	4	4	4	2	2	4	4	2	4	0	4	0
** <u>SU-03</u> **																
600	650	118C24	0	0	0	0	0	0	0	0	1	0	0	1	0	0
600	600	CCSPFW	1	0	1	1	0	0	0	0	0	0	0	1	0	0
600	60C	CCSPFW	1	1	1	1	0	0	0	0	0	0	0	0	0	0
700	700	CCSPFW	1	1	0	1	0	0	0	0	0	0	0	1	0	0
AIS	AIS	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
400	410	CCSPRW	0	0	0	0	1	0	1	1	0	1	1	0	1	0
600	600	CCSPRW	0	0	0	0	1	0	0	1	0	1	0	0	0	0
600	60C	CCSPRW	0	0	0	0	1	0	0	0	0	0	1	0	0	0
700	700	CCSPRW	0	0	0	0	1	1	1	0	0	1	0	0	1	0
AIS	AIS	CCSPRW	0	0	0	0	1	0	1	1	0	1	1	0	1	0
600	600	IOSP14	0	0	0	1	0	0	0	0	0	0	0	0	0	0
600	670	IOSP14	0	0	0	1	0	0	0	0	0	0	0	0	0	0
ATC	ATC	MACSXX	0	1	1	2	1	0	0	1	1	1	2	0	0	0
** Subtotal **			4	4	4	8	6	1	3	4	3	5	5	4	3	0
** <u>SU-05</u> **																
600	600	CCSPFW	1	0	2	0	0	0	0	0	2	0	0	0	0	0
600	60C	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
600	600	CCSPRW	0	0	0	0	2	1	2	2	0	0	2	0	0	0
600	60C	CCSPRW	0	0	0	0	1	1	1	0	0	0	1	0	1	0
S00	S00	MSA	2	2	2	2	2	2	2	2	2	2	2	0	2	0
600	60C	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			5	3	5	3	5	4	5	4	5	2	5	1	3	0
** <u>SU-08</u> **																
MP2	LPZ	2FEFW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
MP2	SSR	2FEFW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
MP2	SEAY	2FERW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
MP2	WLM	2FERW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
MP3	DHL	3FEFW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
MP3	LMS	3FEFW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
MP3	BBO	3FERW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
MP3	PLU	3FERW	0	0	0	0	0	0	0	0	0	0	0	0	0	1

21 MAY 2018

USMC MF TBA by Configuration Code

DIV	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
000	05A	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
000	05A	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
MPS	FLY	MPSFLY	0	0	0	0	0	0	0	0	0	0	0	0	0	1
** Subtotal **			1	1	1	1	1	1	1	1	1	1	1	1	1	9
** <u>SU-12</u> **																
000	05A	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
000	05D	CCSPFW	0	0	0	0	0	0	0	0	1	0	0	1	0	0
600	600	CCSPFW	0	0	0	0	0	0	0	0	0	0	0	1	0	0
AIS	AIS	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
000	040	CCSPRW	0	0	0	0	0	0	1	0	0	0	0	0	0	0
000	05A	CCSPRW	0	0	0	0	1	0	1	1	0	1	1	0	1	0
000	05D	CCSPRW	0	0	0	0	0	0	0	0	0	1	0	0	0	0
400	440	CCSPRW	0	0	0	0	1	1	1	1	0	2	1	0	1	0
600	600	CCSPRW	0	0	0	0	1	0	1	0	0	1	0	0	0	0
AIS	AIS	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
S00	S00	F11812	2	0	0	0	0	0	0	0	0	0	0	0	0	0
S00	S00	F11824	2	0	0	0	0	0	0	0	0	0	0	0	0	0
S00	S00	F15316	0	0	0	0	0	0	0	2	0	0	0	0	0	0
S00	S00	F1KJ09	2	0	0	0	0	0	0	0	0	0	0	0	0	0
S00	S00	F1V212	0	0	0	0	2	2	2	0	0	2	2	0	0	0
S00	S00	F1V816	0	0	0	2	0	0	0	0	0	0	0	0	0	0
S00	S00	F1YZ27	0	0	0	0	0	2	0	2	0	2	2	0	0	0
S00	S00	F21812	0	0	0	0	0	0	0	0	2	0	0	0	0	0
S00	S00	F21824	0	0	0	0	0	0	0	0	2	0	0	0	0	0
S00	S00	F25316	0	0	0	0	0	0	0	2	0	0	0	0	0	0
S00	S00	F2KJ09	0	2	0	0	0	0	0	0	0	0	0	0	0	0
S00	S00	F2V212	0	0	0	0	2	0	2	0	0	0	0	0	0	0
S00	S00	F2V816	0	0	0	2	0	0	0	0	0	0	0	0	0	0
S00	S00	F2YZ27	0	0	0	0	0	0	0	2	0	0	2	0	0	0
S00	S00	F31824	0	2	0	0	0	0	0	0	0	0	0	0	0	0
S00	S00	F35316	0	0	0	0	0	2	0	0	0	0	0	0	0	0
S00	S00	F3KJ09	0	0	0	2	0	0	0	0	0	0	0	0	0	0
S00	S00	F3V816	0	0	2	0	0	0	0	0	0	0	0	0	0	0
S00	S00	F45316	0	0	0	0	2	0	0	0	0	0	0	0	0	0
S00	S00	F4V816	0	0	2	0	0	0	0	0	0	0	0	0	0	0
S00	S00	F55316	0	0	0	0	0	0	0	0	0	2	0	0	0	0
600	670	IOSP14	0	0	0	1	0	0	0	0	0	0	0	0	0	0
S00	S00	MSA	5	3	5	5	5	3	3	5	5	3	5	0	4	0
000	05A	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			14	9	11	14	15	11	12	16	12	15	14	4	7	0
** <u>SW-02</u> **																
800	820	118A36	1	1	0	0	0	0	0	0	1	0	0	1	0	0
800	820	118C24	1	1	0	0	0	0	0	0	1	0	0	0	0	0
800	820	1HML27	0	0	0	0	0	0	0	2	0	0	1	0	2	0
800	820	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0

USMC MF TBA by Configuration Code

DIV	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
800	820	TH1M39	0	0	0	0	0	0	0	0	0	0	1	0	0	0
** Subtotal **			3	2	0	0	0	0	0	2	2	0	2	1	2	0
** <u>TB-01</u> **																
500	520	CCSPRW	0	0	0	0	1	1	0	0	0	1	0	0	0	0
** Subtotal **			0	0	0	0	1	1	0	0	0	1	0	0	0	0
** <u>TB-02</u> **																
500	520	1V2236	0	0	0	0	0	1	2	0	0	1	1	0	0	0
500	520	3V2212	0	0	0	0	1	0	0	0	0	0	0	0	1	0
500	520	TV2226	0	0	0	0	0	0	1	0	0	0	0	0	0	0
** Subtotal **			0	0	0	0	1	1	3	0	0	1	1	0	1	0
** <u>TB-03A</u> **																
500	520	CCSPFW	2	1	1	2	0	0	0	0	1	0	0	1	0	0
500	520	CCSPRW	0	0	0	0	1	1	0	1	0	1	0	0	0	0
500	520	TH1M39	0	0	0	0	0	0	0	0	0	0	1	0	0	0
** Subtotal **			2	1	1	2	1	1	0	1	1	1	1	1	0	0
** <u>TB-04B</u> **																
500	520	CCSPFW	2	1	1	2	0	0	0	0	1	0	0	1	0	0
500	520	CCSPRW	0	0	0	0	1	1	0	1	0	1	0	0	0	0
500	520	TH1M39	0	0	0	0	0	0	0	0	0	0	1	0	0	0
** Subtotal **			2	1	1	2	1	1	0	1	1	1	1	1	0	0
** <u>TL-01</u> **																
000	040	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
600	670	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
000	040	CCSPRW	0	0	0	0	1	1	0	1	0	0	1	0	1	0
600	670	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	1	0
** Subtotal **			2	2	2	2	2	2	1	2	2	0	2	2	2	0
** <u>TR-01</u> **																
400	400	118A12	0	0	0	0	0	0	0	0	0	0	0	1	0	0
400	400	118A36	1	1	0	0	0	0	0	0	0	0	0	0	0	0
400	400	118C24	1	0	0	0	0	0	0	0	0	0	0	0	0	0
400	400	1E6B05	0	1	0	1	0	0	0	0	0	0	0	0	0	0
400	400	2E6B05	0	0	0	1	0	0	0	0	0	0	0	0	0	0
400	400	3E6B05	0	0	0	1	0	0	0	0	0	0	0	0	0	0
000	05D	CCSPFW	1	1	1	1	0	0	0	0	0	0	0	0	0	0
500	500	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
600	600	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	0	0	0
000	05D	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	1	0
400	440	CCSPRW	0	0	0	0	1	0	1	1	0	0	1	0	1	0
500	500	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
600	600	CCSPRW	0	0	0	0	0	1	0	1	0	0	1	0	1	0

USMC MF TBA by Configuration Code

DIV	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
000	05D	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
600	600	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			7	5	3	6	3	3	3	4	2	1	4	2	4	0
** <u>TT-02</u> **																
600	620	1HML27	0	0	0	0	0	1	0	2	0	1	1	0	1	0
600	620	2HML27	0	0	0	0	0	0	0	0	0	0	1	0	0	0
** Subtotal **			0	0	0	0	0	1	0	2	0	1	2	0	1	0
** <u>TT-03A</u> **																
600	620	1HML27	0	0	0	0	0	1	0	2	0	1	1	0	1	0
600	620	2HML27	0	0	0	0	0	0	0	0	0	0	1	0	0	0
** Subtotal **			0	0	0	0	0	1	0	2	0	1	2	0	1	0
** <u>TT-04B</u> **																
600	620	1HML27	0	0	0	0	0	1	0	2	0	1	1	0	1	0
600	620	2HML27	0	0	0	0	0	0	0	0	0	0	1	0	0	0
** Subtotal **			0	0	0	0	0	1	0	2	0	1	2	0	1	0
** <u>TW-05A</u> **																
MP2	LPZ	2FEFW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
MP2	CRF	2FERW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
MP3	LMS	3FEFW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
MP3	CRF	3FERW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
500	510	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
500	510	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
MPS	FLY	MPSFLY	0	0	0	0	0	0	0	0	0	0	0	0	0	1
** Subtotal **			1	1	1	1	1	1	1	1	1	1	1	1	1	5
** <u>TW-06B</u> **																
MP2	LPZ	2FEFW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
MP2	CRF	2FERW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
MP3	LMS	3FEFW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
MP3	CRF	3FERW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
500	510	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
500	510	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
MPS	FLY	MPSFLY	0	0	0	0	0	0	0	0	0	0	0	0	0	1
** Subtotal **			1	1	1	1	1	1	1	1	1	1	1	1	1	5
** <u>VD-05A</u> **																
600	620	CCSPRW	0	0	0	0	0	0	1	1	0	1	1	0	0	0
600	620	T53E29	0	0	0	0	0	0	0	1	0	0	0	0	0	0
600	620	TH1M39	0	0	0	0	0	0	0	0	0	0	1	0	0	0
** Subtotal **			0	0	0	0	0	0	1	2	0	1	2	0	0	0

USMC MF TBA by Configuration Code

DIV	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
** VD-06B **																
600	620	CCSPRW	0	0	0	0	0	0	1	1	0	1	1	0	0	0
600	620	T53E29	0	0	0	0	0	0	0	1	0	0	0	0	0	0
600	620	TH1M39	0	0	0	0	0	0	0	0	0	0	1	0	0	0
** Subtotal **			0	0	0	0	0	0	1	2	0	1	2	0	0	0
** VD-07A **																
600	620	130T12	0	0	0	0	0	0	0	0	0	0	0	0	1	0
600	620	153E16	0	0	0	0	1	0	0	0	0	0	0	0	0	0
600	620	318C24	0	0	0	0	0	0	0	0	1	0	0	0	0	0
600	620	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
600	620	CCSPRW	0	0	0	0	0	1	0	0	0	0	0	0	0	0
600	620	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
600	620	TV8B14	0	0	0	1	0	0	0	0	0	0	0	0	0	0
** Subtotal **			2	1	1	2	1	1	0	0	2	0	0	1	1	0
** VD-08B **																
600	620	130T12	0	0	0	0	0	0	0	0	0	0	0	0	1	0
600	620	153E16	0	0	0	0	1	0	0	0	0	0	0	0	0	0
600	620	318C24	0	0	0	0	0	0	0	0	1	0	0	0	0	0
600	620	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
600	620	CCSPRW	0	0	0	0	0	1	0	0	0	0	0	0	0	0
600	620	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
600	620	TV8B14	0	0	0	1	0	0	0	0	0	0	0	0	0	0
** Subtotal **			2	1	1	2	1	1	0	0	2	0	0	1	1	0
** WC-02 **																
000	030	CCSPFW	2	2	2	1	0	0	0	0	2	0	0	2	0	0
000	040	CCSPFW	1	2	2	2	0	0	0	0	2	0	0	1	0	0
000	030	CCSPRW	0	0	0	0	2	0	2	2	0	0	2	0	2	0
000	040	CCSPRW	0	0	0	0	1	1	0	2	0	0	2	0	2	0
000	030	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
000	040	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			5	4	4	3	3	1	2	4	4	0	4	3	4	0
** WC-08 **																
900	910	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
900	930	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	0	0	0
900	940	CCSPFW	1	1	1	0	0	0	0	0	0	0	0	1	0	0
900	910	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	0	0
900	930	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	1	0
900	940	CCSPRW	0	0	0	0	1	1	1	0	0	0	1	0	1	0
900	910	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
900	940	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			5	3	3	2	3	3	3	2	2	0	3	2	2	0

USMC MF TBA by Configuration Code

DIV	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
** <u>WC-12A</u> **																
600	60C	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
600	60C	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
** Subtotal **			1	1	1	1	1	1	1	1	1	1	1	1	1	0
** <u>WC-13BM</u> **																
600	60C	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
600	60C	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
** Subtotal **			1	1	1	1	1	1	1	1	1	1	1	1	1	0
** <u>WL-04A</u> **																
500	510	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
500	510	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	1	0
500	510	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			2	1	1	1	1	1	1	1	1	0	1	1	1	0
** <u>WL-05A</u> **																
500	510	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
500	510	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	1	0
500	510	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			2	1	1	1	1	1	1	1	1	0	1	1	1	0
** <u>WR-01</u> **																
600	690	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	0	0	0
600	690	CCSPRW	0	0	0	0	0	0	0	1	0	0	0	0	0	0
** Subtotal **			1	1	1	1	0	0	0	1	1	0	0	0	0	0
** <u>WR-02</u> **																
600	690	CCSPRW	0	0	0	0	1	1	1	0	0	1	1	0	1	0
** Subtotal **			0	0	0	0	1	1	1	0	0	1	1	0	1	0
Total			325	254	198	318	227	194	213	234	239	187	241	163	191	58

21 MAY 2018

USMC MF TBA by Contingency Support Package

CONFIG	DIV	BR	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
** <u>118A12</u> **																
FA-02A	500	520	0	0	0	0	0	0	0	0	0	0	0	1	0	0
FA-03B	500	520	0	0	0	0	0	0	0	0	0	0	0	1	0	0
JU-01	500	500	0	0	0	0	0	0	0	0	0	0	0	1	0	0
KA-31	600	650	0	0	0	0	0	0	0	0	0	0	0	1	0	0
TR-01	400	400	0	0	0	0	0	0	0	0	0	0	0	1	0	0
** Subtotal **			0	0	0	0	0	0	0	0	0	0	0	5	0	0
** <u>118A36</u> **																
AT-08	000	S2	2	2	0	0	0	0	0	0	2	0	0	0	0	0
AT-09BM	000	210	2	2	0	0	0	0	0	0	2	0	0	0	0	0
AT-10A	000	210	2	2	0	0	0	0	0	0	2	0	0	0	0	0
BR-01	700	71D	1	1	0	0	0	0	0	0	1	0	0	1	0	0
FA-02A	500	520	1	2	0	0	0	0	0	0	0	0	0	0	0	0
FA-03B	500	520	1	2	0	0	0	0	0	0	0	0	0	0	0	0
GM-02A	700	71B	1	1	0	0	0	0	0	0	1	0	0	1	0	0
GM-03B	700	71B	1	1	0	0	0	0	0	0	1	0	0	1	0	0
JU-01	600	600	1	1	0	0	0	0	0	0	1	0	0	0	0	0
JU-01	500	500	1	1	0	0	0	0	0	0	0	0	0	0	0	0
JU-01	000	000	1	1	0	0	0	0	0	0	1	0	0	0	0	0
KA-31	600	650	2	0	0	0	0	0	0	0	0	0	0	0	0	0
ST-01	600	610	1	1	0	0	0	0	0	0	1	0	0	0	0	0
ST-01	600	620	1	1	0	0	0	0	0	0	1	0	0	0	0	0
ST-01	600	650	0	1	0	0	0	0	0	0	0	0	0	0	0	0
SW-02	800	820	1	1	0	0	0	0	0	0	1	0	0	1	0	0
TR-01	400	400	1	1	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			20	21	0	0	0	0	0	0	14	0	0	4	0	0
** <u>118C24</u> **																
FA-02A	500	520	1	0	0	0	0	0	0	0	0	0	0	0	0	0
FA-03B	500	520	1	0	0	0	0	0	0	0	0	0	0	0	0	0
JU-01	600	600	1	0	0	0	0	0	0	0	1	0	0	1	0	0
JU-01	500	500	1	0	0	0	0	0	0	0	0	0	0	0	0	0
ST-01	600	610	1	0	0	0	0	0	0	0	1	0	0	1	0	0
ST-01	600	620	1	0	0	0	0	0	0	0	1	0	0	1	0	0
SU-03	600	650	0	0	0	0	0	0	0	0	1	0	0	1	0	0
SW-02	800	820	1	1	0	0	0	0	0	0	1	0	0	0	0	0
TR-01	400	400	1	0	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			8	1	0	0	0	0	0	0	5	0	0	4	0	0
** <u>130J12</u> **																
JU-01	800	800	0	1	0	0	0	0	0	0	0	0	0	0	0	0
RR-02	800	810	0	1	0	0	0	0	0	0	0	0	0	0	0	0
RR-03	800	810	0	1	0	0	0	0	0	0	0	0	0	0	0	0
SH-06	600	650	1	1	0	1	0	0	0	0	0	0	0	0	0	0

21 MAY 2018

USMC MF TBA by Contingency Support Package

CONFIG	DIV	BR	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
** Subtotal **			1	4	0	1	0	0	0	0	0	0	0	0	0	0
** <u>130T12</u> **																
JU-01	600	600	0	0	0	0	0	0	0	0	0	0	0	1	2	0
SH-06	600	650	0	0	0	0	0	0	0	0	0	0	0	1	1	0
ST-01	600	610	0	0	0	0	0	0	0	0	0	0	0	3	3	0
ST-01	600	620	0	0	0	0	0	0	0	0	0	0	0	1	1	0
VD-07A	600	620	0	0	0	0	0	0	0	0	0	0	0	0	1	0
VD-08B	600	620	0	0	0	0	0	0	0	0	0	0	0	0	1	0
** Subtotal **			0	0	0	0	0	0	0	0	0	0	0	6	9	0
** <u>135B16</u> **																
BL-01	600	600	0	0	2	0	0	0	0	0	0	0	0	0	0	0
SP-04	500	520	1	0	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			1	0	2	0	0	0	0	0	0	0	0	0	0	0
** <u>153E16</u> **																
JU-01	600	600	0	0	0	0	1	0	0	1	0	0	0	0	0	0
ST-01	600	620	0	0	0	0	1	1	0	2	0	1	0	0	0	0
VD-07A	600	620	0	0	0	0	1	0	0	0	0	0	0	0	0	0
VD-08B	600	620	0	0	0	0	1	0	0	0	0	0	0	0	0	0
** Subtotal **			0	0	0	0	4	1	0	3	0	1	0	0	0	0
** <u>1E6B05</u> **																
JU-09	600	600	0	1	0	1	0	0	0	0	0	0	0	0	0	0
JU-10	600	600	0	1	0	1	0	0	0	0	0	0	0	0	0	0
KA-31	600	650	0	0	0	3	0	0	0	0	0	0	0	0	0	0
PM-01	600	650	0	1	0	1	0	0	0	0	0	0	0	0	0	0
ST-01	600	610	0	2	0	2	0	0	0	0	0	0	0	0	0	0
ST-01	600	620	0	1	0	1	0	0	0	0	0	0	0	0	0	0
TR-01	400	400	0	1	0	1	0	0	0	0	0	0	0	0	0	0
** Subtotal **			0	7	0	10	0	0	0	0	0	0	0	0	0	0
** <u>1HML09</u> **																
BL-01	600	620	0	0	0	0	0	0	0	0	0	0	0	0	1	0
** Subtotal **			0	0	0	0	0	0	0	0	0	0	0	0	1	0
** <u>1HML27</u> **																
BL-01	600	620	0	0	0	0	0	1	0	2	0	2	0	0	0	0
BR-01	700	71D	0	0	0	0	0	0	0	1	0	0	0	0	1	0
JU-01	600	600	0	0	0	0	0	1	0	2	0	1	2	0	1	0
KA-18A	600	600	0	0	0	0	0	0	0	0	0	0	3	0	0	0
KA-31	600	650	0	0	0	0	0	0	0	0	0	0	2	0	0	0
ST-01	600	620	0	0	0	0	0	1	0	2	0	1	1	0	0	0
SW-02	800	820	0	0	0	0	0	0	0	2	0	0	1	0	2	0

21 MAY 2018

USMC MF TBA by Contingency Support Package

CONFIG	DIV	BR	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
TT-02	600	620	0	0	0	0	0	1	0	2	0	1	1	0	1	0
TT-03A	600	620	0	0	0	0	0	1	0	2	0	1	1	0	1	0
TT-04B	600	620	0	0	0	0	0	1	0	2	0	1	1	0	1	0
** Subtotal **			0	0	0	0	0	6	0	15	0	7	12	0	7	0
** <u>1RS53E</u> **																
ST-01	600	620	0	0	0	0	0	0	0	0	0	0	0	0	1	0
** Subtotal **			0	0	0	0	0	0	0	0	0	0	0	0	1	0
** <u>1V2236</u> **																
HY-06C	500	520	0	0	0	0	0	1	1	0	0	1	1	0	0	0
JU-01	800	800	0	0	0	0	0	0	1	0	0	0	0	0	0	0
JU-01	500	500	0	0	0	0	0	1	1	0	0	1	1	0	0	0
KA-18A	600	600	0	0	0	0	2	0	0	0	0	0	0	0	0	0
RR-04A	800	810	0	0	0	0	0	0	2	0	0	1	1	0	0	0
RR-05B	800	810	0	0	0	0	0	0	2	0	0	1	1	0	0	0
RR-06BM	800	810	0	0	0	0	0	0	2	0	0	1	1	0	0	0
TB-02	500	520	0	0	0	0	0	1	2	0	0	1	1	0	0	0
** Subtotal **			0	0	0	0	2	3	11	0	0	6	6	0	0	0
** <u>1V8R14</u> **																
BR-01	700	71D	0	0	1	1	0	0	0	0	0	0	0	0	0	0
GC-01	600	620	0	1	1	1	0	0	0	0	0	0	0	0	0	0
GM-02A	700	71B	0	1	1	1	0	0	0	0	0	0	0	0	0	0
GM-03B	700	71B	0	1	1	1	0	0	0	0	0	0	0	0	0	0
JU-01	600	600	0	1	1	1	0	0	0	0	0	0	0	0	0	0
JU-01	500	500	0	0	0	1	0	0	0	0	0	0	0	0	0	0
PM-02	600	650	0	1	1	1	0	0	0	0	0	0	0	0	0	0
SP-04	500	520	0	1	1	2	0	0	0	0	0	0	0	0	0	0
ST-01	600	610	0	1	1	1	0	0	0	0	0	0	0	0	0	0
ST-01	600	620	0	1	1	1	0	0	0	0	0	0	0	0	0	0
** Subtotal **			0	8	9	11	0	0	0	0	0	0	0	0	0	0
** <u>218A36</u> **																
KA-31	600	650	0	1	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			0	1	0	0	0	0	0	0	0	0	0	0	0	0
** <u>235C10</u> **																
BL-01	600	600	0	0	0	0	0	0	0	0	1	0	0	0	0	0
** Subtotal **			0	0	0	0	0	0	0	0	1	0	0	0	0	0
** <u>253E16</u> **																
ST-01	600	620	0	0	0	0	1	0	0	0	0	0	0	0	0	0
** Subtotal **			0	0	0	0	1	0	0	0	0	0	0	0	0	0

21 MAY 2018

USMC MF TBA by Contingency Support Package

CONFIG	DIV	BR	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
** <u>2E6B05</u> **																
JU-09	600	600	0	0	0	1	0	0	0	0	0	0	0	0	0	0
JU-10	600	600	0	0	0	1	0	0	0	0	0	0	0	0	0	0
KA-31	600	650	0	0	0	3	0	0	0	0	0	0	0	0	0	0
PM-01	600	650	0	0	0	1	0	0	0	0	0	0	0	0	0	0
ST-01	600	610	0	0	0	2	0	0	0	0	0	0	0	0	0	0
ST-01	600	620	0	0	0	1	0	0	0	0	0	0	0	0	0	0
TR-01	400	400	0	0	0	1	0	0	0	0	0	0	0	0	0	0
** Subtotal **			0	0	0	10	0	0	0	0	0	0	0	0	0	0
** <u>2FEFW</u> **																
BL-01	MP2	LPZ	0	0	0	0	0	0	0	0	0	0	0	0	0	2
CU-01	MP2	LPZ	0	0	0	0	0	0	0	0	0	0	0	0	0	1
CU-01	MP2	SSR	0	0	0	0	0	0	0	0	0	0	0	0	0	1
JU-01	MP2	LPZ	0	0	0	0	0	0	0	0	0	0	0	0	0	1
JU-01	MP2	SSR	0	0	0	0	0	0	0	0	0	0	0	0	0	1
ST-01	MP2	LPZ	0	0	0	0	0	0	0	0	0	0	0	0	0	1
ST-01	MP2	SSR	0	0	0	0	0	0	0	0	0	0	0	0	0	1
SU-08	MP2	LPZ	0	0	0	0	0	0	0	0	0	0	0	0	0	1
SU-08	MP2	SSR	0	0	0	0	0	0	0	0	0	0	0	0	0	1
TW-05A	MP2	LPZ	0	0	0	0	0	0	0	0	0	0	0	0	0	1
TW-06B	MP2	LPZ	0	0	0	0	0	0	0	0	0	0	0	0	0	1
** Subtotal **			0	0	0	0	0	0	0	0	0	0	0	0	0	12
** <u>2FERW</u> **																
BL-01	MP2	CRF	0	0	0	0	0	0	0	0	0	0	0	0	0	2
CU-01	MP2	SEAY	0	0	0	0	0	0	0	0	0	0	0	0	0	1
CU-01	MP2	WLM	0	0	0	0	0	0	0	0	0	0	0	0	0	1
JU-01	MP2	SEAY	0	0	0	0	0	0	0	0	0	0	0	0	0	1
JU-01	MP2	WLM	0	0	0	0	0	0	0	0	0	0	0	0	0	1
ST-01	MP2	SEAY	0	0	0	0	0	0	0	0	0	0	0	0	0	1
ST-01	MP2	WLM	0	0	0	0	0	0	0	0	0	0	0	0	0	1
SU-08	MP2	SEAY	0	0	0	0	0	0	0	0	0	0	0	0	0	1
SU-08	MP2	WLM	0	0	0	0	0	0	0	0	0	0	0	0	0	1
TW-05A	MP2	CRF	0	0	0	0	0	0	0	0	0	0	0	0	0	1
TW-06B	MP2	CRF	0	0	0	0	0	0	0	0	0	0	0	0	0	1
** Subtotal **			0	0	0	0	0	0	0	0	0	0	0	0	0	12
** <u>2HML09</u> **																
BL-01	600	620	0	0	0	0	0	0	0	0	0	0	0	0	1	0
** Subtotal **			0	0	0	0	0	0	0	0	0	0	0	0	1	0
** <u>2HML27</u> **																
BL-01	600	620	0	0	0	0	0	0	0	0	0	0	1	0	0	0
JU-01	600	600	0	0	0	0	0	0	0	0	0	0	1	0	0	0
ST-01	600	620	0	0	0	0	0	0	0	0	0	0	1	0	0	0

21 MAY 2018

USMC MF TBA by Contingency Support Package

CONFIG	DIV	BR	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
TT-02	600	620	0	0	0	0	0	0	0	0	0	0	1	0	0	0
TT-03A	600	620	0	0	0	0	0	0	0	0	0	0	1	0	0	0
TT-04B	600	620	0	0	0	0	0	0	0	0	0	0	1	0	0	0
** Subtotal **			0	0	0	0	0	0	0	0	0	0	6	0	0	0
** <u>2V8R14</u> **																
GC-01	600	620	0	0	1	1	0	0	0	0	0	0	0	0	0	0
JU-01	600	600	0	0	1	1	0	0	0	0	0	0	0	0	0	0
ST-01	600	610	0	0	1	1	0	0	0	0	0	0	0	0	0	0
ST-01	600	620	0	0	1	1	0	0	0	0	0	0	0	0	0	0
** Subtotal **			0	0	4	4	0	0	0	0	0	0	0	0	0	0
** <u>318A36</u> **																
FA-02A	500	520	0	0	0	0	0	0	0	0	1	0	0	0	0	0
FA-03B	500	520	0	0	0	0	0	0	0	0	1	0	0	0	0	0
JU-01	600	600	0	0	0	0	0	0	0	0	1	0	0	0	0	0
KA-31	600	650	0	0	0	0	0	0	0	0	4	0	0	0	0	0
** Subtotal **			0	0	0	0	0	0	0	0	7	0	0	0	0	0
** <u>318C24</u> **																
FA-02A	500	520	0	0	0	0	0	0	0	0	1	0	0	0	0	0
FA-03B	500	520	0	0	0	0	0	0	0	0	1	0	0	0	0	0
JU-01	500	500	0	0	0	0	0	0	0	0	1	0	0	0	0	0
VD-07A	600	620	0	0	0	0	0	0	0	0	1	0	0	0	0	0
VD-08B	600	620	0	0	0	0	0	0	0	0	1	0	0	0	0	0
** Subtotal **			0	0	0	0	0	0	0	0	5	0	0	0	0	0
** <u>335B10</u> **																
BL-01	600	600	2	0	0	0	0	0	0	0	0	0	0	1	0	0
** Subtotal **			2	0	0	0	0	0	0	0	0	0	0	1	0	0
** <u>3E6B05</u> **																
JU-09	600	600	0	0	0	1	0	0	0	0	0	0	0	0	0	0
JU-10	600	600	0	0	0	1	0	0	0	0	0	0	0	0	0	0
PM-01	600	650	0	0	0	1	0	0	0	0	0	0	0	0	0	0
ST-01	600	610	0	0	0	2	0	0	0	0	0	0	0	0	0	0
ST-01	600	620	0	0	0	1	0	0	0	0	0	0	0	0	0	0
TR-01	400	400	0	0	0	1	0	0	0	0	0	0	0	0	0	0
** Subtotal **			0	0	0	7	0	0	0	0	0	0	0	0	0	0
** <u>3FEFW</u> **																
BL-01	MP3	LMS	0	0	0	0	0	0	0	0	0	0	0	0	0	2
CU-01	MP3	DHL	0	0	0	0	0	0	0	0	0	0	0	0	0	1
CU-01	MP3	LMS	0	0	0	0	0	0	0	0	0	0	0	0	0	1
JU-01	MP3	DHL	0	0	0	0	0	0	0	0	0	0	0	0	0	1

21 MAY 2018

USMC MF TBA by Contingency Support Package

CONFIG	DIV	BR	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
JU-01	MP3	LMS	0	0	0	0	0	0	0	0	0	0	0	0	0	1
ST-01	MP3	DHL	0	0	0	0	0	0	0	0	0	0	0	0	0	1
ST-01	MP3	LMS	0	0	0	0	0	0	0	0	0	0	0	0	0	1
SU-08	MP3	DHL	0	0	0	0	0	0	0	0	0	0	0	0	0	1
SU-08	MP3	LMS	0	0	0	0	0	0	0	0	0	0	0	0	0	1
TW-05A	MP3	LMS	0	0	0	0	0	0	0	0	0	0	0	0	0	1
TW-06B	MP3	LMS	0	0	0	0	0	0	0	0	0	0	0	0	0	1
** Subtotal **			0	0	0	0	0	0	0	0	0	0	0	0	0	12
** <u>3FERW</u> **																
BL-01	MP3	CRF	0	0	0	0	0	0	0	0	0	0	0	0	0	2
CU-01	MP3	BBO	0	0	0	0	0	0	0	0	0	0	0	0	0	1
CU-01	MP3	PLU	0	0	0	0	0	0	0	0	0	0	0	0	0	1
JU-01	MP3	BBO	0	0	0	0	0	0	0	0	0	0	0	0	0	1
JU-01	MP3	PLU	0	0	0	0	0	0	0	0	0	0	0	0	0	1
ST-01	MP3	BBO	0	0	0	0	0	0	0	0	0	0	0	0	0	1
ST-01	MP3	PLU	0	0	0	0	0	0	0	0	0	0	0	0	0	1
SU-08	MP3	BBO	0	0	0	0	0	0	0	0	0	0	0	0	0	1
SU-08	MP3	PLU	0	0	0	0	0	0	0	0	0	0	0	0	0	1
TW-05A	MP3	CRF	0	0	0	0	0	0	0	0	0	0	0	0	0	1
TW-06B	MP3	CRF	0	0	0	0	0	0	0	0	0	0	0	0	0	1
** Subtotal **			0	0	0	0	0	0	0	0	0	0	0	0	0	12
** <u>3HML27</u> **																
BL-01	600	620	0	0	0	0	0	0	0	0	0	0	1	0	0	0
** Subtotal **			0	0	0	0	0	0	0	0	0	0	1	0	0	0
** <u>3V2212</u> **																
HY-06C	500	520	0	0	0	0	1	0	0	0	0	0	0	0	1	0
JU-01	500	500	0	0	0	0	1	0	0	0	0	0	0	0	1	0
KA-31	600	650	0	0	0	0	1	0	0	0	0	0	0	0	0	0
RR-04A	800	810	0	0	0	0	1	1	0	0	0	0	0	0	1	0
RR-05B	800	810	0	0	0	0	1	1	0	0	0	0	0	0	1	0
RR-06BM	800	810	0	0	0	0	1	1	0	0	0	0	0	0	1	0
TB-02	500	520	0	0	0	0	1	0	0	0	0	0	0	0	1	0
** Subtotal **			0	0	0	0	7	3	0	0	0	0	0	0	6	0
** <u>435B16</u> **																
BL-01	600	600	0	0	0	2	0	0	0	0	0	0	0	1	0	0
** Subtotal **			0	0	0	2	0	0	0	0	0	0	0	1	0	0
** <u>4HML27</u> **																
BL-01	600	620	0	0	0	0	0	0	0	2	0	0	0	0	0	0
JU-01	600	600	0	0	0	0	0	0	0	1	0	0	0	0	0	0
** Subtotal **			0	0	0	0	0	0	0	3	0	0	0	0	0	0

21 MAY 2018

USMC MF TBA by Contingency Support Package

CONFIG	DIV	BR	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
** 535B16 **																
BL-01	600	600	0	1	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			0	1	0	0	0	0	0	0	0	0	0	0	0	0
** BEAFFW **																
EA-01	ZZC	EAF	1	1	1	2	0	0	0	0	1	0	0	0	0	0
EA-02	ZZC	EAF	0	0	0	2	0	0	0	0	0	0	0	0	0	0
** Subtotal **			1	1	1	4	0	0	0	0	1	0	0	0	0	0
** BEAFRW **																
EA-01	ZZC	EAF	0	0	0	0	1	0	1	1	0	1	1	0	0	0
EA-02	ZZC	EAF	0	0	0	0	2	0	0	0	0	2	0	0	0	0
** Subtotal **			0	0	0	0	3	0	1	1	0	3	1	0	0	0
** CCSPFW **																
AM-01	000	05C	0	1	1	0	0	0	0	0	1	0	0	0	0	0
AV-01A	600	600	2	0	2	0	0	0	0	0	2	0	0	0	0	0
AV-02B	600	600	2	0	2	0	0	0	0	0	2	0	0	0	0	0
BL-01	900	940	1	1	1	1	0	0	0	0	1	0	0	0	0	0
BL-01	600	620	1	1	1	1	0	0	0	0	1	0	0	1	0	0
BR-04A	700	71D	1	1	0	1	0	0	0	0	0	0	0	1	0	0
BR-05B	700	71D	1	1	0	1	0	0	0	0	0	0	0	1	0	0
CA-01	600	670	2	2	0	2	0	0	0	0	0	0	0	0	0	0
CA-04	600	670	1	1	1	1	0	0	0	0	1	0	0	1	0	0
CL-01	600	670	2	2	2	2	0	0	0	0	2	0	0	2	0	0
CL-02	600	670	1	1	1	1	0	0	0	0	1	0	0	1	0	0
CL-04	600	610	2	2	2	2	0	0	0	0	2	0	0	2	0	0
CL-04	600	670	2	2	2	2	0	0	0	0	2	0	0	2	0	0
CL-06	600	670	1	1	1	1	0	0	0	0	1	0	0	0	0	0
CL-09	600	670	2	2	2	2	0	0	0	0	2	0	0	2	0	0
CL-10	600	670	2	2	2	2	0	0	0	0	2	0	0	2	0	0
CR-04	600	690	2	2	2	2	0	0	0	0	2	0	0	2	0	0
CS-02A	500	510	1	1	1	1	0	0	0	0	1	0	0	1	0	0
CS-03BM	500	510	1	1	1	1	0	0	0	0	1	0	0	1	0	0
CU-01	900	930	0	0	0	0	0	0	0	0	0	0	0	1	0	0
CU-01	900	940	0	0	0	1	0	0	0	0	1	0	0	0	0	0
CU-01	800	800	1	1	1	1	0	0	0	0	1	0	0	1	0	0
CU-01	700	700	1	1	0	1	0	0	0	0	0	0	0	1	0	0
CU-01	700	730	1	1	0	1	0	0	0	0	0	0	0	1	0	0
CU-01	600	600	3	3	3	3	0	0	0	0	2	0	0	4	0	0
CU-01	600	670	0	0	0	0	0	0	0	0	0	0	0	1	0	0
CU-01	500	500	1	1	1	1	0	0	0	0	1	0	0	1	0	0
CU-01	400	400	1	1	1	1	0	0	0	0	0	0	0	0	0	0
CU-01	000	010	2	2	2	2	0	0	0	0	1	0	0	2	0	0
CU-01	000	020	1	1	1	3	0	0	0	0	3	0	0	1	0	0
CU-01	000	030	0	0	0	1	0	0	0	0	0	0	0	0	0	0

21 MAY 2018

USMC MF TBA by Contingency Support Package

CONFIG	DIV	BR	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
CU-01	000	040	1	0	0	0	0	0	0	0	0	0	0	1	0	0
CU-01	000	05C	1	0	0	1	0	0	0	0	0	0	0	1	0	0
CY-01	600	610	1	1	1	1	0	0	0	0	1	0	0	1	0	0
DP-03	AIS	AIS	1	1	1	1	0	0	0	0	1	0	0	1	0	0
DP-18A	AIS	AIS	1	1	1	1	0	0	0	0	1	0	0	1	0	0
FC-05	700	730	1	1	0	1	0	0	0	0	0	0	0	1	0	0
FS-01	700	700	1	1	0	1	0	0	0	0	0	0	0	1	0	0
FS-01	600	600	1	1	1	1	0	0	0	0	1	0	0	1	0	0
FS-01	500	500	1	1	1	1	0	0	0	0	1	0	0	1	0	0
FS-01	400	400	1	1	1	1	0	0	0	0	1	0	0	0	0	0
HC-01	500	520	1	1	1	1	0	0	0	0	1	0	0	1	1	0
HC-02	500	520	1	1	1	1	0	0	0	0	1	0	0	1	1	0
HY-07A	500	520	1	1	0	1	0	0	0	0	1	0	0	1	0	0
HY-08B	500	520	1	1	0	1	0	0	0	0	1	0	0	1	0	0
JU-01	AIS	AIS	1	1	1	1	0	0	0	0	1	0	0	1	0	0
JU-01	900	900	1	1	1	1	0	0	0	0	1	0	0	1	0	0
JU-01	800	800	1	1	1	1	0	0	0	0	1	0	0	1	0	0
JU-01	700	700	2	2	0	2	0	0	0	0	0	0	0	2	0	0
JU-01	600	600	12	11	12	11	0	0	0	0	12	0	0	10	0	0
JU-01	500	500	5	5	5	5	0	0	0	0	5	0	0	5	1	0
JU-01	000	000	3	3	3	4	0	0	0	0	3	0	0	3	0	0
KA-18A	600	600	7	7	5	7	0	0	0	0	8	0	0	2	0	0
KA-19A	600	650	2	2	2	2	0	0	0	0	2	0	0	1	0	0
KA-20B	600	650	2	2	2	2	0	0	0	0	2	0	0	1	0	0
KA-31	600	650	3	3	3	3	0	0	0	0	3	0	0	3	0	0
MC-01	700	700	1	1	0	1	0	0	0	0	0	0	0	1	0	0
MC-01	600	600	1	1	1	1	0	0	0	0	1	0	0	0	0	0
MC-01	600	670	1	1	1	1	0	0	0	0	1	0	0	1	0	0
MC-01	000	020	2	2	2	0	0	0	0	0	0	0	0	2	0	0
MM-01	500	510	1	1	1	1	0	0	0	0	1	0	0	1	0	0
MM-02	500	510	1	1	1	1	0	0	0	0	1	0	0	1	1	0
MM-03	500	510	1	1	1	1	0	0	0	0	1	0	0	1	1	0
MM-04	500	510	1	1	1	1	0	0	0	0	1	0	0	1	1	0
NT-06	500	530	0	1	0	0	0	0	0	0	0	0	0	0	0	0
NT-08	500	530	1	1	1	1	0	0	0	0	1	0	0	1	0	0
PW-01	500	500	1	1	1	1	0	0	0	0	1	0	0	1	0	0
RR-02	800	810	1	1	1	1	0	0	0	0	1	0	0	1	0	0
RR-03	800	810	1	1	1	1	0	0	0	0	1	0	0	1	0	0
SE-01	800	810	1	1	1	1	0	0	0	0	1	0	0	1	0	0
SM-04B	500	510	1	1	1	1	0	0	0	0	1	0	0	1	0	0
SM-05A	500	510	1	1	1	1	0	0	0	0	1	0	0	1	0	0
SM-06B	500	510	1	1	1	1	0	0	0	0	1	0	0	1	0	0
SM-07A	500	510	1	1	1	1	0	0	0	0	1	0	0	1	0	0
ST-01	AIS	AIS	2	2	2	2	0	0	0	0	2	0	0	2	0	0
ST-01	600	610	1	1	1	1	0	0	0	0	1	0	0	1	0	0
ST-01	600	620	2	2	2	2	0	0	0	0	2	0	0	2	0	0
ST-01	600	650	1	1	1	1	0	0	0	0	1	0	0	1	0	0
ST-01	600	690	1	1	1	1	0	0	0	0	1	0	0	1	0	0

21 MAY 2018

USMC MF TBA by Contingency Support Package

CONFIG	DIV	BR	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
ST-01	500	520	2	2	2	2	0	0	0	0	2	0	0	2	0	0
SU-01	600	600	4	4	4	4	0	0	0	0	4	0	0	3	0	0
SU-01	600	670	4	4	3	4	0	0	0	0	3	0	0	3	0	0
SU-01	000	05C	1	1	1	1	0	0	0	0	1	0	0	1	0	0
SU-01	000	05D	1	1	1	1	0	0	0	0	1	0	0	1	0	0
SU-03	AIS	AIS	1	1	1	1	0	0	0	0	1	0	0	1	0	0
SU-03	700	700	1	1	0	1	0	0	0	0	0	0	0	1	0	0
SU-03	600	600	1	0	1	1	0	0	0	0	0	0	0	1	0	0
SU-03	600	60C	1	1	1	1	0	0	0	0	0	0	0	0	0	0
SU-05	600	600	1	0	2	0	0	0	0	0	2	0	0	0	0	0
SU-05	600	60C	1	1	1	1	0	0	0	0	1	0	0	1	0	0
SU-08	000	05A	1	1	1	1	0	0	0	0	1	0	0	1	0	0
SU-12	AIS	AIS	1	1	1	1	0	0	0	0	1	0	0	1	0	0
SU-12	600	600	0	0	0	0	0	0	0	0	0	0	0	1	0	0
SU-12	000	05A	1	1	1	1	0	0	0	0	1	0	0	1	0	0
SU-12	000	05D	0	0	0	0	0	0	0	0	1	0	0	1	0	0
TB-03A	500	520	2	1	1	2	0	0	0	0	1	0	0	1	0	0
TB-04B	500	520	2	1	1	2	0	0	0	0	1	0	0	1	0	0
TL-01	600	670	1	1	1	1	0	0	0	0	1	0	0	1	0	0
TL-01	000	040	1	1	1	1	0	0	0	0	1	0	0	1	0	0
TR-01	600	600	1	1	1	1	0	0	0	0	1	0	0	0	0	0
TR-01	500	500	1	1	1	1	0	0	0	0	1	0	0	1	0	0
TR-01	000	05D	1	1	1	1	0	0	0	0	0	0	0	0	0	0
TW-05A	500	510	1	1	1	1	0	0	0	0	1	0	0	1	0	0
TW-06B	500	510	1	1	1	1	0	0	0	0	1	0	0	1	0	0
VD-07A	600	620	1	1	1	1	0	0	0	0	1	0	0	1	0	0
VD-08B	600	620	1	1	1	1	0	0	0	0	1	0	0	1	0	0
WC-02	000	030	2	2	2	1	0	0	0	0	2	0	0	2	0	0
WC-02	000	040	1	2	2	2	0	0	0	0	2	0	0	1	0	0
WC-08	900	910	1	1	1	1	0	0	0	0	1	0	0	1	0	0
WC-08	900	930	1	1	1	1	0	0	0	0	1	0	0	0	0	0
WC-08	900	940	1	1	1	0	0	0	0	0	0	0	0	1	0	0
WC-12A	600	60C	1	1	1	1	0	0	0	0	1	0	0	1	0	0
WC-13BM	600	60C	1	1	1	1	0	0	0	0	1	0	0	1	0	0
WL-04A	500	510	1	1	1	1	0	0	0	0	1	0	0	1	0	0
WL-05A	500	510	1	1	1	1	0	0	0	0	1	0	0	1	0	0
WR-01	600	690	1	1	1	1	0	0	0	0	1	0	0	0	0	0
** Subtotal **			161	153	143	156	0	0	0	0	143	0	0	136	6	0
** <u>CCSPRW</u> **																
AM-01	000	05C	0	0	0	0	1	1	1	1	0	0	1	0	1	0
AV-01A	600	600	0	0	0	0	2	2	2	2	0	0	2	0	0	0
AV-02B	600	600	0	0	0	0	2	2	2	2	0	0	2	0	0	0
BL-01	900	940	0	0	0	0	1	1	1	1	0	1	1	0	1	0
BL-01	600	620	0	0	0	0	1	1	1	1	0	1	1	0	1	0
BR-04A	700	71D	0	0	0	0	1	1	1	0	0	1	0	0	1	0
BR-05B	700	71D	0	0	0	0	1	1	1	0	0	1	0	0	1	0

21 MAY 2018

USMC MF TBA by Contingency Support Package

CONFIG	DIV	BR	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
CA-04	600	670	0	0	0	0	1	1	1	1	0	1	1	0	1	0
CA-07A	600	670	0	0	0	0	0	0	1	0	0	1	1	0	0	0
CA-08B	600	670	0	0	0	0	0	0	1	0	0	1	1	0	0	0
CA-09	600	670	0	0	0	0	0	1	1	0	0	0	1	0	0	0
CL-01	600	670	0	0	0	0	2	2	2	2	0	2	2	0	2	0
CL-02	600	670	0	0	0	0	1	1	1	1	0	1	1	0	1	0
CL-04	600	610	0	0	0	0	2	2	2	2	0	2	2	0	2	0
CL-04	600	670	0	0	0	0	2	2	2	2	0	2	2	0	2	0
CL-06	600	670	0	0	0	0	1	1	1	1	0	1	1	0	1	0
CL-09	600	670	0	0	0	0	1	1	1	1	0	1	1	0	1	0
CL-10	600	670	0	0	0	0	2	2	2	2	0	2	2	0	2	0
CR-04	600	690	0	0	0	0	2	2	2	2	0	2	2	0	2	0
CS-02A	500	510	0	0	0	0	1	1	1	1	0	1	1	0	1	0
CS-03BM	500	510	0	0	0	0	1	1	1	1	0	1	1	0	1	0
CU-01	AIS	AIS	0	0	0	0	0	1	0	0	0	0	0	0	0	0
CU-01	900	910	0	0	0	0	0	0	0	0	0	0	0	0	1	0
CU-01	900	940	0	0	0	0	0	0	0	1	0	0	0	0	0	0
CU-01	800	800	0	0	0	0	1	1	1	1	0	1	1	0	1	0
CU-01	700	700	0	0	0	0	1	1	1	0	0	1	0	0	1	0
CU-01	700	730	0	0	0	0	1	1	1	0	0	1	0	0	1	0
CU-01	600	600	0	0	0	0	3	3	3	2	0	3	3	0	3	0
CU-01	500	500	0	0	0	0	1	1	1	1	0	1	1	0	1	0
CU-01	400	400	0	0	0	0	1	1	1	1	0	1	1	0	1	0
CU-01	000	010	0	0	0	0	2	2	2	2	0	2	2	0	2	0
CU-01	000	020	0	0	0	0	1	1	1	1	0	1	1	0	1	0
CU-01	000	040	0	0	0	0	2	1	2	1	0	1	1	0	1	0
CY-01	600	610	0	0	0	0	1	1	1	1	0	1	1	0	1	0
DP-03	AIS	AIS	0	0	0	0	1	0	1	1	0	1	1	0	1	0
DP-18A	AIS	AIS	0	0	0	0	1	1	1	1	0	1	1	0	1	0
FC-05	700	730	0	0	0	0	1	1	1	0	0	0	0	0	1	0
FS-01	700	700	0	0	0	0	1	1	1	0	0	1	0	0	1	0
FS-01	600	600	0	0	0	0	1	1	1	1	0	1	1	0	1	0
FS-01	500	500	0	0	0	0	1	1	1	1	0	1	1	0	1	0
FS-01	400	400	0	0	0	0	1	0	1	1	0	1	1	0	1	0
GM-02A	700	71B	0	0	0	0	1	1	1	0	0	1	0	0	1	0
GM-03B	700	71B	0	0	0	0	1	1	1	0	0	1	0	0	1	0
HC-01	500	520	0	0	0	0	1	1	1	1	0	1	1	0	0	0
HC-02	500	520	0	0	0	0	1	1	1	1	0	1	1	0	0	0
HY-07A	500	520	0	0	0	0	1	1	1	1	0	1	1	0	1	0
HY-08B	500	520	0	0	0	0	1	1	1	1	0	1	1	0	1	0
JU-01	AIS	AIS	0	0	0	0	1	1	1	1	0	1	1	0	1	0
JU-01	900	900	0	0	0	0	1	1	1	1	0	1	1	0	1	0
JU-01	800	800	0	0	0	0	1	1	1	1	0	1	1	0	1	0
JU-01	700	700	0	0	0	0	2	2	2	1	0	2	0	0	1	0
JU-01	600	600	0	0	0	0	11	10	11	11	0	11	12	0	9	0
JU-01	500	500	0	0	0	0	5	5	4	5	0	5	5	0	5	0
JU-01	400	400	0	0	0	0	2	1	2	2	0	2	2	0	2	0
JU-01	000	000	0	0	0	0	3	2	3	3	0	3	3	0	3	0

21 MAY 2018

USMC MF TBA by Contingency Support Package

CONFIG	DIV	BR	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
KA-18A	600	600	0	0	0	0	4	3	4	4	0	3	4	0	2	0
KA-31	600	650	0	0	0	0	3	3	3	3	0	3	3	0	3	0
MC-01	700	700	0	0	0	0	1	1	1	0	0	0	0	0	1	0
MC-01	600	600	0	0	0	0	1	0	1	1	0	0	1	0	1	0
MC-01	600	670	0	0	0	0	1	1	1	1	0	0	1	0	1	0
MC-01	000	020	0	0	0	0	2	1	2	2	0	0	2	0	2	0
MM-01	500	510	0	0	0	0	1	1	1	1	0	0	1	0	0	0
MM-02	500	510	0	0	0	0	1	1	1	1	0	0	1	0	0	0
MM-03	500	510	0	0	0	0	1	1	1	1	0	0	1	0	0	0
MM-04	500	510	0	0	0	0	1	1	1	1	0	0	1	0	0	0
NT-06	500	530	0	0	0	0	1	0	1	0	0	0	1	0	0	0
NT-08	500	530	0	0	0	0	1	1	1	1	0	0	1	0	1	0
PP-01	400	410	0	0	0	0	1	1	1	1	0	0	1	0	1	0
PP-03A	400	440	0	0	0	0	1	1	1	1	0	0	1	0	1	0
PP-04BM	400	440	0	0	0	0	1	1	1	1	0	0	1	0	1	0
PW-01	500	500	0	0	0	0	1	1	1	1	0	1	1	0	1	0
SE-01	800	810	0	0	0	0	1	0	1	1	0	1	1	0	1	0
SE-02B	800	810	0	0	0	0	1	1	1	1	0	1	1	0	1	0
SE-03C	800	810	0	0	0	0	1	1	1	1	0	1	1	0	1	0
SE-04B	800	810	0	0	0	0	1	1	1	1	0	1	1	0	1	0
SH-06	600	650	0	0	0	0	0	2	0	2	0	2	2	0	1	0
SM-04B	500	510	0	0	0	0	1	1	1	1	0	0	1	0	1	0
SM-05A	500	510	0	0	0	0	1	1	1	1	0	0	1	0	1	0
SM-06B	500	510	0	0	0	0	1	1	1	1	0	0	1	0	1	0
SM-07A	500	510	0	0	0	0	1	1	1	1	0	0	1	0	1	0
SP-04	500	520	0	0	0	0	1	0	0	1	0	0	0	0	0	0
ST-01	AIS	AIS	0	0	0	0	2	2	2	2	0	2	2	0	2	0
ST-01	600	610	0	0	0	0	3	3	2	3	0	3	3	0	3	0
ST-01	600	620	0	0	0	0	2	2	2	2	0	2	2	0	2	0
ST-01	600	650	0	0	0	0	1	1	1	1	0	1	1	0	2	0
ST-01	600	690	0	0	0	0	1	1	1	1	0	1	1	0	1	0
ST-01	500	520	0	0	0	0	0	0	0	0	0	0	0	0	5	0
SU-01	600	600	0	0	0	0	4	4	3	3	0	4	4	0	4	0
SU-01	600	650	0	0	0	0	1	1	1	1	0	1	1	0	1	0
SU-01	600	670	0	0	0	0	3	3	4	3	0	4	4	0	3	0
SU-01	000	05C	0	0	0	0	1	1	1	1	0	1	1	0	1	0
SU-01	000	05D	0	0	0	0	1	0	1	1	0	1	1	0	1	0
SU-03	AIS	AIS	0	0	0	0	1	0	1	1	0	1	1	0	1	0
SU-03	700	700	0	0	0	0	1	1	1	0	0	1	0	0	1	0
SU-03	600	600	0	0	0	0	1	0	0	1	0	1	0	0	0	0
SU-03	600	60C	0	0	0	0	1	0	0	0	0	0	1	0	0	0
SU-03	400	410	0	0	0	0	1	0	1	1	0	1	1	0	1	0
SU-05	600	600	0	0	0	0	2	1	2	2	0	0	2	0	0	0
SU-05	600	60C	0	0	0	0	1	1	1	0	0	0	1	0	1	0
SU-08	000	05A	0	0	0	0	1	1	1	1	0	1	1	0	1	0
SU-12	AIS	AIS	0	0	0	0	1	1	1	1	0	1	1	0	1	0
SU-12	600	600	0	0	0	0	1	0	1	0	0	1	0	0	0	0
SU-12	400	440	0	0	0	0	1	1	1	1	0	2	1	0	1	0

21 MAY 2018

USMC MF TBA by Contingency Support Package

CONFIG	DIV	BR	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
SU-12	000	040	0	0	0	0	0	0	1	0	0	0	0	0	0	0
SU-12	000	05A	0	0	0	0	1	0	1	1	0	1	1	0	1	0
SU-12	000	05D	0	0	0	0	0	0	0	0	0	1	0	0	0	0
TB-01	500	520	0	0	0	0	1	1	0	0	0	1	0	0	0	0
TB-03A	500	520	0	0	0	0	1	1	0	1	0	1	0	0	0	0
TB-04B	500	520	0	0	0	0	1	1	0	1	0	1	0	0	0	0
TL-01	600	670	0	0	0	0	1	1	1	1	0	0	1	0	1	0
TL-01	000	040	0	0	0	0	1	1	0	1	0	0	1	0	1	0
TR-01	600	600	0	0	0	0	0	1	0	1	0	0	1	0	1	0
TR-01	500	500	0	0	0	0	1	1	1	1	0	1	1	0	1	0
TR-01	400	440	0	0	0	0	1	0	1	1	0	0	1	0	1	0
TR-01	000	05D	0	0	0	0	1	1	1	1	0	0	1	0	1	0
TW-05A	500	510	0	0	0	0	1	1	1	1	0	1	1	0	1	0
TW-06B	500	510	0	0	0	0	1	1	1	1	0	1	1	0	1	0
VD-05A	600	620	0	0	0	0	0	0	1	1	0	1	1	0	0	0
VD-06B	600	620	0	0	0	0	0	0	1	1	0	1	1	0	0	0
VD-07A	600	620	0	0	0	0	0	1	0	0	0	0	0	0	0	0
VD-08B	600	620	0	0	0	0	0	1	0	0	0	0	0	0	0	0
WC-02	000	030	0	0	0	0	2	0	2	2	0	0	2	0	2	0
WC-02	000	040	0	0	0	0	1	1	0	2	0	0	2	0	2	0
WC-08	900	910	0	0	0	0	1	1	1	1	0	0	1	0	0	0
WC-08	900	930	0	0	0	0	1	1	1	1	0	0	1	0	1	0
WC-08	900	940	0	0	0	0	1	1	1	0	0	0	1	0	1	0
WC-12A	600	60C	0	0	0	0	1	1	1	1	0	1	1	0	1	0
WC-13BM	600	60C	0	0	0	0	1	1	1	1	0	1	1	0	1	0
WL-04A	500	510	0	0	0	0	1	1	1	1	0	0	1	0	1	0
WL-05A	500	510	0	0	0	0	1	1	1	1	0	0	1	0	1	0
WR-01	600	690	0	0	0	0	0	0	0	1	0	0	0	0	0	0
WR-02	600	690	0	0	0	0	1	1	1	0	0	1	1	0	1	0
** Subtotal **			0	0	0	0	162	146	158	149	0	128	154	0	145	0
** <u>EAF</u> **																
EA-01	MP3	BTN	0	0	0	0	0	0	0	0	0	0	0	0	0	1
EA-01	MP2	SKM	0	0	0	0	0	0	0	0	0	0	0	0	0	1
** Subtotal **			0	0	0	0	0	0	0	0	0	0	0	0	0	2
** <u>F11812</u> **																
ED-01	S00	S00	2	0	0	0	0	0	0	0	0	0	0	0	0	0
FS-01	S00	S00	1	0	0	0	0	0	0	0	0	0	0	0	0	0
JU-01	S00	S00	1	0	0	0	0	0	0	0	0	0	0	0	0	0
SU-01	S00	S00	2	0	0	0	0	0	0	0	0	0	0	0	0	0
SU-12	S00	S00	2	0	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			8	0	0	0	0	0	0	0	0	0	0	0	0	0

21 MAY 2018

USMC MF TBA by Contingency Support Package

CONFIG	DIV	BR	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
** F11824 **																
ED-01	S00	S00	2	0	0	0	0	0	0	0	0	0	0	0	0	0
FS-01	S00	S00	1	0	0	0	0	0	0	0	0	0	0	0	0	0
JU-01	S00	S00	1	0	0	0	0	0	0	0	0	0	0	0	0	0
SU-01	S00	S00	2	0	0	0	0	0	0	0	0	0	0	0	0	0
SU-12	S00	S00	2	0	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			8	0	0	0	0	0	0	0	0	0	0	0	0	0
** F15316 **																
ED-01	S00	S00	0	0	0	0	0	0	0	2	0	0	0	0	0	0
FS-01	S00	S00	0	0	0	0	0	0	0	1	0	0	0	0	0	0
JU-01	S00	S00	0	0	0	0	0	0	0	1	0	0	0	0	0	0
SU-01	S00	S00	0	0	0	0	0	0	0	2	0	0	0	0	0	0
SU-12	S00	S00	0	0	0	0	0	0	0	2	0	0	0	0	0	0
** Subtotal **			0	0	0	0	0	0	0	8	0	0	0	0	0	0
** F1KJ09 **																
ED-01	S00	S00	2	0	0	0	0	0	0	0	0	0	0	0	0	0
FS-01	S00	S00	1	0	0	0	0	0	0	0	0	0	0	0	0	0
JU-01	S00	S00	1	0	0	0	0	0	0	0	0	0	0	0	0	0
SU-01	S00	S00	2	0	0	0	0	0	0	0	0	0	0	0	0	0
SU-12	S00	S00	2	0	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			8	0	0	0	0	0	0	0	0	0	0	0	0	0
** F1V212 **																
ED-01	S00	S00	0	0	0	0	2	2	2	0	0	2	2	0	0	0
FS-01	S00	S00	0	0	0	0	1	1	1	0	0	1	1	0	0	0
JU-01	S00	S00	0	0	0	0	1	1	1	0	0	1	1	0	0	0
SU-01	S00	S00	0	0	0	0	2	2	2	0	0	2	2	0	0	0
SU-12	S00	S00	0	0	0	0	2	2	2	0	0	2	2	0	0	0
** Subtotal **			0	0	0	0	8	8	8	0	0	8	8	0	0	0
** F1V816 **																
ED-01	S00	S00	0	0	0	2	0	0	0	0	0	0	0	0	0	0
FS-01	S00	S00	0	0	0	1	0	0	0	0	0	0	0	0	0	0
JU-01	S00	S00	0	0	0	1	0	0	0	0	0	0	0	0	0	0
SU-01	S00	S00	0	0	0	2	0	0	0	0	0	0	0	0	0	0
SU-12	S00	S00	0	0	0	2	0	0	0	0	0	0	0	0	0	0
** Subtotal **			0	0	0	8	0	0	0	0	0	0	0	0	0	0
** F1YZ27 **																
ED-01	S00	S00	0	0	0	0	0	2	0	2	0	2	2	0	0	0
FS-01	S00	S00	0	0	0	0	0	1	0	1	0	1	1	0	0	0
JU-01	S00	S00	0	0	0	0	0	1	0	1	0	1	1	0	0	0
SU-01	S00	S00	0	0	0	0	0	2	0	2	0	2	2	0	0	0

21 MAY 2018

USMC MF TBA by Contingency Support Package

CONFIG	DIV	BR	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
SU-12	S00	S00	0	0	0	0	0	2	0	2	0	2	2	0	0	0
** Subtotal **			0	0	0	0	0	8	0	8	0	8	8	0	0	0
** <u>F21812</u> **																
ED-01	S00	S00	0	0	0	0	0	0	0	0	2	0	0	0	0	0
FS-01	S00	S00	0	0	0	0	0	0	0	0	1	0	0	0	0	0
JU-01	S00	S00	0	0	0	0	0	0	0	0	1	0	0	0	0	0
SU-01	S00	S00	0	0	0	0	0	0	0	0	2	0	0	0	0	0
SU-12	S00	S00	0	0	0	0	0	0	0	0	2	0	0	0	0	0
** Subtotal **			0	0	0	0	0	0	0	0	8	0	0	0	0	0
** <u>F21824</u> **																
ED-01	S00	S00	0	0	0	0	0	0	0	0	2	0	0	0	0	0
FS-01	S00	S00	0	0	0	0	0	0	0	0	1	0	0	0	0	0
JU-01	S00	S00	0	0	0	0	0	0	0	0	1	0	0	0	0	0
SU-01	S00	S00	0	0	0	0	0	0	0	0	2	0	0	0	0	0
SU-12	S00	S00	0	0	0	0	0	0	0	0	2	0	0	0	0	0
** Subtotal **			0	0	0	0	0	0	0	0	8	0	0	0	0	0
** <u>F25316</u> **																
ED-01	S00	S00	0	0	0	0	0	0	0	2	0	0	0	0	0	0
FS-01	S00	S00	0	0	0	0	0	0	0	1	0	0	0	0	0	0
JU-01	S00	S00	0	0	0	0	0	0	0	1	0	0	0	0	0	0
SU-01	S00	S00	0	0	0	0	0	0	0	2	0	0	0	0	0	0
SU-12	S00	S00	0	0	0	0	0	0	0	2	0	0	0	0	0	0
** Subtotal **			0	0	0	0	0	0	0	8	0	0	0	0	0	0
** <u>F2KJ09</u> **																
ED-01	S00	S00	0	2	0	0	0	0	0	0	0	0	0	0	0	0
FS-01	S00	S00	0	1	0	0	0	0	0	0	0	0	0	0	0	0
JU-01	S00	S00	0	1	0	0	0	0	0	0	0	0	0	0	0	0
SU-01	S00	S00	0	2	0	0	0	0	0	0	0	0	0	0	0	0
SU-12	S00	S00	0	2	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			0	8	0	0	0	0	0	0	0	0	0	0	0	0
** <u>F2V212</u> **																
ED-01	S00	S00	0	0	0	0	2	0	2	0	0	0	0	0	0	0
FS-01	S00	S00	0	0	0	0	1	0	1	0	0	0	0	0	0	0
JU-01	S00	S00	0	0	0	0	1	0	1	0	0	0	0	0	0	0
SU-01	S00	S00	0	0	0	0	2	0	2	0	0	0	0	0	0	0
SU-12	S00	S00	0	0	0	0	2	0	2	0	0	0	0	0	0	0
** Subtotal **			0	0	0	0	8	0	8	0	0	0	0	0	0	0
** <u>F2V816</u> **																
ED-01	S00	S00	0	0	0	2	0	0	0	0	0	0	0	0	0	0
FS-01	S00	S00	0	0	0	1	0	0	0	0	0	0	0	0	0	0

21 MAY 2018

USMC MF TBA by Contingency Support Package

CONFIG	DIV	BR	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
JU-01	S00	S00	0	0	0	1	0	0	0	0	0	0	0	0	0	0
SU-01	S00	S00	0	0	0	2	0	0	0	0	0	0	0	0	0	0
SU-12	S00	S00	0	0	0	2	0	0	0	0	0	0	0	0	0	0
** Subtotal **			0	0	0	8	0	0	0	0	0	0	0	0	0	0
** <u>F2YZ27</u> **																
ED-01	S00	S00	0	0	0	0	0	0	0	2	0	0	2	0	0	0
FS-01	S00	S00	0	0	0	0	0	0	0	1	0	0	1	0	0	0
JU-01	S00	S00	0	0	0	0	0	0	0	1	0	0	1	0	0	0
SU-01	S00	S00	0	0	0	0	0	0	0	2	0	0	2	0	0	0
SU-12	S00	S00	0	0	0	0	0	0	0	2	0	0	2	0	0	0
** Subtotal **			0	0	0	0	0	0	0	8	0	0	8	0	0	0
** <u>F31824</u> **																
ED-01	S00	S00	0	2	0	0	0	0	0	0	0	0	0	0	0	0
FS-01	S00	S00	0	1	0	0	0	0	0	0	0	0	0	0	0	0
JU-01	S00	S00	0	1	0	0	0	0	0	0	0	0	0	0	0	0
SU-01	S00	S00	0	2	0	0	0	0	0	0	0	0	0	0	0	0
SU-12	S00	S00	0	2	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			0	8	0	0	0	0	0	0	0	0	0	0	0	0
** <u>F35316</u> **																
ED-01	S00	S00	0	0	0	0	0	2	0	0	0	0	0	0	0	0
FS-01	S00	S00	0	0	0	0	0	1	0	0	0	0	0	0	0	0
JU-01	S00	S00	0	0	0	0	0	1	0	0	0	0	0	0	0	0
SU-01	S00	S00	0	0	0	0	0	2	0	0	0	0	0	0	0	0
SU-12	S00	S00	0	0	0	0	0	2	0	0	0	0	0	0	0	0
** Subtotal **			0	0	0	0	0	8	0	0	0	0	0	0	0	0
** <u>F3KJ09</u> **																
ED-01	S00	S00	0	0	0	2	0	0	0	0	0	0	0	0	0	0
FS-01	S00	S00	0	0	0	1	0	0	0	0	0	0	0	0	0	0
JU-01	S00	S00	0	0	0	1	0	0	0	0	0	0	0	0	0	0
SU-01	S00	S00	0	0	0	2	0	0	0	0	0	0	0	0	0	0
SU-12	S00	S00	0	0	0	2	0	0	0	0	0	0	0	0	0	0
** Subtotal **			0	0	0	8	0	0	0	0	0	0	0	0	0	0
** <u>F3V816</u> **																
ED-01	S00	S00	0	0	2	0	0	0	0	0	0	0	0	0	0	0
FS-01	S00	S00	0	0	1	0	0	0	0	0	0	0	0	0	0	0
JU-01	S00	S00	0	0	1	0	0	0	0	0	0	0	0	0	0	0
SU-01	S00	S00	0	0	2	0	0	0	0	0	0	0	0	0	0	0
SU-12	S00	S00	0	0	2	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			0	0	8	0	0	0	0	0	0	0	0	0	0	0

21 MAY 2018

USMC MF TBA by Contingency Support Package

CONFIG	DIV	BR	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
** <u>F45316</u> **																
ED-01	S00	S00	0	0	0	0	2	0	0	0	0	0	0	0	0	0
FS-01	S00	S00	0	0	0	0	1	0	0	0	0	0	0	0	0	0
JU-01	S00	S00	0	0	0	0	1	0	0	0	0	0	0	0	0	0
SU-01	S00	S00	0	0	0	0	2	0	0	0	0	0	0	0	0	0
SU-12	S00	S00	0	0	0	0	2	0	0	0	0	0	0	0	0	0
** Subtotal **			0	0	0	0	8	0	0	0	0	0	0	0	0	0
** <u>F4V816</u> **																
ED-01	S00	S00	0	0	2	0	0	0	0	0	0	0	0	0	0	0
FS-01	S00	S00	0	0	1	0	0	0	0	0	0	0	0	0	0	0
JU-01	S00	S00	0	0	1	0	0	0	0	0	0	0	0	0	0	0
SU-01	S00	S00	0	0	2	0	0	0	0	0	0	0	0	0	0	0
SU-12	S00	S00	0	0	2	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			0	0	8	0	0	0	0	0	0	0	0	0	0	0
** <u>F55316</u> **																
ED-01	S00	S00	0	0	0	0	0	0	0	0	0	2	0	0	0	0
FS-01	S00	S00	0	0	0	0	0	0	0	0	0	1	0	0	0	0
JU-01	S00	S00	0	0	0	0	0	0	0	0	0	1	0	0	0	0
SU-01	S00	S00	0	0	0	0	0	0	0	0	0	2	0	0	0	0
SU-12	S00	S00	0	0	0	0	0	0	0	0	0	2	0	0	0	0
** Subtotal **			0	0	0	0	0	0	0	0	0	8	0	0	0	0
** <u>IOSP11</u> **																
JU-01	600	600	4	0	0	0	0	0	0	0	0	0	0	0	0	0
KA-18A	600	600	3	0	0	0	0	0	0	0	0	0	0	0	0	0
KA-19A	600	650	1	0	0	0	0	0	0	0	0	0	0	0	0	0
KA-20B	600	650	1	0	0	0	0	0	0	0	0	0	0	0	0	0
KA-31	600	650	11	0	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			20	0	0	0	0	0	0	0	0	0	0	0	0	0
** <u>IOSP12</u> **																
EB-06	600	650	0	1	0	0	0	0	0	0	0	0	0	0	0	0
EB-07	600	650	0	1	0	0	0	0	0	0	0	0	0	0	0	0
EB-09	600	650	0	1	0	0	0	0	0	0	0	0	0	0	0	0
JU-01	600	600	0	3	0	0	0	0	0	0	0	0	0	0	0	0
KA-18A	600	600	0	2	0	0	0	0	0	0	0	0	0	0	0	0
KA-31	600	650	0	11	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			0	19	0	0	0	0	0	0	0	0	0	0	0	0
** <u>IOSP14</u> **																
CL-09	600	670	0	0	0	2	0	0	0	0	0	0	0	0	0	0
DP-18A	AIS	AIS	0	0	0	1	0	0	0	0	0	0	0	0	0	0
EB-06	600	650	0	0	0	2	0	0	0	0	0	0	0	0	0	0

21 MAY 2018

USMC MF TBA by Contingency Support Package

CONFIG	DIV	BR	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
EB-07	600	650	0	0	0	2	0	0	0	0	0	0	0	0	0	0
EB-08	600	650	0	0	0	1	0	0	0	0	0	0	0	0	0	0
EB-09	600	650	0	0	0	2	0	0	0	0	0	0	0	0	0	0
JU-01	600	600	0	0	0	6	0	0	0	0	0	0	0	0	0	0
KA-18A	600	600	0	0	0	1	0	0	0	0	0	0	0	0	0	0
KA-19A	600	650	0	0	0	2	0	0	0	0	0	0	0	0	0	0
KA-20B	600	650	0	0	0	2	0	0	0	0	0	0	0	0	0	0
KA-31	600	650	0	0	0	4	0	0	0	0	0	0	0	0	0	0
SU-01	600	600	0	0	0	4	0	0	0	0	0	0	0	0	0	0
SU-03	600	600	0	0	0	1	0	0	0	0	0	0	0	0	0	0
SU-03	600	670	0	0	0	1	0	0	0	0	0	0	0	0	0	0
SU-12	600	670	0	0	0	1	0	0	0	0	0	0	0	0	0	0
** Subtotal **			0	0	0	32	0	0	0	0	0	0	0	0	0	0
** <u>IOSP16</u> **																
DP-18A	AIS	AIS	0	0	0	0	1	0	0	0	0	0	0	0	0	0
** Subtotal **			0	0	0	0	1	0	0	0	0	0	0	0	0	0
** <u>IOSP31</u> **																
JU-01	600	600	0	0	0	0	0	0	0	0	4	0	0	0	0	0
KA-18A	600	600	0	0	0	0	0	0	0	0	4	0	0	0	0	0
KA-19A	600	650	0	0	0	0	0	0	0	0	1	0	0	0	0	0
KA-20B	600	650	0	0	0	0	0	0	0	0	1	0	0	0	0	0
KA-31	600	650	0	0	0	0	0	0	0	0	9	0	0	0	0	0
** Subtotal **			0	0	0	0	0	0	0	0	19	0	0	0	0	0
** <u>IOSP36</u> **																
DP-18A	AIS	AIS	0	0	0	0	0	0	0	0	0	1	0	0	0	0
** Subtotal **			0	0	0	0	0	0	0	0	0	1	0	0	0	0
** <u>IOSP41</u> **																
DP-18A	AIS	AIS	0	0	0	0	0	0	0	0	0	0	0	1	0	0
** Subtotal **			0	0	0	0	0	0	0	0	0	0	0	1	0	0
** <u>MACSXX</u> **																
AT-11	ATC	ATC	0	1	1	2	1	0	0	1	1	1	2	1	0	0
AT-12	ATC	ATC	0	1	1	2	1	0	0	1	1	1	2	1	0	0
CR-03	ATC	ATC	0	2	2	2	2	0	0	2	2	2	4	2	0	0
JU-01	ATC	ATC	0	1	2	2	1	0	0	1	1	1	2	1	0	0
SU-03	ATC	ATC	0	1	1	2	1	0	0	1	1	1	2	0	0	0
** Subtotal **			0	6	7	10	6	0	0	6	6	6	12	5	0	0
** <u>MPSBLI</u> **																
BL-01	MPS	BLI	0	0	0	0	0	0	0	0	0	0	0	0	0	1
FS-01	MPS	BLI	0	0	0	0	0	0	0	0	0	0	0	0	0	1

21 MAY 2018

USMC MF TBA by Contingency Support Package

CONFIG	DIV	BR	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
** Subtotal **			0	0	0	0	0	0	0	0	0	0	0	0	0	2
** <u>MPSFLY</u> **																
CU-01	MPS	FLY	0	0	0	0	0	0	0	0	0	0	0	0	0	1
JU-01	MPS	FLY	0	0	0	0	0	0	0	0	0	0	0	0	0	1
ST-01	MPS	FLY	0	0	0	0	0	0	0	0	0	0	0	0	0	1
SU-08	MPS	FLY	0	0	0	0	0	0	0	0	0	0	0	0	0	1
TW-05A	MPS	FLY	0	0	0	0	0	0	0	0	0	0	0	0	0	1
TW-06B	MPS	FLY	0	0	0	0	0	0	0	0	0	0	0	0	0	1
** Subtotal **			0	0	0	0	0	0	0	0	0	0	0	0	0	6
** <u>MSA</u> **																
ED-01	S00	S00	0	0	0	0	0	0	4	0	0	0	0	0	0	0
FS-01	S00	S00	1	1	1	1	1	1	1	1	1	1	1	0	1	0
JU-01	S00	S00	2	2	2	2	2	2	2	2	2	2	2	0	2	0
SU-01	S00	S00	2	1	2	2	2	1	2	2	2	1	2	0	2	0
SU-02	S00	S00	4	2	4	4	4	2	2	4	4	2	4	0	4	0
SU-05	S00	S00	2	2	2	2	2	2	2	2	2	2	2	0	2	0
SU-12	S00	S00	5	3	5	5	5	3	3	5	5	3	5	0	4	0
** Subtotal **			16	11	16	16	16	11	16	16	16	11	16	0	15	0
** <u>PALMXX</u> **																
EA-01	ZZC	EAF	1	0	0	0	0	0	0	0	0	0	0	0	0	0
JU-01	ZZC	EAF	1	0	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			2	0	0	0	0	0	0	0	0	0	0	0	0	0
** <u>SCIFXX</u> **																
AB-02	000	S3	1	1	0	0	0	0	0	0	1	0	0	0	0	0
AB-03	000	S3	1	1	0	0	0	0	0	0	1	0	0	0	0	0
JU-01	000	000	1	1	0	0	0	0	0	0	1	0	0	0	0	0
JU-31	000	S3	1	1	0	0	0	0	0	0	1	0	0	0	0	0
JU-32	000	S3	1	1	0	0	0	0	0	0	1	0	0	0	0	0
** Subtotal **			5	5	0	0	0	0	0	0	5	0	0	0	0	0
** <u>T53E29</u> **																
BL-01	600	620	0	0	0	0	0	0	0	1	0	0	0	0	0	0
HY-07A	500	520	0	0	0	0	0	0	0	1	0	0	0	0	0	0
HY-08B	500	520	0	0	0	0	0	0	0	1	0	0	0	0	0	0
JU-01	600	600	0	0	0	0	0	0	0	1	0	0	0	0	0	0
ST-01	600	610	0	0	0	0	0	0	0	2	0	0	0	0	0	0
ST-01	600	620	0	0	0	0	0	0	0	1	0	0	0	0	0	0
VD-05A	600	620	0	0	0	0	0	0	0	1	0	0	0	0	0	0
VD-06B	600	620	0	0	0	0	0	0	0	1	0	0	0	0	0	0
** Subtotal **			0	0	0	0	0	0	0	9	0	0	0	0	0	0

21 MAY 2018

USMC MF TBA by Contingency Support Package

CONFIG	DIV	BR	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
** TF3531 **																
BL-01	600	600	0	0	0	0	0	0	0	0	1	0	0	0	0	0
** Subtotal **			0	0	0	0	0	0	0	0	1	0	0	0	0	0
** TFRS11 **																
AM-01	000	05C	1	0	0	0	0	0	0	0	0	0	0	0	0	0
BL-01	600	620	1	0	0	0	0	0	0	0	0	0	0	0	0	0
CU-01	800	800	1	0	0	0	0	0	0	0	0	0	0	0	0	0
CU-01	600	600	2	0	0	0	0	0	0	0	0	0	0	0	0	0
CU-01	500	500	1	0	0	0	0	0	0	0	0	0	0	0	0	0
CU-01	400	400	1	0	0	0	0	0	0	0	0	0	0	0	0	0
CU-01	000	010	1	0	0	0	0	0	0	0	0	0	0	0	0	0
CU-01	000	020	1	0	0	0	0	0	0	0	0	0	0	0	0	0
CY-01	600	610	1	0	0	0	0	0	0	0	0	0	0	0	0	0
HC-01	500	520	1	0	0	0	0	0	0	0	0	0	0	0	0	0
HC-02	500	520	1	0	0	0	0	0	0	0	0	0	0	0	0	0
HY-07A	500	520	1	0	0	0	0	0	0	0	0	0	0	0	0	0
HY-08B	500	520	1	0	0	0	0	0	0	0	0	0	0	0	0	0
JU-01	900	900	1	0	0	0	0	0	0	0	0	0	0	0	0	0
JU-01	800	800	1	0	0	0	0	0	0	0	0	0	0	0	0	0
JU-01	600	600	4	0	0	0	0	0	0	0	0	0	0	0	0	0
JU-01	500	500	4	0	0	0	0	0	0	0	0	0	0	0	0	0
JU-01	000	000	3	0	0	0	0	0	0	0	0	0	0	0	0	0
KA-18A	600	600	6	0	0	0	0	0	0	0	0	0	0	0	0	0
KA-19A	600	650	1	0	0	0	0	0	0	0	0	0	0	0	0	0
KA-20B	600	650	1	0	0	0	0	0	0	0	0	0	0	0	0	0
MC-01	000	020	1	0	0	0	0	0	0	0	0	0	0	0	0	0
MM-01	500	510	1	0	0	0	0	0	0	0	0	0	0	0	0	0
MM-02	500	510	1	0	0	0	0	0	0	0	0	0	0	0	0	0
MM-03	500	510	1	0	0	0	0	0	0	0	0	0	0	0	0	0
MM-04	500	510	1	0	0	0	0	0	0	0	0	0	0	0	0	0
NT-08	500	530	1	0	0	0	0	0	0	0	0	0	0	0	0	0
PW-01	500	500	1	0	0	0	0	0	0	0	0	0	0	0	0	0
RR-02	800	810	1	0	0	0	0	0	0	0	0	0	0	0	0	0
SE-01	800	810	1	0	0	0	0	0	0	0	0	0	0	0	0	0
SM-04B	500	510	1	0	0	0	0	0	0	0	0	0	0	0	0	0
SM-05A	500	510	1	0	0	0	0	0	0	0	0	0	0	0	0	0
ST-01	600	610	1	0	0	0	0	0	0	0	0	0	0	0	0	0
ST-01	600	620	1	0	0	0	0	0	0	0	0	0	0	0	0	0
ST-01	600	650	1	0	0	0	0	0	0	0	0	0	0	0	0	0
ST-01	500	520	1	0	0	0	0	0	0	0	0	0	0	0	0	0
SU-01	000	05C	1	0	0	0	0	0	0	0	0	0	0	0	0	0
SU-05	600	60C	1	0	0	0	0	0	0	0	0	0	0	0	0	0
SU-12	000	05A	1	0	0	0	0	0	0	0	0	0	0	0	0	0
SW-02	800	820	1	0	0	0	0	0	0	0	0	0	0	0	0	0
TR-01	600	600	1	0	0	0	0	0	0	0	0	0	0	0	0	0
TR-01	000	05D	1	0	0	0	0	0	0	0	0	0	0	0	0	0

21 MAY 2018

USMC MF TBA by Contingency Support Package

CONFIG	DIV	BR	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
VD-07A	600	620	1	0	0	0	0	0	0	0	0	0	0	0	0	0
VD-08B	600	620	1	0	0	0	0	0	0	0	0	0	0	0	0	0
WC-02	000	030	1	0	0	0	0	0	0	0	0	0	0	0	0	0
WC-02	000	040	1	0	0	0	0	0	0	0	0	0	0	0	0	0
WC-08	900	910	1	0	0	0	0	0	0	0	0	0	0	0	0	0
WC-08	900	940	1	0	0	0	0	0	0	0	0	0	0	0	0	0
WL-04A	500	510	1	0	0	0	0	0	0	0	0	0	0	0	0	0
WL-05A	500	510	1	0	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			64	0	0	0	0	0	0	0	0	0	0	0	0	0
** <u>TH1M39</u> **																
BL-01	600	620	0	0	0	0	0	0	0	0	0	0	1	0	0	0
JU-01	600	600	0	0	0	0	0	0	0	0	0	0	1	0	0	0
ST-01	600	610	0	0	0	0	0	0	0	0	0	0	1	0	0	0
ST-01	600	620	0	0	0	0	0	0	0	0	0	0	1	0	0	0
SW-02	800	820	0	0	0	0	0	0	0	0	0	0	1	0	0	0
TB-03A	500	520	0	0	0	0	0	0	0	0	0	0	1	0	0	0
TB-04B	500	520	0	0	0	0	0	0	0	0	0	0	1	0	0	0
VD-05A	600	620	0	0	0	0	0	0	0	0	0	0	1	0	0	0
VD-06B	600	620	0	0	0	0	0	0	0	0	0	0	1	0	0	0
** Subtotal **			0	0	0	0	0	0	0	0	0	0	9	0	0	0
** <u>TV2226</u> **																
HY-06C	500	520	0	0	0	0	0	0	1	0	0	0	0	0	0	0
JU-01	600	600	0	0	0	0	0	0	1	0	0	0	0	0	0	0
JU-01	500	500	0	0	0	0	0	0	1	0	0	0	0	0	0	0
KA-18A	600	600	0	0	0	0	0	0	3	0	0	0	0	0	0	0
KA-31	600	650	0	0	0	0	0	0	1	0	0	0	0	0	0	0
RR-04A	800	810	0	0	0	0	0	0	1	0	0	0	0	0	0	0
RR-05B	800	810	0	0	0	0	0	0	1	0	0	0	0	0	0	0
RR-06BM	800	810	0	0	0	0	0	0	1	0	0	0	0	0	0	0
TB-02	500	520	0	0	0	0	0	0	1	0	0	0	0	0	0	0
** Subtotal **			0	0	0	0	0	0	11	0	0	0	0	0	0	0
** <u>TV8B14</u> **																
BL-01	600	620	0	0	0	1	0	0	0	0	0	0	0	0	0	0
CL-01	600	670	0	0	0	1	0	0	0	0	0	0	0	0	0	0
HY-07A	500	520	0	0	0	1	0	0	0	0	0	0	0	0	0	0
HY-08B	500	520	0	0	0	1	0	0	0	0	0	0	0	0	0	0
JU-01	600	600	0	0	0	4	0	0	0	0	0	0	0	0	0	0
JU-01	000	000	0	0	0	1	0	0	0	0	0	0	0	0	0	0
KA-18A	600	600	0	0	0	5	0	0	0	0	0	0	0	0	0	0
KA-19A	600	650	0	0	0	1	0	0	0	0	0	0	0	0	0	0
KA-20B	600	650	0	0	0	1	0	0	0	0	0	0	0	0	0	0
MC-01	000	020	0	0	0	1	0	0	0	0	0	0	0	0	0	0
ST-01	600	610	0	0	0	6	0	0	0	0	0	0	0	0	0	0
ST-01	600	620	0	0	0	3	0	0	0	0	0	0	0	0	0	0

21 MAY 2018

USMC MF TBA by Contingency Support Package

CONFIG	DIV	BR	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
ST-01	500	520	0	0	0	1	0	0	0	0	0	0	0	0	0	0
SU-01	000	05C	0	0	0	2	0	0	0	0	0	0	0	0	0	0
VD-07A	600	620	0	0	0	1	0	0	0	0	0	0	0	0	0	0
VD-08B	600	620	0	0	0	1	0	0	0	0	0	0	0	0	0	0
** Subtotal **			0	0	0	31	0	0	0	0	0	0	0	0	0	0
** <u>WGISSX</u> **																
BL-01	600	620	0	0	0	0	1	0	0	0	0	0	0	0	0	0
** Subtotal **			0	0	0	0	1	0	0	0	0	0	0	0	0	0
Total			325	254	198	318	227	194	213	234	239	187	241	163	191	58

USMC MF TBA by Division

CONFIG	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
**	000	**														
AB-02	S3	SCIFXX	1	1	0	0	0	0	0	0	1	0	0	0	0	0
AB-03	S3	SCIFXX	1	1	0	0	0	0	0	0	1	0	0	0	0	0
AM-01	05C	CCSPFW	0	1	1	0	0	0	0	0	1	0	0	0	0	0
AM-01	05C	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	1	0
AM-01	05C	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
AT-08	S2	118A36	2	2	0	0	0	0	0	0	2	0	0	0	0	0
AT-09BM	210	118A36	2	2	0	0	0	0	0	0	2	0	0	0	0	0
AT-10A	210	118A36	2	2	0	0	0	0	0	0	2	0	0	0	0	0
CU-01	05C	CCSPFW	1	0	0	1	0	0	0	0	0	0	0	1	0	0
CU-01	040	CCSPFW	1	0	0	0	0	0	0	0	0	0	0	1	0	0
CU-01	040	CCSPRW	0	0	0	0	2	1	2	1	0	1	1	0	1	0
CU-01	030	CCSPFW	0	0	0	1	0	0	0	0	0	0	0	0	0	0
CU-01	020	CCSPFW	1	1	1	3	0	0	0	0	3	0	0	1	0	0
CU-01	020	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
CU-01	020	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
CU-01	010	CCSPFW	2	2	2	2	0	0	0	0	1	0	0	2	0	0
CU-01	010	CCSPRW	0	0	0	0	2	2	2	2	0	2	2	0	2	0
CU-01	010	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
JU-01	000	118A36	1	1	0	0	0	0	0	0	1	0	0	0	0	0
JU-01	000	CCSPFW	3	3	3	4	0	0	0	0	3	0	0	3	0	0
JU-01	000	CCSPRW	0	0	0	0	3	2	3	3	0	3	3	0	3	0
JU-01	000	SCIFXX	1	1	0	0	0	0	0	0	1	0	0	0	0	0
JU-01	000	TFRS11	3	0	0	0	0	0	0	0	0	0	0	0	0	0
JU-01	000	TV8B14	0	0	0	1	0	0	0	0	0	0	0	0	0	0
JU-31	S3	SCIFXX	1	1	0	0	0	0	0	0	1	0	0	0	0	0
JU-32	S3	SCIFXX	1	1	0	0	0	0	0	0	1	0	0	0	0	0
MC-01	020	CCSPFW	2	2	2	0	0	0	0	0	0	0	0	2	0	0
MC-01	020	CCSPRW	0	0	0	0	2	1	2	2	0	0	2	0	2	0
MC-01	020	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
MC-01	020	TV8B14	0	0	0	1	0	0	0	0	0	0	0	0	0	0
SU-01	05D	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
SU-01	05D	CCSPRW	0	0	0	0	1	0	1	1	0	1	1	0	1	0
SU-01	05C	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
SU-01	05C	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
SU-01	05C	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
SU-01	05C	TV8B14	0	0	0	2	0	0	0	0	0	0	0	0	0	0
SU-08	05A	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
SU-08	05A	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
SU-12	05D	CCSPFW	0	0	0	0	0	0	0	0	1	0	0	1	0	0
SU-12	05D	CCSPRW	0	0	0	0	0	0	0	0	0	1	0	0	0	0

USMC MF TBA by Division

CONFIG	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
SU-12	05A	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
SU-12	05A	CCSPRW	0	0	0	0	1	0	1	1	0	1	1	0	1	0
SU-12	05A	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
SU-12	040	CCSPRW	0	0	0	0	0	0	1	0	0	0	0	0	0	0
TL-01	040	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
TL-01	040	CCSPRW	0	0	0	0	1	1	0	1	0	0	1	0	1	0
TR-01	05D	CCSPFW	1	1	1	1	0	0	0	0	0	0	0	0	0	0
TR-01	05D	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	1	0
TR-01	05D	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
WC-02	040	CCSPFW	1	2	2	2	0	0	0	0	2	0	0	1	0	0
WC-02	040	CCSPRW	0	0	0	0	1	1	0	2	0	0	2	0	2	0
WC-02	040	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
WC-02	030	CCSPFW	2	2	2	1	0	0	0	0	2	0	0	2	0	0
WC-02	030	CCSPRW	0	0	0	0	2	0	2	2	0	0	2	0	2	0
WC-02	030	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			43	31	19	24	20	13	19	20	30	12	20	19	20	0
** 400 **																
CU-01	400	CCSPFW	1	1	1	1	0	0	0	0	0	0	0	0	0	0
CU-01	400	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
CU-01	400	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
FS-01	400	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	0	0	0
FS-01	400	CCSPRW	0	0	0	0	1	0	1	1	0	1	1	0	1	0
JU-01	400	CCSPRW	0	0	0	0	2	1	2	2	0	2	2	0	2	0
PP-01	410	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	1	0
PP-03A	440	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	1	0
PP-04BM	440	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	1	0
SU-03	410	CCSPRW	0	0	0	0	1	0	1	1	0	1	1	0	1	0
SU-12	440	CCSPRW	0	0	0	0	1	1	1	1	0	2	1	0	1	0
TR-01	440	CCSPRW	0	0	0	0	1	0	1	1	0	0	1	0	1	0
TR-01	400	118A12	0	0	0	0	0	0	0	0	0	0	0	1	0	0
TR-01	400	118A36	1	1	0	0	0	0	0	0	0	0	0	0	0	0
TR-01	400	118C24	1	0	0	0	0	0	0	0	0	0	0	0	0	0
TR-01	400	1E6B05	0	1	0	1	0	0	0	0	0	0	0	0	0	0
TR-01	400	2E6B05	0	0	0	1	0	0	0	0	0	0	0	0	0	0
TR-01	400	3E6B05	0	0	0	1	0	0	0	0	0	0	0	0	0	0
** Subtotal **			5	4	2	5	10	6	10	10	1	7	10	1	10	0
** 500 **																
CS-02A	510	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
CS-02A	510	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
CS-03BM	510	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0

USMC MF TBA by Division

CONFIG	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
CS-03BM	510	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
CU-01	500	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
CU-01	500	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
CU-01	500	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
FA-02A	520	118A12	0	0	0	0	0	0	0	0	0	0	0	1	0	0
FA-02A	520	118A36	1	2	0	0	0	0	0	0	0	0	0	0	0	0
FA-02A	520	118C24	1	0	0	0	0	0	0	0	0	0	0	0	0	0
FA-02A	520	318A36	0	0	0	0	0	0	0	0	1	0	0	0	0	0
FA-02A	520	318C24	0	0	0	0	0	0	0	0	1	0	0	0	0	0
FA-03B	520	118A12	0	0	0	0	0	0	0	0	0	0	0	1	0	0
FA-03B	520	118A36	1	2	0	0	0	0	0	0	0	0	0	0	0	0
FA-03B	520	118C24	1	0	0	0	0	0	0	0	0	0	0	0	0	0
FA-03B	520	318A36	0	0	0	0	0	0	0	0	1	0	0	0	0	0
FA-03B	520	318C24	0	0	0	0	0	0	0	0	1	0	0	0	0	0
FS-01	500	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
FS-01	500	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
HC-01	520	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	1	0
HC-01	520	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	0	0
HC-01	520	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
HC-02	520	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	1	0
HC-02	520	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	0	0
HC-02	520	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
HY-06C	520	1V2236	0	0	0	0	0	1	1	0	0	1	1	0	0	0
HY-06C	520	3V2212	0	0	0	0	1	0	0	0	0	0	0	0	1	0
HY-06C	520	TV2226	0	0	0	0	0	0	1	0	0	0	0	0	0	0
HY-07A	520	CCSPFW	1	1	0	1	0	0	0	0	1	0	0	1	0	0
HY-07A	520	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
HY-07A	520	T53E29	0	0	0	0	0	0	0	1	0	0	0	0	0	0
HY-07A	520	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
HY-07A	520	TV8B14	0	0	0	1	0	0	0	0	0	0	0	0	0	0
HY-08B	520	CCSPFW	1	1	0	1	0	0	0	0	1	0	0	1	0	0
HY-08B	520	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
HY-08B	520	T53E29	0	0	0	0	0	0	0	1	0	0	0	0	0	0
HY-08B	520	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
HY-08B	520	TV8B14	0	0	0	1	0	0	0	0	0	0	0	0	0	0
JU-01	500	118A12	0	0	0	0	0	0	0	0	0	0	0	1	0	0
JU-01	500	118A36	1	1	0	0	0	0	0	0	0	0	0	0	0	0
JU-01	500	118C24	1	0	0	0	0	0	0	0	0	0	0	0	0	0
JU-01	500	1V2236	0	0	0	0	0	1	1	0	0	1	1	0	0	0
JU-01	500	1V8R14	0	0	0	1	0	0	0	0	0	0	0	0	0	0
JU-01	500	318C24	0	0	0	0	0	0	0	0	1	0	0	0	0	0
JU-01	500	3V2212	0	0	0	0	1	0	0	0	0	0	0	0	1	0

USMC MF TBA by Division

CONFIG	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
JU-01	500	CCSPFW	5	5	5	5	0	0	0	0	5	0	0	5	1	0
JU-01	500	CCSPRW	0	0	0	0	5	5	4	5	0	5	5	0	5	0
JU-01	500	TFRS11	4	0	0	0	0	0	0	0	0	0	0	0	0	0
JU-01	500	TV2226	0	0	0	0	0	0	1	0	0	0	0	0	0	0
MM-01	510	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
MM-01	510	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	0	0
MM-01	510	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
MM-02	510	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	1	0
MM-02	510	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	0	0
MM-02	510	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
MM-03	510	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	1	0
MM-03	510	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	0	0
MM-03	510	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
MM-04	510	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	1	0
MM-04	510	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	0	0
MM-04	510	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
NT-06	530	CCSPFW	0	1	0	0	0	0	0	0	0	0	0	0	0	0
NT-06	530	CCSPRW	0	0	0	0	1	0	1	0	0	0	1	0	0	0
NT-08	530	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
NT-08	530	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	1	0
NT-08	530	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
PW-01	500	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
PW-01	500	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
PW-01	500	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
SM-04B	510	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
SM-04B	510	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	1	0
SM-04B	510	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
SM-05A	510	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
SM-05A	510	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	1	0
SM-05A	510	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
SM-06B	510	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
SM-06B	510	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	1	0
SM-07A	510	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
SM-07A	510	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	1	0
SP-04	520	135B16	1	0	0	0	0	0	0	0	0	0	0	0	0	0
SP-04	520	1V8R14	0	1	1	2	0	0	0	0	0	0	0	0	0	0
SP-04	520	CCSPRW	0	0	0	0	1	0	0	1	0	0	0	0	0	0
ST-01	520	CCSPFW	2	2	2	2	0	0	0	0	2	0	0	2	0	0
ST-01	520	CCSPRW	0	0	0	0	0	0	0	0	0	0	0	0	5	0
ST-01	520	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
ST-01	520	TV8B14	0	0	0	1	0	0	0	0	0	0	0	0	0	0
TB-01	520	CCSPRW	0	0	0	0	1	1	0	0	0	1	0	0	0	0

USMC MF TBA by Division

CONFIG	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
TB-02	520	1V2236	0	0	0	0	0	1	2	0	0	1	1	0	0	0
TB-02	520	3V2212	0	0	0	0	1	0	0	0	0	0	0	0	1	0
TB-02	520	TV2226	0	0	0	0	0	0	1	0	0	0	0	0	0	0
TB-03A	520	CCSPFW	2	1	1	2	0	0	0	0	1	0	0	1	0	0
TB-03A	520	CCSPRW	0	0	0	0	1	1	0	1	0	1	0	0	0	0
TB-03A	520	TH1M39	0	0	0	0	0	0	0	0	0	0	1	0	0	0
TB-04B	520	CCSPFW	2	1	1	2	0	0	0	0	1	0	0	1	0	0
TB-04B	520	CCSPRW	0	0	0	0	1	1	0	1	0	1	0	0	0	0
TB-04B	520	TH1M39	0	0	0	0	0	0	0	0	0	0	1	0	0	0
TR-01	500	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
TR-01	500	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
TW-05A	510	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
TW-05A	510	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
TW-06B	510	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
TW-06B	510	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
WL-04A	510	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
WL-04A	510	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	1	0
WL-04A	510	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
WL-05A	510	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
WL-05A	510	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	1	0
WL-05A	510	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			61	39	31	40	36	34	35	33	37	23	34	35	36	0
** 600 **																
AV-01A	600	CCSPFW	2	0	2	0	0	0	0	0	2	0	0	0	0	0
AV-01A	600	CCSPRW	0	0	0	0	2	2	2	2	0	0	2	0	0	0
AV-02B	600	CCSPFW	2	0	2	0	0	0	0	0	2	0	0	0	0	0
AV-02B	600	CCSPRW	0	0	0	0	2	2	2	2	0	0	2	0	0	0
BL-01	620	1HML09	0	0	0	0	0	0	0	0	0	0	0	0	1	0
BL-01	620	1HML27	0	0	0	0	0	1	0	2	0	2	0	0	0	0
BL-01	620	2HML09	0	0	0	0	0	0	0	0	0	0	0	0	1	0
BL-01	620	2HML27	0	0	0	0	0	0	0	0	0	0	1	0	0	0
BL-01	620	3HML27	0	0	0	0	0	0	0	0	0	0	1	0	0	0
BL-01	620	4HML27	0	0	0	0	0	0	0	2	0	0	0	0	0	0
BL-01	620	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
BL-01	620	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
BL-01	620	T53E29	0	0	0	0	0	0	0	1	0	0	0	0	0	0
BL-01	620	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
BL-01	620	TH1M39	0	0	0	0	0	0	0	0	0	0	1	0	0	0
BL-01	620	TV8B14	0	0	0	1	0	0	0	0	0	0	0	0	0	0
BL-01	620	WGISSX	0	0	0	0	1	0	0	0	0	0	0	0	0	0
BL-01	600	135B16	0	0	2	0	0	0	0	0	0	0	0	0	0	0

USMC MF TBA by Division

CONFIG	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
BL-01	600	235C10	0	0	0	0	0	0	0	0	1	0	0	0	0	0
BL-01	600	335B10	2	0	0	0	0	0	0	0	0	0	0	1	0	0
BL-01	600	435B16	0	0	0	2	0	0	0	0	0	0	0	1	0	0
BL-01	600	535B16	0	1	0	0	0	0	0	0	0	0	0	0	0	0
BL-01	600	TF3531	0	0	0	0	0	0	0	0	1	0	0	0	0	0
CA-01	670	CCSPFW	2	2	0	2	0	0	0	0	0	0	0	0	0	0
CA-04	670	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
CA-04	670	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
CA-07A	670	CCSPRW	0	0	0	0	0	0	1	0	0	1	1	0	0	0
CA-08B	670	CCSPRW	0	0	0	0	0	0	1	0	0	1	1	0	0	0
CA-09	670	CCSPRW	0	0	0	0	0	1	1	0	0	0	1	0	0	0
CL-01	670	CCSPFW	2	2	2	2	0	0	0	0	2	0	0	2	0	0
CL-01	670	CCSPRW	0	0	0	0	2	2	2	2	0	2	2	0	2	0
CL-01	670	TV8B14	0	0	0	1	0	0	0	0	0	0	0	0	0	0
CL-02	670	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
CL-02	670	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
CL-04	670	CCSPFW	2	2	2	2	0	0	0	0	2	0	0	2	0	0
CL-04	670	CCSPRW	0	0	0	0	2	2	2	2	0	2	2	0	2	0
CL-04	610	CCSPFW	2	2	2	2	0	0	0	0	2	0	0	2	0	0
CL-04	610	CCSPRW	0	0	0	0	2	2	2	2	0	2	2	0	2	0
CL-06	670	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	0	0	0
CL-06	670	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
CL-09	670	CCSPFW	2	2	2	2	0	0	0	0	2	0	0	2	0	0
CL-09	670	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
CL-09	670	IOSP14	0	0	0	2	0	0	0	0	0	0	0	0	0	0
CL-10	670	CCSPFW	2	2	2	2	0	0	0	0	2	0	0	2	0	0
CL-10	670	CCSPRW	0	0	0	0	2	2	2	2	0	2	2	0	2	0
CR-04	690	CCSPFW	2	2	2	2	0	0	0	0	2	0	0	2	0	0
CR-04	690	CCSPRW	0	0	0	0	2	2	2	2	0	2	2	0	2	0
CU-01	670	CCSPFW	0	0	0	0	0	0	0	0	0	0	0	1	0	0
CU-01	600	CCSPFW	3	3	3	3	0	0	0	0	2	0	0	4	0	0
CU-01	600	CCSPRW	0	0	0	0	3	3	3	2	0	3	3	0	3	0
CU-01	600	TFRS11	2	0	0	0	0	0	0	0	0	0	0	0	0	0
CY-01	610	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
CY-01	610	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
CY-01	610	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
EB-06	650	IOSP12	0	1	0	0	0	0	0	0	0	0	0	0	0	0
EB-06	650	IOSP14	0	0	0	2	0	0	0	0	0	0	0	0	0	0
EB-07	650	IOSP12	0	1	0	0	0	0	0	0	0	0	0	0	0	0
EB-07	650	IOSP14	0	0	0	2	0	0	0	0	0	0	0	0	0	0
EB-08	650	IOSP14	0	0	0	1	0	0	0	0	0	0	0	0	0	0
EB-09	650	IOSP12	0	1	0	0	0	0	0	0	0	0	0	0	0	0

USMC MF TBA by Division

CONFIG	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
EB-09	650	IOSP14	0	0	0	2	0	0	0	0	0	0	0	0	0	0
FS-01	600	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
FS-01	600	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
GC-01	620	1V8R14	0	1	1	1	0	0	0	0	0	0	0	0	0	0
GC-01	620	2V8R14	0	0	1	1	0	0	0	0	0	0	0	0	0	0
JU-01	600	118A36	1	1	0	0	0	0	0	0	1	0	0	0	0	0
JU-01	600	118C24	1	0	0	0	0	0	0	0	1	0	0	1	0	0
JU-01	600	130T12	0	0	0	0	0	0	0	0	0	0	0	1	2	0
JU-01	600	153E16	0	0	0	0	1	0	0	1	0	0	0	0	0	0
JU-01	600	1HML27	0	0	0	0	0	1	0	2	0	1	2	0	1	0
JU-01	600	1V8R14	0	1	1	1	0	0	0	0	0	0	0	0	0	0
JU-01	600	2HML27	0	0	0	0	0	0	0	0	0	0	1	0	0	0
JU-01	600	2V8R14	0	0	1	1	0	0	0	0	0	0	0	0	0	0
JU-01	600	318A36	0	0	0	0	0	0	0	0	1	0	0	0	0	0
JU-01	600	4HML27	0	0	0	0	0	0	0	1	0	0	0	0	0	0
JU-01	600	CCSPFW	12	11	12	11	0	0	0	0	12	0	0	10	0	0
JU-01	600	CCSPRW	0	0	0	0	11	10	11	11	0	11	12	0	9	0
JU-01	600	IOSP11	4	0	0	0	0	0	0	0	0	0	0	0	0	0
JU-01	600	IOSP12	0	3	0	0	0	0	0	0	0	0	0	0	0	0
JU-01	600	IOSP14	0	0	0	6	0	0	0	0	0	0	0	0	0	0
JU-01	600	IOSP31	0	0	0	0	0	0	0	0	4	0	0	0	0	0
JU-01	600	T53E29	0	0	0	0	0	0	0	1	0	0	0	0	0	0
JU-01	600	TFRS11	4	0	0	0	0	0	0	0	0	0	0	0	0	0
JU-01	600	TH1M39	0	0	0	0	0	0	0	0	0	0	1	0	0	0
JU-01	600	TV2226	0	0	0	0	0	0	1	0	0	0	0	0	0	0
JU-01	600	TV8B14	0	0	0	4	0	0	0	0	0	0	0	0	0	0
JU-09	600	1E6B05	0	1	0	1	0	0	0	0	0	0	0	0	0	0
JU-09	600	2E6B05	0	0	0	1	0	0	0	0	0	0	0	0	0	0
JU-09	600	3E6B05	0	0	0	1	0	0	0	0	0	0	0	0	0	0
JU-10	600	1E6B05	0	1	0	1	0	0	0	0	0	0	0	0	0	0
JU-10	600	2E6B05	0	0	0	1	0	0	0	0	0	0	0	0	0	0
JU-10	600	3E6B05	0	0	0	1	0	0	0	0	0	0	0	0	0	0
KA-18A	600	1HML27	0	0	0	0	0	0	0	0	0	0	3	0	0	0
KA-18A	600	1V2236	0	0	0	0	2	0	0	0	0	0	0	0	0	0
KA-18A	600	CCSPFW	7	7	5	7	0	0	0	0	8	0	0	2	0	0
KA-18A	600	CCSPRW	0	0	0	0	4	3	4	4	0	3	4	0	2	0
KA-18A	600	IOSP11	3	0	0	0	0	0	0	0	0	0	0	0	0	0
KA-18A	600	IOSP12	0	2	0	0	0	0	0	0	0	0	0	0	0	0
KA-18A	600	IOSP14	0	0	0	1	0	0	0	0	0	0	0	0	0	0
KA-18A	600	IOSP31	0	0	0	0	0	0	0	0	4	0	0	0	0	0
KA-18A	600	TFRS11	6	0	0	0	0	0	0	0	0	0	0	0	0	0
KA-18A	600	TV2226	0	0	0	0	0	0	3	0	0	0	0	0	0	0

USMC MF TBA by Division

CONFIG	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
KA-18A	600	TV8B14	0	0	0	5	0	0	0	0	0	0	0	0	0	0
KA-19A	650	CCSPFW	2	2	2	2	0	0	0	0	2	0	0	1	0	0
KA-19A	650	IOSP11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
KA-19A	650	IOSP14	0	0	0	2	0	0	0	0	0	0	0	0	0	0
KA-19A	650	IOSP31	0	0	0	0	0	0	0	0	1	0	0	0	0	0
KA-19A	650	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
KA-19A	650	TV8B14	0	0	0	1	0	0	0	0	0	0	0	0	0	0
KA-20B	650	CCSPFW	2	2	2	2	0	0	0	0	2	0	0	1	0	0
KA-20B	650	IOSP11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
KA-20B	650	IOSP14	0	0	0	2	0	0	0	0	0	0	0	0	0	0
KA-20B	650	IOSP31	0	0	0	0	0	0	0	0	1	0	0	0	0	0
KA-20B	650	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
KA-20B	650	TV8B14	0	0	0	1	0	0	0	0	0	0	0	0	0	0
KA-31	650	118A12	0	0	0	0	0	0	0	0	0	0	0	1	0	0
KA-31	650	118A36	2	0	0	0	0	0	0	0	0	0	0	0	0	0
KA-31	650	1E6B05	0	0	0	3	0	0	0	0	0	0	0	0	0	0
KA-31	650	1HML27	0	0	0	0	0	0	0	0	0	0	2	0	0	0
KA-31	650	218A36	0	1	0	0	0	0	0	0	0	0	0	0	0	0
KA-31	650	2E6B05	0	0	0	3	0	0	0	0	0	0	0	0	0	0
KA-31	650	318A36	0	0	0	0	0	0	0	0	4	0	0	0	0	0
KA-31	650	3V2212	0	0	0	0	1	0	0	0	0	0	0	0	0	0
KA-31	650	CCSPFW	3	3	3	3	0	0	0	0	3	0	0	3	0	0
KA-31	650	CCSPRW	0	0	0	0	3	3	3	3	0	3	3	0	3	0
KA-31	650	IOSP11	11	0	0	0	0	0	0	0	0	0	0	0	0	0
KA-31	650	IOSP12	0	11	0	0	0	0	0	0	0	0	0	0	0	0
KA-31	650	IOSP14	0	0	0	4	0	0	0	0	0	0	0	0	0	0
KA-31	650	IOSP31	0	0	0	0	0	0	0	0	9	0	0	0	0	0
KA-31	650	TV2226	0	0	0	0	0	0	1	0	0	0	0	0	0	0
MC-01	670	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
MC-01	670	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	1	0
MC-01	600	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	0	0	0
MC-01	600	CCSPRW	0	0	0	0	1	0	1	1	0	0	1	0	1	0
PM-01	650	1E6B05	0	1	0	1	0	0	0	0	0	0	0	0	0	0
PM-01	650	2E6B05	0	0	0	1	0	0	0	0	0	0	0	0	0	0
PM-01	650	3E6B05	0	0	0	1	0	0	0	0	0	0	0	0	0	0
PM-02	650	1V8R14	0	1	1	1	0	0	0	0	0	0	0	0	0	0
SH-06	650	130J12	1	1	0	1	0	0	0	0	0	0	0	0	0	0
SH-06	650	130T12	0	0	0	0	0	0	0	0	0	0	0	1	1	0
SH-06	650	CCSPRW	0	0	0	0	0	2	0	2	0	2	2	0	1	0
ST-01	690	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
ST-01	690	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
ST-01	650	118A36	0	1	0	0	0	0	0	0	0	0	0	0	0	0

USMC MF TBA by Division

CONFIG	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
ST-01	650	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
ST-01	650	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	2	0
ST-01	650	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
ST-01	620	118A36	1	1	0	0	0	0	0	0	1	0	0	0	0	0
ST-01	620	118C24	1	0	0	0	0	0	0	0	1	0	0	1	0	0
ST-01	620	130T12	0	0	0	0	0	0	0	0	0	0	0	1	1	0
ST-01	620	153E16	0	0	0	0	1	1	0	2	0	1	0	0	0	0
ST-01	620	1E6B05	0	1	0	1	0	0	0	0	0	0	0	0	0	0
ST-01	620	1HML27	0	0	0	0	0	1	0	2	0	1	1	0	0	0
ST-01	620	1RS53E	0	0	0	0	0	0	0	0	0	0	0	0	1	0
ST-01	620	1V8R14	0	1	1	1	0	0	0	0	0	0	0	0	0	0
ST-01	620	253E16	0	0	0	0	1	0	0	0	0	0	0	0	0	0
ST-01	620	2E6B05	0	0	0	1	0	0	0	0	0	0	0	0	0	0
ST-01	620	2HML27	0	0	0	0	0	0	0	0	0	0	1	0	0	0
ST-01	620	2V8R14	0	0	1	1	0	0	0	0	0	0	0	0	0	0
ST-01	620	3E6B05	0	0	0	1	0	0	0	0	0	0	0	0	0	0
ST-01	620	CCSPFW	2	2	2	2	0	0	0	0	2	0	0	2	0	0
ST-01	620	CCSPRW	0	0	0	0	2	2	2	2	0	2	2	0	2	0
ST-01	620	T53E29	0	0	0	0	0	0	0	1	0	0	0	0	0	0
ST-01	620	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
ST-01	620	TH1M39	0	0	0	0	0	0	0	0	0	0	1	0	0	0
ST-01	620	TV8B14	0	0	0	3	0	0	0	0	0	0	0	0	0	0
ST-01	610	118A36	1	1	0	0	0	0	0	0	1	0	0	0	0	0
ST-01	610	118C24	1	0	0	0	0	0	0	0	1	0	0	1	0	0
ST-01	610	130T12	0	0	0	0	0	0	0	0	0	0	0	3	3	0
ST-01	610	1E6B05	0	2	0	2	0	0	0	0	0	0	0	0	0	0
ST-01	610	1V8R14	0	1	1	1	0	0	0	0	0	0	0	0	0	0
ST-01	610	2E6B05	0	0	0	2	0	0	0	0	0	0	0	0	0	0
ST-01	610	2V8R14	0	0	1	1	0	0	0	0	0	0	0	0	0	0
ST-01	610	3E6B05	0	0	0	2	0	0	0	0	0	0	0	0	0	0
ST-01	610	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
ST-01	610	CCSPRW	0	0	0	0	3	3	2	3	0	3	3	0	3	0
ST-01	610	T53E29	0	0	0	0	0	0	0	2	0	0	0	0	0	0
ST-01	610	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
ST-01	610	TH1M39	0	0	0	0	0	0	0	0	0	0	1	0	0	0
ST-01	610	TV8B14	0	0	0	6	0	0	0	0	0	0	0	0	0	0
SU-01	670	CCSPFW	4	4	3	4	0	0	0	0	3	0	0	3	0	0
SU-01	670	CCSPRW	0	0	0	0	3	3	4	3	0	4	4	0	3	0
SU-01	650	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
SU-01	600	CCSPFW	4	4	4	4	0	0	0	0	4	0	0	3	0	0
SU-01	600	CCSPRW	0	0	0	0	4	4	3	3	0	4	4	0	4	0
SU-01	600	IOSP14	0	0	0	4	0	0	0	0	0	0	0	0	0	0

USMC MF TBA by Division

CONFIG	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
SU-03	670	IOSP14	0	0	0	1	0	0	0	0	0	0	0	0	0	0
SU-03	650	118C24	0	0	0	0	0	0	0	0	1	0	0	1	0	0
SU-03	60C	CCSPFW	1	1	1	1	0	0	0	0	0	0	0	0	0	0
SU-03	60C	CCSPRW	0	0	0	0	1	0	0	0	0	0	1	0	0	0
SU-03	600	CCSPFW	1	0	1	1	0	0	0	0	0	0	0	1	0	0
SU-03	600	CCSPRW	0	0	0	0	1	0	0	1	0	1	0	0	0	0
SU-03	600	IOSP14	0	0	0	1	0	0	0	0	0	0	0	0	0	0
SU-05	60C	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
SU-05	60C	CCSPRW	0	0	0	0	1	1	1	0	0	0	1	0	1	0
SU-05	60C	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
SU-05	600	CCSPFW	1	0	2	0	0	0	0	0	2	0	0	0	0	0
SU-05	600	CCSPRW	0	0	0	0	2	1	2	2	0	0	2	0	0	0
SU-12	670	IOSP14	0	0	0	1	0	0	0	0	0	0	0	0	0	0
SU-12	600	CCSPFW	0	0	0	0	0	0	0	0	0	0	0	1	0	0
SU-12	600	CCSPRW	0	0	0	0	1	0	1	0	0	1	0	0	0	0
TL-01	670	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
TL-01	670	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	1	0
TR-01	600	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	0	0	0
TR-01	600	CCSPRW	0	0	0	0	0	1	0	1	0	0	1	0	1	0
TR-01	600	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
TT-02	620	1HML27	0	0	0	0	0	1	0	2	0	1	1	0	1	0
TT-02	620	2HML27	0	0	0	0	0	0	0	0	0	0	1	0	0	0
TT-03A	620	1HML27	0	0	0	0	0	1	0	2	0	1	1	0	1	0
TT-03A	620	2HML27	0	0	0	0	0	0	0	0	0	0	1	0	0	0
TT-04B	620	1HML27	0	0	0	0	0	1	0	2	0	1	1	0	1	0
TT-04B	620	2HML27	0	0	0	0	0	0	0	0	0	0	1	0	0	0
VD-05A	620	CCSPRW	0	0	0	0	0	0	1	1	0	1	1	0	0	0
VD-05A	620	T53E29	0	0	0	0	0	0	0	1	0	0	0	0	0	0
VD-05A	620	TH1M39	0	0	0	0	0	0	0	0	0	0	1	0	0	0
VD-06B	620	CCSPRW	0	0	0	0	0	0	1	1	0	1	1	0	0	0
VD-06B	620	T53E29	0	0	0	0	0	0	0	1	0	0	0	0	0	0
VD-06B	620	TH1M39	0	0	0	0	0	0	0	0	0	0	1	0	0	0
VD-07A	620	130T12	0	0	0	0	0	0	0	0	0	0	0	0	1	0
VD-07A	620	153E16	0	0	0	0	1	0	0	0	0	0	0	0	0	0
VD-07A	620	318C24	0	0	0	0	0	0	0	0	1	0	0	0	0	0
VD-07A	620	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
VD-07A	620	CCSPRW	0	0	0	0	0	1	0	0	0	0	0	0	0	0
VD-07A	620	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
VD-07A	620	TV8B14	0	0	0	1	0	0	0	0	0	0	0	0	0	0
VD-08B	620	130T12	0	0	0	0	0	0	0	0	0	0	0	0	1	0
VD-08B	620	153E16	0	0	0	0	1	0	0	0	0	0	0	0	0	0
VD-08B	620	318C24	0	0	0	0	0	0	0	0	1	0	0	0	0	0

USMC MF TBA by Division

CONFIG	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
VD-08B	620	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
VD-08B	620	CCSPRW	0	0	0	0	0	1	0	0	0	0	0	0	0	0
VD-08B	620	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
VD-08B	620	TV8B14	0	0	0	1	0	0	0	0	0	0	0	0	0	0
WC-12A	60C	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
WC-12A	60C	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
WC-13BM	60C	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
WC-13BM	60C	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
WR-01	690	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	0	0	0
WR-01	690	CCSPRW	0	0	0	0	0	0	0	1	0	0	0	0	0	0
WR-02	690	CCSPRW	0	0	0	0	1	1	1	0	0	1	1	0	1	0
** Subtotal **			133	109	86	164	78	75	76	94	110	72	101	72	75	0
** 700 **																
BR-01	71D	118A36	1	1	0	0	0	0	0	0	1	0	0	1	0	0
BR-01	71D	1HML27	0	0	0	0	0	0	0	1	0	0	0	0	1	0
BR-01	71D	1V8R14	0	0	1	1	0	0	0	0	0	0	0	0	0	0
BR-04A	71D	CCSPFW	1	1	0	1	0	0	0	0	0	0	0	1	0	0
BR-04A	71D	CCSPRW	0	0	0	0	1	1	1	0	0	1	0	0	1	0
BR-05B	71D	CCSPFW	1	1	0	1	0	0	0	0	0	0	0	1	0	0
BR-05B	71D	CCSPRW	0	0	0	0	1	1	1	0	0	1	0	0	1	0
CU-01	730	CCSPFW	1	1	0	1	0	0	0	0	0	0	0	1	0	0
CU-01	730	CCSPRW	0	0	0	0	1	1	1	0	0	1	0	0	1	0
CU-01	700	CCSPFW	1	1	0	1	0	0	0	0	0	0	0	1	0	0
CU-01	700	CCSPRW	0	0	0	0	1	1	1	0	0	1	0	0	1	0
FC-05	730	CCSPFW	1	1	0	1	0	0	0	0	0	0	0	1	0	0
FC-05	730	CCSPRW	0	0	0	0	1	1	1	0	0	0	0	0	1	0
FS-01	700	CCSPFW	1	1	0	1	0	0	0	0	0	0	0	1	0	0
FS-01	700	CCSPRW	0	0	0	0	1	1	1	0	0	1	0	0	1	0
GM-02A	71B	118A36	1	1	0	0	0	0	0	0	1	0	0	1	0	0
GM-02A	71B	1V8R14	0	1	1	1	0	0	0	0	0	0	0	0	0	0
GM-02A	71B	CCSPRW	0	0	0	0	1	1	1	0	0	1	0	0	1	0
GM-03B	71B	118A36	1	1	0	0	0	0	0	0	1	0	0	1	0	0
GM-03B	71B	1V8R14	0	1	1	1	0	0	0	0	0	0	0	0	0	0
GM-03B	71B	CCSPRW	0	0	0	0	1	1	1	0	0	1	0	0	1	0
JU-01	700	CCSPFW	2	2	0	2	0	0	0	0	0	0	0	2	0	0
JU-01	700	CCSPRW	0	0	0	0	2	2	2	1	0	2	0	0	1	0
MC-01	700	CCSPFW	1	1	0	1	0	0	0	0	0	0	0	1	0	0
MC-01	700	CCSPRW	0	0	0	0	1	1	1	0	0	0	0	0	1	0
SU-03	700	CCSPFW	1	1	0	1	0	0	0	0	0	0	0	1	0	0
SU-03	700	CCSPRW	0	0	0	0	1	1	1	0	0	1	0	0	1	0
** Subtotal **			13	15	3	13	12	12	12	2	3	10	0	13	12	0

USMC MF TBA by Division

CONFIG	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
**	<u>800</u>	**														
CU-01	800	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
CU-01	800	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
CU-01	800	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
JU-01	800	130J12	0	1	0	0	0	0	0	0	0	0	0	0	0	0
JU-01	800	1V2236	0	0	0	0	0	0	1	0	0	0	0	0	0	0
JU-01	800	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
JU-01	800	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
JU-01	800	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
RR-02	810	130J12	0	1	0	0	0	0	0	0	0	0	0	0	0	0
RR-02	810	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
RR-02	810	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
RR-03	810	130J12	0	1	0	0	0	0	0	0	0	0	0	0	0	0
RR-03	810	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
RR-04A	810	1V2236	0	0	0	0	0	0	2	0	0	1	1	0	0	0
RR-04A	810	3V2212	0	0	0	0	1	1	0	0	0	0	0	0	1	0
RR-04A	810	TV2226	0	0	0	0	0	0	1	0	0	0	0	0	0	0
RR-05B	810	1V2236	0	0	0	0	0	0	2	0	0	1	1	0	0	0
RR-05B	810	3V2212	0	0	0	0	1	1	0	0	0	0	0	0	1	0
RR-05B	810	TV2226	0	0	0	0	0	0	1	0	0	0	0	0	0	0
RR-06BM	810	1V2236	0	0	0	0	0	0	2	0	0	1	1	0	0	0
RR-06BM	810	3V2212	0	0	0	0	1	1	0	0	0	0	0	0	1	0
RR-06BM	810	TV2226	0	0	0	0	0	0	1	0	0	0	0	0	0	0
SE-01	810	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
SE-01	810	CCSPRW	0	0	0	0	1	0	1	1	0	1	1	0	1	0
SE-01	810	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
SE-02B	810	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
SE-03C	810	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
SE-04B	810	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
SW-02	820	118A36	1	1	0	0	0	0	0	0	1	0	0	1	0	0
SW-02	820	118C24	1	1	0	0	0	0	0	0	1	0	0	0	0	0
SW-02	820	1HML27	0	0	0	0	0	0	0	2	0	0	1	0	2	0
SW-02	820	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
SW-02	820	TH1M39	0	0	0	0	0	0	0	0	0	0	1	0	0	0
** Subtotal **			12	10	5	5	9	8	16	8	7	9	11	6	11	0
**	<u>900</u>	**														
BL-01	940	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	0	0	0
BL-01	940	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
CU-01	940	CCSPFW	0	0	0	1	0	0	0	0	1	0	0	0	0	0
CU-01	940	CCSPRW	0	0	0	0	0	0	0	1	0	0	0	0	0	0
CU-01	930	CCSPFW	0	0	0	0	0	0	0	0	0	0	0	1	0	0

USMC MF TBA by Division

CONFIG	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
CU-01	910	CCSPRW	0	0	0	0	0	0	0	0	0	0	0	0	1	0
JU-01	900	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
JU-01	900	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
JU-01	900	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
WC-08	940	CCSPFW	1	1	1	0	0	0	0	0	0	0	0	1	0	0
WC-08	940	CCSPRW	0	0	0	0	1	1	1	0	0	0	1	0	1	0
WC-08	940	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
WC-08	930	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	0	0	0
WC-08	930	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	1	0
WC-08	910	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
WC-08	910	CCSPRW	0	0	0	0	1	1	1	1	0	0	1	0	0	0
WC-08	910	TFRS11	1	0	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			8	5	5	5	5	5	5	5	5	2	5	4	5	0
** <u>AIS</u> **																
CU-01	AIS	CCSPRW	0	0	0	0	0	1	0	0	0	0	0	0	0	0
DP-03	AIS	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
DP-03	AIS	CCSPRW	0	0	0	0	1	0	1	1	0	1	1	0	1	0
DP-18A	AIS	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
DP-18A	AIS	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
DP-18A	AIS	IOSP14	0	0	0	1	0	0	0	0	0	0	0	0	0	0
DP-18A	AIS	IOSP16	0	0	0	0	1	0	0	0	0	0	0	0	0	0
DP-18A	AIS	IOSP36	0	0	0	0	0	0	0	0	0	1	0	0	0	0
DP-18A	AIS	IOSP41	0	0	0	0	0	0	0	0	0	0	0	1	0	0
JU-01	AIS	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
JU-01	AIS	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
ST-01	AIS	CCSPFW	2	2	2	2	0	0	0	0	2	0	0	2	0	0
ST-01	AIS	CCSPRW	0	0	0	0	2	2	2	2	0	2	2	0	2	0
SU-03	AIS	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
SU-03	AIS	CCSPRW	0	0	0	0	1	0	1	1	0	1	1	0	1	0
SU-12	AIS	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
SU-12	AIS	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
** Subtotal **			7	7	7	8	8	6	7	7	7	8	7	8	7	0
** <u>ATC</u> **																
AT-11	ATC	MACSXX	0	1	1	2	1	0	0	1	1	1	2	1	0	0
AT-12	ATC	MACSXX	0	1	1	2	1	0	0	1	1	1	2	1	0	0
CR-03	ATC	MACSXX	0	2	2	2	2	0	0	2	2	2	4	2	0	0
JU-01	ATC	MACSXX	0	1	2	2	1	0	0	1	1	1	2	1	0	0
SU-03	ATC	MACSXX	0	1	1	2	1	0	0	1	1	1	2	0	0	0
** Subtotal **			0	6	7	10	6	0	0	6	6	6	12	5	0	0

USMC MF TBA by Division

CONFIG	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
** MP2 **																
BL-01	LPZ	2FEFW	0	0	0	0	0	0	0	0	0	0	0	0	0	2
BL-01	CRF	2FERW	0	0	0	0	0	0	0	0	0	0	0	0	0	2
CU-01	WLM	2FERW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
CU-01	SSR	2FEFW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
CU-01	SEAY	2FERW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
CU-01	LPZ	2FEFW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
EA-01	SKM	EAF	0	0	0	0	0	0	0	0	0	0	0	0	0	1
JU-01	WLM	2FERW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
JU-01	SSR	2FEFW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
JU-01	SEAY	2FERW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
JU-01	LPZ	2FEFW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
ST-01	WLM	2FERW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
ST-01	SSR	2FEFW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
ST-01	SEAY	2FERW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
ST-01	LPZ	2FEFW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
SU-08	WLM	2FERW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
SU-08	SSR	2FEFW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
SU-08	SEAY	2FERW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
SU-08	LPZ	2FEFW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
TW-05A	LPZ	2FEFW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
TW-05A	CRF	2FERW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
TW-06B	LPZ	2FEFW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
TW-06B	CRF	2FERW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
** Subtotal **			0	0	0	0	0	0	0	0	0	0	0	0	0	25
** MP3 **																
BL-01	LMS	3FEFW	0	0	0	0	0	0	0	0	0	0	0	0	0	2
BL-01	CRF	3FERW	0	0	0	0	0	0	0	0	0	0	0	0	0	2
CU-01	PLU	3FERW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
CU-01	LMS	3FEFW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
CU-01	DHL	3FEFW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
CU-01	BBO	3FERW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
EA-01	BTN	EAF	0	0	0	0	0	0	0	0	0	0	0	0	0	1
JU-01	PLU	3FERW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
JU-01	LMS	3FEFW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
JU-01	DHL	3FEFW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
JU-01	BBO	3FERW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
ST-01	PLU	3FERW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
ST-01	LMS	3FEFW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
ST-01	DHL	3FEFW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
ST-01	BBO	3FERW	0	0	0	0	0	0	0	0	0	0	0	0	0	1

USMC MF TBA by Division

CONFIG	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
SU-08	PLU	3FERW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
SU-08	LMS	3FEFW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
SU-08	DHL	3FEFW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
SU-08	BBO	3FERW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
TW-05A	LMS	3FEFW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
TW-05A	CRF	3FERW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
TW-06B	LMS	3FEFW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
TW-06B	CRF	3FERW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
** Subtotal **			0	0	0	0	0	0	0	0	0	0	0	0	0	25
** MPS **																
BL-01	BLI	MPSBLI	0	0	0	0	0	0	0	0	0	0	0	0	0	1
CU-01	FLY	MPSFLY	0	0	0	0	0	0	0	0	0	0	0	0	0	1
FS-01	BLI	MPSBLI	0	0	0	0	0	0	0	0	0	0	0	0	0	1
JU-01	FLY	MPSFLY	0	0	0	0	0	0	0	0	0	0	0	0	0	1
ST-01	FLY	MPSFLY	0	0	0	0	0	0	0	0	0	0	0	0	0	1
SU-08	FLY	MPSFLY	0	0	0	0	0	0	0	0	0	0	0	0	0	1
TW-05A	FLY	MPSFLY	0	0	0	0	0	0	0	0	0	0	0	0	0	1
TW-06B	FLY	MPSFLY	0	0	0	0	0	0	0	0	0	0	0	0	0	1
** Subtotal **			0	0	0	0	0	0	0	0	0	0	0	0	0	8
** S00 **																
ED-01	S00	F11812	2	0	0	0	0	0	0	0	0	0	0	0	0	0
ED-01	S00	F11824	2	0	0	0	0	0	0	0	0	0	0	0	0	0
ED-01	S00	F15316	0	0	0	0	0	0	0	2	0	0	0	0	0	0
ED-01	S00	F1KJ09	2	0	0	0	0	0	0	0	0	0	0	0	0	0
ED-01	S00	F1V212	0	0	0	0	2	2	2	0	0	2	2	0	0	0
ED-01	S00	F1V816	0	0	0	2	0	0	0	0	0	0	0	0	0	0
ED-01	S00	F1YZ27	0	0	0	0	0	2	0	2	0	2	2	0	0	0
ED-01	S00	F21812	0	0	0	0	0	0	0	0	2	0	0	0	0	0
ED-01	S00	F21824	0	0	0	0	0	0	0	0	2	0	0	0	0	0
ED-01	S00	F25316	0	0	0	0	0	0	0	2	0	0	0	0	0	0
ED-01	S00	F2KJ09	0	2	0	0	0	0	0	0	0	0	0	0	0	0
ED-01	S00	F2V212	0	0	0	0	2	0	2	0	0	0	0	0	0	0
ED-01	S00	F2V816	0	0	0	2	0	0	0	0	0	0	0	0	0	0
ED-01	S00	F2YZ27	0	0	0	0	0	0	0	2	0	0	2	0	0	0
ED-01	S00	F31824	0	2	0	0	0	0	0	0	0	0	0	0	0	0
ED-01	S00	F35316	0	0	0	0	0	2	0	0	0	0	0	0	0	0
ED-01	S00	F3KJ09	0	0	0	2	0	0	0	0	0	0	0	0	0	0
ED-01	S00	F3V816	0	0	2	0	0	0	0	0	0	0	0	0	0	0
ED-01	S00	F45316	0	0	0	0	2	0	0	0	0	0	0	0	0	0
ED-01	S00	F4V816	0	0	2	0	0	0	0	0	0	0	0	0	0	0

USMC MF TBA by Division

CONFIG	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
ED-01	S00	F55316	0	0	0	0	0	0	0	0	0	2	0	0	0	0
ED-01	S00	MSA	0	0	0	0	0	0	4	0	0	0	0	0	0	0
FS-01	S00	F11812	1	0	0	0	0	0	0	0	0	0	0	0	0	0
FS-01	S00	F11824	1	0	0	0	0	0	0	0	0	0	0	0	0	0
FS-01	S00	F15316	0	0	0	0	0	0	0	1	0	0	0	0	0	0
FS-01	S00	F1KJ09	1	0	0	0	0	0	0	0	0	0	0	0	0	0
FS-01	S00	F1V212	0	0	0	0	1	1	1	0	0	1	1	0	0	0
FS-01	S00	F1V816	0	0	0	1	0	0	0	0	0	0	0	0	0	0
FS-01	S00	F1YZ27	0	0	0	0	0	1	0	1	0	1	1	0	0	0
FS-01	S00	F21812	0	0	0	0	0	0	0	0	1	0	0	0	0	0
FS-01	S00	F21824	0	0	0	0	0	0	0	0	1	0	0	0	0	0
FS-01	S00	F25316	0	0	0	0	0	0	0	1	0	0	0	0	0	0
FS-01	S00	F2KJ09	0	1	0	0	0	0	0	0	0	0	0	0	0	0
FS-01	S00	F2V212	0	0	0	0	1	0	1	0	0	0	0	0	0	0
FS-01	S00	F2V816	0	0	0	1	0	0	0	0	0	0	0	0	0	0
FS-01	S00	F2YZ27	0	0	0	0	0	0	0	1	0	0	1	0	0	0
FS-01	S00	F31824	0	1	0	0	0	0	0	0	0	0	0	0	0	0
FS-01	S00	F35316	0	0	0	0	0	1	0	0	0	0	0	0	0	0
FS-01	S00	F3KJ09	0	0	0	1	0	0	0	0	0	0	0	0	0	0
FS-01	S00	F3V816	0	0	1	0	0	0	0	0	0	0	0	0	0	0
FS-01	S00	F45316	0	0	0	0	1	0	0	0	0	0	0	0	0	0
FS-01	S00	F4V816	0	0	1	0	0	0	0	0	0	0	0	0	0	0
FS-01	S00	F55316	0	0	0	0	0	0	0	0	0	1	0	0	0	0
FS-01	S00	MSA	1	1	1	1	1	1	1	1	1	1	1	0	1	0
JU-01	S00	F11812	1	0	0	0	0	0	0	0	0	0	0	0	0	0
JU-01	S00	F11824	1	0	0	0	0	0	0	0	0	0	0	0	0	0
JU-01	S00	F15316	0	0	0	0	0	0	0	1	0	0	0	0	0	0
JU-01	S00	F1KJ09	1	0	0	0	0	0	0	0	0	0	0	0	0	0
JU-01	S00	F1V212	0	0	0	0	1	1	1	0	0	1	1	0	0	0
JU-01	S00	F1V816	0	0	0	1	0	0	0	0	0	0	0	0	0	0
JU-01	S00	F1YZ27	0	0	0	0	0	1	0	1	0	1	1	0	0	0
JU-01	S00	F21812	0	0	0	0	0	0	0	0	1	0	0	0	0	0
JU-01	S00	F21824	0	0	0	0	0	0	0	0	1	0	0	0	0	0
JU-01	S00	F25316	0	0	0	0	0	0	0	1	0	0	0	0	0	0
JU-01	S00	F2KJ09	0	1	0	0	0	0	0	0	0	0	0	0	0	0
JU-01	S00	F2V212	0	0	0	0	1	0	1	0	0	0	0	0	0	0
JU-01	S00	F2V816	0	0	0	1	0	0	0	0	0	0	0	0	0	0
JU-01	S00	F2YZ27	0	0	0	0	0	0	0	1	0	0	1	0	0	0
JU-01	S00	F31824	0	1	0	0	0	0	0	0	0	0	0	0	0	0
JU-01	S00	F35316	0	0	0	0	0	1	0	0	0	0	0	0	0	0
JU-01	S00	F3KJ09	0	0	0	1	0	0	0	0	0	0	0	0	0	0
JU-01	S00	F3V816	0	0	1	0	0	0	0	0	0	0	0	0	0	0

USMC MF TBA by Division

CONFIG	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
JU-01	S00	F45316	0	0	0	0	1	0	0	0	0	0	0	0	0	0
JU-01	S00	F4V816	0	0	1	0	0	0	0	0	0	0	0	0	0	0
JU-01	S00	F55316	0	0	0	0	0	0	0	0	0	1	0	0	0	0
JU-01	S00	MSA	2	2	2	2	2	2	2	2	2	2	2	0	2	0
SU-01	S00	F11812	2	0	0	0	0	0	0	0	0	0	0	0	0	0
SU-01	S00	F11824	2	0	0	0	0	0	0	0	0	0	0	0	0	0
SU-01	S00	F15316	0	0	0	0	0	0	0	2	0	0	0	0	0	0
SU-01	S00	F1KJ09	2	0	0	0	0	0	0	0	0	0	0	0	0	0
SU-01	S00	F1V212	0	0	0	0	2	2	2	0	0	2	2	0	0	0
SU-01	S00	F1V816	0	0	0	2	0	0	0	0	0	0	0	0	0	0
SU-01	S00	F1YZ27	0	0	0	0	0	2	0	2	0	2	2	0	0	0
SU-01	S00	F21812	0	0	0	0	0	0	0	0	2	0	0	0	0	0
SU-01	S00	F21824	0	0	0	0	0	0	0	0	2	0	0	0	0	0
SU-01	S00	F25316	0	0	0	0	0	0	0	2	0	0	0	0	0	0
SU-01	S00	F2KJ09	0	2	0	0	0	0	0	0	0	0	0	0	0	0
SU-01	S00	F2V212	0	0	0	0	2	0	2	0	0	0	0	0	0	0
SU-01	S00	F2V816	0	0	0	2	0	0	0	0	0	0	0	0	0	0
SU-01	S00	F2YZ27	0	0	0	0	0	0	0	2	0	0	2	0	0	0
SU-01	S00	F31824	0	2	0	0	0	0	0	0	0	0	0	0	0	0
SU-01	S00	F35316	0	0	0	0	0	2	0	0	0	0	0	0	0	0
SU-01	S00	F3KJ09	0	0	0	2	0	0	0	0	0	0	0	0	0	0
SU-01	S00	F3V816	0	0	2	0	0	0	0	0	0	0	0	0	0	0
SU-01	S00	F45316	0	0	0	0	2	0	0	0	0	0	0	0	0	0
SU-01	S00	F4V816	0	0	2	0	0	0	0	0	0	0	0	0	0	0
SU-01	S00	F55316	0	0	0	0	0	0	0	0	0	2	0	0	0	0
SU-01	S00	MSA	2	1	2	2	2	1	2	2	2	1	2	0	2	0
SU-02	S00	MSA	4	2	4	4	4	2	2	4	4	2	4	0	4	0
SU-05	S00	MSA	2	2	2	2	2	2	2	2	2	2	2	0	2	0
SU-12	S00	F11812	2	0	0	0	0	0	0	0	0	0	0	0	0	0
SU-12	S00	F11824	2	0	0	0	0	0	0	0	0	0	0	0	0	0
SU-12	S00	F15316	0	0	0	0	0	0	0	2	0	0	0	0	0	0
SU-12	S00	F1KJ09	2	0	0	0	0	0	0	0	0	0	0	0	0	0
SU-12	S00	F1V212	0	0	0	0	2	2	2	0	0	2	2	0	0	0
SU-12	S00	F1V816	0	0	0	2	0	0	0	0	0	0	0	0	0	0
SU-12	S00	F1YZ27	0	0	0	0	0	2	0	2	0	2	2	0	0	0
SU-12	S00	F21812	0	0	0	0	0	0	0	0	2	0	0	0	0	0
SU-12	S00	F21824	0	0	0	0	0	0	0	0	2	0	0	0	0	0
SU-12	S00	F25316	0	0	0	0	0	0	0	2	0	0	0	0	0	0
SU-12	S00	F2KJ09	0	2	0	0	0	0	0	0	0	0	0	0	0	0
SU-12	S00	F2V212	0	0	0	0	2	0	2	0	0	0	0	0	0	0
SU-12	S00	F2V816	0	0	0	2	0	0	0	0	0	0	0	0	0	0
SU-12	S00	F2YZ27	0	0	0	0	0	0	0	2	0	0	2	0	0	0

USMC MF TBA by Division

CONFIG	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
SU-12	S00	F31824	0	2	0	0	0	0	0	0	0	0	0	0	0	0
SU-12	S00	F35316	0	0	0	0	0	2	0	0	0	0	0	0	0	0
SU-12	S00	F3KJ09	0	0	0	2	0	0	0	0	0	0	0	0	0	0
SU-12	S00	F3V816	0	0	2	0	0	0	0	0	0	0	0	0	0	0
SU-12	S00	F45316	0	0	0	0	2	0	0	0	0	0	0	0	0	0
SU-12	S00	F4V816	0	0	2	0	0	0	0	0	0	0	0	0	0	0
SU-12	S00	F55316	0	0	0	0	0	0	0	0	0	2	0	0	0	0
SU-12	S00	MSA	5	3	5	5	5	3	3	5	5	3	5	0	4	0
** Subtotal **			40	27	32	40	40	35	32	48	32	35	40	0	15	0
** ZZC **																
EA-01	EAF	BEAFFW	1	1	1	2	0	0	0	0	1	0	0	0	0	0
EA-01	EAF	BEAFRW	0	0	0	0	1	0	1	1	0	1	1	0	0	0
EA-01	EAF	PALMXX	1	0	0	0	0	0	0	0	0	0	0	0	0	0
EA-02	EAF	BEAFFW	0	0	0	2	0	0	0	0	0	0	0	0	0	0
EA-02	EAF	BEAFRW	0	0	0	0	2	0	0	0	0	2	0	0	0	0
JU-01	EAF	PALMXX	1	0	0	0	0	0	0	0	0	0	0	0	0	0
** Subtotal **			3	1	1	4	3	0	1	1	1	3	1	0	0	0
Total			325	254	198	318	227	194	213	234	239	187	241	163	191	58

USMC MF TBA Support Equipment by Configuration Code

DIV	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
** <u>ANCILLARY</u> **																
600	60C	CCSPFW	1	1	1	1	0	0	0	0	1	0	0	1	0	0
600	60C	CCSPRW	0	0	0	0	1	1	1	1	0	1	1	0	1	0
** Subtotal **			1	1	1	1	1	1	1	1	1	1	1	1	1	0
** <u>CDT</u> **																
600	60C	CCSPFW	2	2	2	2	0	0	0	0	2	0	0	2	0	0
600	60C	CCSPRW	0	0	0	0	2	2	2	2	0	2	2	0	2	0
** Subtotal **			2	2	2	2	2	2	2	2	2	2	2	2	2	0
** <u>E-TOOL</u> **																
600	60C	CCSPFW	3	3	3	3	0	0	0	0	3	0	0	3	0	0
600	60C	CCSPRW	0	0	0	0	3	2	3	3	0	3	3	0	3	0
MPS	BLI	MPSBLI	0	0	0	0	0	0	0	0	0	0	0	0	0	2
** Subtotal **			3	3	3	3	3	2	3	3	3	3	3	3	3	2
** <u>LOAD BANK</u> **																
600	60C	CCSPFW	6	6	6	6	0	0	0	0	6	0	0	5	0	0
600	60C	CCSPRW	0	0	0	0	4	2	4	4	0	4	4	0	4	0
MPS	BLI	MPSBLI	0	0	0	0	0	0	0	0	0	0	0	0	0	2
** Subtotal **			6	6	6	6	4	2	4	4	6	4	4	5	4	2
** <u>MEP-807A</u> **																
600	60C	CCSPFW	12	12	12	12	0	0	0	0	12	0	0	12	0	0
600	60C	CCSPRW	0	0	0	0	5	5	5	5	0	5	5	0	5	0
600	60C	PALMXX	1	0	0	0	0	0	0	0	0	0	0	0	0	0
MP2	CRF	2FERW	0	0	0	0	0	0	0	0	0	0	0	0	0	4
MP2	LPZ	2FEFW	0	0	0	0	0	0	0	0	0	0	0	0	0	4
MP2	SEY	2FERW	0	0	0	0	0	0	0	0	0	0	0	0	0	3
MP2	SSR	2FEFW	0	0	0	0	0	0	0	0	0	0	0	0	0	3
MP3	CRF	3FERW	0	0	0	0	0	0	0	0	0	0	0	0	0	4
MP3	DHL	3FEFW	0	0	0	0	0	0	0	0	0	0	0	0	0	3
MP3	LMS	3FEFW	0	0	0	0	0	0	0	0	0	0	0	0	0	4
MP3	PLU	3FERW	0	0	0	0	0	0	0	0	0	0	0	0	0	3
MPS	FLY	MPSFLY	0	0	0	0	0	0	0	0	0	0	0	0	0	1
ZZB	WX	MACSXX	4	2	2	4	2	0	2	0	2	2	2	0	0	0
** Subtotal **			17	14	14	16	7	5	7	5	14	7	7	12	5	29
** <u>MEP-809A</u> **																
600	60C	CCSPFW	18	18	18	18	0	0	0	0	18	0	0	18	0	0
600	60C	CCSPRW	0	0	0	0	14	7	14	14	0	14	14	0	14	0
** Subtotal **			18	18	18	18	14	7	14	14	18	14	14	18	14	0
** <u>PW-BX</u> **																
600	60C	CCSPFW	5	5	5	5	0	0	0	0	5	0	0	3	0	0

USMC MF TBA Support Equipment by Configuration Code

DIV	BR	CSP	M11	M12	M13	M14	M16	M24	M26	M29	M31	M36	M39	M41	M49	MPS
600	60C	CCSPRW	0	0	0	0	4	4	4	4	0	4	4	0	4	0
** Subtotal **			5	5	5	5	4	4	4	4	5	4	4	3	4	0
** RECLAMATOR **																
600	60C	CCSPFW	3	3	3	3	0	0	0	0	3	0	0	3	0	0
600	60C	CCSPRW	0	0	0	0	3	3	3	3	0	3	3	0	3	0
** Subtotal **			3	3	3	3	3	3	3	3	3	3	3	3	3	0
** SMFC **																
600	60C	CCSPFW	0	3	3	2	0	0	0	0	1	0	0	2	0	0
600	60C	CCSPRW	0	0	0	0	4	2	0	0	0	5	0	0	1	0
MP2	LPZ	2FEFW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
MP2	WLM	2FERW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
MP3	BBO	3FERW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
MP3	LMS	3FEFW	0	0	0	0	0	0	0	0	0	0	0	0	0	1
** Subtotal **			0	3	3	2	4	2	0	0	1	5	0	2	1	4
** SMFC ADAPT **																
600	60C	CCSPFW	6	4	3	8	0	0	0	0	7	0	0	3	0	0
600	60C	CCSPRW	0	0	0	0	2	1	4	4	0	2	5	0	2	0
** Subtotal **			6	4	3	8	2	1	4	4	7	2	5	3	2	0
Total			61	59	58	64	44	29	42	40	60	45	43	52	39	37

Mobile Facility/Ancillary Equipment/Administrative Note
Cross Reference

CODE	CONFIGURATION
AB-02	AIRCREW BRIEF/DEBRIEF MF #1
AB-03	AIRCREW BRIEF/DEBRIEF MF #2
AM-01	IMRL MANAGEMENT
AT-08	SQUADRON GROUND SYSTEM
AT-09BM	ATARS POD MAINTENANCE
AT-10A	ATARS PALLET MAINTENANCE
AT-11	EQUIPMENT MAINTENANCE/ATC
AT-12	ADMINISTRATIVE SUPPORT/ATC
AV-01A	600 DIVISION AVO/AVC MF A
AV-02B	600 DIVISION AVO/AVC MF B
BL-01	BATTERY MAINTENANCE SUPPORT FACILITY (REPLACES LA-01 AND NB-03)
BR-01	BRU-33A MAINTENANCE
BR-04A	BRU-33 MF A MAINTENANCE
BR-05B	BRU-33 MF B MAINTENANCE
CA-01	ELECTRO-MECHANICAL
CA-04	PHYSICAL MECHANICAL CALIBRATION
CA-07A	OPTICAL/DIMENSIONAL CALIBRATION MF A
CA-08B	OPTICAL/DIMENSIONAL CALIBRATION MF B
CA-09	PHYSICAL DIMENSIONAL CALIBRATION
CL-01	"I" LEVEL CAL PHASES A, B, C, D
CL-02	"I" LEVEL CAL PHASES E, F
CL-04	TEST EQUIPMENT REPAIR
CL-06	CALIBRATION MANAGEMENT
CL-07	TEST EQUIPMENT STAGING
CL-09	AIMS/TACAN CALIBRATION
CL-10	PHYSICAL DIMENSIONAL CALIB
CR-03	MICRO MINIATURE REPAIR/ATC
CR-04	MICRO MINIATURE REPAIR
CS-02A	COMPOSITE REPAIR/METAL SHOP MF A
CS-03BM	COMPOSITE REPAIR/METAL SHOP MF B MODIFIED
CU-01	MANAGEMENT CONTROL
CY-01	COMMUNICATION SECURITY MAINTENANCE
DP-03	SUPPLY ADP MGMT CENTER
DP-18A	NTCSS
EA-01	EAF MECHANICAL
EA-02	EAF ELECTRICAL

Mobile Facility/Ancillary Equipment/Administrative Note
Cross Reference

CODE	CONFIGURATION
EB-06	EA6B RFI POOL
EB-07	EA6B ANTENNA, RF HEAD POOL
EB-08	EA6B RECEIVER, AWP/AWM
EB-09	EA6B TRANSMITTER, AWP/AWM
ED-01	AVIATION SUPPLY FISP (FUTURE)
FA-02A	SERVO CYLINDER T/S MF A
FA-03B	SERVO CYLINDER T/S MF B
FC-05	FOSAMS
FS-01	FLAMMABLE STORAGE
GC-01	GENERATOR CONTROL UNIT T/S
GM-02A	ORD REPAIR MF A
GM-03B	ORD REPAIR MF B
HC-01	HYDRAULIC COMPONENT ASSEMBLY
HC-02	HYDRAULIC COMPONENT DISASSEMBLY
HY-04A	HYDRAULIC TEST SET A/F27T-10 MF A
HY-05B	HYDRAULIC TEST SET A/F27T-10 MF B
HY-07A	HYDRAULIC TEST SET A/F27T-12 MF A
HY-08B	HYDRAULIC TEST SET A/F27T-12 MF B
HY-06C	MV-22 LANDING GEAR TEST FIXTURE
JU-01	INTEGRATION UNIT, STANDARD
JU-09	INTEGRATION UNIT, EA6B #1
JU-10	INTEGRATION UNIT, EA6B #2
JU-31	INU, F-18 BRIEF/DEBRIEF
JU-32	INU, F-18 TRAINING UNIT # 1
KA-18A	CASS RT TEST STATION (USMC)
KA-19A	CASS HI POWER SOMF A
KA-20B	CASS HI POWER SOMF B
KA-31	OTPS STORAGE, REAPLCED ALL PREVIOUS TPS SUPPORT CONFIGS
MC-01	MAINT/PRODUCTION CONTROL
MM-01	MACHINE SHOP, GRINDER
MM-02	MACHINE SHOP, MILLING MACHINE
MM-03	MACHINE SHOP, LATHE
MM-04	MACHINE SHOP, DRILLING
NT-06	NON-DESTRUCT TEST
NT-08	MAGNETIC PARTICLE MF
PM-01	COUNTERMEASURES CHAFF DISPENSER POD MAINT

Mobile Facility/Ancillary Equipment/Administrative Note
Cross Reference

CODE	CONFIGURATION
PM-02	UNIVERSAL POD MAINTENANCE
PP-01	POWER PLANTS
PP-03A	POWER PLANTS MF A
PP-04BM	POWER PLANTS MF B MODIFIED
PW-01	POWER WASHER/AQUEOUS PARTS WASHER
RR-02	OXYGEN REPAIR
RR-03	ABO ANNALYZER
RR-04A	OXYGEN TEST/REPAIR (RW) MFA
RR-05B	OXYGEN TEST/REPAIR (RW) MFB
RR-06BM	AIR COMPRESSOR MF (RW) B MODIFIED
SE-01	SURVIVAL EQUIPMENT #1
SE-02B	SURVIVAL EQUIPMENT #2
SE-03C	SURVIVAL EQUIPMENT #3
SE-04B	SURVIVAL EQUIPMENT #4
SH-06	A/C SURVIVABILITY EQUIPMENT
SM-04B	SHEET METAL SHOP 1 MF B
SM-05A	SHEET METAL SHOP 1 MF A
SM-06B	SHEET METAL SHOP 2 MF B
SM-07A	SHEET METAL SHOP 2 MF A
SP-04	NOAP (NAVAL OIL ANALYSIS PROGRAM) MF
ST-01	STANDARD MF
SU-01	AVIATION SUPPLY, SHELVES
SU-02	AVIATION SUPPLY, CABINETS
SU-03	AVIATION SUPPLY
SU-04	AVIATION SUPPLY, TECH EDIT
SU-05	AVIATION SUPPLY, SUPPORT CENTER
SU-08	AVIATION SUPPLY, SHIPPING/RECEIVING
SU-12	AVIATION SUPPLY, BULK STORAGE
SW-02	NITROGEN RECEIVER FILL/REPAIR
TB-01	TUBE BENDER MF (REPLACED BY TB-03A/04B IN F/W MALS)
TB-02	MV-22 TUBE BENDER MF
TB-03A	TUBE BENDERS (5FT), MF A
TB-04B	TUBE BENDERS (5FT), MF B
TL-01	TECH LIBRARY
TR-01	TOOL ROOM
TT-02	TURRET TEST SUPPORT

Mobile Facility/Ancillary Equipment/Administrative Note
Cross Reference

CODE	CONFIGURATION
TT-03A	TURRET TEST MF A
TT-04B	TURRET TEST MF B
TW-05A	ACFT TIRE/WHEEL BUILD-UP MF A
TW-06B	ACFT TIRE/WHEEL BUILD-UP MF B
VD-05A	ACFT ENGINE COMPNENT TEST STAND (RW)
VD-06B	ACFT ENGINE COMPNENT TEST STAND (RW)
VD-07A	ACFT ENGINE COMPNENT TEST STAND (FW)
VD-08B	ACFT ENGINE COMPNENT TEST STAND (FW)
WC-02	QUALITY ASSURANCE
WC-08	SUPPORT EQUIPMENT MAINT
WC-12A	WORK CENTER 60C MF A
WC-13BM	WORK CENTER 60C MF B-MOD
WL-04A	WELDING SHOP MF A
WL-05A	WELDING SHOP MF B
WR-01	WIRE REPAIR
WR-02	WIRE REPAIR MV-22
ANCILLARY	ANCILLARY MF EQUIPMENT
CDT	COMPLEXING/DECOMPLEXING TOOL
E-TOOL	TACTICAL QUIET GENERATOR TROUBLESHOOTING COMPUTER
LOAD BANK	RESISTIVE LOAD BANK, LPH200
MEP-807A	GENERATOR, TACTICAL QUIET 100KW
MEP-809A	GENERATOR, TACTICAL QUIET 200KW
SMFC	STATIC MOBILE FREQUENCY CONVERTER
SMFC ADAPT	STATIC MOBILE FREQUENCY CONVERTER ADAPTER KIT
PW-BX	POWER DISTRIBUTION BOX& ASSOCIATED ANCILLARY EQUIPMENT
RECLAMATOR	REFRIGERANT RECOVERY/RECYCLING UNIT

Mobile Facility/Ancillary Equipment/Administrative Note
Cross Reference

NAME	DESCRIPTION
118A12	12 A/C F/A-18A PCSP
118A36	36 A/C F/A-18A PCSP
118C24	24 A/C F/A-18C PCSP
130J12	12 A/C KC-130J PCSP
130T12	12 A/C KC-130T PCSP
135B16	16 A/C F-35B PCSP
153E16	16 A/C CH-53E PCSP
1E6B05	5 A/C EA-6B PCSP
1HML09	9 A/C H-1 PCSP 4 TH MAW
1HML27	27 A/C 9 UH-1Y/18 AH-1Z PCSP
1RS53E	X A/C CH-53E PCSP 4 TH MAW
1V2236	36 A/C MV-22 PCSP
1V8R14	14 A/C AV-8B PCSP
218A36	36 A/C F/A-18A PCSP (2ND PKG ON SITE)
235C10	10 A/C F-35C PCSP (2ND PKG ON SITE)
253E16	16 A/C CH-53E PCSP (2ND PKG ON SITE)
2E6B05	5 A/C EA-6B PCSP (2ND PKG ON SITE)
2FEFW	F/W CSP (MPS SQUADRON 2)
2FERW	R/W CSP (MPS SQUADRON 2)
2HML09	9 A/C H-1 PCSP 4 TH MAW (2ND PKG ON SITE)
2HML27	27 A/C 9 UH-1Y/18 AH-1Z PCSP (2ND PKG ON SITE)
2V8R14	14 A/C AV-8B PCSP (2ND PKG ON SITE)
318A12	12 A/C F/A-18A PCSP (3RD PKG ON SITE)
318A36	36 A/C F/A-18A PCSP (3RD PKG ON SITE)
318C24	24 A/C F/A-18C PCSP (3RD PKG ON SITE)
335B10	10 A/C F-35B PCSP (3RD PKG ON SITE)
3E6B05	5 A/C EA-6B PCSP (3RD PKG ON SITE)
3FEFW	F/W CSP (MPS SQUADRON 3)
3FERW	R/W CSP (MPS SQUADRON 3)
3HML27	27 A/C 9 UH-1Y/18 AH-1Z PCSP (3RD PKG ON SITE)
3V2212	12 A/C MV-22 PCSP (3RD PKG ON SITE)
435B16	16 A/C F-35B PCSP (4TH PKG ON SITE)
4HML27	27 A/C H-1 PCSP (4TH PKG ON SITE)
535B16	16 A/C F-35B PCSP (5TH PKG ON SITE)
553E16	16 A/C CH-53E PCSP (5TH PKG ON SITE)
BEAFFW	EAF F/W PCSP

Mobile Facility/Ancillary Equipment/Administrative Note
Cross Reference

NAME	DESCRIPTION
BEAFRW	EAF R/W PCSP
CCSPFW	COMMON CSP FOR A FIXED WING MALS
CCSPRW	COMMON CSP FOR A ROTARY WING MALS
EAF	EXPEDITIONARY AIR FIELD
F11812	FSA, 12 A/C F/A-18A++/C/C+/D
F11824	FSA, 24 A/C F/A-18A++/C/C+/D
F15316	FSA, 16 A/C CH-53E
F1KJ09	FSA, 9 A/C KC-130J
F1V212	FSA, 12 A/C MV-22
F1V816	FSA, 16 A/C AV-8B
F1YZ27	FSA, 27 A/C 12 UH-1Y/15 AH-1Z
F21812	FSA, 12 A/C F/A-18A++/C/C+/D
F21824	FSA, 24 A/C F/A-18A++/C/C+/D (2ND PACKAGE ASSIGNED)
F25316	FSA, 16 A/C CH-53E (2ND PACKAGE ASSIGNED)
F2KJ09	FSA, 9 A/C KC-130J (2ND PACKAGE ASSIGNED)
F2V212	FSA, 12 A/C MV-22 (2ND PACKAGE ASSIGNED)
F2V816	FSA, 16 A/C AV-8B (2ND PACKAGE ASSIGNED)
F2YZ27	FSA, 27 A/C 12 UH-1Y/15 AH-1Z (2ND PACKAGE ASSIGNED)
F31824	FSA, 24 A/C F/A-18A++/C/C+/D (3RD PACKAGE ASSIGNED)
F35316	FSA, 16 A/C CH-53E (3RD PACKAGE ASSIGNED)
F3KJ09	FSA, 9 A/C KC-130J (3RD PACKAGE ASSIGNED)
F3V816	FSA, 16 A/C AV-8B (3RD PACKAGE ASSIGNED)
F45316	FSA, 16 A/C CH-53E (4TH PACKAGE ASSIGNED)
F4V816	FSA, 16 A/C AV-8B (4TH PACKAGE ASSIGNED)
F55316	FSA, 16 A/C CH-53E (5TH PACKAGE ASSIGNED)
IOSPXX	FOLLOW-ON SUPPORT IDENTIFIED BY ACTIVITY I.E. FOSP11, FOSP12, FOSP13, ETC.
MPSBLI	MPS SUPPORT BLOUNT ISLAND
MPSFLY	MPS SUPPORT FLY IN SUPPORT
MSA	MAG SUPPORT ALLOWANCE
MACSXX	MARINE AIR CONTROL SQUADRON
PALMXX	EAF, AGSE 29 PALM
SCIFXX	IDENTIFIES EQUIPMENT ADMINISTRATIVELY CONTROLLED BY THE INDICATED ACTIVITY BUT OPERATIONALLY CONTROLLED BY CMC
T53E29	TRAINING SQUADRON ALLOWANCE A/C CH-53E MALS 29
TF3531	TRAINING SQUADRON ALLOWANCE A/C F-35 MALS 31
TFRS11	TRAINING SQUADRON ALLOWANCE A/C F/A-18 MALS 11

Mobile Facility/Ancillary Equipment/Administrative Note
Cross Reference

NAME	DESCRIPTION
TH1M39	TRAINING SQUADRON ALLOWANCE A/C UH-1Y/18 AH-1Z MALS 39
TV2226	TRAINING SQUADRON ALLOWANCE A/C MV-22B MALS 26
TV8B14	TRAINING SQUADRON ALLOWANCE A/C AV-8B MALS 14
WGISSX	INTERIM SUPPORT ALLOWANCE (ISAL)

ADMINISTRATIVE NOTES

(A) Whenever the integration units are calculated within a package, the allowance is 1 JU-01 per 6 MFs rated. If there are any additional MFs after the quantity is determined, an additional asset will be authorized when 4 units are rated. Example: If you have 10 MFs authorized you will be authorized 2 JU-01's or equivalent.

(B) The SU-12 is replacing the TL-01 and TR-01 configurations by attrition. Units can utilize their own equipment to configure the SU-12 to meet a tool room or tech library configuration.

(C) The CU-01 is replacing the AM-01, CL-06, DP-03, MC-01, SU-04, SU-05, WC-02, and the WC-08 configurations by attrition.

(D) The HY-07A and HY-08B are replacing the HY-04A and HY-05B as the new A/F27T-12 bench is fielded.

(E) Large scale TBA adjustments due to configuration changes will be accomplished incrementally as the legacy MF configuration becomes unserviceable and disposition is requested.

MF User O-Level Maintenance Syllabus

Name _____ Rank _____ W/C / MOS _____

The following training is required for all personnel performing maintenance actions and quality assurance inspections on MFs (i.e. EAF and MACS) that have mobile facility allocations in accordance with enclosure (3) of MCO 13670.1G. The Mobile Facility Coordinator (MFC) shall maintain a copy of this training track in W/C 60C for all trained personnel currently assigned to the MALS or a unit that receives MF support from the MALS (i.e., EAF and MACS) that do not have an active ASM account.

Periodic Maintenance (PM) Training

Training will be conducted by a W/C 60C CDI on proper procedures for completion of the MF and ECU PM. During this training, the work will be conducted by the MF user with the W/C 60C CDI providing instruction. Training will be hands on training using a MF and NAVAIR-19-600-152-6-2 or NAVAIR 19-600-141-6-2 as a training aid.

7	Day MF PM	MCN _____	Date _____	CDI _____
30	Day MF PM	MCN _____	Date _____	CDI _____
90	Day MF PM	MCN _____	Date _____	CDI _____
180	Day MF PM	MCN _____	Date _____	CDI _____
360	Day MF PM	MCN _____	Date _____	CDI _____
90	Day ECU PM	MCN _____	Date _____	CDI _____
360	Day ECU PM	MCN _____	Date _____	CDI _____

Periodic Maintenance Performance

The MF user will perform the MF PM without W/C 60C instruction. The W/C 60C CDI will ensure proper performance of PM upon completion.

7	Day MF PM	MCN _____	Date _____	CDI _____
30	Day MF PM	MCN _____	Date _____	CDI _____
90	Day MF PM	MCN _____	Date _____	CDI _____
180	Day MF PM	MCN _____	Date _____	CDI _____
360	Day MF PM	MCN _____	Date _____	CDI _____
90	Day ECU PM	MCN _____	Date _____	CDI _____
360	Day ECU PM	MCN _____	Date _____	CDI _____

MF USER O-LEVEL MAINTENANCE QUALIFICATION

Name _____ Rank _____ W/C / MOS _____

Corrosion Prevention/Treatment

Corrosion prevention/treatment training will be provided to the MF user by a W/C 60C CDI. This training will stress the importance of *PROPER* corrosion prevention and treatment of the MF. Forklift pockets, rivets, emergency exit thumbscrews, and the seams between MF structural beams and MF walls will be given special attention during this training as these areas are most susceptible to a corrosive failure. Training will be hands on training using a MF as a training aid.

Date Training Provided _____

Training Provided By _____

Convention for Safe Container (CSC) Introduction

The MF user will receive an introduction to the CSC program from a certified CSC inspector. This training will familiarize the MF user with the purpose of the CSC program as well as common CSC failures that occur with MFs. The MF user should be able to identify structural issues that could result in failing the CSC inspection and identify these issues to W/C 60C. This introduction will not be a substitute for the AMMO-43 Intermodal Dry Cargo Container/CSC Re-inspection Course and will not certify the MF user as a CSC inspector. Training will be hands on training using a MF and MIL-STD-3037 as a training aid.

Date Training Provided _____

Training Provided By _____

Mobile Facility Preparation for Shipping

To prevent damage to the MF and contents during shipment, MF users will receive training from a W/C 60C CDI on the proper way to prepare a MF for shipping. This training will be hands on training using an MF and the AG-360-IIN-000 as training aids.

Date Training Provided _____

Training Provided By _____

MCO 13670.1G
21 MAY 2018



UNITED STATES MARINE CORPS
SQUADRON
MAG
WING
MARFOR PSC BOX #####
CITY STATE ZIP

IN REPLY REFER TO:
13670
AVO
Date

From: Avionics Officer, Marine Aviation Logistics Squadron ##
To: Rank Michael J. Marine, EDIPI/PMOS USMC

Subj: APPOINTMENT AS (UNIT) MOBILE FACILITY PROGRAM MANAGER

Ref: (a) COMNAVAIRFORINST 4790.2C
(b) MCO 13670.1G
(c) MIL-STD-3037
(d) NAVAIRINST 13670.1C
(e) AG-360MF-IIN-000
(f) AG-360MF-CCD-000
(g) NAVAIR 17-1-125
(h) NAVAIR 19-25-177

1. Per the references, you are hereby appointed as the Mobile Facility Program Manager for (UNIT).
2. You are to familiarize yourself with and utilize the references in the performance of your duties.

I. M. LEADER

13670
Date

FIRST ENDORSEMENT

From: Rank Michael J. Marine, EDIPI/PMOS USMC
To: Avionics Officer, Marine Aviation Logistics Squadron ##

1. I have reviewed the references, and hereby assume the duties as the Mobile Facility Program Manager.

M. J. MARINE

FOR OFFICIAL USE ONLY – PRIVACY SENSITIVE